## Investigation Results of Unit 3 Spent Fuel Pool Utilizing an Tokyo Electric Power Company Underwater Camera at Fukushima Daiichi Nuclear Power Station (Performed on February 14, 15, 16 and 18)

## [Results]

- The fuel handling machine mast which fell into the pool on February 6 had no impact on the fuel storage rack, liner, etc.
- No deformation was found on the fuel rack below the fuel handling machine.
- General distribution condition of the debris in the spent fuel pool was confirmed.






Photo 1: The lower part of the fuel handling machine and the fuel rack




Photo 2: Fuel rack (Photo taken from the above)



Photo 3: Sediments on the fuel rack

[Legend]

: Fuel storage rack

: Photo shooting direction



Photo 4: Corridor of the fuel handling machine




Photo 5: Bridge of the fuel handling machine