


Condition of the Bank Protection Area at Fukushima Daiichi Nuclear Power Station

<Reference>
September 11, 2013
Tokyo Electric Power Company




* Automatic measurement data measured by water gauge


Date of measurement

* No measurement could be performed at the groundwater observation hole No.1-3, since chemical has flowed into the hole. A water gauge has temporarily removed from the groundwater observation hole No.1-5 due to the ground improvement work. As for the ground observation hole No.1-9, there are some measurement results missing due to failure of the water gauge.

■Progress Status of Ground Improvement Construction between Unit 1 and 2 (As of the Morning on September 11)




■Progress Status of Ground Improvement Construction between Unit 2 and 3 (As of the Morning on September 11)



* The range of the construction is subject to change depends on the site status.

■Progress Status of Ground Improvement Construction between Unit 3 and 4 (As of the Morning on September 11)

Ground improvement (sea side): 29
out of 132 locations (construction
started on August 23, 2013)



*1 The range of the construction is subject to change depends on the site status.

*2 Groundwater observation hole No.3-1 will be not in use due to the ground improvement construction.