

<Reference>  
November 15, 2013  
Tokyo Electric Power Company

# Results for the Effectiveness Confirmation of Corrosion Prevention at the System C in the Multi-Nuclide Removal Equipment

**Tokyo Electric Power Company**




**東京電力**

---

# Inspection points of corrosion prevention effectiveness at System C

- Inspection points of corrosion prevention effectiveness (○) are described below.



## Main inspection items

- Batch treatment tanks: Whether there is a significant defect/exfoliation with linings, or not.
- Weld line and flange surface: How much corrosion a sacrificial positive electrode has or whether there is a significant corrosion, or not

# Result for corrosion prevention effectiveness at System C

Inspection point		Result
①	Batch treatment tank (1C and 2C) • Rubber lining (Inner inspection)	<b>No abnormality</b> • No significant damage such as defect and exfoliation with the lining
②	Slurry transfer pump outlet pipe • Flange surface • Pipe weld line	<b>No abnormality</b> • No corrosion on flange surface • No significant abrasion in gasket-type sacrificial positive electrode
③	Circulation tank • Tank weld line (UT confirmation)	<b>No abnormality</b> • No significant echo detected
④	Circulation pump 1 inlet pipe • Flange surface • Pipe weld line	<b>No abnormality</b> • No corrosion on flange surface • No significant abrasion in gasket-type sacrificial positive electrode
⑤	Decant pump outlet pipe • Flange surface • Pipe weld line	<b>No abnormality</b> • No corrosion on flange surface • No significant abrasion in gasket-type sacrificial positive electrode
⑥	Back-pulse pot 1 outlet pipe • Flange surface • Pipe weld line	<b>No abnormality</b> • No corrosion on flange surface • No significant abrasion in gasket-type sacrificial positive electrode

# Result for corrosion prevention effectiveness at System C

Inspection point		Result
⑦	Supply pump 1 Outlet pipe <ul style="list-style-type: none"> <li>• Flange surface</li> <li>• Pipe weld line</li> </ul>	<b>No abnormality (a remark described below)</b> <ul style="list-style-type: none"> <li>• corrosion-like minute pits on Flange surface</li> <li>• No significant abrasion in gasket-type sacrificial positive electrode</li> </ul>
⑧	Supply pump 2 Outlet pipe <ul style="list-style-type: none"> <li>• Flange surface</li> <li>• Pipe weld line</li> </ul>	<b>No abnormality</b> <ul style="list-style-type: none"> <li>• No corrosion on flange surface</li> <li>• No significant abrasion in gasket-type sacrificial positive electrode</li> </ul>
⑨	Adsorbent tower 2 <ul style="list-style-type: none"> <li>• Inspection hole (closing flange)</li> <li>• Adsorbent tower inner weld line</li> </ul>	<b>No abnormality</b> <ul style="list-style-type: none"> <li>• No corrosion on flange surface</li> <li>• No significant abrasion in gasket-type sacrificial positive electrode</li> </ul>
⑩	Adsorbent tower 7 <ul style="list-style-type: none"> <li>• Inspection hole (closing flange)</li> <li>• Adsorbent tower inner weld line</li> </ul>	<b>No abnormality</b> <ul style="list-style-type: none"> <li>• No corrosion on flange surface</li> <li>• No significant abrasion in gasket-type sacrificial positive electrode</li> </ul>
⑪	Adsorbent tower 8 <ul style="list-style-type: none"> <li>• Inspection hole (closing flange)</li> <li>• Adsorbent tower inner weld line</li> </ul>	<b>No abnormality</b> <ul style="list-style-type: none"> <li>• No corrosion on flange surface</li> <li>• No significant abrasion in gasket-type sacrificial positive electrode</li> </ul>
⑫	Treatment column 1 <ul style="list-style-type: none"> <li>• Vent pipe flange</li> </ul>	<b>No abnormality</b> <ul style="list-style-type: none"> <li>• No corrosion on flange surface</li> <li>• No significant abrasion in gasket-type sacrificial positive electrode</li> </ul>

# Result for corrosion prevention effectiveness at System C



←  
No significant damage such as defect and exfoliation

① Batch treatment tank 2C



←  
No corrosion on the flange sheet surface

② Slurry transfer pump outlet pipe flange



←  
A slight abrasion in gasket-type sacrificial positive electrode

( No influence on the sheet function )

② Slurry transfer pump outlet pipe gasket-type sacrificial positive electrode



←  
Three minute pits, which seem corrosion, on the flange-sheet surface

⑦ Supply pump 1 outlet pipe flange

# Result for corrosion prevention effectiveness at System C



←  
A slight abrasion in gasket-type sacrificial positive electrode

( No influence on the sheet function )

⑦ Supply pump 1 outlet pipe  
Gasket-type sacrificial positive electrode




←  
No corrosion on the flange-sheet surface

⑧ Supply pump 2 outlet pipe flange



←  
No corrosion on flange-sheet surface

⑨ Adsorbent tower 2C inspection hole



←  
No corrosion along the weld line

⑨ Adsorbent tower 2C weld line

# Result for corrosion prevention effectiveness at System C



←  
No corrosion  
on flange-  
sheet  
surface

With paste-  
like sacrificial  
positive  
electrodes  
applied

⑩ Adsorbent tower 7C inspection hole



←  
No  
corrosion  
along the  
weld line

⑩ Adsorbent tower 7C inner weld line



←  
No  
corrosion  
on the  
flange

⑫ Treatment column vent pipe flange



←  
A slight  
abrasion in  
gasket-type  
sacrificial  
positive  
electrode

No influence  
on the sheet  
function

⑫ Treatment column vent pipe  
gasket-type sacrificial positive electrode

# Corrosion at System A (Reference)

---



Slurry transfer pump outlet pipe (enlarged)  
with crevice corrosion on flange-sheet surface



Circulation tank return pipe nozzle  
with crevice corrosion on flange-sheet surface



Batch treatment tank 2A decant nozzle  
with crevice corrosion on flange-sheet surface



Supply pump 1A outlet pipe  
with crevice corrosion on flange-sheet surface



# Summary

---

- Comparing the inspection outcome at System C with corrosion prevention to the ones at System A and B without former corrosion prevention, we found that **generation of corrosion was definitely restrained and that our corrosion prevention was effective.**
- Although we found crevice corrosion in a part of flange sheet surface, it has no influence on sealing. Corrosion prevention **prevents definitely the progress of corrosion.**
- We **continue the inspection on a regular basis**, and will extend our knowledge
- Based on the confirmation the effectiveness of the corrosion prevention through this inspection, **the inspection period might be re-examined.**

# Hot test schedule

- System A: Currently in operation for treatment; Treatment will be **stopped temporarily in the End November** for confirmation of corrosion prevention effectiveness
- System B: Batch treatment tanks is currently being repaired ; and treatment operation is **scheduled to restart on November 21\***. \*Subject to change depending on work progress.
- System C: Confirmed corrosion prevention effectiveness, treatment will **restart on November 18.**

	November				December			Total amount of treated water (as of Nov. 13)
	3	10	17	24	Early	Mid	End	
System A	Treatment operation ↓ Control system remodeling and suspension of treatment ↑	△ Restart of treatment	Treatment operation			↓ Corrosion prevention effectiveness confirmation ↑	Treatment operation	13,781 m3
System B	Repair of batch treatment tanks and installation of sacrificial electrodes	↓ Filled up with adsorbents	↓ Water feeding to the system and check for leakage	↓ Treatment operation		Corrosion prevention confirmation	Restart of treatment △	10,493m3
System C		Restart of treatment △	↑	Treatment operation				5,475m3
	Corrosion prevention effectiveness confirmation and suspension of treatment							