Two samples were sent to the outside analysis facilities for detailed analysis on Sept 20. Shape will be observed and elements on surface will be analyzed in the future.

1 Unit 1 deposit at the PCV bottom

Sample collected at the PCV bottom during the internal investigation of Unit 1 (Collected in April, 2017)



Unit 1 deposit at the PCV bottom

2Unit 2 obstruction in the TIP tube

Attached material on the tip of the cable inserted for checking TIP tube (Collected in July, 2013)



Unit 2 obstruction in the TIP tube

