

< Reference >

September 24, 2011

Tokyo Electric Power Company

Current Status of Fukushima
Daiichi Nuclear Power Station
in photos

Photos taken on August 17 ~ September 7, 2011

Taken by TEPCO

List of photos

< Unit 5 Indoor facilities >

- (1) Unit 5 High Pressure Coolant Injection System turbine (Reactor building B2F)
Taken by TEPCO employee on August 24, 2011
- (2) Unit 5 residual heat removal system (RHR) pump (B)(D) (Reactor building B2F)
Taken by TEPCO employee on August 26, 2011
- (3) Unit 5 Reactor building ceiling crane
Taken by TEPCO employee on August 25, 2011
- (4) Condition at Unit 5 Primary Containment Vessel 2F
Taken by TEPCO employee on August 17, 2011
- (5) Inside Unit 5 pedestal (reactor foundation)
Taken by TEPCO employee on August 17, 2011
- (6) Unit 5 Emergency diesel generator (Turbine building B1F)
Taken by TEPCO employee on August 19, 2011
- (7) Unit 5 Moisture separator(3) (Turbine building B1F)
Taken by TEPCO employee on August 23, 2011
- (8) Unit 5 Moisture separator drain pipe support (Turbine building B1F)
Taken by TEPCO employee on August 23, 2011
- (9) Unit 5 High pressure turbine (Turbine building 2F)
Taken by TEPCO employee on August 23, 2011
- (10) Unit 5 Boric acid injection pump (A) (Reactor building 4F)
Taken by TEPCO employee on August 19, 2011
- (11) Unit 5 Control rod water pressure control unit (Reactor building 1F)
Taken by TEPCO employee on August 19, 2011
- (12) Unit 5 Main steam isolation valve (Primary Containment Vessel 1F)
Taken by TEPCO employee on August 17, 2011

< Unit 6 Indoor facilities >

- (13) Unit 6 residual heat removal system (RHR) pump (C) (Reactor building B2F)
Taken by TEPCO employee on August 18, 2011
- (14) Unit 6 Emergency diesel generator (A) (Turbine building B1F)
Taken by TEPCO employee on August 19, 2011
- (15) Unit 6 High Pressure Core Spray System diesel generator (Reactor building B1F)
Taken by TEPCO employee on August 19, 2011
- (16) Unit 6 gas treatment System (A)(B) (Reactor building 3F)
Taken by TEPCO employee on August 19, 2011
- (17) Unit 6 Low Pressure Core Spray System pump (Reactor building B2F)
Taken by TEPCO employee on August 18, 2011
- (18) Unit 6 High Pressure Core Spray System pump (Reactor building B2F)
Taken by TEPCO employee on August 18, 2011
- (19) Unit 6 Boric acid injection pump (A) (Reactor building 5F)
Taken by TEPCO employee on August 24, 2011
- (20) Unit 6 High pressure condensate pump (Turbine building B1F)
Taken by TEPCO employee on August 23, 2011
- (21) Unit 6 Reactor building ceiling crane
Taken by TEPCO employee on August 24, 2011
- (22) Unit 6 feed water heater (Turbine building 1F)
Taken by TEPCO employee on August 25, 2011
- (23) Unit 6 Low pressure turbine (Turbine building 2F)
Taken by TEPCO employee on August 23, 2011
- (24) Unit 6 Complex building B2F
Taken by TEPCO employee on August 23, 2011

List of photos

< Unit 5 Outdoor facilities >

- (25) Unit 5 Intake channel
Taken by TEPCO employee on August 23,2011
- (26) Unit 5 Circulating water pump (B)(C)
Taken by TEPCO employee on August 23,2011
- (27) Unit 5 Screen
Taken by TEPCO employee on August 23,2011
- (28) Unit 5 Seaside slope
Taken by TEPCO employee on August 25,2011
- (29) Unit 5 Water intake cable pit
Taken by TEPCO employee on August 25,2011
- (30) Unit 5 Main transformer
Taken by TEPCO employee on August 24,2011
- (31) Unit 5 Basement of Main exhaust stack
Taken by TEPCO employee on September 7,2011
- (32) Unit 5 Insulator cleaning tank
Taken by TEPCO employee on August 24,2011

< Unit 6 Outdoor facilities >

- (33) Unit 6 High pressure core spray system Diesel generator Seawater system pump
Taken by TEPCO employee on August 23,2011
- (34) Unit 6 Around screen
Taken by TEPCO employee on August 28,2011
- (35) Unit 6 Reversing valve pit
Taken by TEPCO employee on August 22,2011
- (36) Unit 6 Main transformer
Taken by TEPCO employee on August 24,2011

< Unit 5 and 6 side Outdoor facilities >

- (37) Unit 5 and 6 Extinction pipes
Taken by TEPCO employee on August 22,2011
- (38) Unit 5 and 6 Extinction pipes
Taken by TEPCO employee on August 22,2011
- (39) Unit 5 and 6 Extinction pipes
Taken by TEPCO employee on August 22,2011

Unit 5 (Indoor facilities)

(1)



(1) Unit 5 High Pressure Coolant Injection System turbine (Reactor building B2F)

Taken by TEPCO employee on August 24, 2011

(3)



(3) Unit 5 Reactor building ceiling crane

Taken by TEPCO employee on August 25, 2011

(2)



(2) Unit 5 residual heat removal system (RHR) pump (B)(D) (Reactor building B2F)

Taken by TEPCO employee on August 26, 2011

(4)



(4) Condition at Unit 5 Primary Containment Vessel 2F

Taken by TEPCO employee on August 17, 2011

Unit 5 (Indoor facilities)

(5)



(5) Inside Unit 5 pedestal (reactor foundation)
Taken by TEPCO employee on August 17, 2011

(7)



(7) Unit 5 Moisture separator(3) (Turbine building B1F)
Taken by TEPCO employee on August 23, 2011

(6)



(6) Unit 5 Emergency diesel generator (Turbine building B1F)

Taken by TEPCO employee on August 19, 2011 (8)



(8) Unit 5 Moisture separator drain pipe support
(Turbine building B1F)

Taken by TEPCO employee on August 23, 2011

Unit 5 (Indoor facilities)

(9)



(9) Unit 5 High pressure turbine (Turbine building 2F)
Taken by TEPCO employee on August 23, 2011

(11)



(11) Unit 5 Control rod water pressure control unit
(Reactor building 1F)
Taken by TEPCO employee on August 19, 2011

(10)



(10) Unit 5 Boric acid injection pump (A)
(Reactor building 4F)
Taken by TEPCO employee on August 19, 2011

(12)



(12) Unit 5 Main steam isolation valve (Primary
Containment Vessel 1F)
Taken by TEPCO employee on August 17, 2011

Unit 6 (Indoor facilities)

(13)



(13) Unit 6 residual heat removal system (RHR) pump (C) (Reactor building B2F)
Taken by TEPCO employee on August 18, 2011

(14)



(14) Unit 6 Emergency diesel generator (A) (Turbine building B1F)
Taken by TEPCO employee on August 19, 2011

(15)



(15) Unit 6 High Pressure Core Spray System diesel generator (Reactor building B1F)
Taken by TEPCO employee on August 19, 2011

(16)



(16) Unit 6 gas treatment System (A)(B) (Reactor building 3F)
Taken by TEPCO employee on August 19, 2011

Unit 6 (Indoor facilities)

(17)



(17) Unit 6 Low Pressure Core Spray System pump
(Reactor building B2F)

Taken by TEPCO employee on August 18, 2011 (19)

(18)



(18) Unit 6 High Pressure Core Spray System pump
(Reactor building B2F)

Taken by TEPCO employee on August 18, 2011 (20)



(19) Unit 6 Boric acid injection pump (A)
(Reactor building 5F)

Taken by TEPCO employee on August 24, 2011



(20) Unit 6 High pressure condensate pump (Turbine building B1F)

Taken by TEPCO employee on August 23, 2011

Unit 6 (Indoor facilities)

(21)



(21) Unit 6 Reactor building ceiling crane
Taken by TEPCO employee on August 24, 2011

(22)



(22) Unit 6 feed water heater (Turbine building 1F)
Taken by TEPCO employee on August 25, 2011

(23)



(23) Unit 6 Low pressure turbine (Turbine building 2F)
Taken by TEPCO employee on August 23, 2011

(24)



(24) Unit 6 Complex building B2F
Taken by TEPCO employee on August 23, 2011

Unit 5 (Outdoor facilities)

(25)



(25) Unit 5 Intake channel
Taken by TEPCO employee on August 23,2011

(26)



(26) Unit 5 Circulating water pump (B)(C)
Taken by TEPCO employee on August 23,2011

(27)



(27) Unit 5 Screen
Taken by TEPCO employee on August 23,2011

(28)



(28) Unit 5 Seaside slope
Taken by TEPCO employee on August 25,2011

Unit 5 (Outdoor facilities)

(29)



(29) Unit 5 Water intake cable pit
Taken by TEPCO employee on August 25,2011

(31)



(31) Unit 5 Basement of Main exhaust stack
Taken by TEPCO employee on September 7,2011

(30)



(30) Unit 5 Main transformer
Taken by TEPCO employee on August 24,2011

(32)



(32) Unit 5 Insulator cleaning tank
Taken by TEPCO employee on August 24,2011

Unit 6 (Outdoor facilities)

(33)



(33) Unit 6 High pressure core spray system Diesel generator
Seawater system pump
Taken by TEPCO employee on August 23,2011

(34)



(34) Unit 6 Around screen
Taken by TEPCO employee on August 28,2011

(35)



(35) Unit 6 Reversing valve pit
Taken by TEPCO employee on August 22,2011

(36)



(36) Unit 6 Main transformer
Taken by TEPCO employee on August 24,2011

Unit 5 and 6 side (Outdoor facilities)

(37)



(37) Unit 5 and 6 Extinction pipes
Taken by TEPCO employee on August 22,2011 (39)

(38)



(38) Unit 5 and 6 Extinction pipes
Taken by TEPCO employee on August 22,2011



(38) Unit 5 and 6 Extinction pipes
Taken by TEPCO employee on August 22,2011