

Status of survey for water leakage at welded part of filter valve at B line of 2nd Cesium adsorption apparatus (SARRY)

At 8:30 am on February 25, 2012, we found water leakage at welded part of filter valve at B line of 2nd Cesium adsorption apparatus (SARRY). On February 26, 2012, we confirm that there was no water leakage after repair work.


On February 28, 2012, we checked the inside of piping using CCD camera.




Status of piping inside (Leakage point)



Picture of piping (at the time of water leakage)



After valve removal (from upper part)



After valve removal (taken with CCD camera)