- Date of investigation: September 13, 2012
- Number of workers involved: 19

An underwater camera was hung from the crawler crane down into the spent fuel pool to investigate the condition of the tip of steel members partially immersed in the pool water.



The entire view of the spent fuel pool



The entire view of the spent fuel pool



Debris in the spent fuel pool (under water)



Debris in the spent fuel pool (water surface)



Debris in the spent fuel pool (under water)



Debris in the spent fuel pool (water surface)