


PN ←




Phase I: Work area where floor tiles have been replaced



Phase II: Work area

1st Floor (Plane)


Replacement of Floor Mat in the Main Anti-Earthquake Building (Plane)



Work Area ③
4/3 (Sun)
Completed

Work Area ②
4/2 (Sat)
Completed


Work Area ① 4/1 (Fri) Completed



Phase I: Work area where floor tiles have been replaced

Phase II: Work area

2nd Floor (Plane)



Work Area ②
4/2 (Sat) Completed

Work Area ③
4/3 (Sun) Completed

Meeting Room (2)

Meeting Room (1)

Rest Room (2)

The area has not been replaced yet because there are heavy materials (APD Shelf, Book Shelf, Goods Shelf, etc.)

Work Area ④
4/5 (Tue) Completed

Work Area ⑥
4/7 (Thu) Completed

Work Area ⑤
4/6 (Wed) Completed

Operation Room for Cooperation Companies

Work Area ⑥
4/7 (Thu) Completed

Work Area ⑤
4/6 (Wed) Completed

Recovery Group

Recovery Group

Generation Group

Technical Group

Security Group

Work Area ③
4/3 (Sun) Completed

Information Group

Medical and Health Group

Copy and Fax Room (1)

Report Group

General Affairs Group

Hot Line Room

Work Area ④
4/5 (Tue) Completed

Emergency Response Room

Work Area ⑤
4/6 (Wed) Completed

Public Relations Group

Procurement Group

Rest Room (1)

Guard and Guidance Group

Work Area ②
4/2 (Sat) Completed

HQ's Officer

Information Collection, SPDS Monitoring, Data Maintenance and Copy/Fax Room

Room for Dispatched Staff

Emergency Stockyard (2)

Work Area