



Oil leakage found around water discharge canal of Unit 3, 4