
Description errors in the Report on the seismic safety assessment of unit 5 and unit 6 of Kashiwazaki-kariwa Nuclear Power Station

1. Errors in the description

· Example of errors in the description of figures

The title of the figures was misstated as "core structure – horizontal direction maximum response acceleration spectrum (NS direction)" which was in correct description "core internals – horizontal direction maximum response acceleration spectrum (NS direction)" (example: Unit 5 Kashiwazaki-Kariwa Nuclear Power Station Report on Seismic Safety Assessment (Equipments and piping systems))




最大応答加速度(NS 方向)

2. Errors in the figures

Example of errors in the description of figures

There were errors in plot data for the figures of "core shroud - vertical direction maximum response acceleration spectrum". The figure was not used in the seismic safety assessment. (example: Unit 6 Kashiwazaki-Kariwa Nuclear Power Station Report on Seismic Safety Assessment (Equipments and piping systems))



参図-7.2.23 炉心シュラウド鉛直方向 最大応答加速度


参図-7.2.23 炉心シュラウド鉛直方向 最大応答加速度

3. Errors in the name of the figures

· Example of errors in the name of the figures

In the figure of the "Turbine Building - maximum response acceleration spectrum", the name of the two figures were placed the other way around.

(example : Unit 6 Kashiwazaki-Kariwa Nuclear Power Station Report on Seismic Safety Assessment (Buildings and structures))



End