


### Image of the actual SFP



On June 12, we corrected the thickness of the stainless steel plate from 3mm to 6mm.

### Image of the SFP used in the coverage

