

Boring Holes Drilled Around the Underground Reservoir No.2 at Fukushima Daiichi Nuclear Power Station in Order to Understand the Contamination Condition

<Reference>
June 7, 2013

Tokyo Electric Power Company

- Boring holes 2-14, 2-15 and 2-16 will be additionally drilled outside of the holes 2-10, 2-11 and 2-12 where all β was detected in order to understand the contaminated range.
- The soil will be removed utilizing a steel pipe based on the result of the contaminated range.
- Drilling of the boring holes 2-14, 2-15 and 2-16 will be performed from June 8, 2013.

