


Leakage detected between cable duct for starting transformer and control building Unit 3, Fukushima Daiichi Nuclear Power Station



Ground plan of transformer yard, Unit 3

