

Strainer washing due to Suction pressure decrease of Primary coolant system pump, in Spent fuel pool closed loop cooling system at Fukushima Daiichi Nuclear Power Station Unit 3

November 7, 2011
Tokyo Electric Power Company

