

Unit 4 Spent Fuel Pool Circulation Cooling System UPS Inside Inspection

1. UPS Inside Inspection (1)

On July 5, UPS installed in the control panel was removed for an appearance and inside inspection.

UPS: Uninterruptible power (-supply) system



Control panel (Front)



Control panel (Back)




Removed (failed) UPS

No damage found on the front and the back of the control panel.

2. UPS Inside Inspection (2)

Failed UPS



Spare UPS



Failed UPS: Covered with soot and dust
Spare UPS: No soot found though a little dusty