
Oil leakage in auxiliary boiler building (non control area), common facilities in Arahama-side



1<sup>st</sup> floor, auxiliary boiler building, Arahama side, Kashiwazaki Kariwa NPS