

May 5th, 2011
Tokyo Electric Power Company

Mistakes in the report on investigation of cause and development of preventive measures regarding exposure exceeding dose limit to radiation dose engaged person at Fukushima Daiichi Nuclear Power Station to NISA

On May 2nd, we reported the causes and measures to NISA regarding “exposure exceeding dose limit to radiation dose engaged person at Fukushima Daiichi Nuclear Power Station,” which were announced on April 27th and May 1st. Since mistakes have been found in the report, we modify them and hereby announce that with apologies.

<Background>

On May 3rd we received inquiries from Labor Department of Fukushima Prefecture as to the work of the female employee who was working in Main Anti-Earthquake Building. Accordingly, we confirmed the work in detail, and found there were mistakes in the report submitted to NISA.

<Details>

In compiling the number of female employees (19 in total), there actually was a worker (radiation worker) who did not work in Main Anti-Earthquake Building while it was reported that the worker was assumed and counted as a worker who worked in Main Anti-Earthquake Building. Also, there actually was a worker (non-radiation worker) who worked in Main Anti-Earthquake Building while the worker was counted as a worker who did not work in Main Anti-Earthquake Building.

With regard to other workers, we confirmed that there are no similar mistakes by directly confirming with the workers or their immediate supervisors.

We will consult with NISA regarding the actions to be taken ahead.

End