


Figure depicting status of oil leakage in the surroundings of the discharge channels of Units 3 and 4



Oil leakage conditions of High-voltage Start-up Transformer