TEPCO Plant Status of Fukushima Daini Nuclear Power Station (as of 3:00 pm on November 25, 2011)

Appendix

	Unit 1	Unit 2	Unit 3	Unit 4
Function to shut down reactor (Shutdown)	Automatic shutdown (at 2:48 pm on March 11)	Automatic shutdown (at 2:48 pm on March 11)	Automatic shutdown (at 2:48 pm on March 11)	Automatic shutdown (at 2:48 pm on March 11)
	All control rods are all inserted	All control rods are all inserted	All control rods are all inserted	All control rods are all inserted
Function to inject water and to remove heat (Cooling)	Residual heat removal system(A) is in operation. Residual heat removal system (B) is not on standby due to the changing the motor of pump (B) of emerency deisel generator cooling system from 5:55 am on November 24.Planned to be at standby on November 26	Residual heat removal system(A) is in operation. Residual heat removal system (B) is on standby.	Residual heat removal system(A) is in operation. Residual heat removal system (B) is on standby.	Residual heat removal system(A) is in operation. Residual heat removal system (B) is on standby.
	Reactor Coolant Filtering System is in operation (From July 16) [Securing alternative heat removal function in cold	Reactor Coolant Filtering System is in operation (From July 17) [Securing alternative heat removal function in cold	Reactor Coolant Filtering System is in operation (From June 6) [Securing alternative heat removal function in cold	Reactor Coolant Filtering System is in operation (From June 4) Securing alternative heat removal function in cold
	shutdown]	shutdown]	shutdown	shutdown]
	Cold shutdown * (From March 14)	Cold shutdown * (From March 14)	Cold shutdown * (From March 12)	Cold shutdown * (From March 15)
Primary Containment Vessel (isolation, removal of heat) (Cooling and containment)	No leakage of coolant in PCV	No leakage of coolant in PCV	No leakage of coolant in PCV	No leakage of coolant in PCV
	Water temperature in Suppression Chamber is stable (generally 30).(On March 14, achieved below 100)	Water temperature in Suppression Chamber is stable (generally 30).(On March 14, achieved below 100)	Water temperature in Suppression Chamber is usual (generally 30).(Having maintained below 100 before the earthquake)	Water temperature in Suppression Chamber is stable (generally 30).(On March 15, achieved below 100)
	No ventilation (measure to decrease the pressure in PCV) implemented	No ventilation (measure to decrease the pressure in PCV) implemented	No ventilation (measure to decrease the pressure in PCV) implemented	No ventilation (measure to decrease the pressure in PCV) implemented
Offsite power	Received	Received	Received	Received
Emergency power supply sources	Receiving electricity from the emergency diesel generator (A) (B) of Unit 2 Residual heat removal system (B) is not on standby due to the changing the motor of pump (B) of emerency deisel generator cooling system from 5:55 am on November 24.Planned to be	Emergency diesel generator (A)(B) The emergency diesel generators (H) is under inspection.	Emergency diesel generator (A)(B)(H)	Emergency diesel generator (A) (B) (H)
Others, any reports regarding abnormal matters	At 5:35 pm on March 11, Occurrence of a Specific Incident Stipulated in Article 10 of the Act on Special Measures Concerning Nuclear Emergency Preparedness (reactor coolant is leaked (increase of pressure in PCV)) At 6:33 pm on March 11, judged that no			
	heat)	At 6:33 pm on March 11, Occurrence of a Specific Incident Stipulated in Article 10 of the Act on Special Measures Concerning Nuclear Emergency Preparedness (loss of function to remove residual heat)		At 6:33 pm on March 11. Occurrence of a Specific Incident Stipulated in Article 10 of the Act on Special Measures Concen Nuclear Emergency Preparedness (loss of function to remove re heat)
	At 1:24 am on March 14, Restored by the start of Resi	At 7:13 am on March 14, Restored by the start of Resi		At 3:42 pm on March 14, Restored by the start of Resi
	At 5:22 am on March 12, Occurrence of a Specific Incident Stipulated in Article 15 of the Act on Special Measures Concerning Nuclear Emergency Preparedness (loss of function to suppress pressure) At 10:15 am on March 14, Restored by the decrease of the	At 5:32 am on March 12, Occurrence of a Specific Incident Stipulated in Article 15 of the Act on Special Measures Concerning Nuclear Emergency Preparedness (loss of function to suppress pressure) At 3:52 pm on March 14, Restored by the decrease of the w		At 6.07 am on March 12, Occurrence of a Specific Incident Stipulated in Article 15 of the Act on Special Measures Concer Nuclear Emergency Preparedness (loss of function to suppressure) At 7:15 am on March 15, Restored by the decrease of the
	At 10:07 pm on March 14th at the MP 1 and 12:12 am on radioactive material at the bou	March 15th at the MP 3, Occurrence of a Specific Incident S	Stipulated in Article 10 of the Act on Special Measures Conce	rning Nuclear Emergency Preparedness (increase in