



Inspection of the inside of Unit 4 main exhaust duct

From April 2 to 13, 2012, a visual inspection of the inside of Unit 4 main exhaust duct was done in order to investigate the air leak from the duct occurred on June 8, 2011 (Press release issued on July 31, 2011). As a result, no issue was found. In addition, a displacement measurement (to measure the amount of duct deformation) was done on the duct from April 19 to 26, 2012. The measurement result will be evaluated and analyzed.



1. Outer appearance of Unit 4 main exhaust duct (Photo taken on April 5, 2012)



2. Inspection door of the main exhaust duct (Photo taken on April 5)



3. Inspecting the inside of the main exhaust duct (Photo taken on April 5, 2012)



4. Displacement measurement done on the main exhaust duct from April 19 to 26, 2012 (Photo taken on April 24, 2012)