


< Reference >
Condition of the fuel assembly where
the water rod was found to be bent



**Overview of the bent fuel assembly water rods found at
Unit 1 at Kashiwazaki-Kariwa Nuclear Power Station**