
Bq/cm3
Fukushima Daiichi Nuclear Power Station
Results of Dust Nuclide Analysis
1.0E-01
1.0E-02
1.0E-03
1.0E-04
1.0E-05
1.0E-06
1.0E-07
I-131(Total; West Gate)
Cs-134(Total; West Gate)
Cs-137(Total ;West Gate)
White marks are additional measurement points
□:I-131 △:Cs-134 ○:Cs-137
①South of Unit 5
②North east of administration office bulding
③North east of the ground
④North west of the ground
⑤West gate
⑥Main gate
⑦South east of Skill training center
⑧West of Industrial waste treatment facility
⑨South side of Centralized Radiation Waste Treatment Facility
⑩Around MP5
Notification Level
Cs-137 (3E-3Bq/cm3)
Cs-134 (2E-3Bq/cm3)
I-131 (1E-3Bq/cm3)
⑩
⑧
⑧
⑥
5/15
5/19
5/23
5/27
5/31
6/4
6/8
6/12
6/16
6/20
6/24
6/28
7/2
7/6
7/10
7/14