

Evaluation of the exposure dose of workers engaged in radiation work at
the Fukushima Daiichi Nuclear Power Station

July 30, 2025
Tokyo Electric Power Company Holdings, Inc.
Fukushima Daiichi D & D Engineering Company

TEPCO has been evaluating the exposure dose of workers who engaged in radiation work at the Fukushima Daiichi Nuclear Power Station under two types, internal and external exposure to radiation, and has submitted the evaluation results to the Ministry of Health, Labour and Welfare regularly.

TEPCO today submitted to the Ministry of Health, Labour and Welfare a report on the exposure dose evaluation the data of which are those we collected until the end of June 2025. Here is part of the report: the maximum value of the external exposure dose among the workers who engaged in the work at the power station in June was 7.51 mSv, and regarding the internal exposure dose, no significant value was measured.

Exposure Dose Distribution

1. Effective Dose from External Exposure

Table 1 shows the distribution of external exposure dose of workers who were involved in radiation work at the Fukushima Daiichi Nuclear Power Station for the past three months.

Table 1. External Exposure Dose

| Dose Ranges (mSv) | April 2025 | | | May 2025 | | | June 2025 | | |
|-------------------|-----------------|-------------|-------|-----------------|-------------|-------|-----------------|-------------|-------|
| | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total |
| Above 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 5-10 | 0 | 18 | 18 | 0 | 24 | 24 | 0 | 9 | 9 |
| 1-5 | 13 | 517 | 530 | 5 | 398 | 403 | 2 | 395 | 397 |
| 1 or less | 997 | 5978 | 6975 | 988 | 6155 | 7143 | 1041 | 6373 | 7414 |
| Total | 1010 | 6513 | 7523 | 993 | 6577 | 7570 | 1043 | 6777 | 7820 |
| Maximum (mSv) | 1.7 | 9.9 | 9.9 | 2.6 | 7.4 | 7.4 | 1.16 | 7.51 | 7.51 |
| Average (mSv) | 0.06 | 0.28 | 0.25 | 0.05 | 0.24 | 0.22 | 0.05 | 0.21 | 0.19 |

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

2. Sum of External and Internal Exposure Dose (Effective Dose)

Table 2 shows the distribution of cumulative exposure dose of workers who are involved in radiation work at Fukushima Daiichi for five years, starting on April 1, 2021. Table 3 shows the distribution of cumulative exposure dose in the fiscal year of 2025. Two different periods of time are shown in the Table 2: from April 1, 2021 to May 31, 2025 and from April 1, 2021 to June 30, 2025, and in the Table 3: from April 1, 2025 to May 31, 2025 and from April 1, 2025 to June 30, 2025, for comparison.

Table 2. Cumulative Exposure Dose for Five Years

| Dose Ranges (mSv) | April 2021 - May 2025 | | | April 2021 - June 2025 | | | Difference | | |
|-------------------|-----------------------|-------------|-------|------------------------|-------------|-------|-----------------|-------------|-------|
| | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total |
| Above 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 50-75 | 0 | 134 | 134 | 0 | 144 | 144 | 0 | 10 | 10 |
| 20-50 | 38 | 1396 | 1434 | 38 | 1436 | 1474 | 0 | 40 | 40 |
| 10-20 | 74 | 2010 | 2084 | 77 | 1991 | 2068 | 3 | -19 | -16 |
| 5-10 | 139 | 1772 | 1911 | 139 | 1797 | 1936 | 0 | 25 | 25 |
| 1-5 | 388 | 2939 | 3327 | 389 | 2936 | 3325 | 1 | -3 | -2 |
| 1 or less | 1292 | 9225 | 10517 | 1367 | 9343 | 10710 | 75 | 118 | 193 |
| Total | 1931 | 17476 | 19407 | 2010 | 17647 | 19657 | 79 | 171 | 250 |
| Maximum (mSv) | 36.92 | 70.06 | 70.06 | 37.26 | 72.37 | 72.37 | - | - | - |
| Average (mSv) | 2.16 | 5.72 | 5.37 | 2.11 | 5.75 | 5.38 | - | - | - |

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

- No significant internal exposure has been reported since October 2011.

Table 3. Cumulative Exposure Dose in the Fiscal Year of 2025

| Dose Ranges (mSv) | April 2025 - May 2025 | | | April 2025 - June 2025 | | | Difference | | |
|-------------------|-----------------------|-------------|-------|------------------------|-------------|-------|-----------------|-------------|-------|
| | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total |
| Above 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10-20 | 0 | 6 | 6 | 0 | 19 | 19 | 0 | 13 | 13 |
| 5-10 | 0 | 99 | 99 | 0 | 190 | 190 | 0 | 91 | 91 |
| 1-5 | 20 | 819 | 839 | 44 | 1042 | 1086 | 24 | 223 | 247 |
| 1 or less | 1094 | 6248 | 7342 | 1189 | 6437 | 7626 | 95 | 189 | 284 |
| Total | 1114 | 7172 | 8286 | 1233 | 7688 | 8921 | 119 | 516 | 635 |
| Maximum (mSv) | 3.8 | 11.7 | 11.7 | 3.88 | 12.68 | 12.68 | - | - | - |
| Average (mSv) | 0.10 | 0.48 | 0.43 | 0.14 | 0.63 | 0.56 | - | - | - |

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

3. Sum of External and Internal Exposure Dose of Workers Exposed to Especially High Radiation (Effective Dose)

Table 4 shows the distribution of cumulative exposure dose of workers exposed to especially high radiation.*¹

Table 4. Cumulative Exposure Dose (workers exposed to especially high radiation)

| Dose Ranges (mSv) | March 2011 - September 2015 |
|-------------------|-----------------------------|
| Above 100 | 1 |
| 75-100 | 191 |
| 50-75 | 233 |
| 20-50 | 267 |
| 10-20 | 186 |
| 5-10 | 129 |
| 1-5 | 145 |
| 1 or less | 51 |
| Total | 1203 |
| Maximum (mSv) | 102.69 |
| Average (mSv) | 36.49 |

(Since October 2015, TEPCO Holdings has opted not to report to the Labour Standards Inspection Office about workers exposed to especially high radiation.)

*1. Workers exposed to especially high radiation means workers who are involved in operations in which they could be exposed to the emergency exposure dose limit (100 mSv), which is stipulated in "Ordinance on Prevention of Ionizing Radiation Hazards, Chapter 7." In more detail, they are workers engaged in the work to maintain the function of the cooling facility to cool down the reactor facility or the spent fuel tank in the reactor facility, the steam turbine and its related facilities or the surrounding area where the radiation doses exceed 0.1 mSv/h. Or they are workers who would engage in keeping running the function to control or prevent the release of a large number of radioactive materials should it be likely to occur due to malfunction or damage of the reactor facility.

So far workers who have worked as "workers exposed to especially high radiation" are all TEPCO employees.

*2. The figures in the cumulative data during the period from March 2011 to September 2015 in Table 4 above include the numbers of workers who have been reported to work as “workers exposed to especially high radiation” at least once.

*3. The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or the dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

*4. The figure shown in the dose range, “Above 100mSv,” in the cumulative data during the period from March 2011 to September 2015 is the figure when the March 2011 data of the internal exposure dose were reevaluated in July 2013.

4. Equivalent Dose

Table 5 and Table 6 show equivalent dose to the skin and the lens of the eye of the workers, respectively, who were involved in radiation work at the Fukushima Daiichi Nuclear Power Station for the past three months.

Table 5. Equivalent Dose to the Skin

| Dose Ranges (mSv) | April 2025 | | | May 2025 | | | June 2025 | | |
|-------------------|-----------------|-------------|-------|-----------------|-------------|-------|-----------------|-------------|-------|
| | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20-50 | 0 | 2 | 2 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10-20 | 0 | 5 | 5 | 0 | 3 | 3 | 0 | 0 | 0 |
| 5-10 | 0 | 31 | 31 | 0 | 39 | 39 | 0 | 12 | 12 |
| 1-5 | 13 | 586 | 599 | 7 | 465 | 472 | 2 | 445 | 447 |
| 1 or less | 997 | 5889 | 6886 | 986 | 6070 | 7056 | 1041 | 6320 | 7361 |
| Total | 1010 | 6513 | 7523 | 993 | 6577 | 7570 | 1043 | 6777 | 7820 |
| Maximum (mSv) | 1.7 | 24.7 | 24.7 | 2.6 | 14.7 | 14.7 | 1.16 | 8.02 | 8.02 |
| Average (mSv) | 0.06 | 0.34 | 0.30 | 0.05 | 0.30 | 0.26 | 0.06 | 0.23 | 0.21 |

• The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or the dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

• Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the skin is 500 mSv/year (the emergency exposure dose limit is 1 Sv).

• Equivalent dose to the skin is measured at a depth of 70 micrometers from the skin surface. When the equivalent dose is measured with a dosimeter other than the one put on around the chest and the abdomen, for example, a finger dosimeter, the maximum measurement value is counted as the equivalent dose.

Table 6. Equivalent Dose to the Lens of the Eye

| Dose Ranges (mSv) | April 2025 | | | May 2025 | | | June 2025 | | |
|-------------------|-----------------|-------------|-------|-----------------|-------------|-------|-----------------|-------------|-------|
| | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10-20 | 0 | 5 | 5 | 0 | 0 | 0 | 0 | 0 | 0 |
| 5-10 | 0 | 23 | 23 | 0 | 24 | 24 | 0 | 11 | 11 |
| 1-5 | 13 | 535 | 548 | 5 | 421 | 426 | 2 | 440 | 442 |
| 1 or less | 997 | 5950 | 6947 | 988 | 6132 | 7120 | 1041 | 6326 | 7367 |
| Total | 1010 | 6513 | 7523 | 993 | 6577 | 7570 | 1043 | 6777 | 7820 |
| Maximum (mSv) | 1.7 | 12.1 | 12.1 | 2.6 | 8.5 | 8.5 | 1.16 | 8.02 | 8.02 |
| Average (mSv) | 0.06 | 0.30 | 0.27 | 0.05 | 0.26 | 0.23 | 0.06 | 0.23 | 0.21 |

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or the dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.
- Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the lens of the eye is 50 mSv/year and 100 mSv/5 years (the emergency exposure dose limit is 300 mSv). The equivalent dose limit to the lens of the eye before April 1, 2021 was 150mSv/year (the emergency exposure dose limit was 300 mSv).
- The equivalent dose to the lens of the eye is measured at a depth of 1 centimeter for neutron ray, 3 millimeters for X-ray, gamma ray and beta ray from the skin surface. However, as for X-ray, gamma ray and beta ray, it is measured at a depth of 1 centimeter or 70 micrometer when deemed appropriate with consideration for radiation type and energy type (since April, 2021).

5. Cumulative Equivalent Dose

Table 7 and Table 8 show the distribution of cumulative equivalent dose to the skin and the lens of the eye of the workers, respectively, who were involved in radiation work at the Fukushima Daiichi Nuclear Power Station during two different periods of time, from April 1, 2025 to May 31, 2025 and from April 1, 2025 to June 30, 2025 for comparison.

Table 9 shows the distribution of cumulative exposure dose for five years, starting on April 1, 2021: from April 1, 2021 to May 31, 2025 and from April 1, 2021 to June 30, 2025 for comparison.

Table 7. Equivalent Dose to the Skin

| Dose Ranges (mSv) | April 2025 - May 2025 | | | April 2025 - June 2025 | | | Difference | | |
|-------------------|-----------------------|-------------|-------|------------------------|-------------|-------|-----------------|-------------|-------|
| | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20-50 | 0 | 2 | 2 | 0 | 3 | 3 | 0 | 1 | 1 |
| 10-20 | 0 | 23 | 23 | 0 | 48 | 48 | 0 | 25 | 25 |
| 5-10 | 0 | 139 | 139 | 0 | 242 | 242 | 0 | 103 | 103 |
| 1-5 | 26 | 879 | 905 | 50 | 1085 | 1135 | 24 | 206 | 230 |
| 1 or less | 1088 | 6129 | 7217 | 1183 | 6310 | 7493 | 95 | 181 | 276 |
| Total | 1114 | 7172 | 8286 | 1233 | 7688 | 8921 | 119 | 516 | 635 |
| Maximum (mSv) | 3.8 | 27.2 | 27.2 | 3.88 | 27.2 | 27.2 | - | - | - |
| Average (mSv) | 0.11 | 0.58 | 0.52 | 0.14 | 0.75 | 0.66 | - | - | - |

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or the dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.
- Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the skin is 500 mSv/year (the emergency exposure dose limit is 1 Sv).
- Equivalent dose to the skin is measured at a depth of 70 micrometers from the skin surface. When the equivalent dose is measured with a dosimeter other than the one put on around the chest and the abdomen, for example, a finger dosimeter, the maximum measurement value is counted as the equivalent dose.

Table 8. Equivalent Dose to the Lens of the Eye

| Dose Ranges (mSv) | April 2025 - May 2025 | | | April 2025 - June 2025 | | | Difference | | |
|----------------------|-----------------------|-------------|-------------|------------------------|--------------|--------------|-----------------|-------------|------------|
| | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10-20 | 0 | 13 | 13 | 0 | 29 | 29 | 0 | 16 | 16 |
| 5-10 | 0 | 114 | 114 | 0 | 208 | 208 | 0 | 94 | 94 |
| 1-5 | 20 | 820 | 840 | 46 | 1073 | 1119 | 26 | 253 | 279 |
| 1 or less | 1094 | 6225 | 7319 | 1187 | 6378 | 7565 | 93 | 153 | 246 |
| Total | 1114 | 7172 | 8286 | 1233 | 7688 | 8921 | 119 | 516 | 635 |
| Maximum (mSv) | 3.8 | 13.1 | 13.1 | 3.88 | 13.98 | 13.98 | - | - | - |
| Average (mSv) | 0.10 | 0.51 | 0.45 | 0.14 | 0.68 | 0.60 | - | - | - |

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or the dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.
- Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the lens of the eye is 50 mSv/year and 100 mSv/5 years (the emergency exposure dose limit is 300 mSv).
- The equivalent dose to the lens of the eye is measured at a depth of 1 centimeter for neutron ray, 3 millimeters for X-ray, gamma ray and beta ray from the skin surface. However, as for X-ray, gamma ray and beta ray, it is measured at a depth of 1 centimeter or 70 micrometer when deemed appropriate with consideration for radiation type and energy type.

Table 9. Equivalent Dose to the Lens of the Eye: Cumulative Exposure Dose for Five Years

| Dose Ranges (mSv) | April 2021 - May 2025 | | | April 2021 - June 2025 | | | Difference | | |
|----------------------|-----------------------|--------------|--------------|------------------------|--------------|--------------|-----------------|-------------|------------|
| | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total | TEPCO Employees | Contractors | Total |
| Above 100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 50-75 | 0 | 169 | 169 | 0 | 178 | 178 | 0 | 9 | 9 |
| 20-50 | 40 | 1494 | 1534 | 40 | 1537 | 1577 | 0 | 43 | 43 |
| 10-20 | 72 | 1997 | 2069 | 75 | 1983 | 2058 | 3 | -14 | -11 |
| 5-10 | 142 | 1703 | 1845 | 142 | 1739 | 1881 | 0 | 36 | 36 |
| 1-5 | 392 | 2921 | 3313 | 393 | 2904 | 3297 | 1 | -17 | -16 |
| 1 or less | 1285 | 9192 | 10477 | 1360 | 9306 | 10666 | 75 | 114 | 189 |
| Total | 1931 | 17476 | 19407 | 2010 | 17647 | 19657 | 79 | 171 | 250 |
| Maximum (mSv) | 36.92 | 71.10 | 71.10 | 37.27 | 73.39 | 73.39 | - | - | - |
| Average (mSv) | 2.20 | 6.02 | 5.64 | 2.14 | 6.05 | 5.65 | - | - | - |

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or the dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.
- Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the lens of the eye is 50 mSv/year and 100 mSv/5 years (the emergency exposure dose limit is 300 mSv).
- The equivalent dose to the lens of the eye is measured at a depth of 1 centimeter for neutron ray, 3 millimeters for X-ray, gamma ray and beta ray from the skin surface. However, as for X-ray, gamma ray and beta ray, it is measured at a depth of 1 centimeter or 70 micrometer when deemed appropriate with consideration for radiation type and energy type.

(Aggregation period: April 1, 2021 - June 30, 2025)

Table 10. Exposure Dose Data by Age

18-19 years old

| Dose ranges (mSv) | TEPCO's employees | Contractors | Total |
|-------------------|-------------------|-------------|-------|
| Above 100 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 1 | 1 |
| 5-10 | 1 | 0 | 1 |
| 1-5 | 1 | 5 | 6 |
| 1 or less | 21 | 20 | 41 |
| Total | 23 | 26 | 49 |
| Maximum dose | 7.96 | 15.4 | 15.4 |
| Average dose | 0.46 | 0.95 | 0.72 |

20-29 years old

| Dose ranges (mSv) | TEPCO's employees | Contractors | Total |
|-------------------|-------------------|-------------|-------|
| Above 100 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 3 | 3 |
| 20-50 | 10 | 113 | 123 |
| 10-20 | 24 | 170 | 194 |
| 5-10 | 40 | 175 | 215 |
| 1-5 | 86 | 298 | 384 |
| 1 or less | 200 | 865 | 1065 |
| Total | 360 | 1624 | 1984 |
| Maximum dose | 32.53 | 58.62 | 58.62 |
| Average dose | 3.15 | 4.85 | 4.54 |

30-39 years old

| Dose ranges (mSv) | TEPCO's employees | Contractors | Total |
|-------------------|-------------------|-------------|-------|
| Above 100 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 24 | 24 |
| 20-50 | 14 | 297 | 311 |
| 10-20 | 25 | 398 | 423 |
| 5-10 | 42 | 353 | 395 |
| 1-5 | 96 | 539 | 635 |
| 1 or less | 275 | 1573 | 1848 |
| Total | 452 | 3184 | 3636 |
| Maximum dose | 37.26 | 64.81 | 64.81 |
| Average dose | 2.87 | 6.39 | 5.96 |

40-49 years old

| Dose ranges (mSv) | TEPCO's employees | Contractors | Total |
|-------------------|-------------------|-------------|-------|
| Above 100 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 54 | 54 |
| 20-50 | 8 | 407 | 415 |
| 10-20 | 13 | 509 | 522 |
| 5-10 | 19 | 450 | 469 |
| 1-5 | 89 | 670 | 759 |
| 1 or less | 282 | 2028 | 2310 |
| Total | 411 | 4118 | 4529 |
| Maximum dose | 35.24 | 72.37 | 72.37 |
| Average dose | 1.96 | 6.74 | 6.31 |

50-59 years old

| Dose ranges (mSv) | TEPCO's employees | Contractors | Total |
|-------------------|-------------------|-------------|-------------|
| Above 100 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 43 | 43 |
| 20-50 | 4 | 395 | 399 |
| 10-20 | 10 | 599 | 609 |
| 5-10 | 30 | 514 | 544 |
| 1-5 | 82 | 848 | 930 |
| 1 or less | 417 | 2879 | 3296 |
| Total | 543 | 5278 | 5821 |
| Maximum dose | 35.04 | 72.05 | 72.05 |
| Average dose | 1.28 | 5.56 | 5.16 |

60-69 years old

| Dose ranges (mSv) | TEPCO's employees | Contractors | Total |
|-------------------|-------------------|-------------|-------------|
| Above 100 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 18 | 18 |
| 20-50 | 2 | 208 | 210 |
| 10-20 | 5 | 300 | 305 |
| 5-10 | 7 | 290 | 297 |
| 1-5 | 33 | 519 | 552 |
| 1 or less | 161 | 1733 | 1894 |
| Total | 208 | 3068 | 3276 |
| Maximum dose | 34.93 | 63.61 | 63.61 |
| Average dose | 1.39 | 4.90 | 4.68 |

70 years old and over

| Dose ranges (mSv) | TEPCO's employees | Contractors | Total |
|-------------------|-------------------|-------------|------------|
| Above 100 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 2 | 2 |
| 20-50 | 0 | 16 | 16 |
| 10-20 | 0 | 14 | 14 |
| 5-10 | 0 | 15 | 15 |
| 1-5 | 2 | 57 | 59 |
| 1 or less | 11 | 245 | 256 |
| Total | 13 | 349 | 362 |
| Maximum dose | 3.02 | 57.82 | 57.82 |
| Average dose | 0.54 | 3.06 | 2.97 |

Number of workers by age

| Age ranges (years old) | TEPCO's employees | Contractors | Total |
|------------------------|-------------------|--------------|--------------|
| 18-19 years old | 23 | 26 | 49 |
| 20-29 years old | 360 | 1624 | 1984 |
| 30-39 years old | 452 | 3184 | 3636 |
| 40-49 years old | 411 | 4118 | 4529 |
| 50-59 years old | 543 | 5278 | 5821 |
| 60-69 years old | 208 | 3068 | 3276 |
| 70 years old and over | 13 | 349 | 362 |
| Total | 2010 | 17647 | 19657 |
| Maximum dose (mSv) | 37.26 | 72.37 | 72.37 |
| Average dose (mSv) | 2.11 | 5.75 | 5.38 |

Note)

•The ages above are as of June 30, 2025.

•The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

Table 11. Monthly Exposure Dose Data

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201103 | TEPCO | 40 | 66 | 239 | 529 | 539 | 119 | 77 | 65 | 16 | | 6 | 1696 | 670.36 | 31.53 |
| | Contractors | 397 | 537 | 399 | 460 | 373 | 65 | 34 | 17 | 2 | 2 | | 2286 | 238.42 | 14.15 |
| | Total | 437 | 603 | 638 | 989 | 912 | 184 | 111 | 82 | 18 | 2 | 6 | 3982 | 670.36 | 21.55 |
| 201104 | TEPCO | 228 | 323 | 857 | 186 | 62 | 1 | | | | | | 1657 | 59.60 | 6.66 |
| | Contractors | 1550 | 1468 | 625 | 433 | 128 | | | | | | | 4204 | 49.61 | 4.35 |
| | Total | 1778 | 1791 | 1482 | 619 | 190 | 1 | | | | | | 5861 | 59.60 | 5.00 |
| 201105 | TEPCO | 437 | 782 | 171 | 73 | 14 | | | | | | | 1477 | 33.42 | 3.14 |
| | Contractors | 2221 | 2369 | 809 | 349 | 80 | | | | | | | 5828 | 48.80 | 3.37 |
| | Total | 2658 | 3151 | 980 | 422 | 94 | | | | | | | 7305 | 48.80 | 3.32 |
| 201106 | TEPCO | 513 | 723 | 85 | 30 | | | | | | | | 1351 | 16.29 | 2.12 |
| | Contractors | 2559 | 2653 | 772 | 350 | 66 | 1 | 1 | | | | | 6402 | 89.50 | 3.08 |
| | Total | 3072 | 3376 | 857 | 380 | 66 | 1 | 1 | | | | | 7753 | 89.50 | 2.91 |
| 201107 | TEPCO | 653 | 625 | 53 | 17 | 3 | | | | | | | 1351 | 31.13 | 1.69 |
| | Contractors | 2934 | 2759 | 587 | 200 | 38 | 3 | | | | | | 6521 | 61.97 | 2.43 |
| | Total | 3587 | 3384 | 640 | 217 | 41 | 3 | | | | | | 7872 | 61.97 | 2.30 |
| 201108 | TEPCO | 543 | 666 | 57 | 19 | 1 | | | | | | | 1286 | 23.33 | 1.72 |
| | Contractors | 2826 | 2731 | 485 | 162 | 24 | 2 | | | | | | 6230 | 66.50 | 2.20 |
| | Total | 3369 | 3397 | 542 | 181 | 25 | 2 | | | | | | 7516 | 66.50 | 2.12 |
| 201109 | TEPCO | 534 | 633 | 38 | 2 | | | | | | | | 1207 | 11.35 | 1.45 |
| | Contractors | 2856 | 2582 | 399 | 140 | 23 | | | | | | | 6000 | 33.40 | 2.01 |
| | Total | 3390 | 3215 | 437 | 142 | 23 | | | | | | | 7207 | 33.40 | 1.92 |
| 201110 | TEPCO | 564 | 552 | 45 | 15 | 3 | | | | | | | 1179 | 36.35 | 1.57 |
| | Contractors | 2823 | 2352 | 337 | 103 | 8 | | | | | | | 5623 | 23.50 | 1.84 |
| | Total | 3387 | 2904 | 382 | 118 | 11 | | | | | | | 6802 | 36.35 | 1.80 |
| 201111 | TEPCO | 853 | 280 | 37 | 10 | | | | | | | | 1180 | 13.40 | 1.07 |
| | Contractors | 3354 | 1911 | 228 | 82 | 5 | | | | | | | 5580 | 23.03 | 1.46 |
| | Total | 4207 | 2191 | 265 | 92 | 5 | | | | | | | 6760 | 23.03 | 1.39 |
| 201112 | TEPCO | 868 | 282 | 26 | 13 | 3 | | | | | | | 1192 | 23.20 | 1.10 |
| | Contractors | 3345 | 1729 | 258 | 76 | | | | | | | | 5408 | 19.20 | 1.43 |
| | Total | 4213 | 2011 | 284 | 89 | 3 | | | | | | | 6600 | 23.20 | 1.37 |
| 201201 | TEPCO | 761 | 284 | 37 | 13 | | | | | | | | 1095 | 17.00 | 1.19 |
| | Contractors | 3236 | 1435 | 203 | 72 | 1 | | | | | | | 4947 | 21.90 | 1.36 |
| | Total | 3997 | 1719 | 240 | 85 | 1 | | | | | | | 6042 | 21.90 | 1.33 |
| 201202 | TEPCO | 845 | 231 | 25 | 8 | | | | | | | | 1109 | 17.63 | 0.91 |
| | Contractors | 2940 | 1584 | 221 | 100 | 2 | | | | | | | 4847 | 20.91 | 1.51 |
| | Total | 3785 | 1815 | 246 | 108 | 2 | | | | | | | 5956 | 20.91 | 1.40 |
| 201203 | TEPCO | 874 | 220 | 23 | 2 | | | | | | | | 1119 | 12.10 | 0.83 |
| | Contractors | 3029 | 1465 | 206 | 53 | 3 | | | | | | | 4756 | 21.83 | 1.36 |
| | Total | 3903 | 1685 | 229 | 55 | 3 | | | | | | | 5875 | 21.83 | 1.26 |
| 201204 | TEPCO | 870 | 179 | 19 | 3 | | | | | | | | 1071 | 13.00 | 0.75 |
| | Contractors | 2835 | 1305 | 151 | 75 | 3 | | | | | | | 4369 | 23.90 | 1.30 |
| | Total | 3705 | 1484 | 170 | 78 | 3 | | | | | | | 5440 | 23.90 | 1.19 |
| 201205 | TEPCO | 854 | 177 | 10 | 1 | | | | | | | | 1042 | 10.20 | 0.66 |
| | Contractors | 2898 | 1406 | 246 | 49 | | | | | | | | 4599 | 18.22 | 1.41 |
| | Total | 3752 | 1583 | 256 | 50 | | | | | | | | 5641 | 18.22 | 1.28 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201206 | TEPCO | 829 | 162 | 20 | 3 | | | | | | | | 1014 | 12.10 | 0.78 |
| | Contractors | 3086 | 1652 | 220 | 29 | | | | | | | | 4987 | 14.94 | 1.29 |
| | Total | 3915 | 1814 | 240 | 32 | | | | | | | | 6001 | 14.94 | 1.21 |
| 201207 | TEPCO | 854 | 150 | 9 | | | | | | | | | 1013 | 6.60 | 0.62 |
| | Contractors | 3065 | 1621 | 222 | 38 | | | | | | | | 4946 | 17.33 | 1.34 |
| | Total | 3919 | 1771 | 231 | 38 | | | | | | | | 5959 | 17.33 | 1.21 |
| 201208 | TEPCO | 835 | 144 | 7 | | | | | | | | | 986 | 7.20 | 0.62 |
| | Contractors | 3299 | 1341 | 120 | 4 | | | | | | | | 4764 | 11.64 | 1.04 |
| | Total | 4134 | 1485 | 127 | 4 | | | | | | | | 5750 | 11.64 | 0.97 |
| 201209 | TEPCO | 850 | 123 | 9 | | | | | | | | | 982 | 8.20 | 0.57 |
| | Contractors | 3272 | 1274 | 163 | 29 | 1 | | | | | | | 4739 | 20.50 | 1.15 |
| | Total | 4122 | 1397 | 172 | 29 | 1 | | | | | | | 5721 | 20.50 | 1.05 |
| 201210 | TEPCO | 826 | 145 | 7 | | | | | | | | | 978 | 6.30 | 0.61 |
| | Contractors | 3307 | 1325 | 136 | 31 | | | | | | | | 4799 | 16.00 | 1.11 |
| | Total | 4133 | 1470 | 143 | 31 | | | | | | | | 5777 | 16.00 | 1.03 |
| 201211 | TEPCO | 812 | 149 | 7 | | | | | | | | | 968 | 9.50 | 0.61 |
| | Contractors | 3306 | 1222 | 145 | 27 | | | | | | | | 4700 | 18.70 | 1.09 |
| | Total | 4118 | 1371 | 152 | 27 | | | | | | | | 5668 | 18.70 | 1.01 |
| 201212 | TEPCO | 846 | 149 | 10 | | | | | | | | | 1005 | 7.50 | 0.58 |
| | Contractors | 3489 | 1363 | 180 | 10 | | | | | | | | 5042 | 15.00 | 1.10 |
| | Total | 4335 | 1512 | 190 | 10 | | | | | | | | 6047 | 15.00 | 1.01 |
| 201301 | TEPCO | 870 | 96 | 3 | | | | | | | | | 969 | 7.39 | 0.42 |
| | Contractors | 3768 | 1310 | 115 | 7 | | | | | | | | 5200 | 12.90 | 0.96 |
| | Total | 4638 | 1406 | 118 | 7 | | | | | | | | 6169 | 12.90 | 0.88 |
| 201302 | TEPCO | 870 | 105 | 2 | | | | | | | | | 977 | 5.43 | 0.45 |
| | Contractors | 3917 | 1415 | 263 | 35 | | | | | | | | 5630 | 18.50 | 1.21 |
| | Total | 4787 | 1520 | 265 | 35 | | | | | | | | 6607 | 18.50 | 1.09 |
| 201303 | TEPCO | 845 | 140 | 10 | 2 | | | | | | | | 997 | 11.03 | 0.60 |
| | Contractors | 3908 | 1706 | 335 | 35 | | | | | | | | 5984 | 19.30 | 1.35 |
| | Total | 4753 | 1846 | 345 | 37 | | | | | | | | 6981 | 19.30 | 1.24 |
| 201304 | TEPCO | 948 | 108 | 4 | | | | | | | | | 1060 | 5.90 | 0.49 |
| | Contractors | 4029 | 1165 | 111 | 5 | | | | | | | | 5310 | 14.40 | 0.88 |
| | Total | 4977 | 1273 | 115 | 5 | | | | | | | | 6370 | 14.40 | 0.81 |
| 201305 | TEPCO | 896 | 100 | 4 | | | | | | | | | 1000 | 8.60 | 0.45 |
| | Contractors | 3920 | 1141 | 92 | 5 | | | | | | | | 5158 | 15.80 | 0.85 |
| | Total | 4816 | 1241 | 96 | 5 | | | | | | | | 6158 | 15.80 | 0.78 |
| 201306 | TEPCO | 931 | 87 | 6 | | | | | | | | | 1024 | 7.40 | 0.42 |
| | Contractors | 3731 | 1182 | 85 | 7 | | | | | | | | 5005 | 17.50 | 0.87 |
| | Total | 4662 | 1269 | 91 | 7 | | | | | | | | 6029 | 17.50 | 0.79 |
| 201307 | TEPCO | 891 | 96 | 1 | | | | | | | | | 988 | 5.50 | 0.43 |
| | Contractors | 3752 | 1128 | 107 | 9 | | | | | | | | 4996 | 14.80 | 0.89 |
| | Total | 4643 | 1224 | 108 | 9 | | | | | | | | 5984 | 14.80 | 0.81 |
| 201308 | TEPCO | 834 | 118 | 4 | | | | | | | | | 956 | 6.10 | 0.49 |
| | Contractors | 3665 | 1211 | 142 | 40 | | | | | | | | 5058 | 19.89 | 1.03 |
| | Total | 4499 | 1329 | 146 | 40 | | | | | | | | 6014 | 19.89 | 0.94 |
| 201309 | TEPCO | 933 | 102 | 3 | | | | | | | | | 1038 | 5.60 | 0.44 |
| | Contractors | 3525 | 1420 | 247 | 61 | 1 | | | | | | | 5254 | 20.58 | 1.28 |
| | Total | 4458 | 1522 | 250 | 61 | 1 | | | | | | | 6292 | 20.58 | 1.14 |
| 201310 | TEPCO | 893 | 146 | 8 | | | | | | | | | 1047 | 9.50 | 0.55 |
| | Contractors | 3460 | 1556 | 343 | 47 | | | | | | | | 5406 | 19.36 | 1.43 |
| | Total | 4353 | 1702 | 351 | 47 | | | | | | | | 6453 | 19.36 | 1.29 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201311 | TEPCO | 954 | 120 | 5 | | | | | | | | | 1079 | 9.20 | 0.48 |
| | Contractors | 3700 | 1533 | 303 | 32 | | | | | | | | 5568 | 16.91 | 1.28 |
| | Total | 4654 | 1653 | 308 | 32 | | | | | | | | 6647 | 16.91 | 1.15 |
| 201312 | TEPCO | 968 | 116 | 2 | | | | | | | | | 1086 | 5.40 | 0.44 |
| | Contractors | 3852 | 1627 | 199 | 23 | | | | | | | | 5701 | 16.81 | 1.13 |
| | Total | 4820 | 1743 | 201 | 23 | | | | | | | | 6787 | 16.81 | 1.02 |
| 201401 | TEPCO | 997 | 84 | | | | | | | | | | 1081 | 4.50 | 0.37 |
| | Contractors | 4112 | 1505 | 221 | 53 | | | | | | | | 5891 | 15.80 | 1.16 |
| | Total | 5109 | 1589 | 221 | 53 | | | | | | | | 6972 | 15.80 | 1.04 |
| 201402 | TEPCO | 1018 | 56 | 4 | | | | | | | | | 1078 | 6.50 | 0.34 |
| | Contractors | 4611 | 1611 | 168 | 30 | | | | | | | | 6420 | 17.29 | 1.02 |
| | Total | 5629 | 1667 | 172 | 30 | | | | | | | | 7498 | 17.29 | 0.92 |
| 201403 | TEPCO | 1012 | 85 | | | | | | | | | | 1097 | 4.80 | 0.36 |
| | Contractors | 4940 | 1867 | 227 | 23 | | | | | | | | 7057 | 18.49 | 1.07 |
| | Total | 5952 | 1952 | 227 | 23 | | | | | | | | 8154 | 18.49 | 0.98 |
| 201404 | TEPCO | 999 | 94 | 1 | | | | | | | | | 1094 | 5.70 | 0.38 |
| | Contractors | 5449 | 1743 | 234 | 19 | | | | | | | | 7445 | 16.00 | 0.98 |
| | Total | 6448 | 1837 | 235 | 19 | | | | | | | | 8539 | 16.00 | 0.91 |
| 201405 | TEPCO | 1053 | 65 | 1 | | | | | | | | | 1119 | 5.60 | 0.31 |
| | Contractors | 5974 | 1794 | 209 | 47 | 1 | | | | | | | 8025 | 20.70 | 0.95 |
| | Total | 7027 | 1859 | 210 | 47 | 1 | | | | | | | 9144 | 20.70 | 0.87 |
| 201406 | TEPCO | 1056 | 66 | 1 | | | | | | | | | 1123 | 6.80 | 0.32 |
| | Contractors | 6773 | 1790 | 329 | 26 | | | | | | | | 8918 | 16.89 | 0.95 |
| | Total | 7829 | 1856 | 330 | 26 | | | | | | | | 10041 | 16.89 | 0.88 |
| 201407 | TEPCO | 1092 | 39 | 1 | | | | | | | | | 1132 | 5.40 | 0.27 |
| | Contractors | 7292 | 1728 | 258 | 49 | | | | | | | | 9327 | 18.69 | 0.89 |
| | Total | 8384 | 1767 | 259 | 49 | | | | | | | | 10459 | 18.69 | 0.82 |
| 201408 | TEPCO | 1062 | 39 | | | | | | | | | | 1101 | 3.40 | 0.25 |
| | Contractors | 7818 | 1338 | 214 | 9 | | | | | | | | 9379 | 17.13 | 0.71 |
| | Total | 8880 | 1377 | 214 | 9 | | | | | | | | 10480 | 17.13 | 0.67 |
| 201409 | TEPCO | 1110 | 51 | 1 | | | | | | | | | 1162 | 6.00 | 0.27 |
| | Contractors | 8013 | 1634 | 287 | 36 | | | | | | | | 9970 | 18.22 | 0.84 |
| | Total | 9123 | 1685 | 288 | 36 | | | | | | | | 11132 | 18.22 | 0.78 |
| 201410 | TEPCO | 1112 | 62 | | | | | | | | | | 1174 | 2.70 | 0.29 |
| | Contractors | 7951 | 1766 | 234 | 18 | | | | | | | | 9969 | 14.92 | 0.80 |
| | Total | 9063 | 1828 | 234 | 18 | | | | | | | | 11143 | 14.92 | 0.74 |
| 201411 | TEPCO | 1141 | 45 | | | | | | | | | | 1186 | 3.00 | 0.21 |
| | Contractors | 8198 | 1644 | 269 | 19 | | | | | | | | 10130 | 15.92 | 0.78 |
| | Total | 9339 | 1689 | 269 | 19 | | | | | | | | 11316 | 15.92 | 0.72 |
| 201412 | TEPCO | 1099 | 60 | | | | | | | | | | 1159 | 4.30 | 0.24 |
| | Contractors | 8272 | 1912 | 283 | 34 | | | | | | | | 10501 | 16.74 | 0.85 |
| | Total | 9371 | 1972 | 283 | 34 | | | | | | | | 11660 | 16.74 | 0.79 |
| 201501 | TEPCO | 1111 | 37 | | | | | | | | | | 1148 | 4.20 | 0.22 |
| | Contractors | 8514 | 1513 | 56 | 1 | | | | | | | | 10084 | 12.80 | 0.56 |
| | Total | 9625 | 1550 | 56 | 1 | | | | | | | | 11232 | 12.80 | 0.53 |
| 201502 | TEPCO | 1096 | 74 | 6 | | | | | | | | | 1176 | 8.00 | 0.33 |
| | Contractors | 8498 | 2214 | 285 | 36 | | | | | | | | 11033 | 16.80 | 0.89 |
| | Total | 9594 | 2288 | 291 | 36 | | | | | | | | 12209 | 16.80 | 0.83 |
| 201503 | TEPCO | 1060 | 79 | 3 | | | | | | | | | 1142 | 6.40 | 0.32 |
| | Contractors | 8036 | 2466 | 553 | 118 | | | | | | | | 11173 | 19.90 | 1.21 |
| | Total | 9096 | 2545 | 556 | 118 | | | | | | | | 12315 | 19.90 | 1.13 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201504 | TEPCO | 1100 | 66 | | | | | | | | | | 1166 | 4.80 | 0.27 |
| | Contractors | 7693 | 2414 | 248 | 20 | | | | | | | | 10375 | 15.60 | 0.93 |
| | Total | 8793 | 2480 | 248 | 20 | | | | | | | | 11541 | 15.60 | 0.86 |
| 201505 | TEPCO | 1092 | 42 | | | | | | | | | | 1134 | 2.12 | 0.20 |
| | Contractors | 8100 | 1746 | 98 | 4 | | | | | | | | 9948 | 11.40 | 0.66 |
| | Total | 9192 | 1788 | 98 | 4 | | | | | | | | 11082 | 11.40 | 0.61 |
| 201506 | TEPCO | 1128 | 64 | | | | | | | | | | 1192 | 3.90 | 0.25 |
| | Contractors | 8185 | 1737 | 167 | 12 | | | | | | | | 10101 | 11.50 | 0.72 |
| | Total | 9313 | 1801 | 167 | 12 | | | | | | | | 11293 | 11.50 | 0.67 |
| 201507 | TEPCO | 1119 | 53 | 1 | | | | | | | | | 1173 | 5.10 | 0.24 |
| | Contractors | 8140 | 1646 | 134 | 7 | | | | | | | | 9927 | 10.72 | 0.66 |
| | Total | 9259 | 1699 | 135 | 7 | | | | | | | | 11100 | 10.72 | 0.62 |
| 201508 | TEPCO | 1083 | 53 | | | | | | | | | | 1136 | 3.38 | 0.21 |
| | Contractors | 8369 | 1040 | 36 | 1 | | | | | | | | 9446 | 10.30 | 0.43 |
| | Total | 9452 | 1093 | 36 | 1 | | | | | | | | 10582 | 10.30 | 0.41 |
| 201509 | TEPCO | 1144 | 51 | 1 | | | | | | | | | 1196 | 5.60 | 0.24 |
| | Contractors | 8034 | 1590 | 140 | 16 | | | | | | | | 9780 | 15.30 | 0.67 |
| | Total | 9178 | 1641 | 141 | 16 | | | | | | | | 10976 | 15.30 | 0.63 |
| 201510 | TEPCO | 1130 | 52 | | | | | | | | | | 1182 | 3.20 | 0.22 |
| | Contractors | 7864 | 1699 | 145 | 9 | | | | | | | | 9717 | 14.42 | 0.70 |
| | Total | 8994 | 1751 | 145 | 9 | | | | | | | | 10899 | 14.42 | 0.64 |
| 201511 | TEPCO | 1119 | 48 | | | | | | | | | | 1167 | 4.96 | 0.22 |
| | Contractors | 7920 | 1451 | 110 | 7 | | | | | | | | 9488 | 13.88 | 0.61 |
| | Total | 9039 | 1499 | 110 | 7 | | | | | | | | 10655 | 13.88 | 0.57 |
| 201512 | TEPCO | 1122 | 47 | | | | | | | | | | 1169 | 2.70 | 0.21 |
| | Contractors | 8026 | 1335 | 73 | 5 | | | | | | | | 9439 | 13.50 | 0.56 |
| | Total | 9148 | 1382 | 73 | 5 | | | | | | | | 10608 | 13.50 | 0.52 |
| 201601 | TEPCO | 1108 | 38 | | | | | | | | | | 1146 | 3.30 | 0.20 |
| | Contractors | 8070 | 1194 | 60 | 4 | | | | | | | | 9328 | 16.00 | 0.51 |
| | Total | 9178 | 1232 | 60 | 4 | | | | | | | | 10474 | 16.00 | 0.48 |
| 201602 | TEPCO | 1128 | 49 | | | | | | | | | | 1177 | 4.70 | 0.22 |
| | Contractors | 7896 | 1461 | 78 | 12 | | | | | | | | 9447 | 12.36 | 0.59 |
| | Total | 9024 | 1510 | 78 | 12 | | | | | | | | 10624 | 12.36 | 0.55 |
| 201603 | TEPCO | 1125 | 44 | | | | | | | | | | 1169 | 2.71 | 0.20 |
| | Contractors | 8051 | 1291 | 93 | 19 | | | | | | | | 9454 | 13.82 | 0.59 |
| | Total | 9176 | 1335 | 93 | 19 | | | | | | | | 10623 | 13.82 | 0.55 |
| 201604 | TEPCO | 1097 | 16 | | | | | | | | | | 1113 | 1.90 | 0.16 |
| | Contractors | 7852 | 870 | 42 | | | | | | | | | 8764 | 9.78 | 0.41 |
| | Total | 8949 | 886 | 42 | | | | | | | | | 9877 | 9.78 | 0.38 |
| 201605 | TEPCO | 1128 | 9 | | | | | | | | | | 1137 | 2.50 | 0.14 |
| | Contractors | 7738 | 651 | 19 | | | | | | | | | 8408 | 9.70 | 0.32 |
| | Total | 8866 | 660 | 19 | | | | | | | | | 9545 | 9.70 | 0.30 |
| 201606 | TEPCO | 1166 | 26 | | | | | | | | | | 1192 | 2.00 | 0.16 |
| | Contractors | 7928 | 833 | 56 | 6 | | | | | | | | 8823 | 13.81 | 0.42 |
| | Total | 9094 | 859 | 56 | 6 | | | | | | | | 10015 | 13.81 | 0.38 |
| 201607 | TEPCO | 1138 | 12 | | | | | | | | | | 1150 | 1.92 | 0.11 |
| | Contractors | 7849 | 791 | 80 | 3 | | | | | | | | 8723 | 10.70 | 0.41 |
| | Total | 8987 | 803 | 80 | 3 | | | | | | | | 9873 | 10.70 | 0.38 |
| 201608 | TEPCO | 1125 | 41 | | | | | | | | | | 1166 | 4.39 | 0.17 |
| | Contractors | 7951 | 532 | 19 | | | | | | | | | 8502 | 7.10 | 0.28 |
| | Total | 9076 | 573 | 19 | | | | | | | | | 9668 | 7.10 | 0.27 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201609 | TEPCO | 1160 | 20 | | | | | | | | | | 1180 | 3.50 | 0.14 |
| | Contractors | 8041 | 689 | 35 | | | | | | | | | 8765 | 8.80 | 0.35 |
| | Total | 9201 | 709 | 35 | | | | | | | | | 9945 | 8.80 | 0.33 |
| 201610 | TEPCO | 1142 | 21 | | | | | | | | | | 1163 | 2.40 | 0.14 |
| | Contractors | 7693 | 875 | 48 | | | | | | | | | 8616 | 8.34 | 0.42 |
| | Total | 8835 | 896 | 48 | | | | | | | | | 9779 | 8.34 | 0.39 |
| 201611 | TEPCO | 1167 | 29 | | | | | | | | | | 1196 | 3.10 | 0.15 |
| | Contractors | 7646 | 1000 | 50 | 5 | | | | | | | | 8701 | 12.00 | 0.45 |
| | Total | 8813 | 1029 | 50 | 5 | | | | | | | | 9897 | 12.00 | 0.42 |
| 201612 | TEPCO | 1144 | 16 | 2 | | | | | | | | | 1162 | 6.24 | 0.16 |
| | Contractors | 7667 | 856 | 46 | 4 | | | | | | | | 8573 | 12.60 | 0.41 |
| | Total | 8811 | 872 | 48 | 4 | | | | | | | | 9735 | 12.60 | 0.38 |
| 201701 | TEPCO | 1105 | 24 | | | | | | | | | | 1129 | 2.40 | 0.15 |
| | Contractors | 7729 | 785 | 69 | 5 | | | | | | | | 8588 | 11.00 | 0.42 |
| | Total | 8834 | 809 | 69 | 5 | | | | | | | | 9717 | 11.00 | 0.38 |
| 201702 | TEPCO | 1127 | 49 | | | | | | | | | | 1176 | 3.40 | 0.17 |
| | Contractors | 7659 | 1111 | 121 | 6 | | | | | | | | 8897 | 13.70 | 0.53 |
| | Total | 8786 | 1160 | 121 | 6 | | | | | | | | 10073 | 13.70 | 0.48 |
| 201703 | TEPCO | 1132 | 38 | | | | | | | | | | 1170 | 3.70 | 0.18 |
| | Contractors | 7525 | 1130 | 162 | 26 | | | | | | | | 8843 | 16.30 | 0.61 |
| | Total | 8657 | 1168 | 162 | 26 | | | | | | | | 10013 | 16.30 | 0.56 |
| 201704 | TEPCO | 1027 | 26 | | | | | | | | | | 1053 | 2.74 | 0.17 |
| | Contractors | 7165 | 892 | 87 | 5 | | | | | | | | 8149 | 11.40 | 0.47 |
| | Total | 8192 | 918 | 87 | 5 | | | | | | | | 9202 | 11.40 | 0.43 |
| 201705 | TEPCO | 1023 | 12 | | | | | | | | | | 1035 | 2.40 | 0.13 |
| | Contractors | 7247 | 713 | 78 | | | | | | | | | 8038 | 8.80 | 0.39 |
| | Total | 8270 | 725 | 78 | | | | | | | | | 9073 | 8.80 | 0.36 |
| 201706 | TEPCO | 1023 | 26 | | | | | | | | | | 1049 | 3.30 | 0.16 |
| | Contractors | 7301 | 890 | 64 | 9 | | | | | | | | 8264 | 12.90 | 0.45 |
| | Total | 8324 | 916 | 64 | 9 | | | | | | | | 9313 | 12.90 | 0.42 |
| 201707 | TEPCO | 1001 | 14 | | | | | | | | | | 1015 | 3.80 | 0.13 |
| | Contractors | 7211 | 847 | 55 | 2 | | | | | | | | 8115 | 11.50 | 0.42 |
| | Total | 8212 | 861 | 55 | 2 | | | | | | | | 9130 | 11.50 | 0.39 |
| 201708 | TEPCO | 979 | 19 | | | | | | | | | | 998 | 3.20 | 0.13 |
| | Contractors | 7164 | 651 | 19 | | | | | | | | | 7834 | 7.60 | 0.32 |
| | Total | 8143 | 670 | 19 | | | | | | | | | 8832 | 7.60 | 0.30 |
| 201709 | TEPCO | 1033 | 15 | | | | | | | | | | 1048 | 3.30 | 0.11 |
| | Contractors | 7082 | 657 | 16 | | | | | | | | | 7755 | 7.50 | 0.32 |
| | Total | 8115 | 672 | 16 | | | | | | | | | 8803 | 7.50 | 0.30 |
| 201710 | TEPCO | 1035 | 29 | | | | | | | | | | 1064 | 2.50 | 0.14 |
| | Contractors | 6886 | 715 | 32 | 2 | | | | | | | | 7635 | 10.30 | 0.37 |
| | Total | 7921 | 744 | 32 | 2 | | | | | | | | 8699 | 10.30 | 0.34 |
| 201711 | TEPCO | 1027 | 23 | | | | | | | | | | 1050 | 2.40 | 0.12 |
| | Contractors | 6874 | 660 | 35 | 5 | | | | | | | | 7574 | 11.20 | 0.37 |
| | Total | 7901 | 683 | 35 | 5 | | | | | | | | 8624 | 11.20 | 0.34 |
| 201712 | TEPCO | 961 | 22 | | | | | | | | | | 983 | 2.60 | 0.14 |
| | Contractors | 6683 | 578 | 18 | 1 | | | | | | | | 7280 | 10.31 | 0.32 |
| | Total | 7644 | 600 | 18 | 1 | | | | | | | | 8263 | 10.31 | 0.30 |
| 201801 | TEPCO | 914 | 24 | | | | | | | | | | 938 | 4.14 | 0.13 |
| | Contractors | 6444 | 614 | 23 | 1 | | | | | | | | 7082 | 10.60 | 0.35 |
| | Total | 7358 | 638 | 23 | 1 | | | | | | | | 8020 | 10.60 | 0.32 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201802 | TEPCO | 941 | 50 | | | | | | | | | | 991 | 3.83 | 0.21 |
| | Contractors | 6353 | 791 | 56 | | | | | | | | | 7200 | 9.80 | 0.43 |
| | Total | 7294 | 841 | 56 | | | | | | | | | 8191 | 9.80 | 0.41 |
| 201803 | TEPCO | 935 | 46 | | | | | | | | | | 981 | 2.96 | 0.17 |
| | Contractors | 6394 | 768 | 69 | | | | | | | | | 7231 | 8.83 | 0.45 |
| | Total | 7329 | 814 | 69 | | | | | | | | | 8212 | 8.83 | 0.42 |
| 201804 | TEPCO | 1001 | 13 | | | | | | | | | | 1014 | 2.40 | 0.11 |
| | Contractors | 5840 | 509 | 26 | | | | | | | | | 6375 | 8.40 | 0.33 |
| | Total | 6841 | 522 | 26 | | | | | | | | | 7389 | 8.40 | 0.30 |
| 201805 | TEPCO | 927 | 15 | | | | | | | | | | 942 | 1.90 | 0.12 |
| | Contractors | 5820 | 481 | 18 | | | | | | | | | 6319 | 9.40 | 0.30 |
| | Total | 6747 | 496 | 18 | | | | | | | | | 7261 | 9.40 | 0.28 |
| 201806 | TEPCO | 939 | 29 | | | | | | | | | | 968 | 2.68 | 0.14 |
| | Contractors | 5795 | 488 | 4 | | | | | | | | | 6287 | 7.37 | 0.30 |
| | Total | 6734 | 517 | 4 | | | | | | | | | 7255 | 7.37 | 0.28 |
| 201807 | TEPCO | 867 | 27 | | | | | | | | | | 894 | 2.72 | 0.13 |
| | Contractors | 5665 | 597 | 21 | | | | | | | | | 6283 | 9.70 | 0.34 |
| | Total | 6532 | 624 | 21 | | | | | | | | | 7177 | 9.70 | 0.32 |
| 201808 | TEPCO | 947 | 25 | | | | | | | | | | 972 | 2.30 | 0.13 |
| | Contractors | 5784 | 453 | 9 | | | | | | | | | 6246 | 6.30 | 0.29 |
| | Total | 6731 | 478 | 9 | | | | | | | | | 7218 | 6.30 | 0.27 |
| 201809 | TEPCO | 985 | 17 | | | | | | | | | | 1002 | 1.90 | 0.11 |
| | Contractors | 5684 | 469 | 8 | | | | | | | | | 6161 | 8.00 | 0.28 |
| | Total | 6669 | 486 | 8 | | | | | | | | | 7163 | 8.00 | 0.26 |
| 201810 | TEPCO | 976 | 26 | | | | | | | | | | 1002 | 4.17 | 0.15 |
| | Contractors | 5579 | 567 | 18 | | | | | | | | | 6164 | 8.20 | 0.35 |
| | Total | 6555 | 593 | 18 | | | | | | | | | 7166 | 8.20 | 0.32 |
| 201811 | TEPCO | 1009 | 13 | | | | | | | | | | 1022 | 2.95 | 0.11 |
| | Contractors | 5556 | 626 | 42 | | | | | | | | | 6224 | 9.88 | 0.39 |
| | Total | 6565 | 639 | 42 | | | | | | | | | 7246 | 9.88 | 0.35 |
| 201812 | TEPCO | 981 | 21 | | | | | | | | | | 1002 | 4.52 | 0.13 |
| | Contractors | 5562 | 621 | 55 | 4 | | | | | | | | 6242 | 14.10 | 0.42 |
| | Total | 6543 | 642 | 55 | 4 | | | | | | | | 7244 | 14.10 | 0.38 |
| 201901 | TEPCO | 944 | 16 | | | | | | | | | | 960 | 2.32 | 0.10 |
| | Contractors | 5569 | 511 | 37 | | | | | | | | | 6117 | 7.81 | 0.36 |
| | Total | 6513 | 527 | 37 | | | | | | | | | 7077 | 7.81 | 0.32 |
| 201902 | TEPCO | 974 | 28 | 1 | | | | | | | | | 1003 | 5.38 | 0.15 |
| | Contractors | 5575 | 676 | 58 | 2 | | | | | | | | 6311 | 12.60 | 0.44 |
| | Total | 6549 | 704 | 59 | 2 | | | | | | | | 7314 | 12.60 | 0.40 |
| 201903 | TEPCO | 960 | 34 | 1 | | | | | | | | | 995 | 5.70 | 0.16 |
| | Contractors | 5532 | 613 | 32 | 1 | | | | | | | | 6178 | 11.41 | 0.39 |
| | Total | 6492 | 647 | 33 | 1 | | | | | | | | 7173 | 11.41 | 0.35 |
| 201904 | TEPCO | 920 | 24 | | | | | | | | | | 944 | 2.66 | 0.13 |
| | Contractors | 4780 | 491 | 8 | | | | | | | | | 5279 | 7.80 | 0.33 |
| | Total | 5700 | 515 | 8 | | | | | | | | | 6223 | 7.80 | 0.30 |
| 201905 | TEPCO | 967 | 20 | | | | | | | | | | 987 | 2.80 | 0.13 |
| | Contractors | 4876 | 552 | 5 | | | | | | | | | 5433 | 5.60 | 0.33 |
| | Total | 5843 | 572 | 5 | | | | | | | | | 6420 | 5.60 | 0.30 |
| 201906 | TEPCO | 1016 | 17 | 1 | | | | | | | | | 1034 | 5.20 | 0.12 |
| | Contractors | 4993 | 538 | 12 | | | | | | | | | 5543 | 7.11 | 0.35 |
| | Total | 6009 | 555 | 13 | | | | | | | | | 6577 | 7.11 | 0.31 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201907 | TEPCO | 964 | 19 | | | | | | | | | | 983 | 3.60 | 0.13 |
| | Contractors | 5048 | 547 | 10 | | | | | | | | | 5605 | 9.70 | 0.35 |
| | Total | 6012 | 566 | 10 | | | | | | | | | 6588 | 9.70 | 0.32 |
| 201908 | TEPCO | 1006 | 12 | | | | | | | | | | 1018 | 2.75 | 0.10 |
| | Contractors | 5037 | 471 | 6 | | | | | | | | | 5514 | 7.99 | 0.30 |
| | Total | 6043 | 483 | 6 | | | | | | | | | 6532 | 7.99 | 0.27 |
| 201909 | TEPCO | 942 | 12 | | | | | | | | | | 954 | 3.52 | 0.10 |
| | Contractors | 4953 | 594 | 12 | | | | | | | | | 5559 | 8.15 | 0.37 |
| | Total | 5895 | 606 | 12 | | | | | | | | | 6513 | 8.15 | 0.33 |
| 201910 | TEPCO | 935 | 22 | | | | | | | | | | 957 | 3.22 | 0.12 |
| | Contractors | 5066 | 613 | 31 | | | | | | | | | 5710 | 7.49 | 0.39 |
| | Total | 6001 | 635 | 31 | | | | | | | | | 6667 | 7.49 | 0.35 |
| 201911 | TEPCO | 1024 | 23 | | | | | | | | | | 1047 | 3.48 | 0.12 |
| | Contractors | 5255 | 595 | 13 | | | | | | | | | 5863 | 7.21 | 0.35 |
| | Total | 6279 | 618 | 13 | | | | | | | | | 6910 | 7.21 | 0.32 |
| 201912 | TEPCO | 967 | 13 | | | | | | | | | | 980 | 2.54 | 0.11 |
| | Contractors | 5212 | 604 | 33 | 5 | | | | | | | | 5854 | 12.20 | 0.40 |
| | Total | 6179 | 617 | 33 | 5 | | | | | | | | 6834 | 12.20 | 0.36 |
| 202001 | TEPCO | 982 | 10 | | | | | | | | | | 992 | 2.07 | 0.09 |
| | Contractors | 5239 | 558 | 54 | 1 | | | | | | | | 5852 | 10.01 | 0.39 |
| | Total | 6221 | 568 | 54 | 1 | | | | | | | | 6844 | 10.01 | 0.35 |
| 202002 | TEPCO | 918 | 15 | | | | | | | | | | 933 | 2.96 | 0.11 |
| | Contractors | 5208 | 740 | 61 | 10 | | | | | | | | 6019 | 11.07 | 0.49 |
| | Total | 6126 | 755 | 61 | 10 | | | | | | | | 6952 | 11.07 | 0.44 |
| 202003 | TEPCO | 900 | 17 | | | | | | | | | | 917 | 1.86 | 0.12 |
| | Contractors | 5252 | 765 | 46 | 4 | | | | | | | | 6067 | 14.30 | 0.47 |
| | Total | 6152 | 782 | 46 | 4 | | | | | | | | 6984 | 14.30 | 0.42 |
| 202004 | TEPCO | 807 | 18 | | | | | | | | | | 825 | 3.37 | 0.11 |
| | Contractors | 4737 | 591 | 28 | 1 | | | | | | | | 5357 | 10.40 | 0.39 |
| | Total | 5544 | 609 | 28 | 1 | | | | | | | | 6182 | 10.40 | 0.35 |
| 202005 | TEPCO | 773 | 9 | | | | | | | | | | 782 | 1.81 | 0.09 |
| | Contractors | 4762 | 561 | 25 | | | | | | | | | 5348 | 8.80 | 0.38 |
| | Total | 5535 | 570 | 25 | | | | | | | | | 6130 | 8.80 | 0.34 |
| 202006 | TEPCO | 929 | 18 | | | | | | | | | | 947 | 3.00 | 0.13 |
| | Contractors | 4920 | 692 | 52 | | | | | | | | | 5664 | 9.30 | 0.46 |
| | Total | 5849 | 710 | 52 | | | | | | | | | 6611 | 9.30 | 0.41 |
| 202007 | TEPCO | 997 | 15 | | | | | | | | | | 1012 | 2.90 | 0.10 |
| | Contractors | 4967 | 661 | 51 | | | | | | | | | 5679 | 8.42 | 0.42 |
| | Total | 5964 | 676 | 51 | | | | | | | | | 6691 | 8.42 | 0.38 |
| 202008 | TEPCO | 951 | 5 | | | | | | | | | | 956 | 1.44 | 0.08 |
| | Contractors | 4969 | 407 | 4 | | | | | | | | | 5380 | 5.40 | 0.26 |
| | Total | 5920 | 412 | 4 | | | | | | | | | 6336 | 5.40 | 0.24 |
| 202009 | TEPCO | 1002 | 13 | | | | | | | | | | 1015 | 2.70 | 0.10 |
| | Contractors | 5001 | 496 | 32 | 1 | | | | | | | | 5530 | 10.51 | 0.34 |
| | Total | 6003 | 509 | 32 | 1 | | | | | | | | 6545 | 10.51 | 0.30 |
| 202010 | TEPCO | 965 | 11 | 1 | | | | | | | | | 977 | 6.99 | 0.11 |
| | Contractors | 5125 | 510 | 31 | 1 | | | | | | | | 5667 | 10.50 | 0.37 |
| | Total | 6090 | 521 | 32 | 1 | | | | | | | | 6644 | 10.50 | 0.33 |
| 202011 | TEPCO | 971 | 25 | | | | | | | | | | 996 | 4.84 | 0.12 |
| | Contractors | 5054 | 579 | 48 | 2 | | | | | | | | 5683 | 11.00 | 0.42 |
| | Total | 6025 | 604 | 48 | 2 | | | | | | | | 6679 | 11.00 | 0.37 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202012 | TEPCO | 975 | 36 | | | | | | | | | | 1011 | 2.29 | 0.13 |
| | Contractors | 5242 | 485 | 26 | | | | | | | | | 5753 | 9.00 | 0.33 |
| | Total | 6217 | 521 | 26 | | | | | | | | | 6764 | 9.00 | 0.30 |
| 202101 | TEPCO | 897 | 20 | | | | | | | | | | 917 | 2.53 | 0.11 |
| | Contractors | 5258 | 517 | 8 | | | | | | | | | 5783 | 6.70 | 0.33 |
| | Total | 6155 | 537 | 8 | | | | | | | | | 6700 | 6.70 | 0.30 |
| 202102 | TEPCO | 909 | 21 | 1 | | | | | | | | | 931 | 6.10 | 0.13 |
| | Contractors | 5328 | 517 | 45 | 2 | | | | | | | | 5892 | 12.40 | 0.39 |
| | Total | 6237 | 538 | 46 | 2 | | | | | | | | 6823 | 12.40 | 0.36 |
| 202103 | TEPCO | 957 | 40 | | | | | | | | | | 997 | 3.42 | 0.16 |
| | Contractors | 5032 | 654 | 55 | | | | | | | | | 5741 | 8.90 | 0.44 |
| | Total | 5989 | 694 | 55 | | | | | | | | | 6738 | 8.90 | 0.40 |
| 202104 | TEPCO | 944 | 25 | | | | | | | | | | 969 | 2.19 | 0.10 |
| | Contractors | 4602 | 366 | 6 | | | | | | | | | 4974 | 6.40 | 0.28 |
| | Total | 5546 | 391 | 6 | | | | | | | | | 5943 | 6.40 | 0.25 |
| 202105 | TEPCO | 916 | 24 | | | | | | | | | | 940 | 2.99 | 0.10 |
| | Contractors | 4666 | 354 | 7 | | | | | | | | | 5027 | 5.79 | 0.28 |
| | Total | 5582 | 378 | 7 | | | | | | | | | 5967 | 5.79 | 0.25 |
| 202106 | TEPCO | 1034 | 23 | | | | | | | | | | 1057 | 2.65 | 0.09 |
| | Contractors | 4783 | 505 | 39 | | | | | | | | | 5327 | 7.76 | 0.38 |
| | Total | 5817 | 528 | 39 | | | | | | | | | 6384 | 7.76 | 0.33 |
| 202107 | TEPCO | 1012 | 16 | | | | | | | | | | 1028 | 3.89 | 0.10 |
| | Contractors | 4929 | 476 | 22 | | | | | | | | | 5427 | 7.81 | 0.34 |
| | Total | 5941 | 492 | 22 | | | | | | | | | 6455 | 7.81 | 0.30 |
| 202108 | TEPCO | 919 | 6 | | | | | | | | | | 925 | 1.45 | 0.06 |
| | Contractors | 4986 | 353 | 15 | | | | | | | | | 5354 | 6.93 | 0.26 |
| | Total | 5905 | 359 | 15 | | | | | | | | | 6279 | 6.93 | 0.23 |
| 202109 | TEPCO | 980 | 12 | | | | | | | | | | 992 | 2.60 | 0.07 |
| | Contractors | 4821 | 607 | 66 | 1 | | | | | | | | 5495 | 11.30 | 0.45 |
| | Total | 5801 | 619 | 66 | 1 | | | | | | | | 6487 | 11.30 | 0.39 |
| 202110 | TEPCO | 998 | 19 | | | | | | | | | | 1017 | 1.96 | 0.09 |
| | Contractors | 5070 | 472 | 40 | | | | | | | | | 5582 | 8.69 | 0.36 |
| | Total | 6068 | 491 | 40 | | | | | | | | | 6599 | 8.69 | 0.32 |
| 202111 | TEPCO | 998 | 9 | | | | | | | | | | 1007 | 2.00 | 0.09 |
| | Contractors | 5187 | 534 | 22 | | | | | | | | | 5743 | 7.70 | 0.36 |
| | Total | 6185 | 543 | 22 | | | | | | | | | 6750 | 7.70 | 0.32 |
| 202112 | TEPCO | 1001 | 34 | | | | | | | | | | 1035 | 3.50 | 0.12 |
| | Contractors | 5284 | 524 | 27 | | | | | | | | | 5835 | 8.43 | 0.36 |
| | Total | 6285 | 558 | 27 | | | | | | | | | 6870 | 8.43 | 0.32 |
| 202201 | TEPCO | 942 | 17 | | | | | | | | | | 959 | 3.31 | 0.10 |
| | Contractors | 5169 | 630 | 44 | 1 | | | | | | | | 5844 | 10.28 | 0.41 |
| | Total | 6111 | 647 | 44 | 1 | | | | | | | | 6803 | 10.28 | 0.37 |
| 202202 | TEPCO | 877 | 20 | | | | | | | | | | 897 | 4.43 | 0.11 |
| | Contractors | 5106 | 708 | 43 | 8 | | | | | | | | 5865 | 12.70 | 0.46 |
| | Total | 5983 | 728 | 43 | 8 | | | | | | | | 6762 | 12.70 | 0.41 |
| 202203 | TEPCO | 969 | 32 | | | | | | | | | | 1001 | 3.77 | 0.13 |
| | Contractors | 5150 | 670 | 37 | 3 | | | | | | | | 5860 | 11.20 | 0.43 |
| | Total | 6119 | 702 | 37 | 3 | | | | | | | | 6861 | 11.20 | 0.39 |
| 202204 | TEPCO | 988 | 35 | | | | | | | | | | 1023 | 4.53 | 0.14 |
| | Contractors | 5198 | 398 | 4 | | | | | | | | | 5600 | 5.90 | 0.28 |
| | Total | 6186 | 433 | 4 | | | | | | | | | 6623 | 5.90 | 0.26 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202205 | TEPCO | 980 | 10 | | | | | | | | | | 990 | 2.78 | 0.08 |
| | Contractors | 5347 | 340 | | | | | | | | | | 5687 | 4.90 | 0.24 |
| | Total | 6327 | 350 | | | | | | | | | | 6677 | 4.90 | 0.22 |
| 202206 | TEPCO | 1045 | 29 | | | | | | | | | | 1074 | 2.27 | 0.10 |
| | Contractors | 5431 | 612 | 14 | | | | | | | | | 6057 | 7.40 | 0.36 |
| | Total | 6476 | 641 | 14 | | | | | | | | | 7131 | 7.40 | 0.33 |
| 202207 | TEPCO | 992 | 15 | | | | | | | | | | 1007 | 4.37 | 0.09 |
| | Contractors | 5593 | 495 | 18 | | | | | | | | | 6106 | 10.00 | 0.32 |
| | Total | 6585 | 510 | 18 | | | | | | | | | 7113 | 10.00 | 0.29 |
| 202208 | TEPCO | 1013 | 11 | | | | | | | | | | 1024 | 1.49 | 0.07 |
| | Contractors | 5677 | 354 | 8 | | | | | | | | | 6039 | 6.35 | 0.23 |
| | Total | 6690 | 365 | 8 | | | | | | | | | 7063 | 6.35 | 0.21 |
| 202209 | TEPCO | 1081 | 9 | | | | | | | | | | 1090 | 4.60 | 0.08 |
| | Contractors | 5763 | 528 | 30 | | | | | | | | | 6321 | 7.10 | 0.34 |
| | Total | 6844 | 537 | 30 | | | | | | | | | 7411 | 7.10 | 0.30 |
| 202210 | TEPCO | 1020 | 22 | | | | | | | | | | 1042 | 3.79 | 0.10 |
| | Contractors | 5932 | 514 | 35 | | | | | | | | | 6481 | 9.39 | 0.31 |
| | Total | 6952 | 536 | 35 | | | | | | | | | 7523 | 9.39 | 0.28 |
| 202211 | TEPCO | 1040 | 14 | | | | | | | | | | 1054 | 2.44 | 0.09 |
| | Contractors | 6091 | 585 | 34 | 1 | | | | | | | | 6711 | 11.76 | 0.35 |
| | Total | 7131 | 599 | 34 | 1 | | | | | | | | 7765 | 11.76 | 0.32 |
| 202212 | TEPCO | 1031 | 16 | | | | | | | | | | 1047 | 2.03 | 0.09 |
| | Contractors | 6169 | 501 | 32 | | | | | | | | | 6702 | 9.91 | 0.30 |
| | Total | 7200 | 517 | 32 | | | | | | | | | 7749 | 9.91 | 0.27 |
| 202301 | TEPCO | 1025 | 10 | | | | | | | | | | 1035 | 2.80 | 0.07 |
| | Contractors | 6143 | 431 | 13 | | | | | | | | | 6587 | 9.30 | 0.26 |
| | Total | 7168 | 441 | 13 | | | | | | | | | 7622 | 9.30 | 0.23 |
| 202302 | TEPCO | 1013 | 18 | | | | | | | | | | 1031 | 2.45 | 0.09 |
| | Contractors | 6044 | 578 | 29 | 1 | | | | | | | | 6652 | 10.71 | 0.32 |
| | Total | 7057 | 596 | 29 | 1 | | | | | | | | 7683 | 10.71 | 0.29 |
| 202303 | TEPCO | 1062 | 19 | | | | | | | | | | 1081 | 3.44 | 0.08 |
| | Contractors | 6139 | 638 | 39 | 4 | | | | | | | | 6820 | 13.42 | 0.35 |
| | Total | 7201 | 657 | 39 | 4 | | | | | | | | 7901 | 13.42 | 0.32 |
| 202304 | TEPCO | 1034 | 18 | | | | | | | | | | 1052 | 3.1 | 0.09 |
| | Contractors | 5797 | 613 | 76 | 1 | | | | | | | | 6487 | 10.1 | 0.41 |
| | Total | 6831 | 631 | 76 | 1 | | | | | | | | 7539 | 10.1 | 0.36 |
| 202305 | TEPCO | 1029 | 8 | | | | | | | | | | 1037 | 3.0 | 0.05 |
| | Contractors | 5975 | 446 | 35 | 1 | | | | | | | | 6457 | 10.1 | 0.29 |
| | Total | 7004 | 454 | 35 | 1 | | | | | | | | 7494 | 10.1 | 0.25 |
| 202306 | TEPCO | 1092 | 5 | | | | | | | | | | 1097 | 2.0 | 0.06 |
| | Contractors | 5888 | 644 | 44 | | | | | | | | | 6576 | 9.0 | 0.37 |
| | Total | 6980 | 649 | 44 | | | | | | | | | 7673 | 9.0 | 0.32 |
| 202307 | TEPCO | 996 | 2 | | | | | | | | | | 998 | 2.3 | 0.06 |
| | Contractors | 6020 | 580 | 21 | | | | | | | | | 6621 | 7.6 | 0.31 |
| | Total | 7016 | 582 | 21 | | | | | | | | | 7619 | 7.6 | 0.28 |
| 202308 | TEPCO | 1029 | 4 | | | | | | | | | | 1033 | 2.6 | 0.05 |
| | Contractors | 6045 | 326 | 12 | | | | | | | | | 6383 | 7.6 | 0.21 |
| | Total | 7074 | 330 | 12 | | | | | | | | | 7416 | 7.6 | 0.19 |
| 202309 | TEPCO | 1045 | 11 | | | | | | | | | | 1056 | 3.6 | 0.07 |
| | Contractors | 6084 | 520 | 39 | 1 | | | | | | | | 6644 | 10.3 | 0.32 |
| | Total | 7129 | 531 | 39 | 1 | | | | | | | | 7700 | 10.3 | 0.29 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202310 | TEPCO | 1057 | 13 | | | | | | | | | | 1070 | 3.9 | 0.07 |
| | Contractors | 6127 | 612 | 45 | 1 | | | | | | | | 6785 | 10.1 | 0.36 |
| | Total | 7184 | 625 | 45 | 1 | | | | | | | | 7855 | 10.1 | 0.32 |
| 202311 | TEPCO | 1059 | 9 | | | | | | | | | | 1068 | 2.9 | 0.07 |
| | Contractors | 6326 | 499 | 61 | 1 | | | | | | | | 6887 | 11.6 | 0.34 |
| | Total | 7385 | 508 | 61 | 1 | | | | | | | | 7955 | 11.6 | 0.30 |
| 202312 | TEPCO | 1037 | 17 | | | | | | | | | | 1054 | 3.7 | 0.08 |
| | Contractors | 6378 | 522 | 61 | 2 | | | | | | | | 6963 | 10.2 | 0.33 |
| | Total | 7415 | 539 | 61 | 2 | | | | | | | | 8017 | 10.2 | 0.29 |
| 202401 | TEPCO | 984 | 9 | | | | | | | | | | 993 | 1.9 | 0.06 |
| | Contractors | 6457 | 380 | 18 | | | | | | | | | 6855 | 8.0 | 0.24 |
| | Total | 7441 | 389 | 18 | | | | | | | | | 7848 | 8.0 | 0.22 |
| 202402 | TEPCO | 1041 | 3 | | | | | | | | | | 1044 | 1.9 | 0.06 |
| | Contractors | 6460 | 468 | 35 | 4 | | | | | | | | 6967 | 10.8 | 0.30 |
| | Total | 7501 | 471 | 35 | 4 | | | | | | | | 8011 | 10.8 | 0.26 |
| 202403 | TEPCO | 1005 | 12 | | | | | | | | | | 1017 | 3.9 | 0.08 |
| | Contractors | 6422 | 440 | 37 | | | | | | | | | 6899 | 8.6 | 0.28 |
| | Total | 7427 | 452 | 37 | | | | | | | | | 7916 | 8.6 | 0.26 |
| 202404 | TEPCO | 1003 | 11 | | | | | | | | | | 1014 | 3.0 | 0.07 |
| | Contractors | 6031 | 370 | 24 | | | | | | | | | 6425 | 8.8 | 0.25 |
| | Total | 7034 | 381 | 24 | | | | | | | | | 7439 | 8.8 | 0.22 |
| 202405 | TEPCO | 971 | 8 | | | | | | | | | | 979 | 4.2 | 0.08 |
| | Contractors | 6162 | 354 | 17 | | | | | | | | | 6533 | 7.2 | 0.22 |
| | Total | 7133 | 362 | 17 | | | | | | | | | 7512 | 7.2 | 0.20 |
| 202406 | TEPCO | 1024 | 18 | | | | | | | | | | 1042 | 3.8 | 0.08 |
| | Contractors | 6201 | 529 | 28 | | | | | | | | | 6758 | 7.7 | 0.31 |
| | Total | 7225 | 547 | 28 | | | | | | | | | 7800 | 7.7 | 0.28 |
| 202407 | TEPCO | 923 | 16 | | | | | | | | | | 939 | 4.2 | 0.08 |
| | Contractors | 6308 | 424 | 42 | | | | | | | | | 6774 | 9.4 | 0.29 |
| | Total | 7231 | 440 | 42 | | | | | | | | | 7713 | 9.4 | 0.26 |
| 202408 | TEPCO | 965 | 13 | | | | | | | | | | 978 | 2.7 | 0.07 |
| | Contractors | 6084 | 347 | 25 | 2 | | | | | | | | 6458 | 11.1 | 0.23 |
| | Total | 7049 | 360 | 25 | 2 | | | | | | | | 7436 | 11.1 | 0.21 |
| 202409 | TEPCO | 982 | 10 | | | | | | | | | | 992 | 1.9 | 0.07 |
| | Contractors | 6147 | 378 | 10 | | | | | | | | | 6535 | 7.9 | 0.22 |
| | Total | 7129 | 388 | 10 | | | | | | | | | 7527 | 7.9 | 0.20 |
| 202410 | TEPCO | 1022 | 16 | | | | | | | | | | 1038 | 4.1 | 0.09 |
| | Contractors | 6289 | 554 | 62 | | | | | | | | | 6905 | 9.9 | 0.34 |
| | Total | 7311 | 570 | 62 | | | | | | | | | 7943 | 9.9 | 0.31 |
| 202411 | TEPCO | 1034 | 17 | 1 | | | | | | | | | 1052 | 5.1 | 0.09 |
| | Contractors | 6318 | 501 | 81 | 3 | | | | | | | | 6903 | 10.9 | 0.35 |
| | Total | 7352 | 518 | 82 | 3 | | | | | | | | 7955 | 10.9 | 0.31 |
| 202412 | TEPCO | 997 | 19 | | | | | | | | | | 1016 | 2.2 | 0.08 |
| | Contractors | 6489 | 412 | 58 | | | | | | | | | 6959 | 9.3 | 0.28 |
| | Total | 7486 | 431 | 58 | | | | | | | | | 7975 | 9.3 | 0.25 |
| 202501 | TEPCO | 985 | 13 | | | | | | | | | | 998 | 4.5 | 0.08 |
| | Contractors | 6391 | 481 | 34 | | | | | | | | | 6906 | 10.0 | 0.28 |
| | Total | 7376 | 494 | 34 | | | | | | | | | 7904 | 10.0 | 0.25 |
| 202502 | TEPCO | 982 | 6 | | | | | | | | | | 988 | 2.7 | 0.06 |
| | Contractors | 6347 | 604 | 91 | 1 | | | | | | | | 7043 | 10.3 | 0.38 |
| | Total | 7329 | 610 | 91 | 1 | | | | | | | | 8031 | 10.3 | 0.34 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202503 | TEPCO | 985 | 17 | | | | | | | | | | 1002 | 3.6 | 0.08 |
| | Contractors | 6174 | 602 | 76 | 2 | | | | | | | | 6854 | 10.8 | 0.36 |
| | Total | 7159 | 619 | 76 | 2 | | | | | | | | 7856 | 10.8 | 0.33 |
| 202504 | TEPCO | 997 | 13 | | | | | | | | | | 1010 | 1.7 | 0.06 |
| | Contractors | 5978 | 517 | 18 | | | | | | | | | 6513 | 9.9 | 0.28 |
| | Total | 6975 | 530 | 18 | | | | | | | | | 7523 | 9.9 | 0.25 |
| 202505 | TEPCO | 988 | 5 | | | | | | | | | | 993 | 2.6 | 0.05 |
| | Contractors | 6155 | 398 | 24 | | | | | | | | | 6577 | 7.4 | 0.24 |
| | Total | 7143 | 403 | 24 | | | | | | | | | 7570 | 7.4 | 0.22 |
| 202506 | TEPCO | 1041 | 2 | | | | | | | | | | 1043 | 1.16 | 0.05 |
| | Contractors | 6373 | 395 | 9 | | | | | | | | | 6777 | 7.51 | 0.21 |
| | Total | 7414 | 397 | 9 | | | | | | | | | 7820 | 7.51 | 0.19 |

Note)

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.
- The record months of the internal exposure dose of workers in the data above could be changed, even if the evaluation values of their internal exposure dose have not changed, when their "inhalation exposure days" (the days when they inhaled radioactive materials) are reviewed. In the case that the record months have been changed, that effect will be described.

(Aggregation period: March 11, 2011 - June 30, 2025)

Table 12. Cumulative Exposure Dose Data by Fiscal Year

FY2011

| Dose ranges (mSv) | March 2011-March 2012 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 6 | 0 | 6 |
| 200-250 | 1 | 2 | 3 |
| 150-200 | 26 | 2 | 28 |
| 100-150 | 117 | 20 | 137 |
| 75-100 | 186 | 65 | 251 |
| 50-75 | 257 | 262 | 519 |
| 20-50 | 630 | 2660 | 3290 |
| 10-20 | 491 | 2897 | 3388 |
| 5-10 | 377 | 2559 | 2936 |
| 1-5 | 589 | 4623 | 5212 |
| 1 or less | 735 | 4633 | 5368 |
| Total | 3415 | 17723 | 21138 |
| Maximum (mSv) | 678.80 | 238.42 | 678.80 |
| Average (mSv) | 25.15 | 10.07 | 12.50 |

FY2012

| Dose ranges (mSv) | April 2012-March 2013 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 1 | 0 | 1 |
| 20-50 | 62 | 675 | 737 |
| 10-20 | 129 | 2000 | 2129 |
| 5-10 | 266 | 1875 | 2141 |
| 1-5 | 579 | 3327 | 3906 |
| 1 or less | 589 | 4239 | 4828 |
| Total | 1626 | 12116 | 13742 |
| Maximum (mSv) | 54.10 | 43.30 | 54.10 |
| Average (mSv) | 4.49 | 5.90 | 5.74 |

FY2013

| Dose ranges (mSv) | April 2013-March 2014 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 31 | 629 | 660 |
| 10-20 | 95 | 2067 | 2162 |
| 5-10 | 195 | 1897 | 2092 |
| 1-5 | 670 | 3739 | 4409 |
| 1 or less | 701 | 4722 | 5423 |
| Total | 1692 | 13054 | 14746 |
| Maximum (mSv) | 41.90 | 41.40 | 41.90 |
| Average (mSv) | 3.24 | 5.51 | 5.25 |

FY2014

| Dose ranges (mSv) | April 2014-March 2015 | | |
|-------------------|-----------------------|--------------|--------------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 11 | 996 | 1007 |
| 10-20 | 60 | 2599 | 2659 |
| 5-10 | 158 | 2774 | 2932 |
| 1-5 | 637 | 5315 | 5952 |
| 1 or less | 822 | 7358 | 8180 |
| Total | 1688 | 19042 | 20730 |
| Maximum (mSv) | 29.50 | 39.85 | 39.85 |
| Average (mSv) | 2.30 | 5.29 | 5.04 |

FY2015

| Dose ranges (mSv) | April 2015-March 2016 | | |
|-------------------|-----------------------|--------------|--------------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 6 | 592 | 598 |
| 10-20 | 52 | 1947 | 1999 |
| 5-10 | 108 | 2247 | 2355 |
| 1-5 | 533 | 5114 | 5647 |
| 1 or less | 998 | 6599 | 7597 |
| Total | 1697 | 16499 | 18196 |
| Maximum (mSv) | 24.00 | 43.20 | 43.20 |
| Average (mSv) | 1.85 | 4.52 | 4.27 |

FY2016

| Dose ranges (mSv) | April 2016-March 2017 | | |
|-------------------|-----------------------|--------------|--------------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 216 | 216 |
| 10-20 | 22 | 1139 | 1161 |
| 5-10 | 90 | 1393 | 1483 |
| 1-5 | 404 | 4371 | 4775 |
| 1 or less | 1162 | 7038 | 8200 |
| Total | 1678 | 14157 | 15835 |
| Maximum (mSv) | 14.75 | 38.83 | 38.83 |
| Average (mSv) | 1.27 | 3.09 | 2.90 |

FY2017

| Dose ranges (mSv) | April 2017-March 2018 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 74 | 74 |
| 10-20 | 18 | 1133 | 1151 |
| 5-10 | 85 | 1038 | 1123 |
| 1-5 | 306 | 3571 | 3877 |
| 1 or less | 1121 | 6597 | 7718 |
| Total | 1530 | 12413 | 13943 |
| Maximum (mSv) | 15.94 | 32.74 | 32.74 |
| Average (mSv) | 1.15 | 2.88 | 2.69 |

FY2018

| Dose ranges (mSv) | April 2018-March 2019 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 21 | 853 | 874 |
| 5-10 | 70 | 870 | 940 |
| 1-5 | 247 | 2856 | 3103 |
| 1 or less | 1105 | 5284 | 6389 |
| Total | 1443 | 9863 | 11306 |
| Maximum (mSv) | 15.55 | 19.90 | 19.90 |
| Average (mSv) | 1.04 | 2.65 | 2.44 |

FY2019

| Dose ranges (mSv) | April 2019-March 2020 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 13 | 917 | 930 |
| 5-10 | 57 | 857 | 914 |
| 1-5 | 284 | 2365 | 2649 |
| 1 or less | 1030 | 5185 | 6215 |
| Total | 1384 | 9324 | 10708 |
| Maximum (mSv) | 13.92 | 19.60 | 19.60 |
| Average (mSv) | 0.98 | 2.77 | 2.54 |

FY2020

| Dose ranges (mSv) | April 2020-March 2021 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 12 | 926 | 938 |
| 5-10 | 62 | 854 | 916 |
| 1-5 | 232 | 2319 | 2551 |
| 1 or less | 1031 | 4883 | 5914 |
| Total | 1337 | 8982 | 10319 |
| Maximum (mSv) | 14.83 | 19.31 | 19.31 |
| Average (mSv) | 0.97 | 2.84 | 2.60 |

FY2021

| Dose ranges (mSv) | April 2021-March 2022 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 7 | 836 | 843 |
| 5-10 | 59 | 925 | 984 |
| 1-5 | 209 | 2247 | 2456 |
| 1 or less | 1083 | 4771 | 5854 |
| Total | 1358 | 8779 | 10137 |
| Maximum (mSv) | 13.10 | 17.46 | 17.46 |
| Average (mSv) | 0.85 | 2.77 | 2.51 |

FY2022

| Dose ranges (mSv) | April 2022-March 2023 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 6 | 708 | 714 |
| 5-10 | 50 | 966 | 1016 |
| 1-5 | 225 | 2261 | 2486 |
| 1 or less | 1131 | 5967 | 7098 |
| Total | 1412 | 9902 | 11314 |
| Maximum (mSv) | 11.84 | 17.60 | 17.60 |
| Average (mSv) | 0.80 | 2.35 | 2.16 |

FY2023

| Dose ranges (mSv) | April 2023-March 2024 | | |
|-------------------|-----------------------|--------------|--------------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 5 | 809 | 814 |
| 5-10 | 26 | 1135 | 1161 |
| 1-5 | 178 | 2137 | 2315 |
| 1 or less | 1207 | 6448 | 7655 |
| Total | 1416 | 10529 | 11945 |
| Maximum (mSv) | 13.8 | 17.0 | 17.0 |
| Average (mSv) | 0.59 | 2.39 | 2.18 |

FY2024

| Dose ranges (mSv) | April 2024-March 2025 | | |
|-------------------|-----------------------|--------------|--------------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 4 | 804 | 808 |
| 5-10 | 44 | 990 | 1034 |
| 1-5 | 166 | 2078 | 2244 |
| 1 or less | 1196 | 6627 | 7823 |
| Total | 1410 | 10499 | 11909 |
| Maximum (mSv) | 11.5 | 16.8 | 16.8 |
| Average (mSv) | 0.66 | 2.27 | 2.08 |

FY2025

| Dose ranges (mSv) | April 2025-June 2025 | | |
|-------------------|----------------------|-------------|-------------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 19 | 19 |
| 5-10 | 0 | 190 | 190 |
| 1-5 | 44 | 1042 | 1086 |
| 1 or less | 1189 | 6437 | 7626 |
| Total | 1233 | 7688 | 8921 |
| Maximum (mSv) | 11.5 | 12.68 | 16.8 |
| Average (mSv) | 0.14 | 0.63 | 0.56 |

Note)

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

(Aggregation period: March 11, 2011 - June 30, 2025)

Table 12 (1) Cumulative External Exposure Dose Data by Fiscal Year

FY2011

| Dose ranges (mSv) | March 2011-March 2012 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 7 | 3 | 10 |
| 100-150 | 58 | 8 | 66 |
| 75-100 | 107 | 29 | 136 |
| 50-75 | 231 | 195 | 426 |
| 20-50 | 674 | 2459 | 3133 |
| 10-20 | 554 | 2849 | 3403 |
| 5-10 | 428 | 2589 | 3017 |
| 1-5 | 600 | 4743 | 5343 |
| 1 or less | 756 | 4848 | 5604 |
| Total | 3415 | 17723 | 21138 |
| Maximum (mSv) | 188.14 | 199.42 | 199.42 |
| Average (mSv) | 19.15 | 9.16 | 10.78 |

FY2012

| Dose ranges (mSv) | April 2012-March 2013 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 1 | 0 | 1 |
| 20-50 | 62 | 675 | 737 |
| 10-20 | 129 | 2000 | 2129 |
| 5-10 | 266 | 1875 | 2141 |
| 1-5 | 579 | 3327 | 3906 |
| 1 or less | 589 | 4239 | 4828 |
| Total | 1626 | 12116 | 13742 |
| Maximum (mSv) | 54.10 | 43.30 | 54.10 |
| Average (mSv) | 4.49 | 5.90 | 5.74 |

FY2013

| Dose ranges (mSv) | April 2013-March 2014 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 31 | 629 | 660 |
| 10-20 | 95 | 2067 | 2162 |
| 5-10 | 195 | 1897 | 2092 |
| 1-5 | 670 | 3739 | 4409 |
| 1 or less | 701 | 4722 | 5423 |
| Total | 1692 | 13054 | 14746 |
| Maximum (mSv) | 41.90 | 41.40 | 41.90 |
| Average (mSv) | 3.24 | 5.51 | 5.25 |

FY2014

| Dose ranges (mSv) | April 2014-March 2015 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 11 | 996 | 1007 |
| 10-20 | 60 | 2599 | 2659 |
| 5-10 | 158 | 2774 | 2932 |
| 1-5 | 637 | 5315 | 5952 |
| 1 or less | 822 | 7358 | 8180 |
| Total | 1688 | 19042 | 20730 |
| Maximum (mSv) | 29.50 | 39.85 | 39.85 |
| Average (mSv) | 2.30 | 5.29 | 5.04 |

FY2015

| Dose ranges (mSv) | April 2015-March 2016 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 6 | 592 | 598 |
| 10-20 | 52 | 1947 | 1999 |
| 5-10 | 108 | 2247 | 2355 |
| 1-5 | 533 | 5114 | 5647 |
| 1 or less | 998 | 6599 | 7597 |
| Total | 1697 | 16499 | 18196 |
| Maximum (mSv) | 24.00 | 43.20 | 43.20 |
| Average (mSv) | 1.85 | 4.52 | 4.27 |

FY2016

| Dose ranges (mSv) | April 2016- March 2017 | | |
|-------------------|------------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 216 | 216 |
| 10-20 | 22 | 1139 | 1161 |
| 5-10 | 90 | 1393 | 1483 |
| 1-5 | 404 | 4371 | 4775 |
| 1 or less | 1162 | 7038 | 8200 |
| Total | 1678 | 14157 | 15835 |
| Maximum (mSv) | 14.75 | 38.83 | 38.83 |
| Average (mSv) | 1.27 | 3.09 | 2.90 |

FY2017

| Dose ranges (mSv) | April 2017- March 2018 | | |
|-------------------|------------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 74 | 74 |
| 10-20 | 18 | 1133 | 1151 |
| 5-10 | 85 | 1038 | 1123 |
| 1-5 | 306 | 3571 | 3877 |
| 1 or less | 1121 | 6597 | 7718 |
| Total | 1530 | 12413 | 13943 |
| Maximum (mSv) | 15.94 | 32.74 | 32.74 |
| Average (mSv) | 1.15 | 2.88 | 2.69 |

FY2018

| Dose ranges (mSv) | April 2018- March 2019 | | |
|-------------------|------------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 21 | 853 | 874 |
| 5-10 | 70 | 870 | 940 |
| 1-5 | 247 | 2856 | 3103 |
| 1 or less | 1105 | 5284 | 6389 |
| Total | 1443 | 9863 | 11306 |
| Maximum (mSv) | 15.55 | 19.90 | 19.90 |
| Average (mSv) | 1.04 | 2.65 | 2.44 |

FY2019

| Dose ranges (mSv) | April 2019-March 2020 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 13 | 917 | 930 |
| 5-10 | 57 | 857 | 914 |
| 1-5 | 284 | 2365 | 2649 |
| 1 or less | 1030 | 5185 | 6215 |
| Total | 1384 | 9324 | 10708 |
| Maximum (mSv) | 13.92 | 19.60 | 19.60 |
| Average (mSv) | 0.98 | 2.77 | 2.54 |

FY2020

| Dose ranges (mSv) | April 2020-March 2021 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 12 | 926 | 938 |
| 5-10 | 62 | 854 | 916 |
| 1-5 | 232 | 2319 | 2551 |
| 1 or less | 1031 | 4883 | 5914 |
| Total | 1337 | 8982 | 10319 |
| Maximum (mSv) | 14.83 | 19.31 | 19.31 |
| Average (mSv) | 0.97 | 2.84 | 2.60 |

FY2021

| Dose ranges (mSv) | April 2021-March 2022 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 7 | 836 | 843 |
| 5-10 | 59 | 925 | 984 |
| 1-5 | 209 | 2247 | 2456 |
| 1 or less | 1083 | 4771 | 5854 |
| Total | 1358 | 8779 | 10137 |
| Maximum (mSv) | 13.10 | 17.46 | 17.46 |
| Average (mSv) | 0.85 | 2.77 | 2.51 |

FY2022

| Dose ranges (mSv) | April 2022-March 2023 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 6 | 708 | 714 |
| 5-10 | 50 | 966 | 1016 |
| 1-5 | 225 | 2261 | 2486 |
| 1 or less | 1131 | 5967 | 7098 |
| Total | 1412 | 9902 | 11314 |
| Maximum (mSv) | 11.84 | 17.60 | 17.60 |
| Average (mSv) | 0.80 | 2.35 | 2.16 |

FY2023

| Dose ranges (mSv) | April 2023-March 2024 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 5 | 809 | 814 |
| 5-10 | 26 | 1135 | 1161 |
| 1-5 | 178 | 2137 | 2315 |
| 1 or less | 1207 | 6448 | 7655 |
| Total | 1416 | 10529 | 11945 |
| Maximum (mSv) | 13.8 | 17.0 | 17.0 |
| Average (mSv) | 0.59 | 2.39 | 2.18 |

FY2024

| Dose ranges (mSv) | April 2024-March 2025 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 4 | 804 | 808 |
| 5-10 | 44 | 990 | 1034 |
| 1-5 | 166 | 2078 | 2244 |
| 1 or less | 1196 | 6627 | 7823 |
| Total | 1410 | 10499 | 11909 |
| Maximum (mSv) | 11.5 | 16.8 | 16.8 |
| Average (mSv) | 0.66 | 2.27 | 2.08 |

FY2025

| Dose ranges (mSv) | April 2025-June2025 | | |
|-------------------|---------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 19 | 19 |
| 5-10 | 0 | 190 | 190 |
| 1-5 | 44 | 1042 | 1086 |
| 1 or less | 1189 | 6437 | 7626 |
| Total | 1233 | 7688 | 8921 |
| Maximum (mSv) | 3.88 | 12.68 | 12.68 |
| Average (mSv) | 0.14 | 0.63 | 0.56 |

Note)

- The table shows the external exposure part of the cumulative exposure dose data by fiscal year.
- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

(Aggregation period: March 11, 2011 - June 30, 2025)

Table 12 (2) Cumulative Internal Exposure Dose Data by Fiscal Year

FY2011

| Dose ranges (mSv) | March 2011-March 2012 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 5 | 0 | 5 |
| 200-250 | 1 | 0 | 1 |
| 150-200 | 1 | 0 | 1 |
| 100-150 | 7 | 0 | 7 |
| 75-100 | 11 | 11 | 22 |
| 50-75 | 27 | 17 | 44 |
| 20-50 | 191 | 125 | 316 |
| 10-20 | 399 | 313 | 712 |
| 5-10 | 281 | 411 | 692 |
| 2-5 | 223 | 691 | 914 |
| 2 or less | 2269 | 16155 | 18424 |
| Total | 3415 | 17723 | 21138 |
| Maximum (mSv) | 590.00 | 98.53 | 590.00 |
| Average (mSv) | 6.01 | 0.90 | 1.73 |

FY2012

| Dose ranges (mSv) | April 2012-March 2013 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1626 | 12116 | 13742 |
| Total | 1626 | 12116 | 13742 |
| Maximum (mSv) | 0.00 | 0.10 | 0.10 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2013

| Dose ranges (mSv) | April 2013-March 2014 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1692 | 13054 | 14746 |
| Total | 1692 | 13054 | 14746 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2014

| Dose ranges (mSv) | April 2014-March 2015 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1688 | 19042 | 20730 |
| Total | 1688 | 19042 | 20730 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2015

| Dose ranges (mSv) | April 2015-March 2016 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1697 | 16499 | 18196 |
| Total | 1697 | 16499 | 18196 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2016

| Dose ranges (mSv) | April 2016-March 2017 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1678 | 14157 | 15835 |
| Total | 1678 | 14157 | 15835 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2017

| Dose ranges (mSv) | April 2017-March 2018 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1530 | 12413 | 13943 |
| Total | 1530 | 12413 | 13943 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2018

| Dose ranges (mSv) | April 2018- March 2019 | | |
|-------------------|------------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1443 | 9863 | 11306 |
| Total | 1443 | 9863 | 11306 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2019

| Dose ranges (mSv) | April 2019-March 2020 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1384 | 9324 | 10708 |
| Total | 1384 | 9324 | 10708 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2020

| Dose ranges (mSv) | April 2020-March 2021 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1337 | 8982 | 10319 |
| Total | 1337 | 8982 | 10319 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2021

| Dose ranges (mSv) | April 2021-March 2022 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1358 | 8779 | 10137 |
| Total | 1358 | 8779 | 10137 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2022

| Dose ranges (mSv) | April 2022-March 2023 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1412 | 9902 | 11314 |
| Total | 1412 | 9902 | 11314 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2023

| Dose ranges (mSv) | April 2023-March 2024 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1416 | 10529 | 11945 |
| Total | 1416 | 10529 | 11945 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2024

| Dose ranges (mSv) | April 2024-June 2025 | | |
|-------------------|----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1410 | 10499 | 11909 |
| Total | 1410 | 10499 | 11909 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

FY2025

| Dose ranges (mSv) | April 2025-June 2025 | | |
|-------------------|----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 250 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 0 | 0 |
| 5-10 | 0 | 0 | 0 |
| 2-5 | 0 | 0 | 0 |
| 2 or less | 1233 | 7688 | 8921 |
| Total | 1233 | 7688 | 8921 |
| Maximum (mSv) | 0.00 | 0.00 | 0.00 |
| Average (mSv) | 0.00 | 0.00 | 0.00 |

Note)

- The table shows the internal exposure part of the cumulative exposure dose data by fiscal year.
- Depending on the prime contractors, there are some cases in which the internal exposure dose is recorded as that of the WBC measurement month, not the inhalation exposure month.

Table 13. Monthly External Exposure Dose Data

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201103 | TEPCO | 60 | 88 | 522 | 604 | 287 | 67 | 41 | 21 | 6 | | | 1696 | 182.33 | 19.52 |
| | Contractors | 542 | 775 | 387 | 330 | 183 | 36 | 22 | 8 | 3 | | | 2286 | 199.42 | 9.08 |
| | Total | 602 | 863 | 909 | 934 | 470 | 103 | 63 | 29 | 9 | | | 3982 | 199.42 | 13.52 |
| 201104 | TEPCO | 233 | 321 | 859 | 182 | 61 | 1 | | | | | | 1657 | 59.60 | 6.61 |
| | Contractors | 1647 | 1445 | 583 | 406 | 106 | | | | | | | 4187 | 48.10 | 4.03 |
| | Total | 1880 | 1766 | 1442 | 588 | 167 | 1 | | | | | | 5844 | 59.60 | 4.76 |
| 201105 | TEPCO | 438 | 782 | 170 | 73 | 14 | | | | | | | 1477 | 33.42 | 3.13 |
| | Contractors | 2258 | 2391 | 786 | 304 | 70 | | | | | | | 5809 | 48.80 | 3.19 |
| | Total | 2696 | 3173 | 956 | 377 | 84 | | | | | | | 7286 | 48.80 | 3.18 |
| 201106 | TEPCO | 515 | 723 | 83 | 30 | | | | | | | | 1351 | 16.29 | 2.10 |
| | Contractors | 2520 | 2604 | 743 | 323 | 60 | | | | | | | 6250 | 43.00 | 2.99 |
| | Total | 3035 | 3327 | 826 | 353 | 60 | | | | | | | 7601 | 43.00 | 2.84 |
| 201107 | TEPCO | 655 | 626 | 50 | 17 | 3 | | | | | | | 1351 | 31.13 | 1.67 |
| | Contractors | 2865 | 2724 | 580 | 195 | 31 | | | | | | | 6395 | 34.42 | 2.38 |
| | Total | 3520 | 3350 | 630 | 212 | 34 | | | | | | | 7746 | 34.42 | 2.26 |
| 201108 | TEPCO | 543 | 666 | 57 | 19 | 1 | | | | | | | 1286 | 23.33 | 1.72 |
| | Contractors | 2826 | 2712 | 485 | 161 | 24 | | | | | | | 6208 | 36.10 | 2.18 |
| | Total | 3369 | 3378 | 542 | 180 | 25 | | | | | | | 7494 | 36.10 | 2.10 |
| 201109 | TEPCO | 534 | 633 | 38 | 2 | | | | | | | | 1207 | 11.35 | 1.45 |
| | Contractors | 2856 | 2567 | 398 | 140 | 22 | | | | | | | 5983 | 33.40 | 2.01 |
| | Total | 3390 | 3200 | 436 | 142 | 22 | | | | | | | 7190 | 33.40 | 1.91 |
| 201110 | TEPCO | 564 | 552 | 45 | 15 | 3 | | | | | | | 1179 | 36.35 | 1.57 |
| | Contractors | 2825 | 2346 | 336 | 103 | 8 | | | | | | | 5618 | 23.50 | 1.84 |
| | Total | 3389 | 2898 | 381 | 118 | 11 | | | | | | | 6797 | 36.35 | 1.79 |
| 201111 | TEPCO | 853 | 280 | 37 | 10 | | | | | | | | 1180 | 13.40 | 1.07 |
| | Contractors | 3355 | 1909 | 228 | 81 | 5 | | | | | | | 5578 | 23.03 | 1.46 |
| | Total | 4208 | 2189 | 265 | 91 | 5 | | | | | | | 6758 | 23.03 | 1.39 |
| 201112 | TEPCO | 868 | 282 | 26 | 13 | 3 | | | | | | | 1192 | 23.20 | 1.10 |
| | Contractors | 3348 | 1725 | 258 | 76 | | | | | | | | 5407 | 19.20 | 1.43 |
| | Total | 4216 | 2007 | 284 | 89 | 3 | | | | | | | 6599 | 23.20 | 1.37 |
| 201201 | TEPCO | 761 | 284 | 37 | 13 | | | | | | | | 1095 | 17.00 | 1.19 |
| | Contractors | 3240 | 1430 | 203 | 72 | 1 | | | | | | | 4946 | 21.90 | 1.36 |
| | Total | 4001 | 1714 | 240 | 85 | 1 | | | | | | | 6041 | 21.90 | 1.33 |
| 201202 | TEPCO | 845 | 231 | 25 | 8 | | | | | | | | 1109 | 17.63 | 0.91 |
| | Contractors | 2945 | 1579 | 221 | 100 | 2 | | | | | | | 4847 | 20.91 | 1.50 |
| | Total | 3790 | 1810 | 246 | 108 | 2 | | | | | | | 5956 | 20.91 | 1.39 |
| 201203 | TEPCO | 874 | 220 | 23 | 2 | | | | | | | | 1119 | 12.10 | 0.83 |
| | Contractors | 3030 | 1463 | 206 | 53 | 3 | | | | | | | 4755 | 21.83 | 1.36 |
| | Total | 3904 | 1683 | 229 | 55 | 3 | | | | | | | 5874 | 21.83 | 1.26 |
| 201204 | TEPCO | 870 | 179 | 19 | 3 | | | | | | | | 1071 | 13.00 | 0.75 |
| | Contractors | 2835 | 1305 | 151 | 75 | 3 | | | | | | | 4369 | 23.90 | 1.30 |
| | Total | 3705 | 1484 | 170 | 78 | 3 | | | | | | | 5440 | 23.90 | 1.19 |
| 201205 | TEPCO | 854 | 177 | 10 | 1 | | | | | | | | 1042 | 10.20 | 0.66 |
| | Contractors | 2897 | 1406 | 246 | 49 | | | | | | | | 4598 | 18.22 | 1.42 |
| | Total | 3751 | 1583 | 256 | 50 | | | | | | | | 5640 | 18.22 | 1.28 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201206 | TEPCO | 829 | 162 | 20 | 3 | | | | | | | | 1014 | 12.10 | 0.78 |
| | Contractors | 3086 | 1652 | 220 | 29 | | | | | | | | 4987 | 14.94 | 1.29 |
| | Total | 3915 | 1814 | 240 | 32 | | | | | | | | 6001 | 14.94 | 1.21 |
| 201207 | TEPCO | 854 | 150 | 9 | | | | | | | | | 1013 | 6.60 | 0.62 |
| | Contractors | 3065 | 1621 | 222 | 38 | | | | | | | | 4946 | 17.33 | 1.34 |
| | Total | 3919 | 1771 | 231 | 38 | | | | | | | | 5959 | 17.33 | 1.21 |
| 201208 | TEPCO | 835 | 144 | 7 | | | | | | | | | 986 | 7.20 | 0.62 |
| | Contractors | 3299 | 1341 | 120 | 4 | | | | | | | | 4764 | 11.64 | 1.04 |
| | Total | 4134 | 1485 | 127 | 4 | | | | | | | | 5750 | 11.64 | 0.97 |
| 201209 | TEPCO | 850 | 123 | 9 | | | | | | | | | 982 | 8.20 | 0.57 |
| | Contractors | 3272 | 1274 | 163 | 29 | 1 | | | | | | | 4739 | 20.50 | 1.15 |
| | Total | 4122 | 1397 | 172 | 29 | 1 | | | | | | | 5721 | 20.50 | 1.05 |
| 201210 | TEPCO | 826 | 145 | 7 | | | | | | | | | 978 | 6.30 | 0.61 |
| | Contractors | 3307 | 1325 | 136 | 31 | | | | | | | | 4799 | 16.00 | 1.11 |
| | Total | 4133 | 1470 | 143 | 31 | | | | | | | | 5777 | 16.00 | 1.03 |
| 201211 | TEPCO | 812 | 149 | 7 | | | | | | | | | 968 | 9.50 | 0.61 |
| | Contractors | 3306 | 1222 | 145 | 27 | | | | | | | | 4700 | 18.70 | 1.09 |
| | Total | 4118 | 1371 | 152 | 27 | | | | | | | | 5668 | 18.70 | 1.01 |
| 201212 | TEPCO | 846 | 149 | 10 | | | | | | | | | 1005 | 7.50 | 0.58 |
| | Contractors | 3489 | 1363 | 180 | 10 | | | | | | | | 5042 | 15.00 | 1.10 |
| | Total | 4335 | 1512 | 190 | 10 | | | | | | | | 6047 | 15.00 | 1.01 |
| 201301 | TEPCO | 870 | 96 | 3 | | | | | | | | | 969 | 7.39 | 0.42 |
| | Contractors | 3768 | 1310 | 115 | 7 | | | | | | | | 5200 | 12.90 | 0.96 |
| | Total | 4638 | 1406 | 118 | 7 | | | | | | | | 6169 | 12.90 | 0.88 |
| 201302 | TEPCO | 870 | 105 | 2 | | | | | | | | | 977 | 5.43 | 0.45 |
| | Contractors | 3917 | 1415 | 263 | 35 | | | | | | | | 5630 | 18.50 | 1.21 |
| | Total | 4787 | 1520 | 265 | 35 | | | | | | | | 6607 | 18.50 | 1.09 |
| 201303 | TEPCO | 845 | 140 | 10 | 2 | | | | | | | | 997 | 11.03 | 0.60 |
| | Contractors | 3908 | 1706 | 335 | 35 | | | | | | | | 5984 | 19.30 | 1.35 |
| | Total | 4753 | 1846 | 345 | 37 | | | | | | | | 6981 | 19.30 | 1.24 |
| 201304 | TEPCO | 948 | 108 | 4 | | | | | | | | | 1060 | 5.90 | 0.49 |
| | Contractors | 4029 | 1165 | 111 | 5 | | | | | | | | 5310 | 14.40 | 0.88 |
| | Total | 4977 | 1273 | 115 | 5 | | | | | | | | 6370 | 14.40 | 0.81 |
| 201305 | TEPCO | 896 | 100 | 4 | | | | | | | | | 1000 | 8.60 | 0.45 |
| | Contractors | 3920 | 1141 | 92 | 5 | | | | | | | | 5158 | 15.80 | 0.85 |
| | Total | 4816 | 1241 | 96 | 5 | | | | | | | | 6158 | 15.80 | 0.78 |
| 201306 | TEPCO | 931 | 87 | 6 | | | | | | | | | 1024 | 7.40 | 0.42 |
| | Contractors | 3731 | 1182 | 85 | 7 | | | | | | | | 5005 | 17.50 | 0.87 |
| | Total | 4662 | 1269 | 91 | 7 | | | | | | | | 6029 | 17.50 | 0.79 |
| 201307 | TEPCO | 891 | 96 | 1 | | | | | | | | | 988 | 5.50 | 0.43 |
| | Contractors | 3752 | 1128 | 107 | 9 | | | | | | | | 4996 | 14.80 | 0.89 |
| | Total | 4643 | 1224 | 108 | 9 | | | | | | | | 5984 | 14.80 | 0.81 |
| 201308 | TEPCO | 834 | 118 | 4 | | | | | | | | | 956 | 6.10 | 0.49 |
| | Contractors | 3665 | 1211 | 142 | 40 | | | | | | | | 5058 | 19.89 | 1.03 |
| | Total | 4499 | 1329 | 146 | 40 | | | | | | | | 6014 | 19.89 | 0.94 |
| 201309 | TEPCO | 933 | 102 | 3 | | | | | | | | | 1038 | 5.60 | 0.44 |
| | Contractors | 3525 | 1420 | 247 | 61 | 1 | | | | | | | 5254 | 20.58 | 1.28 |
| | Total | 4458 | 1522 | 250 | 61 | 1 | | | | | | | 6292 | 20.58 | 1.14 |
| 201310 | TEPCO | 893 | 146 | 8 | | | | | | | | | 1047 | 9.50 | 0.55 |
| | Contractors | 3460 | 1556 | 343 | 47 | | | | | | | | 5406 | 19.36 | 1.43 |
| | Total | 4353 | 1702 | 351 | 47 | | | | | | | | 6453 | 19.36 | 1.29 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201311 | TEPCO | 954 | 120 | 5 | | | | | | | | | 1079 | 9.20 | 0.48 |
| | Contractors | 3700 | 1533 | 303 | 32 | | | | | | | | 5568 | 16.91 | 1.28 |
| | Total | 4654 | 1653 | 308 | 32 | | | | | | | | 6647 | 16.91 | 1.15 |
| 201312 | TEPCO | 968 | 116 | 2 | | | | | | | | | 1086 | 5.40 | 0.44 |
| | Contractors | 3852 | 1627 | 199 | 23 | | | | | | | | 5701 | 16.81 | 1.13 |
| | Total | 4820 | 1743 | 201 | 23 | | | | | | | | 6787 | 16.81 | 1.02 |
| 201401 | TEPCO | 997 | 84 | | | | | | | | | | 1081 | 4.50 | 0.37 |
| | Contractors | 4112 | 1505 | 221 | 53 | | | | | | | | 5891 | 15.80 | 1.16 |
| | Total | 5109 | 1589 | 221 | 53 | | | | | | | | 6972 | 15.80 | 1.04 |
| 201402 | TEPCO | 1018 | 56 | 4 | | | | | | | | | 1078 | 6.50 | 0.34 |
| | Contractors | 4611 | 1611 | 168 | 30 | | | | | | | | 6420 | 17.29 | 1.02 |
| | Total | 5629 | 1667 | 172 | 30 | | | | | | | | 7498 | 17.29 | 0.92 |
| 201403 | TEPCO | 1012 | 85 | | | | | | | | | | 1097 | 4.80 | 0.36 |
| | Contractors | 4940 | 1867 | 227 | 23 | | | | | | | | 7057 | 18.49 | 1.07 |
| | Total | 5952 | 1952 | 227 | 23 | | | | | | | | 8154 | 18.49 | 0.98 |
| 201404 | TEPCO | 999 | 94 | 1 | | | | | | | | | 1094 | 5.70 | 0.38 |
| | Contractors | 5449 | 1743 | 234 | 19 | | | | | | | | 7445 | 16.00 | 0.98 |
| | Total | 6448 | 1837 | 235 | 19 | | | | | | | | 8539 | 16.00 | 0.91 |
| 201405 | TEPCO | 1053 | 65 | 1 | | | | | | | | | 1119 | 5.60 | 0.31 |
| | Contractors | 5974 | 1794 | 209 | 47 | 1 | | | | | | | 8025 | 20.70 | 0.95 |
| | Total | 7027 | 1859 | 210 | 47 | 1 | | | | | | | 9144 | 20.70 | 0.87 |
| 201406 | TEPCO | 1056 | 66 | 1 | | | | | | | | | 1123 | 6.80 | 0.32 |
| | Contractors | 6773 | 1790 | 329 | 26 | | | | | | | | 8918 | 16.89 | 0.95 |
| | Total | 7829 | 1856 | 330 | 26 | | | | | | | | 10041 | 16.89 | 0.88 |
| 201407 | TEPCO | 1092 | 39 | 1 | | | | | | | | | 1132 | 5.40 | 0.27 |
| | Contractors | 7292 | 1728 | 258 | 49 | | | | | | | | 9327 | 18.69 | 0.89 |
| | Total | 8384 | 1767 | 259 | 49 | | | | | | | | 10459 | 18.69 | 0.82 |
| 201408 | TEPCO | 1062 | 39 | | | | | | | | | | 1101 | 3.40 | 0.25 |
| | Contractors | 7818 | 1338 | 214 | 9 | | | | | | | | 9379 | 17.13 | 0.71 |
| | Total | 8880 | 1377 | 214 | 9 | | | | | | | | 10480 | 17.13 | 0.67 |
| 201409 | TEPCO | 1110 | 51 | 1 | | | | | | | | | 1162 | 6.00 | 0.27 |
| | Contractors | 8013 | 1634 | 287 | 36 | | | | | | | | 9970 | 18.22 | 0.84 |
| | Total | 9123 | 1685 | 288 | 36 | | | | | | | | 11132 | 18.22 | 0.78 |
| 201410 | TEPCO | 1112 | 62 | | | | | | | | | | 1174 | 2.70 | 0.29 |
| | Contractors | 7951 | 1766 | 234 | 18 | | | | | | | | 9969 | 14.92 | 0.80 |
| | Total | 9063 | 1828 | 234 | 18 | | | | | | | | 11143 | 14.92 | 0.74 |
| 201411 | TEPCO | 1141 | 45 | | | | | | | | | | 1186 | 3.00 | 0.21 |
| | Contractors | 8198 | 1644 | 269 | 19 | | | | | | | | 10130 | 15.92 | 0.78 |
| | Total | 9339 | 1689 | 269 | 19 | | | | | | | | 11316 | 15.92 | 0.72 |
| 201412 | TEPCO | 1099 | 60 | | | | | | | | | | 1159 | 4.30 | 0.24 |
| | Contractors | 8272 | 1912 | 283 | 34 | | | | | | | | 10501 | 16.74 | 0.85 |
| | Total | 9371 | 1972 | 283 | 34 | | | | | | | | 11660 | 16.74 | 0.79 |
| 201501 | TEPCO | 1111 | 37 | | | | | | | | | | 1148 | 4.20 | 0.22 |
| | Contractors | 8514 | 1513 | 56 | 1 | | | | | | | | 10084 | 12.80 | 0.56 |
| | Total | 9625 | 1550 | 56 | 1 | | | | | | | | 11232 | 12.80 | 0.53 |
| 201502 | TEPCO | 1096 | 74 | 6 | | | | | | | | | 1176 | 8.00 | 0.33 |
| | Contractors | 8498 | 2214 | 285 | 36 | | | | | | | | 11033 | 16.80 | 0.89 |
| | Total | 9594 | 2288 | 291 | 36 | | | | | | | | 12209 | 16.80 | 0.83 |
| 201503 | TEPCO | 1060 | 79 | 3 | | | | | | | | | 1142 | 6.40 | 0.32 |
| | Contractors | 8036 | 2466 | 553 | 118 | | | | | | | | 11173 | 19.90 | 1.21 |
| | Total | 9096 | 2545 | 556 | 118 | | | | | | | | 12315 | 19.90 | 1.13 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201504 | TEPCO | 1100 | 66 | | | | | | | | | | 1166 | 4.80 | 0.27 |
| | Contractors | 7693 | 2414 | 248 | 20 | | | | | | | | 10375 | 15.60 | 0.93 |
| | Total | 8793 | 2480 | 248 | 20 | | | | | | | | 11541 | 15.60 | 0.86 |
| 201505 | TEPCO | 1092 | 42 | | | | | | | | | | 1134 | 2.12 | 0.20 |
| | Contractors | 8100 | 1746 | 98 | 4 | | | | | | | | 9948 | 11.40 | 0.66 |
| | Total | 9192 | 1788 | 98 | 4 | | | | | | | | 11082 | 11.40 | 0.61 |
| 201506 | TEPCO | 1128 | 64 | | | | | | | | | | 1192 | 3.90 | 0.25 |
| | Contractors | 8185 | 1737 | 167 | 12 | | | | | | | | 10101 | 11.50 | 0.72 |
| | Total | 9313 | 1801 | 167 | 12 | | | | | | | | 11293 | 11.50 | 0.67 |
| 201507 | TEPCO | 1119 | 53 | 1 | | | | | | | | | 1173 | 5.10 | 0.24 |
| | Contractors | 8140 | 1646 | 134 | 7 | | | | | | | | 9927 | 10.72 | 0.66 |
| | Total | 9259 | 1699 | 135 | 7 | | | | | | | | 11100 | 10.72 | 0.62 |
| 201508 | TEPCO | 1083 | 53 | | | | | | | | | | 1136 | 3.38 | 0.21 |
| | Contractors | 8369 | 1040 | 36 | 1 | | | | | | | | 9446 | 10.30 | 0.43 |
| | Total | 9452 | 1093 | 36 | 1 | | | | | | | | 10582 | 10.30 | 0.41 |
| 201509 | TEPCO | 1144 | 51 | 1 | | | | | | | | | 1196 | 5.60 | 0.24 |
| | Contractors | 8034 | 1590 | 140 | 16 | | | | | | | | 9780 | 15.30 | 0.67 |
| | Total | 9178 | 1641 | 141 | 16 | | | | | | | | 10976 | 15.30 | 0.63 |
| 201510 | TEPCO | 1130 | 52 | | | | | | | | | | 1182 | 3.20 | 0.22 |
| | Contractors | 7864 | 1699 | 145 | 9 | | | | | | | | 9717 | 14.42 | 0.70 |
| | Total | 8994 | 1751 | 145 | 9 | | | | | | | | 10899 | 14.42 | 0.64 |
| 201511 | TEPCO | 1119 | 48 | | | | | | | | | | 1167 | 4.96 | 0.22 |
| | Contractors | 7920 | 1451 | 110 | 7 | | | | | | | | 9488 | 13.88 | 0.61 |
| | Total | 9039 | 1499 | 110 | 7 | | | | | | | | 10655 | 13.88 | 0.57 |
| 201512 | TEPCO | 1122 | 47 | | | | | | | | | | 1169 | 2.70 | 0.21 |
| | Contractors | 8026 | 1335 | 73 | 5 | | | | | | | | 9439 | 13.50 | 0.56 |
| | Total | 9148 | 1382 | 73 | 5 | | | | | | | | 10608 | 13.50 | 0.52 |
| 201601 | TEPCO | 1108 | 38 | | | | | | | | | | 1146 | 3.30 | 0.20 |
| | Contractors | 8070 | 1194 | 60 | 4 | | | | | | | | 9328 | 16.00 | 0.51 |
| | Total | 9178 | 1232 | 60 | 4 | | | | | | | | 10474 | 16.00 | 0.48 |
| 201602 | TEPCO | 1128 | 49 | | | | | | | | | | 1177 | 4.70 | 0.22 |
| | Contractors | 7896 | 1461 | 78 | 12 | | | | | | | | 9447 | 12.36 | 0.59 |
| | Total | 9024 | 1510 | 78 | 12 | | | | | | | | 10624 | 12.36 | 0.55 |
| 201603 | TEPCO | 1125 | 44 | | | | | | | | | | 1169 | 2.71 | 0.20 |
| | Contractors | 8051 | 1291 | 93 | 19 | | | | | | | | 9454 | 13.82 | 0.59 |
| | Total | 9176 | 1335 | 93 | 19 | | | | | | | | 10623 | 13.82 | 0.55 |
| 201604 | TEPCO | 1097 | 16 | | | | | | | | | | 1113 | 1.90 | 0.16 |
| | Contractors | 7852 | 870 | 42 | | | | | | | | | 8764 | 9.78 | 0.41 |
| | Total | 8949 | 886 | 42 | | | | | | | | | 9877 | 9.78 | 0.38 |
| 201605 | TEPCO | 1128 | 9 | | | | | | | | | | 1137 | 2.50 | 0.14 |
| | Contractors | 7738 | 651 | 19 | | | | | | | | | 8408 | 9.70 | 0.32 |
| | Total | 8866 | 660 | 19 | | | | | | | | | 9545 | 9.70 | 0.30 |
| 201606 | TEPCO | 1166 | 26 | | | | | | | | | | 1192 | 2.00 | 0.16 |
| | Contractors | 7928 | 833 | 56 | 6 | | | | | | | | 8823 | 13.81 | 0.42 |
| | Total | 9094 | 859 | 56 | 6 | | | | | | | | 10015 | 13.81 | 0.38 |
| 201607 | TEPCO | 1138 | 12 | | | | | | | | | | 1150 | 1.92 | 0.11 |
| | Contractors | 7849 | 791 | 80 | 3 | | | | | | | | 8723 | 10.70 | 0.41 |
| | Total | 8987 | 803 | 80 | 3 | | | | | | | | 9873 | 10.70 | 0.38 |
| 201608 | TEPCO | 1125 | 41 | | | | | | | | | | 1166 | 4.39 | 0.17 |
| | Contractors | 7951 | 532 | 19 | | | | | | | | | 8502 | 7.10 | 0.28 |
| | Total | 9076 | 573 | 19 | | | | | | | | | 9668 | 7.10 | 0.27 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201609 | TEPCO | 1160 | 20 | | | | | | | | | | 1180 | 3.50 | 0.14 |
| | Contractors | 8041 | 689 | 35 | | | | | | | | | 8765 | 8.80 | 0.35 |
| | Total | 9201 | 709 | 35 | | | | | | | | | 9945 | 8.80 | 0.33 |
| 201610 | TEPCO | 1142 | 21 | | | | | | | | | | 1163 | 2.40 | 0.14 |
| | Contractors | 7693 | 875 | 48 | | | | | | | | | 8616 | 8.34 | 0.42 |
| | Total | 8835 | 896 | 48 | | | | | | | | | 9779 | 8.34 | 0.39 |
| 201611 | TEPCO | 1167 | 29 | | | | | | | | | | 1196 | 3.10 | 0.15 |
| | Contractors | 7646 | 1000 | 50 | 5 | | | | | | | | 8701 | 12.00 | 0.45 |
| | Total | 8813 | 1029 | 50 | 5 | | | | | | | | 9897 | 12.00 | 0.42 |
| 201612 | TEPCO | 1144 | 16 | 2 | | | | | | | | | 1162 | 6.24 | 0.16 |
| | Contractors | 7667 | 856 | 46 | 4 | | | | | | | | 8573 | 12.60 | 0.41 |
| | Total | 8811 | 872 | 48 | 4 | | | | | | | | 9735 | 12.60 | 0.38 |
| 201701 | TEPCO | 1105 | 24 | | | | | | | | | | 1129 | 2.40 | 0.15 |
| | Contractors | 7729 | 785 | 69 | 5 | | | | | | | | 8588 | 11.00 | 0.42 |
| | Total | 8834 | 809 | 69 | 5 | | | | | | | | 9717 | 11.00 | 0.38 |
| 201702 | TEPCO | 1127 | 49 | | | | | | | | | | 1176 | 3.40 | 0.17 |
| | Contractors | 7659 | 1111 | 121 | 6 | | | | | | | | 8897 | 13.70 | 0.53 |
| | Total | 8786 | 1160 | 121 | 6 | | | | | | | | 10073 | 13.70 | 0.48 |
| 201703 | TEPCO | 1132 | 38 | | | | | | | | | | 1170 | 3.70 | 0.18 |
| | Contractors | 7525 | 1130 | 162 | 26 | | | | | | | | 8843 | 16.30 | 0.61 |
| | Total | 8657 | 1168 | 162 | 26 | | | | | | | | 10013 | 16.30 | 0.56 |
| 201704 | TEPCO | 1027 | 26 | | | | | | | | | | 1053 | 2.74 | 0.17 |
| | Contractors | 7165 | 892 | 87 | 5 | | | | | | | | 8149 | 11.40 | 0.47 |
| | Total | 8192 | 918 | 87 | 5 | | | | | | | | 9202 | 11.40 | 0.43 |
| 201705 | TEPCO | 1023 | 12 | | | | | | | | | | 1035 | 2.40 | 0.13 |
| | Contractors | 7247 | 713 | 78 | | | | | | | | | 8038 | 8.80 | 0.39 |
| | Total | 8270 | 725 | 78 | | | | | | | | | 9073 | 8.80 | 0.36 |
| 201706 | TEPCO | 1023 | 26 | | | | | | | | | | 1049 | 3.30 | 0.16 |
| | Contractors | 7301 | 890 | 64 | 9 | | | | | | | | 8264 | 12.90 | 0.45 |
| | Total | 8324 | 916 | 64 | 9 | | | | | | | | 9313 | 12.90 | 0.42 |
| 201707 | TEPCO | 1001 | 14 | | | | | | | | | | 1015 | 3.80 | 0.13 |
| | Contractors | 7211 | 847 | 55 | 2 | | | | | | | | 8115 | 11.50 | 0.42 |
| | Total | 8212 | 861 | 55 | 2 | | | | | | | | 9130 | 11.50 | 0.39 |
| 201708 | TEPCO | 979 | 19 | | | | | | | | | | 998 | 3.20 | 0.13 |
| | Contractors | 7164 | 651 | 19 | | | | | | | | | 7834 | 7.60 | 0.32 |
| | Total | 8143 | 670 | 19 | | | | | | | | | 8832 | 7.60 | 0.30 |
| 201709 | TEPCO | 1033 | 15 | | | | | | | | | | 1048 | 3.30 | 0.11 |
| | Contractors | 7082 | 657 | 16 | | | | | | | | | 7755 | 7.50 | 0.32 |
| | Total | 8115 | 672 | 16 | | | | | | | | | 8803 | 7.50 | 0.30 |
| 201710 | TEPCO | 1035 | 29 | | | | | | | | | | 1064 | 2.50 | 0.14 |
| | Contractors | 6886 | 715 | 32 | 2 | | | | | | | | 7635 | 10.30 | 0.37 |
| | Total | 7921 | 744 | 32 | 2 | | | | | | | | 8699 | 10.30 | 0.34 |
| 201711 | TEPCO | 1027 | 23 | | | | | | | | | | 1050 | 2.40 | 0.12 |
| | Contractors | 6874 | 660 | 35 | 5 | | | | | | | | 7574 | 11.20 | 0.37 |
| | Total | 7901 | 683 | 35 | 5 | | | | | | | | 8624 | 11.20 | 0.34 |
| 201712 | TEPCO | 961 | 22 | | | | | | | | | | 983 | 2.60 | 0.14 |
| | Contractors | 6683 | 578 | 18 | 1 | | | | | | | | 7280 | 10.31 | 0.32 |
| | Total | 7644 | 600 | 18 | 1 | | | | | | | | 8263 | 10.31 | 0.30 |
| 201801 | TEPCO | 914 | 24 | | | | | | | | | | 938 | 4.14 | 0.13 |
| | Contractors | 6444 | 614 | 23 | 1 | | | | | | | | 7082 | 10.60 | 0.35 |
| | Total | 7358 | 638 | 23 | 1 | | | | | | | | 8020 | 10.60 | 0.32 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201802 | TEPCO | 941 | 50 | | | | | | | | | | 991 | 3.83 | 0.21 |
| | Contractors | 6353 | 791 | 56 | | | | | | | | | 7200 | 9.80 | 0.43 |
| | Total | 7294 | 841 | 56 | | | | | | | | | 8191 | 9.80 | 0.41 |
| 201803 | TEPCO | 935 | 46 | | | | | | | | | | 981 | 2.96 | 0.17 |
| | Contractors | 6394 | 768 | 69 | | | | | | | | | 7231 | 8.83 | 0.45 |
| | Total | 7329 | 814 | 69 | | | | | | | | | 8212 | 8.83 | 0.42 |
| 201804 | TEPCO | 1001 | 13 | | | | | | | | | | 1014 | 2.40 | 0.11 |
| | Contractors | 5840 | 509 | 26 | | | | | | | | | 6375 | 8.40 | 0.33 |
| | Total | 6841 | 522 | 26 | | | | | | | | | 7389 | 8.40 | 0.30 |
| 201805 | TEPCO | 927 | 15 | | | | | | | | | | 942 | 1.90 | 0.12 |
| | Contractors | 5820 | 481 | 18 | | | | | | | | | 6319 | 9.40 | 0.30 |
| | Total | 6747 | 496 | 18 | | | | | | | | | 7261 | 9.40 | 0.28 |
| 201806 | TEPCO | 939 | 29 | | | | | | | | | | 968 | 2.68 | 0.14 |
| | Contractors | 5795 | 488 | 4 | | | | | | | | | 6287 | 7.37 | 0.30 |
| | Total | 6734 | 517 | 4 | | | | | | | | | 7255 | 7.37 | 0.28 |
| 201807 | TEPCO | 867 | 27 | | | | | | | | | | 894 | 2.72 | 0.13 |
| | Contractors | 5665 | 597 | 21 | | | | | | | | | 6283 | 9.70 | 0.34 |
| | Total | 6532 | 624 | 21 | | | | | | | | | 7177 | 9.70 | 0.32 |
| 201808 | TEPCO | 947 | 25 | | | | | | | | | | 972 | 2.30 | 0.13 |
| | Contractors | 5784 | 453 | 9 | | | | | | | | | 6246 | 6.30 | 0.29 |
| | Total | 6731 | 478 | 9 | | | | | | | | | 7218 | 6.30 | 0.27 |
| 201809 | TEPCO | 985 | 17 | | | | | | | | | | 1002 | 1.90 | 0.11 |
| | Contractors | 5684 | 469 | 8 | | | | | | | | | 6161 | 8.00 | 0.28 |
| | Total | 6669 | 486 | 8 | | | | | | | | | 7163 | 8.00 | 0.26 |
| 201810 | TEPCO | 976 | 26 | | | | | | | | | | 1002 | 4.17 | 0.15 |
| | Contractors | 5579 | 567 | 18 | | | | | | | | | 6164 | 8.20 | 0.35 |
| | Total | 6555 | 593 | 18 | | | | | | | | | 7166 | 8.20 | 0.32 |
| 201811 | TEPCO | 1009 | 13 | | | | | | | | | | 1022 | 2.95 | 0.11 |
| | Contractors | 5556 | 626 | 42 | | | | | | | | | 6224 | 9.88 | 0.39 |
| | Total | 6565 | 639 | 42 | | | | | | | | | 7246 | 9.88 | 0.35 |
| 201812 | TEPCO | 981 | 21 | | | | | | | | | | 1002 | 4.52 | 0.13 |
| | Contractors | 5562 | 621 | 55 | 4 | | | | | | | | 6242 | 14.10 | 0.42 |
| | Total | 6543 | 642 | 55 | 4 | | | | | | | | 7244 | 14.10 | 0.38 |
| 201901 | TEPCO | 944 | 16 | | | | | | | | | | 960 | 2.32 | 0.10 |
| | Contractors | 5569 | 511 | 37 | | | | | | | | | 6117 | 7.81 | 0.36 |
| | Total | 6513 | 527 | 37 | | | | | | | | | 7077 | 7.81 | 0.32 |
| 201902 | TEPCO | 974 | 28 | 1 | | | | | | | | | 1003 | 5.38 | 0.15 |
| | Contractors | 5575 | 676 | 58 | 2 | | | | | | | | 6311 | 12.60 | 0.44 |
| | Total | 6549 | 704 | 59 | 2 | | | | | | | | 7314 | 12.60 | 0.40 |
| 201903 | TEPCO | 960 | 34 | 1 | | | | | | | | | 995 | 5.70 | 0.16 |
| | Contractors | 5532 | 613 | 32 | 1 | | | | | | | | 6178 | 11.41 | 0.39 |
| | Total | 6492 | 647 | 33 | 1 | | | | | | | | 7173 | 11.41 | 0.35 |
| 201904 | TEPCO | 920 | 24 | | | | | | | | | | 944 | 2.66 | 0.13 |
| | Contractors | 4780 | 491 | 8 | | | | | | | | | 5279 | 7.80 | 0.33 |
| | Total | 5700 | 515 | 8 | | | | | | | | | 6223 | 7.80 | 0.30 |
| 201905 | TEPCO | 967 | 20 | | | | | | | | | | 987 | 2.80 | 0.13 |
| | Contractors | 4876 | 552 | 5 | | | | | | | | | 5433 | 5.60 | 0.33 |
| | Total | 5843 | 572 | 5 | | | | | | | | | 6420 | 5.60 | 0.30 |
| 201906 | TEPCO | 1016 | 17 | 1 | | | | | | | | | 1034 | 5.20 | 0.12 |
| | Contractors | 4993 | 538 | 12 | | | | | | | | | 5543 | 7.11 | 0.35 |
| | Total | 6009 | 555 | 13 | | | | | | | | | 6577 | 7.11 | 0.31 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201907 | TEPCO | 964 | 19 | | | | | | | | | | 983 | 3.60 | 0.13 |
| | Contractors | 5048 | 547 | 10 | | | | | | | | | 5605 | 9.70 | 0.35 |
| | Total | 6012 | 566 | 10 | | | | | | | | | 6588 | 9.70 | 0.32 |
| 201908 | TEPCO | 1006 | 12 | | | | | | | | | | 1018 | 2.75 | 0.10 |
| | Contractors | 5037 | 471 | 6 | | | | | | | | | 5514 | 7.99 | 0.30 |
| | Total | 6043 | 483 | 6 | | | | | | | | | 6532 | 7.99 | 0.27 |
| 201909 | TEPCO | 942 | 12 | | | | | | | | | | 954 | 3.52 | 0.10 |
| | Contractors | 4953 | 594 | 12 | | | | | | | | | 5559 | 8.15 | 0.37 |
| | Total | 5895 | 606 | 12 | | | | | | | | | 6513 | 8.15 | 0.33 |
| 201910 | TEPCO | 935 | 22 | | | | | | | | | | 957 | 3.22 | 0.12 |
| | Contractors | 5066 | 613 | 31 | | | | | | | | | 5710 | 7.49 | 0.39 |
| | Total | 6001 | 635 | 31 | | | | | | | | | 6667 | 7.49 | 0.35 |
| 201911 | TEPCO | 1024 | 23 | | | | | | | | | | 1047 | 3.48 | 0.12 |
| | Contractors | 5255 | 595 | 13 | | | | | | | | | 5863 | 7.21 | 0.35 |
| | Total | 6279 | 618 | 13 | | | | | | | | | 6910 | 7.21 | 0.32 |
| 201912 | TEPCO | 967 | 13 | | | | | | | | | | 980 | 2.54 | 0.11 |
| | Contractors | 5212 | 604 | 33 | 5 | | | | | | | | 5854 | 12.20 | 0.40 |
| | Total | 6179 | 617 | 33 | 5 | | | | | | | | 6834 | 12.20 | 0.36 |
| 202001 | TEPCO | 982 | 10 | | | | | | | | | | 992 | 2.07 | 0.09 |
| | Contractors | 5239 | 558 | 54 | 1 | | | | | | | | 5852 | 10.01 | 0.39 |
| | Total | 6221 | 568 | 54 | 1 | | | | | | | | 6844 | 10.01 | 0.35 |
| 202002 | TEPCO | 918 | 15 | | | | | | | | | | 933 | 2.96 | 0.11 |
| | Contractors | 5208 | 740 | 61 | 10 | | | | | | | | 6019 | 11.07 | 0.49 |
| | Total | 6126 | 755 | 61 | 10 | | | | | | | | 6952 | 11.07 | 0.44 |
| 202003 | TEPCO | 900 | 17 | | | | | | | | | | 917 | 1.86 | 0.12 |
| | Contractors | 5252 | 765 | 46 | 4 | | | | | | | | 6067 | 14.30 | 0.47 |
| | Total | 6152 | 782 | 46 | 4 | | | | | | | | 6984 | 14.30 | 0.42 |
| 202004 | TEPCO | 807 | 18 | | | | | | | | | | 825 | 3.37 | 0.11 |
| | Contractors | 4737 | 591 | 28 | 1 | | | | | | | | 5357 | 10.40 | 0.39 |
| | Total | 5544 | 609 | 28 | 1 | | | | | | | | 6182 | 10.40 | 0.35 |
| 202005 | TEPCO | 773 | 9 | | | | | | | | | | 782 | 1.81 | 0.09 |
| | Contractors | 4762 | 561 | 25 | | | | | | | | | 5348 | 8.80 | 0.38 |
| | Total | 5535 | 570 | 25 | | | | | | | | | 6130 | 8.80 | 0.34 |
| 202006 | TEPCO | 929 | 18 | | | | | | | | | | 947 | 3.00 | 0.13 |
| | Contractors | 4920 | 692 | 52 | | | | | | | | | 5664 | 9.30 | 0.46 |
| | Total | 5849 | 710 | 52 | | | | | | | | | 6611 | 9.30 | 0.41 |
| 202007 | TEPCO | 997 | 15 | | | | | | | | | | 1012 | 2.90 | 0.10 |
| | Contractors | 4967 | 661 | 51 | | | | | | | | | 5679 | 8.42 | 0.42 |
| | Total | 5964 | 676 | 51 | | | | | | | | | 6691 | 8.42 | 0.38 |
| 202008 | TEPCO | 951 | 5 | | | | | | | | | | 956 | 1.44 | 0.08 |
| | Contractors | 4969 | 407 | 4 | | | | | | | | | 5380 | 5.40 | 0.26 |
| | Total | 5920 | 412 | 4 | | | | | | | | | 6336 | 5.40 | 0.24 |
| 202009 | TEPCO | 1002 | 13 | | | | | | | | | | 1015 | 2.70 | 0.10 |
| | Contractors | 5001 | 496 | 32 | 1 | | | | | | | | 5530 | 10.51 | 0.34 |
| | Total | 6003 | 509 | 32 | 1 | | | | | | | | 6545 | 10.51 | 0.30 |
| 202010 | TEPCO | 965 | 11 | 1 | | | | | | | | | 977 | 6.99 | 0.11 |
| | Contractors | 5125 | 510 | 31 | 1 | | | | | | | | 5667 | 10.50 | 0.37 |
| | Total | 6090 | 521 | 32 | 1 | | | | | | | | 6644 | 10.50 | 0.33 |
| 202011 | TEPCO | 971 | 25 | | | | | | | | | | 996 | 4.84 | 0.12 |
| | Contractors | 5054 | 579 | 48 | 2 | | | | | | | | 5683 | 11.00 | 0.42 |
| | Total | 6025 | 604 | 48 | 2 | | | | | | | | 6679 | 11.00 | 0.37 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202012 | TEPCO | 975 | 36 | | | | | | | | | | 1011 | 2.29 | 0.13 |
| | Contractors | 5242 | 485 | 26 | | | | | | | | | 5753 | 9.00 | 0.33 |
| | Total | 6217 | 521 | 26 | | | | | | | | | 6764 | 9.00 | 0.30 |
| 202101 | TEPCO | 897 | 20 | | | | | | | | | | 917 | 2.53 | 0.11 |
| | Contractors | 5258 | 517 | 8 | | | | | | | | | 5783 | 6.70 | 0.33 |
| | Total | 6155 | 537 | 8 | | | | | | | | | 6700 | 6.70 | 0.30 |
| 202102 | TEPCO | 909 | 21 | 1 | | | | | | | | | 931 | 6.10 | 0.13 |
| | Contractors | 5328 | 517 | 45 | 2 | | | | | | | | 5892 | 12.40 | 0.39 |
| | Total | 6237 | 538 | 46 | 2 | | | | | | | | 6823 | 12.40 | 0.36 |
| 202103 | TEPCO | 957 | 40 | | | | | | | | | | 997 | 3.42 | 0.16 |
| | Contractors | 5032 | 654 | 55 | | | | | | | | | 5741 | 8.90 | 0.44 |
| | Total | 5989 | 694 | 55 | | | | | | | | | 6738 | 8.90 | 0.40 |
| 202104 | TEPCO | 944 | 25 | | | | | | | | | | 969 | 2.19 | 0.10 |
| | Contractors | 4602 | 366 | 6 | | | | | | | | | 4974 | 6.40 | 0.28 |
| | Total | 5546 | 391 | 6 | | | | | | | | | 5943 | 6.40 | 0.25 |
| 202105 | TEPCO | 916 | 24 | | | | | | | | | | 940 | 2.99 | 0.10 |
| | Contractors | 4666 | 354 | 7 | | | | | | | | | 5027 | 5.79 | 0.28 |
| | Total | 5582 | 378 | 7 | | | | | | | | | 5967 | 5.79 | 0.25 |
| 202106 | TEPCO | 1034 | 23 | | | | | | | | | | 1057 | 2.65 | 0.09 |
| | Contractors | 4783 | 505 | 39 | | | | | | | | | 5327 | 7.76 | 0.38 |
| | Total | 5817 | 528 | 39 | | | | | | | | | 6384 | 7.76 | 0.33 |
| 202107 | TEPCO | 1012 | 16 | | | | | | | | | | 1028 | 3.89 | 0.10 |
| | Contractors | 4929 | 476 | 22 | | | | | | | | | 5427 | 7.81 | 0.34 |
| | Total | 5941 | 492 | 22 | | | | | | | | | 6455 | 7.81 | 0.30 |
| 202108 | TEPCO | 919 | 6 | | | | | | | | | | 925 | 1.45 | 0.06 |
| | Contractors | 4986 | 353 | 15 | | | | | | | | | 5354 | 6.93 | 0.26 |
| | Total | 5905 | 359 | 15 | | | | | | | | | 6279 | 6.93 | 0.23 |
| 202109 | TEPCO | 980 | 12 | | | | | | | | | | 992 | 2.60 | 0.07 |
| | Contractors | 4821 | 607 | 66 | 1 | | | | | | | | 5495 | 11.30 | 0.45 |
| | Total | 5801 | 619 | 66 | 1 | | | | | | | | 6487 | 11.30 | 0.39 |
| 202110 | TEPCO | 998 | 19 | | | | | | | | | | 1017 | 1.96 | 0.09 |
| | Contractors | 5070 | 472 | 40 | | | | | | | | | 5582 | 8.69 | 0.36 |
| | Total | 6068 | 491 | 40 | | | | | | | | | 6599 | 8.69 | 0.32 |
| 202111 | TEPCO | 998 | 9 | | | | | | | | | | 1007 | 2.00 | 0.09 |
| | Contractors | 5187 | 534 | 22 | | | | | | | | | 5743 | 7.70 | 0.36 |
| | Total | 6185 | 543 | 22 | | | | | | | | | 6750 | 7.70 | 0.32 |
| 202112 | TEPCO | 1001 | 34 | | | | | | | | | | 1035 | 3.50 | 0.12 |
| | Contractors | 5284 | 524 | 27 | | | | | | | | | 5835 | 8.43 | 0.36 |
| | Total | 6285 | 558 | 27 | | | | | | | | | 6870 | 8.43 | 0.32 |
| 202201 | TEPCO | 942 | 17 | | | | | | | | | | 959 | 3.31 | 0.10 |
| | Contractors | 5169 | 630 | 44 | 1 | | | | | | | | 5844 | 10.28 | 0.41 |
| | Total | 6111 | 647 | 44 | 1 | | | | | | | | 6803 | 10.28 | 0.37 |
| 202202 | TEPCO | 877 | 20 | | | | | | | | | | 897 | 4.43 | 0.11 |
| | Contractors | 5106 | 708 | 43 | 8 | | | | | | | | 5865 | 12.70 | 0.46 |
| | Total | 5983 | 728 | 43 | 8 | | | | | | | | 6762 | 12.70 | 0.41 |
| 202203 | TEPCO | 969 | 32 | | | | | | | | | | 1001 | 3.77 | 0.13 |
| | Contractors | 5150 | 670 | 37 | 3 | | | | | | | | 5860 | 11.20 | 0.43 |
| | Total | 6119 | 702 | 37 | 3 | | | | | | | | 6861 | 11.20 | 0.39 |
| 202204 | TEPCO | 988 | 35 | | | | | | | | | | 1023 | 4.53 | 0.14 |
| | Contractors | 5198 | 398 | 4 | | | | | | | | | 5600 | 5.90 | 0.28 |
| | Total | 6186 | 433 | 4 | | | | | | | | | 6623 | 5.90 | 0.26 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202205 | TEPCO | 980 | 10 | | | | | | | | | | 990 | 2.78 | 0.08 |
| | Contractors | 5347 | 340 | | | | | | | | | | 5687 | 4.90 | 0.24 |
| | Total | 6327 | 350 | | | | | | | | | | 6677 | 4.90 | 0.22 |
| 202206 | TEPCO | 1045 | 29 | | | | | | | | | | 1074 | 2.27 | 0.10 |
| | Contractors | 5431 | 612 | 14 | | | | | | | | | 6057 | 7.40 | 0.36 |
| | Total | 6476 | 641 | 14 | | | | | | | | | 7131 | 7.40 | 0.33 |
| 202207 | TEPCO | 992 | 15 | | | | | | | | | | 1007 | 4.37 | 0.09 |
| | Contractors | 5593 | 495 | 18 | | | | | | | | | 6106 | 10.00 | 0.32 |
| | Total | 6585 | 510 | 18 | | | | | | | | | 7113 | 10.00 | 0.29 |
| 202208 | TEPCO | 1013 | 11 | | | | | | | | | | 1024 | 1.49 | 0.07 |
| | Contractors | 5677 | 354 | 8 | | | | | | | | | 6039 | 6.35 | 0.23 |
| | Total | 6690 | 365 | 8 | | | | | | | | | 7063 | 6.35 | 0.21 |
| 202209 | TEPCO | 1081 | 9 | | | | | | | | | | 1090 | 4.60 | 0.08 |
| | Contractors | 5763 | 528 | 30 | | | | | | | | | 6321 | 7.10 | 0.34 |
| | Total | 6844 | 537 | 30 | | | | | | | | | 7411 | 7.10 | 0.30 |
| 202210 | TEPCO | 1020 | 22 | | | | | | | | | | 1042 | 3.79 | 0.10 |
| | Contractors | 5932 | 514 | 35 | | | | | | | | | 6481 | 9.39 | 0.31 |
| | Total | 6952 | 536 | 35 | | | | | | | | | 7523 | 9.39 | 0.28 |
| 202211 | TEPCO | 1040 | 14 | | | | | | | | | | 1054 | 2.44 | 0.09 |
| | Contractors | 6091 | 585 | 34 | 1 | | | | | | | | 6711 | 11.76 | 0.35 |
| | Total | 7131 | 599 | 34 | 1 | | | | | | | | 7765 | 11.76 | 0.32 |
| 202212 | TEPCO | 1031 | 16 | | | | | | | | | | 1047 | 2.03 | 0.09 |
| | Contractors | 6169 | 501 | 32 | | | | | | | | | 6702 | 9.91 | 0.30 |
| | Total | 7200 | 517 | 32 | | | | | | | | | 7749 | 9.91 | 0.27 |
| 202301 | TEPCO | 1025 | 10 | | | | | | | | | | 1035 | 2.80 | 0.07 |
| | Contractors | 6143 | 431 | 13 | | | | | | | | | 6587 | 9.30 | 0.26 |
| | Total | 7168 | 441 | 13 | | | | | | | | | 7622 | 9.30 | 0.23 |
| 202302 | TEPCO | 1013 | 18 | | | | | | | | | | 1031 | 2.45 | 0.09 |
| | Contractors | 6044 | 578 | 29 | 1 | | | | | | | | 6652 | 10.71 | 0.32 |
| | Total | 7057 | 596 | 29 | 1 | | | | | | | | 7683 | 10.71 | 0.29 |
| 202303 | TEPCO | 1062 | 19 | | | | | | | | | | 1081 | 3.44 | 0.08 |
| | Contractors | 6139 | 638 | 39 | 4 | | | | | | | | 6820 | 13.42 | 0.35 |
| | Total | 7201 | 657 | 39 | 4 | | | | | | | | 7901 | 13.42 | 0.32 |
| 202304 | TEPCO | 1034 | 18 | | | | | | | | | | 1052 | 3.1 | 0.09 |
| | Contractors | 5797 | 613 | 76 | 1 | | | | | | | | 6487 | 10.1 | 0.41 |
| | Total | 6831 | 631 | 76 | 1 | | | | | | | | 7539 | 10.1 | 0.36 |
| 202305 | TEPCO | 1029 | 8 | | | | | | | | | | 1037 | 3.0 | 0.05 |
| | Contractors | 5975 | 446 | 35 | 1 | | | | | | | | 6457 | 10.1 | 0.29 |
| | Total | 7004 | 454 | 35 | 1 | | | | | | | | 7494 | 10.1 | 0.25 |
| 202306 | TEPCO | 1092 | 5 | | | | | | | | | | 1097 | 2.0 | 0.06 |
| | Contractors | 5888 | 644 | 44 | | | | | | | | | 6576 | 9.0 | 0.37 |
| | Total | 6980 | 649 | 44 | | | | | | | | | 7673 | 9.0 | 0.32 |
| 202307 | TEPCO | 996 | 2 | | | | | | | | | | 998 | 2.3 | 0.06 |
| | Contractors | 6020 | 580 | 21 | | | | | | | | | 6621 | 7.6 | 0.31 |
| | Total | 7016 | 582 | 21 | | | | | | | | | 7619 | 7.6 | 0.28 |
| 202308 | TEPCO | 1029 | 4 | | | | | | | | | | 1033 | 2.6 | 0.05 |
| | Contractors | 6045 | 326 | 12 | | | | | | | | | 6383 | 7.6 | 0.21 |
| | Total | 7074 | 330 | 12 | | | | | | | | | 7416 | 7.6 | 0.19 |
| 202309 | TEPCO | 1045 | 11 | | | | | | | | | | 1056 | 3.6 | 0.07 |
| | Contractors | 6084 | 520 | 39 | 1 | | | | | | | | 6644 | 10.3 | 0.32 |
| | Total | 7129 | 531 | 39 | 1 | | | | | | | | 7700 | 10.3 | 0.29 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202310 | TEPCO | 1057 | 13 | | | | | | | | | | 1070 | 3.9 | 0.07 |
| | Contractors | 6127 | 612 | 45 | 1 | | | | | | | | 6785 | 10.1 | 0.36 |
| | Total | 7184 | 625 | 45 | 1 | | | | | | | | 7855 | 10.1 | 0.32 |
| 202311 | TEPCO | 1059 | 9 | | | | | | | | | | 1068 | 2.9 | 0.07 |
| | Contractors | 6326 | 499 | 61 | 1 | | | | | | | | 6887 | 11.6 | 0.34 |
| | Total | 7385 | 508 | 61 | 1 | | | | | | | | 7955 | 11.6 | 0.30 |
| 202312 | TEPCO | 1037 | 17 | | | | | | | | | | 1054 | 3.7 | 0.08 |
| | Contractors | 6378 | 522 | 61 | 2 | | | | | | | | 6963 | 10.2 | 0.33 |
| | Total | 7415 | 539 | 61 | 2 | | | | | | | | 8017 | 10.2 | 0.29 |
| 202401 | TEPCO | 984 | 9 | | | | | | | | | | 993 | 1.9 | 0.06 |
| | Contractors | 6457 | 380 | 18 | | | | | | | | | 6855 | 8.0 | 0.24 |
| | Total | 7441 | 389 | 18 | | | | | | | | | 7848 | 8.0 | 0.22 |
| 202402 | TEPCO | 1041 | 3 | | | | | | | | | | 1044 | 1.9 | 0.06 |
| | Contractors | 6460 | 468 | 35 | 4 | | | | | | | | 6967 | 10.8 | 0.30 |
| | Total | 7501 | 471 | 35 | 4 | | | | | | | | 8011 | 10.8 | 0.26 |
| 202403 | TEPCO | 1005 | 12 | | | | | | | | | | 1017 | 3.9 | 0.08 |
| | Contractors | 6422 | 440 | 37 | | | | | | | | | 6899 | 8.6 | 0.28 |
| | Total | 7427 | 452 | 37 | | | | | | | | | 7916 | 8.6 | 0.26 |
| 202404 | TEPCO | 1003 | 11 | | | | | | | | | | 1014 | 3.0 | 0.07 |
| | Contractors | 6031 | 370 | 24 | | | | | | | | | 6425 | 8.8 | 0.25 |
| | Total | 7034 | 381 | 24 | | | | | | | | | 7439 | 8.8 | 0.22 |
| 202405 | TEPCO | 971 | 8 | | | | | | | | | | 979 | 4.2 | 0.08 |
| | Contractors | 6162 | 354 | 17 | | | | | | | | | 6533 | 7.2 | 0.22 |
| | Total | 7133 | 362 | 17 | | | | | | | | | 7512 | 7.2 | 0.20 |
| 202406 | TEPCO | 1024 | 18 | | | | | | | | | | 1042 | 3.8 | 0.08 |
| | Contractors | 6201 | 529 | 28 | | | | | | | | | 6758 | 7.7 | 0.31 |
| | Total | 7225 | 547 | 28 | | | | | | | | | 7800 | 7.7 | 0.28 |
| 202407 | TEPCO | 923 | 16 | | | | | | | | | | 939 | 4.2 | 0.08 |
| | Contractors | 6308 | 424 | 42 | | | | | | | | | 6774 | 9.4 | 0.29 |
| | Total | 7231 | 440 | 42 | | | | | | | | | 7713 | 9.4 | 0.26 |
| 202408 | TEPCO | 965 | 13 | | | | | | | | | | 978 | 2.7 | 0.07 |
| | Contractors | 6084 | 347 | 25 | 2 | | | | | | | | 6458 | 11.1 | 0.23 |
| | Total | 7049 | 360 | 25 | 2 | | | | | | | | 7436 | 11.1 | 0.21 |
| 202409 | TEPCO | 982 | 10 | | | | | | | | | | 992 | 1.9 | 0.07 |
| | Contractors | 6147 | 378 | 10 | | | | | | | | | 6535 | 7.9 | 0.22 |
| | Total | 7129 | 388 | 10 | | | | | | | | | 7527 | 7.9 | 0.20 |
| 202410 | TEPCO | 1022 | 16 | | | | | | | | | | 1038 | 4.1 | 0.09 |
| | Contractors | 6289 | 554 | 62 | | | | | | | | | 6905 | 9.9 | 0.34 |
| | Total | 7311 | 570 | 62 | | | | | | | | | 7943 | 9.9 | 0.31 |
| 202411 | TEPCO | 1034 | 17 | 1 | | | | | | | | | 1052 | 5.1 | 0.09 |
| | Contractors | 6318 | 501 | 81 | 3 | | | | | | | | 6903 | 10.9 | 0.35 |
| | Total | 7352 | 518 | 82 | 3 | | | | | | | | 7955 | 10.9 | 0.31 |
| 202412 | TEPCO | 997 | 19 | | | | | | | | | | 1016 | 2.2 | 0.08 |
| | Contractors | 6489 | 412 | 58 | | | | | | | | | 6959 | 9.3 | 0.28 |
| | Total | 7486 | 431 | 58 | | | | | | | | | 7975 | 9.3 | 0.25 |
| 202501 | TEPCO | 985 | 13 | | | | | | | | | | 998 | 4.5 | 0.08 |
| | Contractors | 6391 | 481 | 34 | | | | | | | | | 6906 | 10.0 | 0.28 |
| | Total | 7376 | 494 | 34 | | | | | | | | | 7904 | 10.0 | 0.25 |
| 202502 | TEPCO | 982 | 6 | | | | | | | | | | 988 | 2.7 | 0.06 |
| | Contractors | 6347 | 604 | 91 | 1 | | | | | | | | 7043 | 10.3 | 0.38 |
| | Total | 7329 | 610 | 91 | 1 | | | | | | | | 8031 | 10.3 | 0.34 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of Workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202503 | TEPCO | 985 | 17 | | | | | | | | | | 1002 | 3.6 | 0.08 |
| | Contractors | 6174 | 602 | 76 | 2 | | | | | | | | 6854 | 10.8 | 0.36 |
| | Total | 7159 | 619 | 76 | 2 | | | | | | | | 7856 | 10.8 | 0.33 |
| 202504 | TEPCO | 997 | 13 | | | | | | | | | | 1010 | 1.7 | 0.06 |
| | Contractors | 5978 | 517 | 18 | | | | | | | | | 6513 | 9.9 | 0.28 |
| | Total | 6975 | 530 | 18 | | | | | | | | | 7523 | 9.9 | 0.25 |
| 202505 | TEPCO | 988 | 5 | | | | | | | | | | 993 | 2.6 | 0.05 |
| | Contractors | 6155 | 398 | 24 | | | | | | | | | 6577 | 7.4 | 0.24 |
| | Total | 7143 | 403 | 24 | | | | | | | | | 7570 | 7.4 | 0.22 |
| 202506 | TEPCO | 1041 | 2 | | | | | | | | | | 1043 | 1.16 | 0.05 |
| | Contractors | 6373 | 395 | 9 | | | | | | | | | 6777 | 7.51 | 0.21 |
| | Total | 7414 | 397 | 9 | | | | | | | | | 7820 | 7.51 | 0.19 |

Note)

•The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

Table 14. Monthly Internal Exposure Dose Data

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201103 | TEPCO | 574 | 207 | 275 | 399 | 189 | 27 | 11 | 7 | 1 | 1 | 5 | 1696 | 590.00 | 12.01 |
| | Contractors | 1276 | 342 | 291 | 253 | 103 | 11 | 10 | | | | | 2286 | 98.53 | 5.08 |
| | Total | 1850 | 549 | 566 | 652 | 292 | 38 | 21 | 7 | 1 | 1 | 5 | 3982 | 590.00 | 8.03 |
| 201104 | TEPCO | 1638 | 15 | 2 | 2 | | | | | | | | 1657 | 18.81 | 0.05 |
| | Contractors | 3959 | 157 | 50 | 16 | #5 | | | | | | | 4187 | 38.40 | 0.33 |
| | Total | 5597 | 172 | 52 | 18 | 5 | | | | | | | 5844 | 38.40 | 0.25 |
| 201105 | TEPCO | 1473 | 3 | 1 | | | | | | | | | 1477 | 7.89 | 0.01 |
| | Contractors | 5635 | 110 | 44 | 16 | 4 | | | | | | | 5809 | 32.80 | 0.19 |
| | Total | 7108 | 113 | 45 | 16 | 4 | | | | | | | 7286 | 32.80 | 0.15 |
| 201106 | TEPCO | 1345 | 5 | 1 | | | | | | | | | 1351 | 6.94 | 0.02 |
| | Contractors | 6118 | #85 | #30 | #15 | | #1 | #1 | | | | | 6250 | 89.20 | 0.16 |
| | Total | 7463 | 90 | 31 | 15 | | 1 | 1 | | | | | 7601 | 89.20 | 0.14 |
| 201107 | TEPCO | 1348 | 1 | 2 | | | | | | | | | 1351 | 6.33 | 0.01 |
| | Contractors | 6364 | # 12 | #4 | # 5 | # 7 | # 3 | | | | | | 6395 | 59.35 | 0.10 |
| | Total | 7712 | 13 | 6 | 5 | 7 | 3 | | | | | | 7746 | 59.35 | 0.08 |
| 201108 | TEPCO | 1285 | 1 | | | | | | | | | | 1286 | 2.66 | 0.00 |
| | Contractors | 6201 | # 5 | | | | # 2 | | | | | | 6208 | 66.50 | 0.03 |
| | Total | 7486 | 6 | | | | 2 | | | | | | 7494 | 66.50 | 0.02 |
| 201109 | TEPCO | 1207 | | | | | | | | | | | 1207 | 0.00 | 0.00 |
| | Contractors | 5980 | # 1 | #1 | | #1 | | | | | | | 5983 | 23.70 | 0.01 |
| | Total | 7187 | 1 | 1 | | 1 | | | | | | | 7190 | 23.70 | 0.01 |
| 201110 | TEPCO | 1179 | | | | | | | | | | | 1179 | 0.00 | 0.00 |
| | Contractors | 5616 | # 1 | #1 | | | | | | | | | 5618 | 6.90 | 0.00 |
| | Total | 6795 | 1 | 1 | | | | | | | | | 6797 | 6.90 | 0.00 |
| 201111 | TEPCO | 1180 | | | | | | | | | | | 1180 | 0.00 | 0.00 |
| | Contractors | 5578 | | | | | | | | | | | 5578 | 1.99 | 0.00 |
| | Total | 6758 | | | | | | | | | | | 6758 | 1.99 | 0.00 |
| 201112 | TEPCO | 1192 | | | | | | | | | | | 1192 | 0.00 | 0.00 |
| | Contractors | 5407 | | | | | | | | | | | 5407 | 0.50 | 0.00 |
| | Total | 6599 | | | | | | | | | | | 6599 | 0.50 | 0.00 |
| 201201 | TEPCO | 1095 | | | | | | | | | | | 1095 | 0.00 | 0.00 |
| | Contractors | 4945 | # 1 | | | | | | | | | | 4946 | 2.47 | 0.00 |
| | Total | 6040 | 1 | | | | | | | | | | 6041 | 2.47 | 0.00 |
| 201202 | TEPCO | 1109 | | | | | | | | | | | 1109 | 0.00 | 0.00 |
| | Contractors | 4847 | | | | | | | | | | | 4847 | 0.85 | 0.00 |
| | Total | 5956 | | | | | | | | | | | 5956 | 0.85 | 0.00 |
| 201203 | TEPCO | 1119 | | | | | | | | | | | 1119 | 0.00 | 0.00 |
| | Contractors | 4755 | | | | | | | | | | | 4755 | 0.20 | 0.00 |
| | Total | 5874 | | | | | | | | | | | 5874 | 0.20 | 0.00 |
| 201204 | TEPCO | 1071 | | | | | | | | | | | 1071 | 0.00 | 0.00 |
| | Contractors | 4369 | | | | | | | | | | | 4369 | 0.00 | 0.00 |
| | Total | 5440 | | | | | | | | | | | 5440 | 0.00 | 0.00 |
| 201205 | TEPCO | 1042 | | | | | | | | | | | 1042 | 0.00 | 0.00 |
| | Contractors | 4598 | | | | | | | | | | | 4598 | 0.10 | 0.00 |
| | Total | 5640 | | | | | | | | | | | 5640 | 0.10 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201206 | TEPCO | 1014 | | | | | | | | | | | 1014 | 0.00 | 0.00 |
| | Contractors | 4987 | | | | | | | | | | | 4987 | 0.00 | 0.00 |
| | Total | 6001 | | | | | | | | | | | 6001 | 0.00 | 0.00 |
| 201207 | TEPCO | 1013 | | | | | | | | | | | 1013 | 0.00 | 0.00 |
| | Contractors | 4946 | | | | | | | | | | | 4946 | 0.00 | 0.00 |
| | Total | 5959 | | | | | | | | | | | 5959 | 0.00 | 0.00 |
| 201208 | TEPCO | 986 | | | | | | | | | | | 986 | 0.00 | 0.00 |
| | Contractors | 4764 | | | | | | | | | | | 4764 | 0.00 | 0.00 |
| | Total | 5750 | | | | | | | | | | | 5750 | 0.00 | 0.00 |
| 201209 | TEPCO | 982 | | | | | | | | | | | 982 | 0.00 | 0.00 |
| | Contractors | 4739 | | | | | | | | | | | 4739 | 0.00 | 0.00 |
| | Total | 5721 | | | | | | | | | | | 5721 | 0.00 | 0.00 |
| 201210 | TEPCO | 978 | | | | | | | | | | | 978 | 0.00 | 0.00 |
| | Contractors | 4799 | | | | | | | | | | | 4799 | 0.00 | 0.00 |
| | Total | 5777 | | | | | | | | | | | 5777 | 0.00 | 0.00 |
| 201211 | TEPCO | 968 | | | | | | | | | | | 968 | 0.00 | 0.00 |
| | Contractors | 4700 | | | | | | | | | | | 4700 | 0.00 | 0.00 |
| | Total | 5668 | | | | | | | | | | | 5668 | 0.00 | 0.00 |
| 201212 | TEPCO | 1005 | | | | | | | | | | | 1005 | 0.00 | 0.00 |
| | Contractors | 5042 | | | | | | | | | | | 5042 | 0.00 | 0.00 |
| | Total | 6047 | | | | | | | | | | | 6047 | 0.00 | 0.00 |
| 201301 | TEPCO | 969 | | | | | | | | | | | 969 | 0.00 | 0.00 |
| | Contractors | 5200 | | | | | | | | | | | 5200 | 0.00 | 0.00 |
| | Total | 6169 | | | | | | | | | | | 6169 | 0.00 | 0.00 |
| 201302 | TEPCO | 977 | | | | | | | | | | | 977 | 0.00 | 0.00 |
| | Contractors | 5630 | | | | | | | | | | | 5630 | 0.00 | 0.00 |
| | Total | 6607 | | | | | | | | | | | 6607 | 0.00 | 0.00 |
| 201303 | TEPCO | 997 | | | | | | | | | | | 997 | 0.00 | 0.00 |
| | Contractors | 5984 | | | | | | | | | | | 5984 | 0.00 | 0.00 |
| | Total | 6981 | | | | | | | | | | | 6981 | 0.00 | 0.00 |
| 201304 | TEPCO | 1060 | | | | | | | | | | | 1060 | 0.00 | 0.00 |
| | Contractors | 5310 | | | | | | | | | | | 5310 | 0.00 | 0.00 |
| | Total | 6370 | | | | | | | | | | | 6370 | 0.00 | 0.00 |
| 201305 | TEPCO | 1000 | | | | | | | | | | | 1000 | 0.00 | 0.00 |
| | Contractors | 5158 | | | | | | | | | | | 5158 | 0.00 | 0.00 |
| | Total | 6158 | | | | | | | | | | | 6158 | 0.00 | 0.00 |
| 201306 | TEPCO | 1024 | | | | | | | | | | | 1024 | 0.00 | 0.00 |
| | Contractors | 5005 | | | | | | | | | | | 5005 | 0.00 | 0.00 |
| | Total | 6029 | | | | | | | | | | | 6029 | 0.00 | 0.00 |
| 201307 | TEPCO | 988 | | | | | | | | | | | 988 | 0.00 | 0.00 |
| | Contractors | 4996 | | | | | | | | | | | 4996 | 0.00 | 0.00 |
| | Total | 5984 | | | | | | | | | | | 5984 | 0.00 | 0.00 |
| 201308 | TEPCO | 956 | | | | | | | | | | | 956 | 0.00 | 0.00 |
| | Contractors | 5058 | | | | | | | | | | | 5058 | 0.00 | 0.00 |
| | Total | 6014 | | | | | | | | | | | 6014 | 0.00 | 0.00 |
| 201309 | TEPCO | 1038 | | | | | | | | | | | 1038 | 0.00 | 0.00 |
| | Contractors | 5254 | | | | | | | | | | | 5254 | 0.00 | 0.00 |
| | Total | 6292 | | | | | | | | | | | 6292 | 0.00 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201310 | TEPCO | 1047 | | | | | | | | | | | 1047 | 0.00 | 0.00 |
| | Contractors | 5406 | | | | | | | | | | | 5406 | 0.00 | 0.00 |
| | Total | 6453 | | | | | | | | | | | 6453 | 0.00 | 0.00 |
| 201311 | TEPCO | 1079 | | | | | | | | | | | 1079 | 0.00 | 0.00 |
| | Contractors | 5568 | | | | | | | | | | | 5568 | 0.00 | 0.00 |
| | Total | 6647 | | | | | | | | | | | 6647 | 0.00 | 0.00 |
| 201312 | TEPCO | 1086 | | | | | | | | | | | 1086 | 0.00 | 0.00 |
| | Contractors | 5701 | | | | | | | | | | | 5701 | 0.00 | 0.00 |
| | Total | 6787 | | | | | | | | | | | 6787 | 0.00 | 0.00 |
| 201401 | TEPCO | 1081 | | | | | | | | | | | 1081 | 0.00 | 0.00 |
| | Contractors | 5891 | | | | | | | | | | | 5891 | 0.00 | 0.00 |
| | Total | 6972 | | | | | | | | | | | 6972 | 0.00 | 0.00 |
| 201402 | TEPCO | 1078 | | | | | | | | | | | 1078 | 0.00 | 0.00 |
| | Contractors | 6420 | | | | | | | | | | | 6420 | 0.00 | 0.00 |
| | Total | 7498 | | | | | | | | | | | 7498 | 0.00 | 0.00 |
| 201403 | TEPCO | 1097 | | | | | | | | | | | 1097 | 0.00 | 0.00 |
| | Contractors | 7057 | | | | | | | | | | | 7057 | 0.00 | 0.00 |
| | Total | 8154 | | | | | | | | | | | 8154 | 0.00 | 0.00 |
| 201404 | TEPCO | 1094 | | | | | | | | | | | 1094 | 0.00 | 0.00 |
| | Contractors | 7445 | | | | | | | | | | | 7445 | 0.00 | 0.00 |
| | Total | 8539 | | | | | | | | | | | 8539 | 0.00 | 0.00 |
| 201405 | TEPCO | 1119 | | | | | | | | | | | 1119 | 0.00 | 0.00 |
| | Contractors | 8025 | | | | | | | | | | | 8025 | 0.00 | 0.00 |
| | Total | 9144 | | | | | | | | | | | 9144 | 0.00 | 0.00 |
| 201406 | TEPCO | 1123 | | | | | | | | | | | 1123 | 0.00 | 0.00 |
| | Contractors | 8918 | | | | | | | | | | | 8918 | 0.00 | 0.00 |
| | Total | 10041 | | | | | | | | | | | 10041 | 0.00 | 0.00 |
| 201407 | TEPCO | 1132 | | | | | | | | | | | 1132 | 0.00 | 0.00 |
| | Contractors | 9327 | | | | | | | | | | | 9327 | 0.00 | 0.00 |
| | Total | 10459 | | | | | | | | | | | 10459 | 0.00 | 0.00 |
| 201408 | TEPCO | 1101 | | | | | | | | | | | 1101 | 0.00 | 0.00 |
| | Contractors | 9379 | | | | | | | | | | | 9379 | 0.00 | 0.00 |
| | Total | 10480 | | | | | | | | | | | 10480 | 0.00 | 0.00 |
| 201409 | TEPCO | 1162 | | | | | | | | | | | 1162 | 0.00 | 0.00 |
| | Contractors | 9970 | | | | | | | | | | | 9970 | 0.00 | 0.00 |
| | Total | 11132 | | | | | | | | | | | 11132 | 0.00 | 0.00 |
| 201410 | TEPCO | 1174 | | | | | | | | | | | 1174 | 0.00 | 0.00 |
| | Contractors | 9969 | | | | | | | | | | | 9969 | 0.00 | 0.00 |
| | Total | 11143 | | | | | | | | | | | 11143 | 0.00 | 0.00 |
| 201411 | TEPCO | 1186 | | | | | | | | | | | 1186 | 0.00 | 0.00 |
| | Contractors | 10130 | | | | | | | | | | | 10130 | 0.00 | 0.00 |
| | Total | 11316 | | | | | | | | | | | 11316 | 0.00 | 0.00 |
| 201412 | TEPCO | 1159 | | | | | | | | | | | 1159 | 0.00 | 0.00 |
| | Contractors | 10501 | | | | | | | | | | | 10501 | 0.00 | 0.00 |
| | Total | 11660 | | | | | | | | | | | 11660 | 0.00 | 0.00 |
| 201501 | TEPCO | 1148 | | | | | | | | | | | 1148 | 0.00 | 0.00 |
| | Contractors | 10084 | | | | | | | | | | | 10084 | 0.00 | 0.00 |
| | Total | 11232 | | | | | | | | | | | 11232 | 0.00 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201502 | TEPCO | 1176 | | | | | | | | | | | 1176 | 0.00 | 0.00 |
| | Contractors | 11033 | | | | | | | | | | | 11033 | 0.00 | 0.00 |
| | Total | 12209 | | | | | | | | | | | 12209 | 0.00 | 0.00 |
| 201503 | TEPCO | 1142 | | | | | | | | | | | 1142 | 0.00 | 0.00 |
| | Contractors | 11173 | | | | | | | | | | | 11173 | 0.00 | 0.00 |
| | Total | 12315 | | | | | | | | | | | 12315 | 0.00 | 0.00 |
| 201504 | TEPCO | 1166 | | | | | | | | | | | 1166 | 0.00 | 0.00 |
| | Contractors | 10375 | | | | | | | | | | | 10375 | 0.00 | 0.00 |
| | Total | 11541 | | | | | | | | | | | 11541 | 0.00 | 0.00 |
| 201505 | TEPCO | 1134 | | | | | | | | | | | 1134 | 0.00 | 0.00 |
| | Contractors | 9948 | | | | | | | | | | | 9948 | 0.00 | 0.00 |
| | Total | 11082 | | | | | | | | | | | 11082 | 0.00 | 0.00 |
| 201506 | TEPCO | 1192 | | | | | | | | | | | 1192 | 0.00 | 0.00 |
| | Contractors | 10101 | | | | | | | | | | | 10101 | 0.00 | 0.00 |
| | Total | 11293 | | | | | | | | | | | 11293 | 0.00 | 0.00 |
| 201507 | TEPCO | 1173 | | | | | | | | | | | 1173 | 0.00 | 0.00 |
| | Contractors | 9927 | | | | | | | | | | | 9927 | 0.00 | 0.00 |
| | Total | 11100 | | | | | | | | | | | 11100 | 0.00 | 0.00 |
| 201508 | TEPCO | 1136 | | | | | | | | | | | 1136 | 0.00 | 0.00 |
| | Contractors | 9446 | | | | | | | | | | | 9446 | 0.00 | 0.00 |
| | Total | 10582 | | | | | | | | | | | 10582 | 0.00 | 0.00 |
| 201509 | TEPCO | 1196 | | | | | | | | | | | 1196 | 0.00 | 0.00 |
| | Contractors | 9780 | | | | | | | | | | | 9780 | 0.00 | 0.00 |
| | Total | 10976 | | | | | | | | | | | 10976 | 0.00 | 0.00 |
| 201510 | TEPCO | 1182 | | | | | | | | | | | 1182 | 0.00 | 0.00 |
| | Contractors | 9717 | | | | | | | | | | | 9717 | 0.00 | 0.00 |
| | Total | 10899 | | | | | | | | | | | 10899 | 0.00 | 0.00 |
| 201511 | TEPCO | 1167 | | | | | | | | | | | 1167 | 0.00 | 0.00 |
| | Contractors | 9488 | | | | | | | | | | | 9488 | 0.00 | 0.00 |
| | Total | 10655 | | | | | | | | | | | 10655 | 0.00 | 0.00 |
| 201512 | TEPCO | 1169 | | | | | | | | | | | 1169 | 0.00 | 0.00 |
| | Contractors | 9439 | | | | | | | | | | | 9439 | 0.00 | 0.00 |
| | Total | 10608 | | | | | | | | | | | 10608 | 0.00 | 0.00 |
| 201601 | TEPCO | 1146 | | | | | | | | | | | 1146 | 0.00 | 0.00 |
| | Contractors | 9328 | | | | | | | | | | | 9328 | 0.00 | 0.00 |
| | Total | 10474 | | | | | | | | | | | 10474 | 0.00 | 0.00 |
| 201602 | TEPCO | 1177 | | | | | | | | | | | 1177 | 0.00 | 0.00 |
| | Contractors | 9447 | | | | | | | | | | | 9447 | 0.00 | 0.00 |
| | Total | 10624 | | | | | | | | | | | 10624 | 0.00 | 0.00 |
| 201603 | TEPCO | 1169 | | | | | | | | | | | 1169 | 0.00 | 0.00 |
| | Contractors | 9454 | | | | | | | | | | | 9454 | 0.00 | 0.00 |
| | Total | 10623 | | | | | | | | | | | 10623 | 0.00 | 0.00 |
| 201604 | TEPCO | 1113 | | | | | | | | | | | 1113 | 0.00 | 0.00 |
| | Contractors | 8764 | | | | | | | | | | | 8764 | 0.00 | 0.00 |
| | Total | 9877 | | | | | | | | | | | 9877 | 0.00 | 0.00 |
| 201605 | TEPCO | 1137 | | | | | | | | | | | 1137 | 0.00 | 0.00 |
| | Contractors | 8408 | | | | | | | | | | | 8408 | 0.00 | 0.00 |
| | Total | 9545 | | | | | | | | | | | 9545 | 0.00 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201606 | TEPCO | 1192 | | | | | | | | | | | 1192 | 0.00 | 0.00 |
| | Contractors | 8823 | | | | | | | | | | | 8823 | 0.00 | 0.00 |
| | Total | 10015 | | | | | | | | | | | 10015 | 0.00 | 0.00 |
| 201607 | TEPCO | 1150 | | | | | | | | | | | 1150 | 0.00 | 0.00 |
| | Contractors | 8723 | | | | | | | | | | | 8723 | 0.00 | 0.00 |
| | Total | 9873 | | | | | | | | | | | 9873 | 0.00 | 0.00 |
| 201608 | TEPCO | 1166 | | | | | | | | | | | 1166 | 0.00 | 0.00 |
| | Contractors | 8502 | | | | | | | | | | | 8502 | 0.00 | 0.00 |
| | Total | 9668 | | | | | | | | | | | 9668 | 0.00 | 0.00 |
| 201609 | TEPCO | 1180 | | | | | | | | | | | 1180 | 0.00 | 0.00 |
| | Contractors | 8765 | | | | | | | | | | | 8765 | 0.00 | 0.00 |
| | Total | 9945 | | | | | | | | | | | 9945 | 0.00 | 0.00 |
| 201610 | TEPCO | 1163 | | | | | | | | | | | 1163 | 0.00 | 0.00 |
| | Contractors | 8616 | | | | | | | | | | | 8616 | 0.00 | 0.00 |
| | Total | 9779 | | | | | | | | | | | 9779 | 0.00 | 0.00 |
| 201611 | TEPCO | 1196 | | | | | | | | | | | 1196 | 0.00 | 0.00 |
| | Contractors | 8701 | | | | | | | | | | | 8701 | 0.00 | 0.00 |
| | Total | 9897 | | | | | | | | | | | 9897 | 0.00 | 0.00 |
| 201612 | TEPCO | 1162 | | | | | | | | | | | 1162 | 0.00 | 0.00 |
| | Contractors | 8573 | | | | | | | | | | | 8573 | 0.00 | 0.00 |
| | Total | 9735 | | | | | | | | | | | 9735 | 0.00 | 0.00 |
| 201701 | TEPCO | 1129 | | | | | | | | | | | 1129 | 0.00 | 0.00 |
| | Contractors | 8588 | | | | | | | | | | | 8588 | 0.00 | 0.00 |
| | Total | 9717 | | | | | | | | | | | 9717 | 0.00 | 0.00 |
| 201702 | TEPCO | 1176 | | | | | | | | | | | 1176 | 0.00 | 0.00 |
| | Contractors | 8897 | | | | | | | | | | | 8897 | 0.00 | 0.00 |
| | Total | 10073 | | | | | | | | | | | 10073 | 0.00 | 0.00 |
| 201703 | TEPCO | 1170 | | | | | | | | | | | 1170 | 0.00 | 0.00 |
| | Contractors | 8843 | | | | | | | | | | | 8843 | 0.00 | 0.00 |
| | Total | 10013 | | | | | | | | | | | 10013 | 0.00 | 0.00 |
| 201704 | TEPCO | 1053 | | | | | | | | | | | 1053 | 0.00 | 0.00 |
| | Contractors | 8149 | | | | | | | | | | | 8149 | 0.00 | 0.00 |
| | Total | 9202 | | | | | | | | | | | 9202 | 0.00 | 0.00 |
| 201705 | TEPCO | 1035 | | | | | | | | | | | 1035 | 0.00 | 0.00 |
| | Contractors | 8038 | | | | | | | | | | | 8038 | 0.00 | 0.00 |
| | Total | 9073 | | | | | | | | | | | 9073 | 0.00 | 0.00 |
| 201706 | TEPCO | 1049 | | | | | | | | | | | 1049 | 0.00 | 0.00 |
| | Contractors | 8264 | | | | | | | | | | | 8264 | 0.00 | 0.00 |
| | Total | 9313 | | | | | | | | | | | 9313 | 0.00 | 0.00 |
| 201707 | TEPCO | 1015 | | | | | | | | | | | 1015 | 0.00 | 0.00 |
| | Contractors | 8115 | | | | | | | | | | | 8115 | 0.00 | 0.00 |
| | Total | 9130 | | | | | | | | | | | 9130 | 0.00 | 0.00 |
| 201708 | TEPCO | 998 | | | | | | | | | | | 998 | 0.00 | 0.00 |
| | Contractors | 7834 | | | | | | | | | | | 7834 | 0.00 | 0.00 |
| | Total | 8832 | | | | | | | | | | | 8832 | 0.00 | 0.00 |
| 201709 | TEPCO | 1048 | | | | | | | | | | | 1048 | 0.00 | 0.00 |
| | Contractors | 7755 | | | | | | | | | | | 7755 | 0.00 | 0.00 |
| | Total | 8803 | | | | | | | | | | | 8803 | 0.00 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201710 | TEPCO | 1064 | | | | | | | | | | | 1064 | 0.00 | 0.00 |
| | Contractors | 7635 | | | | | | | | | | | 7635 | 0.00 | 0.00 |
| | Total | 8699 | | | | | | | | | | | 8699 | 0.00 | 0.00 |
| 201711 | TEPCO | 1050 | | | | | | | | | | | 1050 | 0.00 | 0.00 |
| | Contractors | 7574 | | | | | | | | | | | 7574 | 0.00 | 0.00 |
| | Total | 8624 | | | | | | | | | | | 8624 | 0.00 | 0.00 |
| 201712 | TEPCO | 983 | | | | | | | | | | | 983 | 0.00 | 0.00 |
| | Contractors | 7280 | | | | | | | | | | | 7280 | 0.00 | 0.00 |
| | Total | 8263 | | | | | | | | | | | 8263 | 0.00 | 0.00 |
| 201801 | TEPCO | 938 | | | | | | | | | | | 938 | 0.00 | 0.00 |
| | Contractors | 7082 | | | | | | | | | | | 7082 | 0.00 | 0.00 |
| | Total | 8020 | | | | | | | | | | | 8020 | 0.00 | 0.00 |
| 201802 | TEPCO | 991 | | | | | | | | | | | 991 | 0.00 | 0.00 |
| | Contractors | 7200 | | | | | | | | | | | 7200 | 0.00 | 0.00 |
| | Total | 8191 | | | | | | | | | | | 8191 | 0.00 | 0.00 |
| 201803 | TEPCO | 981 | | | | | | | | | | | 981 | 0.00 | 0.00 |
| | Contractors | 7231 | | | | | | | | | | | 7231 | 0.00 | 0.00 |
| | Total | 8212 | | | | | | | | | | | 8212 | 0.00 | 0.00 |
| 201804 | TEPCO | 1014 | | | | | | | | | | | 1014 | 0.00 | 0.00 |
| | Contractors | 6375 | | | | | | | | | | | 6375 | 0.00 | 0.00 |
| | Total | 7389 | | | | | | | | | | | 7389 | 0.00 | 0.00 |
| 201805 | TEPCO | 942 | | | | | | | | | | | 942 | 0.00 | 0.00 |
| | Contractors | 6319 | | | | | | | | | | | 6319 | 0.00 | 0.00 |
| | Total | 7261 | | | | | | | | | | | 7261 | 0.00 | 0.00 |
| 201806 | TEPCO | 968 | | | | | | | | | | | 968 | 0.00 | 0.00 |
| | Contractors | 6287 | | | | | | | | | | | 6287 | 0.00 | 0.00 |
| | Total | 7255 | | | | | | | | | | | 7255 | 0.00 | 0.00 |
| 201807 | TEPCO | 894 | | | | | | | | | | | 894 | 0.00 | 0.00 |
| | Contractors | 6283 | | | | | | | | | | | 6283 | 0.00 | 0.00 |
| | Total | 7177 | | | | | | | | | | | 7177 | 0.00 | 0.00 |
| 201808 | TEPCO | 972 | | | | | | | | | | | 972 | 0.00 | 0.00 |
| | Contractors | 6246 | | | | | | | | | | | 6246 | 0.00 | 0.00 |
| | Total | 7218 | | | | | | | | | | | 7218 | 0.00 | 0.00 |
| 201809 | TEPCO | 1002 | | | | | | | | | | | 1002 | 0.00 | 0.00 |
| | Contractors | 6161 | | | | | | | | | | | 6161 | 0.00 | 0.00 |
| | Total | 7163 | | | | | | | | | | | 7163 | 0.00 | 0.00 |
| 201810 | TEPCO | 1002 | | | | | | | | | | | 1002 | 0.00 | 0.00 |
| | Contractors | 6164 | | | | | | | | | | | 6164 | 0.00 | 0.00 |
| | Total | 7166 | | | | | | | | | | | 7166 | 0.00 | 0.00 |
| 201811 | TEPCO | 1022 | | | | | | | | | | | 1022 | 0.00 | 0.00 |
| | Contractors | 6224 | | | | | | | | | | | 6224 | 0.00 | 0.00 |
| | Total | 7246 | | | | | | | | | | | 7246 | 0.00 | 0.00 |
| 201812 | TEPCO | 1002 | | | | | | | | | | | 1002 | 0.00 | 0.00 |
| | Contractors | 6242 | | | | | | | | | | | 6242 | 0.00 | 0.00 |
| | Total | 7244 | | | | | | | | | | | 7244 | 0.00 | 0.00 |
| 201901 | TEPCO | 960 | | | | | | | | | | | 960 | 0.00 | 0.00 |
| | Contractors | 6117 | | | | | | | | | | | 6117 | 0.00 | 0.00 |
| | Total | 7077 | | | | | | | | | | | 7077 | 0.00 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 201902 | TEPCO | 1003 | | | | | | | | | | | 1003 | 0.00 | 0.00 |
| | Contractors | 6311 | | | | | | | | | | | 6311 | 0.00 | 0.00 |
| | Total | 7314 | | | | | | | | | | | 7314 | 0.00 | 0.00 |
| 201903 | TEPCO | 995 | | | | | | | | | | | 995 | 0.00 | 0.00 |
| | Contractors | 6178 | | | | | | | | | | | 6178 | 0.00 | 0.00 |
| | Total | 7173 | | | | | | | | | | | 7173 | 0.00 | 0.00 |
| 201904 | TEPCO | 944 | | | | | | | | | | | 944 | 0.00 | 0.00 |
| | Contractors | 5279 | | | | | | | | | | | 5279 | 0.00 | 0.00 |
| | Total | 6223 | | | | | | | | | | | 6223 | 0.00 | 0.00 |
| 201905 | TEPCO | 987 | | | | | | | | | | | 987 | 0.00 | 0.00 |
| | Contractors | 5433 | | | | | | | | | | | 5433 | 0.00 | 0.00 |
| | Total | 6420 | | | | | | | | | | | 6420 | 0.00 | 0.00 |
| 201906 | TEPCO | 1034 | | | | | | | | | | | 1034 | 0.00 | 0.00 |
| | Contractors | 5543 | | | | | | | | | | | 5543 | 0.00 | 0.00 |
| | Total | 6577 | | | | | | | | | | | 6577 | 0.00 | 0.00 |
| 201907 | TEPCO | 983 | | | | | | | | | | | 983 | 0.00 | 0.00 |
| | Contractors | 5605 | | | | | | | | | | | 5605 | 0.00 | 0.00 |
| | Total | 6588 | | | | | | | | | | | 6588 | 0.00 | 0.00 |
| 201908 | TEPCO | 1018 | | | | | | | | | | | 1018 | 0.00 | 0.00 |
| | Contractors | 5514 | | | | | | | | | | | 5514 | 0.00 | 0.00 |
| | Total | 6532 | | | | | | | | | | | 6532 | 0.00 | 0.00 |
| 201909 | TEPCO | 954 | | | | | | | | | | | 954 | 0.00 | 0.00 |
| | Contractors | 5559 | | | | | | | | | | | 5559 | 0.00 | 0.00 |
| | Total | 6513 | | | | | | | | | | | 6513 | 0.00 | 0.00 |
| 201910 | TEPCO | 957 | | | | | | | | | | | 957 | 0.00 | 0.00 |
| | Contractors | 5710 | | | | | | | | | | | 5710 | 0.00 | 0.00 |
| | Total | 6667 | | | | | | | | | | | 6667 | 0.00 | 0.00 |
| 201911 | TEPCO | 1047 | | | | | | | | | | | 1047 | 0.00 | 0.00 |
| | Contractors | 5863 | | | | | | | | | | | 5863 | 0.00 | 0.00 |
| | Total | 6910 | | | | | | | | | | | 6910 | 0.00 | 0.00 |
| 201912 | TEPCO | 980 | | | | | | | | | | | 980 | 0.00 | 0.00 |
| | Contractors | 5854 | | | | | | | | | | | 5854 | 0.00 | 0.00 |
| | Total | 6834 | | | | | | | | | | | 6834 | 0.00 | 0.00 |
| 202001 | TEPCO | 992 | | | | | | | | | | | 992 | 0.00 | 0.00 |
| | Contractors | 5852 | | | | | | | | | | | 5852 | 0.00 | 0.00 |
| | Total | 6844 | | | | | | | | | | | 6844 | 0.00 | 0.00 |
| 202002 | TEPCO | 933 | | | | | | | | | | | 933 | 0.00 | 0.00 |
| | Contractors | 6019 | | | | | | | | | | | 6019 | 0.00 | 0.00 |
| | Total | 6952 | | | | | | | | | | | 6952 | 0.00 | 0.00 |
| 202003 | TEPCO | 917 | | | | | | | | | | | 917 | 0.00 | 0.00 |
| | Contractors | 6067 | | | | | | | | | | | 6067 | 0.00 | 0.00 |
| | Total | 6984 | | | | | | | | | | | 6984 | 0.00 | 0.00 |
| 202004 | TEPCO | 825 | | | | | | | | | | | 825 | 0.00 | 0.00 |
| | Contractors | 5357 | | | | | | | | | | | 5357 | 0.00 | 0.00 |
| | Total | 6182 | | | | | | | | | | | 6182 | 0.00 | 0.00 |
| 202005 | TEPCO | 782 | | | | | | | | | | | 782 | 0.00 | 0.00 |
| | Contractors | 5348 | | | | | | | | | | | 5348 | 0.00 | 0.00 |
| | Total | 6130 | | | | | | | | | | | 6130 | 0.00 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202006 | TEPCO | 947 | | | | | | | | | | | 947 | 0.00 | 0.00 |
| | Contractors | 5664 | | | | | | | | | | | 5664 | 0.00 | 0.00 |
| | Total | 6611 | | | | | | | | | | | 6611 | 0.00 | 0.00 |
| 202007 | TEPCO | 1012 | | | | | | | | | | | 1012 | 0.00 | 0.00 |
| | Contractors | 5679 | | | | | | | | | | | 5679 | 0.00 | 0.00 |
| | Total | 6691 | | | | | | | | | | | 6691 | 0.00 | 0.00 |
| 202008 | TEPCO | 956 | | | | | | | | | | | 956 | 0.00 | 0.00 |
| | Contractors | 5380 | | | | | | | | | | | 5380 | 0.00 | 0.00 |
| | Total | 6336 | | | | | | | | | | | 6336 | 0.00 | 0.00 |
| 202009 | TEPCO | 1015 | | | | | | | | | | | 1015 | 0.00 | 0.00 |
| | Contractors | 5530 | | | | | | | | | | | 5530 | 0.00 | 0.00 |
| | Total | 6545 | | | | | | | | | | | 6545 | 0.00 | 0.00 |
| 202010 | TEPCO | 977 | | | | | | | | | | | 977 | 0.00 | 0.00 |
| | Contractors | 5667 | | | | | | | | | | | 5667 | 0.00 | 0.00 |
| | Total | 6644 | | | | | | | | | | | 6644 | 0.00 | 0.00 |
| 202011 | TEPCO | 996 | | | | | | | | | | | 996 | 0.00 | 0.00 |
| | Contractors | 5683 | | | | | | | | | | | 5683 | 0.00 | 0.00 |
| | Total | 6679 | | | | | | | | | | | 6679 | 0.00 | 0.00 |
| 202012 | TEPCO | 1011 | | | | | | | | | | | 1011 | 0.00 | 0.00 |
| | Contractors | 5753 | | | | | | | | | | | 5753 | 0.00 | 0.00 |
| | Total | 6764 | | | | | | | | | | | 6764 | 0.00 | 0.00 |
| 202101 | TEPCO | 917 | | | | | | | | | | | 917 | 0.00 | 0.00 |
| | Contractors | 5783 | | | | | | | | | | | 5783 | 0.00 | 0.00 |
| | Total | 6700 | | | | | | | | | | | 6700 | 0.00 | 0.00 |
| 202102 | TEPCO | 931 | | | | | | | | | | | 931 | 0.00 | 0.00 |
| | Contractors | 5892 | | | | | | | | | | | 5892 | 0.00 | 0.00 |
| | Total | 6823 | | | | | | | | | | | 6823 | 0.00 | 0.00 |
| 202103 | TEPCO | 997 | | | | | | | | | | | 997 | 0.00 | 0.00 |
| | Contractors | 5741 | | | | | | | | | | | 5741 | 0.00 | 0.00 |
| | Total | 6738 | | | | | | | | | | | 6738 | 0.00 | 0.00 |
| 202104 | TEPCO | 969 | | | | | | | | | | | 969 | 0.00 | 0.00 |
| | Contractors | 4974 | | | | | | | | | | | 4974 | 0.00 | 0.00 |
| | Total | 5943 | | | | | | | | | | | 5943 | 0.00 | 0.00 |
| 202105 | TEPCO | 940 | | | | | | | | | | | 940 | 0.00 | 0.00 |
| | Contractors | 5027 | | | | | | | | | | | 5027 | 0.00 | 0.00 |
| | Total | 5967 | | | | | | | | | | | 5967 | 0.00 | 0.00 |
| 202106 | TEPCO | 1057 | | | | | | | | | | | 1057 | 0.00 | 0.00 |
| | Contractors | 5327 | | | | | | | | | | | 5327 | 0.00 | 0.00 |
| | Total | 6384 | | | | | | | | | | | 6384 | 0.00 | 0.00 |
| 202107 | TEPCO | 1028 | | | | | | | | | | | 1028 | 0.00 | 0.00 |
| | Contractors | 5427 | | | | | | | | | | | 5427 | 0.00 | 0.00 |
| | Total | 6455 | | | | | | | | | | | 6455 | 0.00 | 0.00 |
| 202108 | TEPCO | 925 | | | | | | | | | | | 925 | 0.00 | 0.00 |
| | Contractors | 5354 | | | | | | | | | | | 5354 | 0.00 | 0.00 |
| | Total | 6279 | | | | | | | | | | | 6279 | 0.00 | 0.00 |
| 202109 | TEPCO | 992 | | | | | | | | | | | 992 | 0.00 | 0.00 |
| | Contractors | 5495 | | | | | | | | | | | 5495 | 0.00 | 0.00 |
| | Total | 6487 | | | | | | | | | | | 6487 | 0.00 | 0.00 |

| Year/ month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|--------------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|--------------------|----------------------|------------------|------------------|
| 202110 | TEPCO | 1017 | | | | | | | | | | | 1017 | 0.00 | 0.00 |
| | Contractors | 5582 | | | | | | | | | | | 5582 | 0.00 | 0.00 |
| | Total | 6599 | | | | | | | | | | | 6599 | 0.00 | 0.00 |
| 202111 | TEPCO | 1007 | | | | | | | | | | | 1007 | 0.00 | 0.00 |
| | Contractors | 5743 | | | | | | | | | | | 5743 | 0.00 | 0.00 |
| | Total | 6750 | | | | | | | | | | | 6750 | 0.00 | 0.00 |
| 202112 | TEPCO | 1035 | | | | | | | | | | | 1035 | 0.00 | 0.00 |
| | Contractors | 5835 | | | | | | | | | | | 5835 | 0.00 | 0.00 |
| | Total | 6870 | | | | | | | | | | | 6870 | 0.00 | 0.00 |
| 202201 | TEPCO | 959 | | | | | | | | | | | 959 | 0.00 | 0.00 |
| | Contractors | 5844 | | | | | | | | | | | 5844 | 0.00 | 0.00 |
| | Total | 6803 | | | | | | | | | | | 6803 | 0.00 | 0.00 |
| 202202 | TEPCO | 897 | | | | | | | | | | | 897 | 0.00 | 0.00 |
| | Contractors | 5865 | | | | | | | | | | | 5865 | 0.00 | 0.00 |
| | Total | 6762 | | | | | | | | | | | 6762 | 0.00 | 0.00 |
| 202203 | TEPCO | 1001 | | | | | | | | | | | 1001 | 0.00 | 0.00 |
| | Contractors | 5860 | | | | | | | | | | | 5860 | 0.00 | 0.00 |
| | Total | 6861 | | | | | | | | | | | 6861 | 0.00 | 0.00 |
| 202204 | TEPCO | 1023 | | | | | | | | | | | 1023 | 0.00 | 0.00 |
| | Contractors | 5600 | | | | | | | | | | | 5600 | 0.00 | 0.00 |
| | Total | 6623 | | | | | | | | | | | 6623 | 0.00 | 0.00 |
| 202205 | TEPCO | 990 | | | | | | | | | | | 990 | 0.00 | 0.00 |
| | Contractors | 5687 | | | | | | | | | | | 5687 | 0.00 | 0.00 |
| | Total | 6677 | | | | | | | | | | | 6677 | 0.00 | 0.00 |
| 202206 | TEPCO | 1074 | | | | | | | | | | | 1074 | 0.00 | 0.00 |
| | Contractors | 6057 | | | | | | | | | | | 6057 | 0.00 | 0.00 |
| | Total | 7131 | | | | | | | | | | | 7131 | 0.00 | 0.00 |
| 202207 | TEPCO | 1007 | | | | | | | | | | | 1007 | 0.00 | 0.00 |
| | Contractors | 6106 | | | | | | | | | | | 6106 | 0.00 | 0.00 |
| | Total | 7113 | | | | | | | | | | | 7113 | 0.00 | 0.00 |
| 202208 | TEPCO | 1024 | | | | | | | | | | | 1024 | 0.00 | 0.00 |
| | Contractors | 6039 | | | | | | | | | | | 6039 | 0.00 | 0.00 |
| | Total | 7063 | | | | | | | | | | | 7063 | 0.00 | 0.00 |
| 202209 | TEPCO | 1090 | | | | | | | | | | | 1090 | 0.00 | 0.00 |
| | Contractors | 6321 | | | | | | | | | | | 6321 | 0.00 | 0.00 |
| | Total | 7411 | | | | | | | | | | | 7411 | 0.00 | 0.00 |
| 202210 | TEPCO | 1042 | | | | | | | | | | | 1042 | 0.00 | 0.00 |
| | Contractors | 6481 | | | | | | | | | | | 6481 | 0.00 | 0.00 |
| | Total | 7523 | | | | | | | | | | | 7523 | 0.00 | 0.00 |
| 202211 | TEPCO | 1054 | | | | | | | | | | | 1054 | 0.00 | 0.00 |
| | Contractors | 6711 | | | | | | | | | | | 6711 | 0.00 | 0.00 |
| | Total | 7765 | | | | | | | | | | | 7765 | 0.00 | 0.00 |
| 202212 | TEPCO | 1047 | | | | | | | | | | | 1047 | 0.00 | 0.00 |
| | Contractors | 6702 | | | | | | | | | | | 6702 | 0.00 | 0.00 |
| | Total | 7749 | | | | | | | | | | | 7749 | 0.00 | 0.00 |
| 202301 | TEPCO | 1035 | | | | | | | | | | | 1035 | 0.00 | 0.00 |
| | Contractors | 6587 | | | | | | | | | | | 6587 | 0.00 | 0.00 |
| | Total | 7622 | | | | | | | | | | | 7622 | 0.00 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|--------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|-------------------|---------------|---------------|
| 202302 | TEPCO | 1031 | | | | | | | | | | | 1031 | 0.00 | 0.00 |
| | Contractors | 6652 | | | | | | | | | | | 6652 | 0.00 | 0.00 |
| | Total | 7683 | | | | | | | | | | | 7683 | 0.00 | 0.00 |
| 202303 | TEPCO | 1081 | | | | | | | | | | | 1081 | 0.00 | 0.00 |
| | Contractors | 6820 | | | | | | | | | | | 6820 | 0.00 | 0.00 |
| | Total | 7901 | | | | | | | | | | | 7901 | 0.00 | 0.00 |
| 202304 | TEPCO | 1052 | | | | | | | | | | | 1052 | 0.00 | 0.00 |
| | Contractors | 6487 | | | | | | | | | | | 6487 | 0.00 | 0.00 |
| | Total | 7539 | | | | | | | | | | | 7539 | 0.00 | 0.00 |
| 202305 | TEPCO | 1037 | | | | | | | | | | | 1037 | 0.00 | 0.00 |
| | Contractors | 6457 | | | | | | | | | | | 6457 | 0.00 | 0.00 |
| | Total | 7494 | | | | | | | | | | | 7494 | 0.00 | 0.00 |
| 202306 | TEPCO | 1097 | | | | | | | | | | | 1097 | 0.00 | 0.00 |
| | Contractors | 6576 | | | | | | | | | | | 6576 | 0.00 | 0.00 |
| | Total | 7673 | | | | | | | | | | | 7673 | 0.00 | 0.00 |
| 202307 | TEPCO | 998 | | | | | | | | | | | 998 | 0.00 | 0.00 |
| | Contractors | 6621 | | | | | | | | | | | 6621 | 0.00 | 0.00 |
| | Total | 7619 | | | | | | | | | | | 7619 | 0.00 | 0.00 |
| 202308 | TEPCO | 1033 | | | | | | | | | | | 1033 | 0.00 | 0.00 |
| | Contractors | 6383 | | | | | | | | | | | 6383 | 0.00 | 0.00 |
| | Total | 7416 | | | | | | | | | | | 7416 | 0.00 | 0.00 |
| 202309 | TEPCO | 1056 | | | | | | | | | | | 1056 | 0.00 | 0.00 |
| | Contractors | 6644 | | | | | | | | | | | 6644 | 0.00 | 0.00 |
| | Total | 7700 | | | | | | | | | | | 7700 | 0.00 | 0.00 |
| 202310 | TEPCO | 1070 | | | | | | | | | | | 1070 | 0.00 | 0.00 |
| | Contractors | 6785 | | | | | | | | | | | 6785 | 0.00 | 0.00 |
| | Total | 7855 | | | | | | | | | | | 7855 | 0.00 | 0.00 |
| 202311 | TEPCO | 1068 | | | | | | | | | | | 1068 | 0.00 | 0.00 |
| | Contractors | 6887 | | | | | | | | | | | 6887 | 0.00 | 0.00 |
| | Total | 7955 | | | | | | | | | | | 7955 | 0.00 | 0.00 |
| 202312 | TEPCO | 1054 | | | | | | | | | | | 1054 | 0.00 | 0.00 |
| | Contractors | 6963 | | | | | | | | | | | 6963 | 0.00 | 0.00 |
| | Total | 8017 | | | | | | | | | | | 8017 | 0.00 | 0.00 |
| 202401 | TEPCO | 993 | | | | | | | | | | | 993 | 0.00 | 0.00 |
| | Contractors | 6855 | | | | | | | | | | | 6855 | 0.00 | 0.00 |
| | Total | 7848 | | | | | | | | | | | 7848 | 0.00 | 0.00 |
| 202402 | TEPCO | 1044 | | | | | | | | | | | 1044 | 0.00 | 0.00 |
| | Contractors | 6967 | | | | | | | | | | | 6967 | 0.00 | 0.00 |
| | Total | 8011 | | | | | | | | | | | 8011 | 0.00 | 0.00 |
| 202403 | TEPCO | 1017 | | | | | | | | | | | 1017 | 0.00 | 0.00 |
| | Contractors | 6899 | | | | | | | | | | | 6899 | 0.00 | 0.00 |
| | Total | 7916 | | | | | | | | | | | 7916 | 0.00 | 0.00 |
| 202404 | TEPCO | 1014 | | | | | | | | | | | 1014 | 0.00 | 0.00 |
| | Contractors | 6425 | | | | | | | | | | | 6425 | 0.00 | 0.00 |
| | Total | 7439 | | | | | | | | | | | 7439 | 0.00 | 0.00 |
| 202405 | TEPCO | 979 | | | | | | | | | | | 979 | 0.00 | 0.00 |
| | Contractors | 6533 | | | | | | | | | | | 6533 | 0.00 | 0.00 |
| | Total | 7512 | | | | | | | | | | | 7512 | 0.00 | 0.00 |

| Year and month | TEPCO/ Contractors | 2 or less (mSv) | 2-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|--------------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|--------------------|-------------------|------------------|------------------|
| 202406 | TEPCO | 1042 | | | | | | | | | | | 1042 | 0.00 | 0.00 |
| | Contractors | 6758 | | | | | | | | | | | 6758 | 0.00 | 0.00 |
| | Total | 7800 | | | | | | | | | | | 7800 | 0.00 | 0.00 |
| 202407 | TEPCO | 939 | | | | | | | | | | | 939 | 0.00 | 0.00 |
| | Contractors | 6774 | | | | | | | | | | | 6774 | 0.00 | 0.00 |
| | Total | 7713 | | | | | | | | | | | 7713 | 0.00 | 0.00 |
| 202408 | TEPCO | 978 | | | | | | | | | | | 978 | 0.00 | 0.00 |
| | Contractors | 6458 | | | | | | | | | | | 6458 | 0.00 | 0.00 |
| | Total | 7436 | | | | | | | | | | | 7436 | 0.00 | 0.00 |
| 202409 | TEPCO | 992 | | | | | | | | | | | 992 | 0.00 | 0.00 |
| | Contractors | 6535 | | | | | | | | | | | 6535 | 0.00 | 0.00 |
| | Total | 7527 | | | | | | | | | | | 7527 | 0.00 | 0.00 |
| 202410 | TEPCO | 1038 | | | | | | | | | | | 1038 | 0.00 | 0.00 |
| | Contractors | 6905 | | | | | | | | | | | 6905 | 0.00 | 0.00 |
| | Total | 7943 | | | | | | | | | | | 7943 | 0.00 | 0.00 |
| 202411 | TEPCO | 1052 | | | | | | | | | | | 1052 | 0.00 | 0.00 |
| | Contractors | 6903 | | | | | | | | | | | 6903 | 0.00 | 0.00 |
| | Total | 7955 | | | | | | | | | | | 7955 | 0.00 | 0.00 |
| 202412 | TEPCO | 1016 | | | | | | | | | | | 1016 | 0.00 | 0.00 |
| | Contractors | 6959 | | | | | | | | | | | 6959 | 0.00 | 0.00 |
| | Total | 7975 | | | | | | | | | | | 7975 | 0.00 | 0.00 |
| 202501 | TEPCO | 998 | | | | | | | | | | | 998 | 0.00 | 0.00 |
| | Contractors | 6906 | | | | | | | | | | | 6906 | 0.00 | 0.00 |
| | Total | 7904 | | | | | | | | | | | 7904 | 0.00 | 0.00 |
| 202502 | TEPCO | 988 | | | | | | | | | | | 988 | 0.00 | 0.00 |
| | Contractors | 7043 | | | | | | | | | | | 7043 | 0.00 | 0.00 |
| | Total | 8031 | | | | | | | | | | | 8031 | 0.00 | 0.00 |
| 202503 | TEPCO | 1002 | | | | | | | | | | | 1002 | 0.00 | 0.00 |
| | Contractors | 6854 | | | | | | | | | | | 6854 | 0.00 | 0.00 |
| | Total | 7856 | | | | | | | | | | | 7856 | 0.00 | 0.00 |
| 202504 | TEPCO | 1010 | | | | | | | | | | | 1010 | 0.00 | 0.00 |
| | Contractors | 6513 | | | | | | | | | | | 6513 | 0.00 | 0.00 |
| | Total | 7523 | | | | | | | | | | | 7523 | 0.00 | 0.00 |
| 202505 | TEPCO | 993 | | | | | | | | | | | 993 | 0.00 | 0.00 |
| | Contractors | 6577 | | | | | | | | | | | 6577 | 0.00 | 0.00 |
| | Total | 7570 | | | | | | | | | | | 7570 | 0.00 | 0.00 |
| 202506 | TEPCO | 1043 | | | | | | | | | | | 1043 | 0.00 | 0.00 |
| | Contractors | 6777 | | | | | | | | | | | 6777 | 0.00 | 0.00 |
| | Total | 7820 | | | | | | | | | | | 7820 | 0.00 | 0.00 |

Note)

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.
- Depending on the prime contractors, there are some cases in which the internal exposure dose is recorded as that of the WBC measurement month, not the inhalation exposure month.
- Basically, internal exposure dose should be recorded as that of the month including the day when radioactive materials were inhaled, which we call here an "inhalation day." However, regarding all or most of the data indicated with # in the table, they are recorded as the exposure dose of the month including the WBC measurement day, not the inhalation day.

Table 15. Cumulative Exposure Dose Data of Subsequent Month(s) After March 2011

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 201103-201103 | TEPCO | 40 | 66 | 239 | 529 | 539 | 119 | 77 | 65 | 16 | 0 | 6 | 1696 | 670.36 | 31.53 |
| | Contractors | 397 | 537 | 399 | 460 | 373 | 65 | 34 | 17 | 2 | 2 | 0 | 2286 | 238.42 | 14.15 |
| | Total | 437 | 603 | 638 | 989 | 912 | 184 | 111 | 82 | 18 | 2 | 6 | 3982 | 670.36 | 21.55 |
| 201103-201104 | TEPCO | 196 | 288 | 350 | 479 | 623 | 170 | 79 | 95 | 19 | 1 | 6 | 2306 | 678.08 | 27.97 |
| | Contractors | 1450 | 1561 | 772 | 710 | 569 | 95 | 42 | 18 | 2 | 2 | 0 | 5221 | 238.42 | 9.70 |
| | Total | 1646 | 1849 | 1122 | 1189 | 1192 | 265 | 121 | 113 | 21 | 3 | 6 | 7527 | 678.08 | 15.30 |
| 201103-201105 | TEPCO | 312 | 404 | 354 | 489 | 637 | 190 | 95 | 101 | 20 | 1 | 6 | 2609 | 678.80 | 26.50 |
| | Contractors | 2255 | 2520 | 1222 | 1081 | 779 | 121 | 47 | 20 | 2 | 2 | 0 | 8049 | 238.42 | 8.73 |
| | Total | 2567 | 2924 | 1576 | 1570 | 1416 | 311 | 142 | 121 | 22 | 3 | 6 | 10658 | 678.80 | 13.08 |
| 201103-201106 | TEPCO | 399 | 444 | 364 | 498 | 647 | 185 | 112 | 105 | 22 | 1 | 6 | 2783 | 678.80 | 25.87 |
| | Contractors | 2692 | 2986 | 1553 | 1475 | 1078 | 137 | 50 | 20 | 2 | 2 | 0 | 9995 | 238.42 | 9.01 |
| | Total | 3091 | 3430 | 1917 | 1973 | 1725 | 322 | 162 | 125 | 24 | 3 | 6 | 12778 | 678.80 | 12.68 |
| 201103-201107 | TEPCO | 521 | 482 | 362 | 498 | 655 | 186 | 122 | 109 | 22 | 1 | 6 | 2964 | 678.80 | 25.06 |
| | Contractors | 3075 | 3655 | 1874 | 1747 | 1284 | 160 | 52 | 20 | 2 | 2 | 0 | 11871 | 238.42 | 8.92 |
| | Total | 3596 | 4137 | 2236 | 2245 | 1939 | 346 | 174 | 129 | 24 | 3 | 6 | 14835 | 678.80 | 12.14 |
| 201103-201108 | TEPCO | 565 | 505 | 358 | 495 | 659 | 201 | 125 | 115 | 22 | 1 | 6 | 3052 | 678.80 | 25.06 |
| | Contractors | 3133 | 3835 | 2186 | 1980 | 1522 | 172 | 53 | 20 | 2 | 2 | 0 | 12905 | 238.42 | 9.26 |
| | Total | 3698 | 4340 | 2544 | 2475 | 2181 | 373 | 178 | 135 | 24 | 3 | 6 | 15957 | 678.80 | 12.29 |
| 201103-201109 | TEPCO | 604 | 496 | 363 | 494 | 654 | 214 | 132 | 117 | 24 | 1 | 6 | 3105 | 678.80 | 25.20 |
| | Contractors | 3308 | 4014 | 2283 | 2270 | 1693 | 189 | 57 | 20 | 2 | 2 | 0 | 13838 | 238.42 | 9.51 |
| | Total | 3912 | 4510 | 2646 | 2764 | 2347 | 403 | 189 | 137 | 26 | 3 | 6 | 16943 | 678.80 | 12.39 |
| 201103-201110 | TEPCO | 627 | 511 | 355 | 490 | 651 | 226 | 144 | 116 | 26 | 1 | 6 | 3153 | 678.80 | 25.40 |
| | Contractors | 3522 | 4111 | 2362 | 2458 | 1860 | 221 | 58 | 20 | 2 | 2 | 0 | 14616 | 238.42 | 9.72 |
| | Total | 4149 | 4622 | 2717 | 2948 | 2511 | 447 | 202 | 136 | 28 | 3 | 6 | 17769 | 678.80 | 12.50 |
| 201103-201111 | TEPCO | 656 | 543 | 350 | 486 | 654 | 229 | 152 | 116 | 26 | 1 | 6 | 3219 | 678.80 | 25.27 |
| | Contractors | 4073 | 4235 | 2373 | 2585 | 2034 | 233 | 62 | 20 | 2 | 2 | 0 | 15619 | 238.42 | 9.61 |
| | Total | 4729 | 4778 | 2723 | 3071 | 2688 | 462 | 214 | 136 | 28 | 3 | 6 | 18838 | 678.80 | 12.29 |
| 201103-201112 | TEPCO | 687 | 557 | 354 | 487 | 647 | 240 | 161 | 116 | 26 | 1 | 6 | 3282 | 678.80 | 25.19 |
| | Contractors | 4252 | 4403 | 2434 | 2720 | 2173 | 240 | 62 | 20 | 2 | 2 | 0 | 16308 | 238.42 | 9.68 |
| | Total | 4939 | 4960 | 2788 | 3207 | 2820 | 480 | 223 | 136 | 28 | 3 | 6 | 19590 | 678.80 | 12.28 |
| 201103-201201 | TEPCO | 698 | 575 | 366 | 485 | 643 | 241 | 173 | 116 | 26 | 1 | 6 | 3330 | 678.80 | 25.21 |
| | Contractors | 4421 | 4528 | 2466 | 2787 | 2323 | 247 | 62 | 20 | 2 | 2 | 0 | 16858 | 238.42 | 9.77 |
| | Total | 5119 | 5103 | 2832 | 3272 | 2966 | 488 | 235 | 136 | 28 | 3 | 6 | 20188 | 678.80 | 12.31 |
| 201103-201202 | TEPCO | 705 | 590 | 374 | 490 | 639 | 246 | 178 | 116 | 26 | 1 | 6 | 3371 | 678.80 | 25.21 |
| | Contractors | 4450 | 4593 | 2526 | 2827 | 2511 | 252 | 64 | 20 | 2 | 2 | 0 | 17247 | 238.42 | 9.97 |
| | Total | 5155 | 5183 | 2900 | 3317 | 3150 | 498 | 242 | 136 | 28 | 3 | 6 | 20618 | 678.80 | 12.46 |
| 201103-201203 | TEPCO | 735 | 589 | 377 | 491 | 630 | 257 | 186 | 117 | 26 | 1 | 6 | 3415 | 678.80 | 25.15 |
| | Contractors | 4633 | 4623 | 2559 | 2897 | 2660 | 262 | 65 | 20 | 2 | 2 | 0 | 17723 | 238.42 | 10.07 |
| | Total | 5368 | 5212 | 2936 | 3388 | 3290 | 519 | 251 | 137 | 28 | 3 | 6 | 21138 | 678.80 | 12.50 |
| 201103-201204 | TEPCO | 753 | 591 | 374 | 505 | 623 | 259 | 195 | 117 | 26 | 1 | 6 | 3450 | 678.80 | 25.13 |
| | Contractors | 4957 | 4710 | 2555 | 2956 | 2758 | 279 | 65 | 20 | 2 | 2 | 0 | 18304 | 238.42 | 10.06 |
| | Total | 5710 | 5301 | 2929 | 3461 | 3381 | 538 | 260 | 137 | 28 | 3 | 6 | 21754 | 678.80 | 12.45 |
| 201103-201205 | TEPCO | 771 | 594 | 377 | 500 | 624 | 262 | 201 | 117 | 26 | 1 | 6 | 3479 | 678.80 | 25.12 |
| | Contractors | 5248 | 4830 | 2600 | 2962 | 2858 | 314 | 66 | 20 | 2 | 2 | 0 | 18902 | 238.42 | 10.08 |
| | Total | 6019 | 5424 | 2977 | 3462 | 3482 | 576 | 267 | 137 | 28 | 3 | 6 | 22381 | 678.80 | 12.42 |
| 201103-201206 | TEPCO | 778 | 598 | 383 | 500 | 621 | 268 | 206 | 117 | 26 | 1 | 6 | 3504 | 678.80 | 25.17 |
| | Contractors | 5324 | 5132 | 2635 | 3004 | 2932 | 349 | 69 | 20 | 2 | 2 | 0 | 19469 | 238.42 | 10.12 |
| Total | | 6102 | 5730 | 3018 | 3504 | 3553 | 617 | 275 | 137 | 28 | 3 | 6 | 22973 | 678.80 | 12.42 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 201103-201207 | TEPCO | 813 | 602 | 384 | 502 | 622 | 266 | 213 | 117 | 26 | 1 | 6 | 3552 | 678.80 | 25.00 |
| | Contractors | 5383 | 5302 | 2682 | 3054 | 3022 | 392 | 70 | 20 | 2 | 2 | 0 | 19929 | 238.42 | 10.22 |
| | Total | 6196 | 5904 | 3066 | 3556 | 3644 | 658 | 283 | 137 | 28 | 3 | 6 | 23481 | 678.80 | 12.45 |
| 201103-201208 | TEPCO | 825 | 612 | 387 | 502 | 616 | 277 | 213 | 117 | 26 | 1 | 6 | 3582 | 678.80 | 24.96 |
| | Contractors | 5510 | 5399 | 2728 | 3085 | 3090 | 411 | 73 | 20 | 2 | 2 | 0 | 20320 | 238.42 | 10.27 |
| | Total | 6335 | 6011 | 3115 | 3587 | 3706 | 688 | 286 | 137 | 28 | 3 | 6 | 23902 | 678.80 | 12.47 |
| 201103-201209 | TEPCO | 812 | 621 | 391 | 502 | 614 | 281 | 218 | 117 | 26 | 1 | 6 | 3589 | 678.80 | 25.07 |
| | Contractors | 5575 | 5501 | 2833 | 3088 | 3178 | 438 | 73 | 20 | 2 | 2 | 0 | 20710 | 238.42 | 10.34 |
| | Total | 6387 | 6122 | 3224 | 3590 | 3792 | 719 | 291 | 137 | 28 | 3 | 6 | 24299 | 678.80 | 12.51 |
| 201103-201210 | TEPCO | 841 | 630 | 392 | 501 | 616 | 288 | 220 | 117 | 26 | 1 | 6 | 3638 | 678.80 | 24.90 |
| | Contractors | 5700 | 5595 | 2948 | 3144 | 3227 | 459 | 76 | 20 | 2 | 2 | 0 | 21173 | 238.42 | 10.36 |
| | Total | 6541 | 6225 | 3340 | 3645 | 3843 | 747 | 296 | 137 | 28 | 3 | 6 | 24811 | 678.80 | 12.49 |
| 201103-201211 | TEPCO | 824 | 647 | 395 | 498 | 612 | 294 | 225 | 117 | 26 | 1 | 6 | 3645 | 678.80 | 25.01 |
| | Contractors | 5841 | 5653 | 3021 | 3215 | 3281 | 474 | 80 | 20 | 2 | 2 | 0 | 21589 | 238.42 | 10.40 |
| | Total | 6665 | 6300 | 3416 | 3713 | 3893 | 768 | 305 | 137 | 28 | 3 | 6 | 25234 | 678.80 | 12.51 |
| 201103-201212 | TEPCO | 824 | 642 | 409 | 494 | 612 | 297 | 229 | 117 | 26 | 1 | 6 | 3657 | 678.80 | 25.09 |
| | Contractors | 6016 | 5786 | 3085 | 3256 | 3356 | 496 | 80 | 20 | 2 | 2 | 0 | 22099 | 238.42 | 10.41 |
| | Total | 6840 | 6428 | 3494 | 3750 | 3968 | 793 | 309 | 137 | 28 | 3 | 6 | 25756 | 678.80 | 12.49 |
| 201103-201301 | TEPCO | 824 | 645 | 411 | 495 | 615 | 294 | 234 | 117 | 26 | 1 | 6 | 3668 | 678.80 | 25.13 |
| | Contractors | 6192 | 5868 | 3157 | 3318 | 3427 | 512 | 80 | 20 | 2 | 2 | 0 | 22578 | 238.42 | 10.41 |
| | Total | 7016 | 6513 | 3568 | 3813 | 4042 | 806 | 314 | 137 | 28 | 3 | 6 | 26246 | 678.80 | 12.47 |
| 201103-201302 | TEPCO | 828 | 645 | 413 | 498 | 618 | 295 | 235 | 117 | 26 | 1 | 6 | 3682 | 678.80 | 25.15 |
| | Contractors | 6358 | 5962 | 3168 | 3431 | 3515 | 540 | 83 | 20 | 2 | 2 | 0 | 23081 | 238.42 | 10.48 |
| | Total | 7186 | 6607 | 3581 | 3929 | 4133 | 835 | 318 | 137 | 28 | 3 | 6 | 26763 | 678.80 | 12.50 |
| 201103-201303 | TEPCO | 836 | 639 | 423 | 500 | 617 | 298 | 238 | 117 | 26 | 1 | 6 | 3701 | 678.80 | 25.18 |
| | Contractors | 6513 | 6063 | 3238 | 3508 | 3628 | 570 | 86 | 20 | 2 | 2 | 0 | 23630 | 238.42 | 10.58 |
| | Total | 7349 | 6702 | 3661 | 4008 | 4245 | 868 | 324 | 137 | 28 | 3 | 6 | 27331 | 678.80 | 12.55 |
| 201103-201304 | TEPCO | 874 | 654 | 432 | 501 | 619 | 301 | 239 | 117 | 26 | 1 | 6 | 3770 | 678.80 | 24.86 |
| | Contractors | 6734 | 6157 | 3285 | 3545 | 3685 | 590 | 87 | 20 | 2 | 2 | 0 | 24107 | 238.42 | 10.56 |
| | Total | 7608 | 6811 | 3717 | 4046 | 4304 | 891 | 326 | 137 | 28 | 3 | 6 | 27877 | 678.80 | 12.49 |
| 201103-201305 | TEPCO | 878 | 657 | 433 | 510 | 620 | 300 | 242 | 117 | 26 | 1 | 6 | 3790 | 678.80 | 24.85 |
| | Contractors | 6887 | 6275 | 3291 | 3569 | 3740 | 614 | 88 | 20 | 2 | 2 | 0 | 24488 | 238.42 | 10.57 |
| | Total | 7765 | 6932 | 3724 | 4079 | 4360 | 914 | 330 | 137 | 28 | 3 | 6 | 28278 | 678.80 | 12.49 |
| 201103-201306 | TEPCO | 878 | 661 | 430 | 520 | 618 | 301 | 245 | 117 | 26 | 1 | 6 | 3803 | 678.80 | 24.88 |
| | Contractors | 6964 | 6340 | 3324 | 3565 | 3807 | 644 | 91 | 20 | 2 | 2 | 0 | 24759 | 238.42 | 10.63 |
| | Total | 7842 | 7001 | 3754 | 4085 | 4425 | 945 | 336 | 137 | 28 | 3 | 6 | 28562 | 678.80 | 12.53 |
| 201103-201307 | TEPCO | 910 | 667 | 426 | 531 | 615 | 306 | 245 | 117 | 26 | 1 | 6 | 3850 | 678.80 | 24.68 |
| | Contractors | 7109 | 6403 | 3390 | 3574 | 3841 | 678 | 93 | 20 | 2 | 2 | 0 | 25112 | 238.42 | 10.66 |
| | Total | 8019 | 7070 | 3816 | 4105 | 4456 | 984 | 338 | 137 | 28 | 3 | 6 | 28962 | 678.80 | 12.53 |
| 201103-201308 | TEPCO | 908 | 679 | 425 | 536 | 612 | 311 | 249 | 117 | 26 | 1 | 6 | 3870 | 678.80 | 24.68 |
| | Contractors | 7177 | 6503 | 3429 | 3601 | 3908 | 705 | 99 | 20 | 2 | 2 | 0 | 25446 | 238.42 | 10.73 |
| | Total | 8085 | 7182 | 3854 | 4137 | 4520 | 1016 | 348 | 137 | 28 | 3 | 6 | 29316 | 678.80 | 12.57 |
| 201103-201309 | TEPCO | 978 | 685 | 432 | 539 | 607 | 315 | 252 | 117 | 26 | 1 | 6 | 3958 | 678.80 | 24.24 |
| | Contractors | 7280 | 6521 | 3532 | 3654 | 3984 | 740 | 101 | 20 | 2 | 2 | 0 | 25836 | 238.42 | 10.82 |
| | Total | 8258 | 7206 | 3964 | 4193 | 4591 | 1055 | 353 | 137 | 28 | 3 | 6 | 29794 | 678.80 | 12.61 |
| 201103-201310 | TEPCO | 1018 | 700 | 436 | 540 | 611 | 315 | 257 | 117 | 26 | 1 | 6 | 4027 | 678.80 | 23.97 |
| | Contractors | 7394 | 6631 | 3584 | 3739 | 4077 | 778 | 106 | 20 | 2 | 2 | 0 | 26333 | 238.42 | 10.91 |
| | Total | 8412 | 7331 | 4020 | 4279 | 4688 | 1093 | 363 | 137 | 28 | 3 | 6 | 30360 | 678.80 | 12.65 |
| 201103-201311 | TEPCO | 1014 | 724 | 438 | 542 | 611 | 320 | 258 | 117 | 26 | 1 | 6 | 4057 | 678.80 | 23.92 |
| | Contractors | 7582 | 6703 | 3632 | 3808 | 4144 | 830 | 111 | 20 | 2 | 2 | 0 | 26834 | 238.42 | 10.97 |
| | Total | 8596 | 7427 | 4070 | 4350 | 4755 | 1150 | 369 | 137 | 28 | 3 | 6 | 30891 | 678.80 | 12.68 |
| 201103-201312 | TEPCO | 1013 | 736 | 437 | 546 | 613 | 322 | 259 | 117 | 26 | 1 | 6 | 4076 | 678.80 | 23.93 |
| | Contractors | 7678 | 6824 | 3681 | 3895 | 4214 | 858 | 116 | 20 | 2 | 2 | 0 | 27290 | 238.42 | 11.03 |
| | Total | 8691 | 7560 | 4118 | 4441 | 4827 | 1180 | 375 | 137 | 28 | 3 | 6 | 31366 | 678.80 | 12.70 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 201103-201401 | TEPCO | 1005 | 751 | 439 | 548 | 616 | 321 | 262 | 117 | 26 | 1 | 6 | 4092 | 678.80 | 23.93 |
| | Contractors | 7884 | 6959 | 3783 | 3965 | 4310 | 882 | 123 | 20 | 2 | 2 | 0 | 27930 | 238.42 | 11.02 |
| | Total | 8889 | 7710 | 4222 | 4513 | 4926 | 1203 | 385 | 137 | 28 | 3 | 6 | 32022 | 678.80 | 12.67 |
| 201103-201402 | TEPCO | 1013 | 753 | 446 | 547 | 620 | 319 | 265 | 117 | 26 | 1 | 6 | 4113 | 678.80 | 23.90 |
| | Contractors | 8030 | 7085 | 3804 | 4078 | 4384 | 913 | 125 | 20 | 2 | 2 | 0 | 28443 | 238.42 | 11.05 |
| | Total | 9043 | 7838 | 4250 | 4625 | 5004 | 1232 | 390 | 137 | 28 | 3 | 6 | 32556 | 678.80 | 12.67 |
| 201103-201403 | TEPCO | 1015 | 752 | 452 | 553 | 618 | 319 | 269 | 117 | 26 | 1 | 6 | 4128 | 678.80 | 23.91 |
| | Contractors | 8250 | 7250 | 3899 | 4179 | 4459 | 948 | 131 | 20 | 2 | 2 | 0 | 29140 | 238.42 | 11.05 |
| | Total | 9265 | 8002 | 4351 | 4732 | 5077 | 1267 | 400 | 137 | 28 | 3 | 6 | 33268 | 678.80 | 12.64 |
| 201103-201404 | TEPCO | 1025 | 753 | 467 | 558 | 612 | 323 | 273 | 117 | 26 | 1 | 6 | 4161 | 678.80 | 23.82 |
| | Contractors | 8671 | 7476 | 3969 | 4229 | 4565 | 978 | 137 | 20 | 2 | 2 | 0 | 30049 | 238.42 | 10.95 |
| | Total | 9696 | 8229 | 4436 | 4787 | 5177 | 1301 | 410 | 137 | 28 | 3 | 6 | 34210 | 678.80 | 12.52 |
| 201103-201405 | TEPCO | 1043 | 760 | 469 | 565 | 613 | 321 | 276 | 117 | 26 | 1 | 6 | 4197 | 678.80 | 23.70 |
| | Contractors | 9079 | 7752 | 4040 | 4281 | 4673 | 1012 | 140 | 20 | 2 | 2 | 0 | 31001 | 238.42 | 10.87 |
| | Total | 10122 | 8512 | 4509 | 4846 | 5286 | 1333 | 416 | 137 | 28 | 3 | 6 | 35198 | 678.80 | 12.39 |
| 201103-201406 | TEPCO | 1050 | 764 | 472 | 566 | 617 | 322 | 278 | 117 | 26 | 1 | 6 | 4219 | 678.80 | 23.66 |
| | Contractors | 9485 | 7929 | 4233 | 4344 | 4756 | 1051 | 147 | 20 | 2 | 2 | 0 | 31969 | 238.42 | 10.80 |
| | Total | 10535 | 8693 | 4705 | 4910 | 5373 | 1373 | 425 | 137 | 28 | 3 | 6 | 36188 | 678.80 | 12.30 |
| 201103-201407 | TEPCO | 1095 | 775 | 469 | 572 | 620 | 321 | 279 | 117 | 26 | 1 | 6 | 4281 | 678.80 | 23.39 |
| | Contractors | 9892 | 8077 | 4296 | 4485 | 4844 | 1078 | 157 | 20 | 2 | 2 | 0 | 32853 | 238.42 | 10.76 |
| | Total | 10987 | 8852 | 4765 | 5057 | 5464 | 1399 | 436 | 137 | 28 | 3 | 6 | 37134 | 678.80 | 12.22 |
| 201103-201408 | TEPCO | 1097 | 783 | 473 | 570 | 623 | 320 | 282 | 117 | 26 | 1 | 6 | 4298 | 678.80 | 23.36 |
| | Contractors | 10125 | 8148 | 4410 | 4539 | 4933 | 1104 | 162 | 20 | 2 | 2 | 0 | 33445 | 238.42 | 10.77 |
| | Total | 11222 | 8931 | 4883 | 5109 | 5556 | 1424 | 444 | 137 | 28 | 3 | 6 | 37743 | 678.80 | 12.21 |
| 201103-201409 | TEPCO | 1107 | 788 | 481 | 570 | 624 | 321 | 283 | 117 | 26 | 1 | 6 | 4324 | 678.80 | 23.29 |
| | Contractors | 10421 | 8283 | 4464 | 4671 | 5055 | 1136 | 165 | 20 | 2 | 2 | 0 | 34219 | 238.42 | 10.77 |
| | Total | 11528 | 9071 | 4945 | 5241 | 5679 | 1457 | 448 | 137 | 28 | 3 | 6 | 38543 | 678.80 | 12.18 |
| 201103-201410 | TEPCO | 1111 | 796 | 484 | 575 | 626 | 322 | 285 | 117 | 26 | 1 | 6 | 4349 | 678.80 | 23.23 |
| | Contractors | 10637 | 8461 | 4522 | 4729 | 5158 | 1179 | 168 | 20 | 2 | 2 | 0 | 34878 | 238.42 | 10.80 |
| | Total | 11748 | 9257 | 5006 | 5304 | 5784 | 1501 | 453 | 137 | 28 | 3 | 6 | 39227 | 678.80 | 12.18 |
| 201103-201411 | TEPCO | 1111 | 805 | 484 | 579 | 621 | 325 | 287 | 117 | 26 | 1 | 6 | 4362 | 678.80 | 23.22 |
| | Contractors | 10941 | 8560 | 4586 | 4868 | 5242 | 1218 | 171 | 20 | 2 | 2 | 0 | 35610 | 238.42 | 10.80 |
| | Total | 12052 | 9365 | 5070 | 5447 | 5863 | 1543 | 458 | 137 | 28 | 3 | 6 | 39972 | 678.80 | 12.15 |
| 201103-201412 | TEPCO | 1132 | 805 | 489 | 581 | 617 | 328 | 290 | 117 | 26 | 1 | 6 | 4392 | 678.80 | 23.12 |
| | Contractors | 11078 | 8742 | 4671 | 4958 | 5357 | 1256 | 177 | 20 | 2 | 2 | 0 | 36263 | 238.42 | 10.85 |
| | Total | 12210 | 9547 | 5160 | 5539 | 5974 | 1584 | 467 | 137 | 28 | 3 | 6 | 40655 | 678.80 | 12.18 |
| 201103-201501 | TEPCO | 1136 | 811 | 494 | 581 | 617 | 330 | 290 | 117 | 26 | 1 | 6 | 4409 | 678.80 | 23.09 |
| | Contractors | 11322 | 8886 | 4721 | 4989 | 5444 | 1284 | 178 | 20 | 2 | 2 | 0 | 36848 | 238.42 | 10.83 |
| | Total | 12458 | 9697 | 5215 | 5570 | 6061 | 1614 | 468 | 137 | 28 | 3 | 6 | 41257 | 678.80 | 12.14 |
| 201103-201502 | TEPCO | 1128 | 820 | 494 | 590 | 619 | 329 | 292 | 117 | 26 | 1 | 6 | 4422 | 678.80 | 23.11 |
| | Contractors | 11452 | 9162 | 4924 | 5047 | 5565 | 1322 | 184 | 20 | 2 | 2 | 0 | 37680 | 238.42 | 10.85 |
| | Total | 12580 | 9982 | 5418 | 5637 | 6184 | 1651 | 476 | 137 | 28 | 3 | 6 | 42102 | 678.80 | 12.14 |
| 201103-201503 | TEPCO | 1117 | 828 | 494 | 596 | 620 | 331 | 293 | 117 | 26 | 1 | 6 | 4429 | 678.80 | 23.16 |
| | Contractors | 11475 | 9059 | 5008 | 5385 | 5704 | 1361 | 198 | 20 | 2 | 2 | 0 | 38214 | 238.42 | 11.06 |
| | Total | 12592 | 9887 | 5502 | 5981 | 6324 | 1692 | 491 | 137 | 28 | 3 | 6 | 42643 | 678.80 | 12.31 |
| 201103-201504 | TEPCO | 1146 | 837 | 496 | 597 | 621 | 333 | 295 | 117 | 26 | 1 | 6 | 4475 | 678.80 | 22.99 |
| | Contractors | 11630 | 9075 | 5081 | 5457 | 5855 | 1398 | 206 | 20 | 2 | 2 | 0 | 38726 | 238.42 | 11.16 |
| | Total | 12776 | 9912 | 5577 | 6054 | 6476 | 1731 | 501 | 137 | 28 | 3 | 6 | 43201 | 678.80 | 12.39 |
| 201103-201505 | TEPCO | 1149 | 840 | 492 | 603 | 620 | 333 | 298 | 117 | 26 | 1 | 6 | 4485 | 678.80 | 22.99 |
| | Contractors | 11793 | 9141 | 5091 | 5471 | 5968 | 1431 | 208 | 20 | 2 | 2 | 0 | 39127 | 238.42 | 11.21 |
| | Total | 12942 | 9981 | 5583 | 6074 | 6588 | 1764 | 506 | 137 | 28 | 3 | 6 | 43612 | 678.80 | 12.42 |
| 201103-201506 | TEPCO | 1148 | 836 | 494 | 605 | 627 | 331 | 301 | 117 | 26 | 1 | 6 | 4492 | 678.80 | 23.02 |
| | Contractors | 11914 | 9230 | 5140 | 5510 | 6032 | 1476 | 217 | 20 | 2 | 2 | 0 | 39543 | 238.42 | 11.28 |
| | Total | 13062 | 10066 | 5634 | 6115 | 6659 | 1807 | 518 | 137 | 28 | 3 | 6 | 44035 | 678.80 | 12.48 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 201103-201507 | TEPCO | 1228 | 837 | 498 | 605 | 628 | 335 | 301 | 117 | 26 | 1 | 6 | 4582 | 678.80 | 22.63 |
| | Contractors | 12113 | 9258 | 5197 | 5526 | 6112 | 1515 | 221 | 20 | 2 | 2 | 0 | 39966 | 238.42 | 11.32 |
| | Total | 13341 | 10095 | 5695 | 6131 | 6740 | 1850 | 522 | 137 | 28 | 3 | 6 | 44548 | 678.80 | 12.49 |
| 201103-201508 | TEPCO | 1237 | 843 | 496 | 611 | 627 | 335 | 302 | 117 | 26 | 1 | 6 | 4601 | 678.80 | 22.59 |
| | Contractors | 12256 | 9308 | 5201 | 5554 | 6141 | 1552 | 227 | 20 | 2 | 2 | 0 | 40263 | 238.42 | 11.34 |
| | Total | 13493 | 10151 | 5697 | 6165 | 6768 | 1887 | 529 | 137 | 28 | 3 | 6 | 44864 | 678.80 | 12.50 |
| 201103-201509 | TEPCO | 1265 | 846 | 496 | 612 | 631 | 333 | 305 | 117 | 26 | 1 | 6 | 4638 | 678.80 | 22.47 |
| | Contractors | 12327 | 9401 | 5264 | 5556 | 6201 | 1603 | 239 | 20 | 2 | 2 | 0 | 40615 | 238.42 | 11.41 |
| | Total | 13592 | 10247 | 5760 | 6168 | 6832 | 1936 | 544 | 137 | 28 | 3 | 6 | 45253 | 678.80 | 12.54 |
| 201103-201510 | TEPCO | 1258 | 859 | 495 | 616 | 632 | 331 | 308 | 117 | 26 | 1 | 6 | 4649 | 678.80 | 22.47 |
| | Contractors | 12404 | 9459 | 5298 | 5600 | 6252 | 1656 | 248 | 20 | 2 | 2 | 0 | 40941 | 238.42 | 11.48 |
| | Total | 13662 | 10318 | 5793 | 6216 | 6884 | 1987 | 556 | 137 | 28 | 3 | 6 | 45590 | 678.80 | 12.60 |
| 201103-201511 | TEPCO | 1255 | 873 | 495 | 619 | 632 | 330 | 311 | 117 | 26 | 1 | 6 | 4665 | 678.80 | 22.45 |
| | Contractors | 12482 | 9506 | 5328 | 5639 | 6310 | 1689 | 262 | 20 | 2 | 2 | 0 | 41240 | 238.42 | 11.54 |
| | Total | 13737 | 10379 | 5823 | 6258 | 6942 | 2019 | 573 | 137 | 28 | 3 | 6 | 45905 | 678.80 | 12.65 |
| 201103-201512 | TEPCO | 1259 | 879 | 496 | 621 | 632 | 329 | 314 | 117 | 26 | 1 | 6 | 4680 | 678.80 | 22.43 |
| | Contractors | 12567 | 9543 | 5371 | 5661 | 6358 | 1718 | 273 | 20 | 2 | 2 | 0 | 41515 | 238.42 | 11.59 |
| | Total | 13826 | 10422 | 5867 | 6282 | 6990 | 2047 | 587 | 137 | 28 | 3 | 6 | 46195 | 678.80 | 12.69 |
| 201103-201601 | TEPCO | 1253 | 892 | 497 | 622 | 632 | 328 | 316 | 117 | 26 | 1 | 6 | 4690 | 678.80 | 22.43 |
| | Contractors | 12685 | 9593 | 5403 | 5672 | 6420 | 1743 | 282 | 20 | 2 | 2 | 0 | 41822 | 238.42 | 11.62 |
| | Total | 13938 | 10485 | 5900 | 6294 | 7052 | 2071 | 598 | 137 | 28 | 3 | 6 | 46512 | 678.80 | 12.71 |
| 201103-201602 | TEPCO | 1252 | 898 | 508 | 618 | 633 | 329 | 318 | 117 | 26 | 1 | 6 | 4706 | 678.80 | 22.41 |
| | Contractors | 12720 | 9602 | 5467 | 5711 | 6471 | 1772 | 296 | 20 | 2 | 2 | 0 | 42063 | 238.42 | 11.68 |
| | Total | 13972 | 10500 | 5975 | 6329 | 7104 | 2101 | 614 | 137 | 28 | 3 | 6 | 46769 | 678.80 | 12.76 |
| 201103-201603 | TEPCO | 1246 | 908 | 507 | 619 | 633 | 328 | 321 | 117 | 26 | 1 | 6 | 4712 | 678.80 | 22.43 |
| | Contractors | 12759 | 9617 | 5439 | 5798 | 6515 | 1798 | 315 | 20 | 2 | 2 | 0 | 42265 | 238.42 | 11.76 |
| | Total | 14005 | 10525 | 5946 | 6417 | 7148 | 2126 | 636 | 137 | 28 | 3 | 6 | 46977 | 678.80 | 12.83 |

Note)

• The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

• The record months of the internal exposure dose of workers in the data above can be changed, even if the evaluation values of their internal exposure dose have not changed, when their "inhalation exposure days" (the days when they inhaled radioactive materials) are reviewed. In the case that the record months have been changed, that effect will be described.

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 201604-201604 | TEPCO | 1097 | 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1113 | 1.90 | 0.16 |
| | Contractors | 7852 | 870 | 42 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8764 | 9.78 | 0.41 |
| | Total | 8949 | 886 | 42 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9877 | 9.78 | 0.38 |
| 201604-201605 | TEPCO | 1139 | 61 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1200 | 3.20 | 0.28 |
| | Contractors | 7904 | 1430 | 126 | 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9482 | 19.28 | 0.67 |
| | Total | 9043 | 1491 | 126 | 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 10682 | 19.28 | 0.63 |
| 201604-201606 | TEPCO | 1164 | 142 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1306 | 4.90 | 0.40 |
| | Contractors | 7891 | 2014 | 328 | 61 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 10300 | 32.46 | 0.97 |
| | Total | 9055 | 2156 | 328 | 61 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 11606 | 32.46 | 0.91 |
| 201604-201607 | TEPCO | 1254 | 182 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1440 | 6.22 | 0.46 |
| | Contractors | 7732 | 2477 | 465 | 155 | 15 | 0 | 0 | 0 | 0 | 0 | 0 | 10844 | 33.36 | 1.26 |
| | Total | 8986 | 2659 | 469 | 155 | 15 | 0 | 0 | 0 | 0 | 0 | 0 | 12284 | 33.36 | 1.16 |
| 201604-201608 | TEPCO | 1249 | 232 | 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1493 | 9.19 | 0.57 |
| | Contractors | 7679 | 2836 | 572 | 208 | 25 | 0 | 0 | 0 | 0 | 0 | 0 | 11320 | 35.81 | 1.41 |
| | Total | 8928 | 3068 | 584 | 208 | 25 | 0 | 0 | 0 | 0 | 0 | 0 | 12813 | 35.81 | 1.31 |
| 201604-201609 | TEPCO | 1272 | 259 | 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1547 | 9.51 | 0.66 |
| | Contractors | 7476 | 3363 | 662 | 293 | 32 | 0 | 0 | 0 | 0 | 0 | 0 | 11826 | 36.21 | 1.61 |
| | Total | 8748 | 3622 | 678 | 293 | 32 | 0 | 0 | 0 | 0 | 0 | 0 | 13373 | 36.21 | 1.50 |
| 201604-201610 | TEPCO | 1256 | 288 | 27 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1573 | 11.20 | 0.76 |
| | Contractors | 7306 | 3718 | 808 | 380 | 53 | 0 | 0 | 0 | 0 | 0 | 0 | 12265 | 36.21 | 1.85 |
| | Total | 8562 | 4006 | 835 | 382 | 53 | 0 | 0 | 0 | 0 | 0 | 0 | 13838 | 36.21 | 1.73 |
| 201604-201611 | TEPCO | 1252 | 307 | 42 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1605 | 11.21 | 0.85 |
| | Contractors | 7298 | 3876 | 963 | 499 | 78 | 0 | 0 | 0 | 0 | 0 | 0 | 12714 | 38.76 | 2.10 |
| | Total | 8550 | 4183 | 1005 | 503 | 78 | 0 | 0 | 0 | 0 | 0 | 0 | 14319 | 38.76 | 1.96 |
| 201604-201612 | TEPCO | 1219 | 342 | 54 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1621 | 11.71 | 0.96 |
| | Contractors | 7247 | 3964 | 1076 | 631 | 93 | 0 | 0 | 0 | 0 | 0 | 0 | 13011 | 38.83 | 2.32 |
| | Total | 8466 | 4306 | 1130 | 637 | 93 | 0 | 0 | 0 | 0 | 0 | 0 | 14632 | 38.83 | 2.17 |
| 201604-201701 | TEPCO | 1194 | 376 | 62 | 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1643 | 11.91 | 1.05 |
| | Contractors | 7164 | 4152 | 1179 | 770 | 114 | 0 | 0 | 0 | 0 | 0 | 0 | 13379 | 38.83 | 2.52 |
| | Total | 8358 | 4528 | 1241 | 781 | 114 | 0 | 0 | 0 | 0 | 0 | 0 | 15022 | 38.83 | 2.36 |
| 201604-201702 | TEPCO | 1188 | 395 | 74 | 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1671 | 12.83 | 1.15 |
| | Contractors | 7033 | 4397 | 1288 | 941 | 154 | 0 | 0 | 0 | 0 | 0 | 0 | 13813 | 38.83 | 2.78 |
| | Total | 8221 | 4792 | 1362 | 955 | 154 | 0 | 0 | 0 | 0 | 0 | 0 | 15484 | 38.83 | 2.60 |
| 201604-201703 | TEPCO | 1162 | 404 | 90 | 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1678 | 14.75 | 1.27 |
| | Contractors | 7038 | 4371 | 1393 | 1139 | 216 | 0 | 0 | 0 | 0 | 0 | 0 | 14157 | 38.83 | 3.09 |
| | Total | 8200 | 4775 | 1483 | 1161 | 216 | 0 | 0 | 0 | 0 | 0 | 0 | 15835 | 38.83 | 2.90 |
| 201604-201704 | TEPCO | 1154 | 411 | 102 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1693 | 15.75 | 1.36 |
| | Contractors | 7162 | 4402 | 1436 | 1224 | 287 | 0 | 0 | 0 | 0 | 0 | 0 | 14511 | 41.81 | 3.28 |
| | Total | 8316 | 4813 | 1538 | 1250 | 287 | 0 | 0 | 0 | 0 | 0 | 0 | 16204 | 41.81 | 3.08 |
| 201604-201705 | TEPCO | 1138 | 428 | 102 | 34 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1702 | 16.35 | 1.43 |
| | Contractors | 7183 | 4467 | 1487 | 1266 | 354 | 0 | 0 | 0 | 0 | 0 | 0 | 14757 | 47.67 | 3.43 |
| | Total | 8321 | 4895 | 1589 | 1300 | 354 | 0 | 0 | 0 | 0 | 0 | 0 | 16459 | 47.67 | 3.23 |
| 201604-201706 | TEPCO | 1125 | 440 | 106 | 41 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1712 | 16.95 | 1.52 |
| | Contractors | 7305 | 4517 | 1535 | 1323 | 433 | 1 | 0 | 0 | 0 | 0 | 0 | 15114 | 50.23 | 3.60 |
| | Total | 8430 | 4957 | 1641 | 1364 | 433 | 1 | 0 | 0 | 0 | 0 | 0 | 16826 | 50.23 | 3.39 |
| 201604-201707 | TEPCO | 1170 | 456 | 109 | 48 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1783 | 17.75 | 1.53 |
| | Contractors | 7374 | 4540 | 1582 | 1364 | 507 | 4 | 0 | 0 | 0 | 0 | 0 | 15371 | 52.19 | 3.76 |
| | Total | 8544 | 4996 | 1691 | 1412 | 507 | 4 | 0 | 0 | 0 | 0 | 0 | 17154 | 52.19 | 3.53 |
| 201604-201708 | TEPCO | 1175 | 460 | 116 | 53 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1804 | 18.55 | 1.59 |
| | Contractors | 7473 | 4515 | 1637 | 1381 | 565 | 6 | 0 | 0 | 0 | 0 | 0 | 15577 | 53.46 | 3.87 |
| | Total | 8648 | 4975 | 1753 | 1434 | 565 | 6 | 0 | 0 | 0 | 0 | 0 | 17381 | 53.46 | 3.63 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 201604-201709 | TEPCO | 1208 | 463 | 127 | 54 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1852 | 19.21 | 1.61 |
| | Contractors | 7565 | 4525 | 1695 | 1403 | 612 | 7 | 0 | 0 | 0 | 0 | 0 | 15807 | 55.56 | 3.97 |
| | Total | 8773 | 4988 | 1822 | 1457 | 612 | 7 | 0 | 0 | 0 | 0 | 0 | 17659 | 55.56 | 3.72 |
| 201604-201710 | TEPCO | 1224 | 466 | 125 | 64 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1880 | 20.41 | 1.66 |
| | Contractors | 7654 | 4539 | 1755 | 1449 | 661 | 8 | 0 | 0 | 0 | 0 | 0 | 16066 | 57.51 | 4.08 |
| | Total | 8878 | 5005 | 1880 | 1513 | 662 | 8 | 0 | 0 | 0 | 0 | 0 | 17946 | 57.51 | 3.83 |
| 201604-201711 | TEPCO | 1225 | 460 | 129 | 70 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1886 | 22.38 | 1.72 |
| | Contractors | 7761 | 4511 | 1771 | 1516 | 718 | 11 | 0 | 0 | 0 | 0 | 0 | 16288 | 58.94 | 4.20 |
| | Total | 8986 | 4971 | 1900 | 1586 | 720 | 11 | 0 | 0 | 0 | 0 | 0 | 18174 | 58.94 | 3.94 |
| 201604-201712 | TEPCO | 1212 | 474 | 128 | 77 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1893 | 22.88 | 1.79 |
| | Contractors | 7796 | 4517 | 1815 | 1543 | 771 | 13 | 0 | 0 | 0 | 0 | 0 | 16455 | 60.44 | 4.30 |
| | Total | 9008 | 4991 | 1943 | 1620 | 773 | 13 | 0 | 0 | 0 | 0 | 0 | 18348 | 60.44 | 4.04 |
| 201604-201801 | TEPCO | 1208 | 477 | 124 | 86 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 1899 | 23.35 | 1.85 |
| | Contractors | 7839 | 4508 | 1869 | 1581 | 823 | 13 | 0 | 0 | 0 | 0 | 0 | 16633 | 61.95 | 4.40 |
| | Total | 9047 | 4985 | 1993 | 1667 | 827 | 13 | 0 | 0 | 0 | 0 | 0 | 18532 | 61.95 | 4.14 |
| 201604-201802 | TEPCO | 1185 | 496 | 126 | 92 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 1906 | 23.65 | 1.95 |
| | Contractors | 7868 | 4492 | 1893 | 1658 | 879 | 16 | 0 | 0 | 0 | 0 | 0 | 16806 | 63.63 | 4.54 |
| | Total | 9053 | 4988 | 2019 | 1750 | 886 | 16 | 0 | 0 | 0 | 0 | 0 | 18712 | 63.63 | 4.28 |
| 201604-201803 | TEPCO | 1180 | 491 | 142 | 95 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 1916 | 24.05 | 2.03 |
| | Contractors | 7944 | 4446 | 1924 | 1747 | 928 | 23 | 0 | 0 | 0 | 0 | 0 | 17012 | 68.50 | 4.68 |
| | Total | 9124 | 4937 | 2066 | 1842 | 936 | 23 | 0 | 0 | 0 | 0 | 0 | 18928 | 68.50 | 4.41 |
| 201604-201804 | TEPCO | 1183 | 494 | 145 | 98 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 1928 | 24.55 | 2.07 |
| | Contractors | 8038 | 4445 | 1941 | 1760 | 970 | 31 | 0 | 0 | 0 | 0 | 0 | 17185 | 70.76 | 4.75 |
| | Total | 9221 | 4939 | 2086 | 1858 | 978 | 31 | 0 | 0 | 0 | 0 | 0 | 19113 | 70.76 | 4.48 |
| 201604-201805 | TEPCO | 1185 | 496 | 146 | 101 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 1937 | 24.96 | 2.12 |
| | Contractors | 8096 | 4456 | 1957 | 1769 | 1012 | 35 | 0 | 0 | 0 | 0 | 0 | 17325 | 71.80 | 4.82 |
| | Total | 9281 | 4952 | 2103 | 1870 | 1021 | 35 | 0 | 0 | 0 | 0 | 0 | 19262 | 71.80 | 4.55 |
| 201604-201806 | TEPCO | 1183 | 499 | 147 | 106 | 10 | 0 | 0 | 0 | 0 | 0 | 0 | 1945 | 25.98 | 2.18 |
| | Contractors | 8139 | 4443 | 1980 | 1784 | 1052 | 38 | 0 | 0 | 0 | 0 | 0 | 17436 | 74.08 | 4.90 |
| | Total | 9322 | 4942 | 2127 | 1890 | 1062 | 38 | 0 | 0 | 0 | 0 | 0 | 19381 | 74.08 | 4.63 |
| 201604-201807 | TEPCO | 1211 | 502 | 147 | 110 | 11 | 0 | 0 | 0 | 0 | 0 | 0 | 1981 | 26.71 | 2.20 |
| | Contractors | 8214 | 4442 | 2008 | 1784 | 1104 | 39 | 1 | 0 | 0 | 0 | 0 | 17592 | 75.27 | 4.98 |
| | Total | 9425 | 4944 | 2155 | 1894 | 1115 | 39 | 1 | 0 | 0 | 0 | 0 | 19573 | 75.27 | 4.70 |
| 201604-201808 | TEPCO | 1263 | 507 | 148 | 113 | 14 | 0 | 0 | 0 | 0 | 0 | 0 | 2045 | 27.48 | 2.19 |
| | Contractors | 8252 | 4448 | 2022 | 1810 | 1136 | 44 | 1 | 0 | 0 | 0 | 0 | 17713 | 75.50 | 5.04 |
| | Total | 9515 | 4955 | 2170 | 1923 | 1150 | 44 | 1 | 0 | 0 | 0 | 0 | 19758 | 75.50 | 4.75 |
| 201604-201809 | TEPCO | 1273 | 503 | 156 | 117 | 14 | 0 | 0 | 0 | 0 | 0 | 0 | 2063 | 28.48 | 2.23 |
| | Contractors | 8287 | 4453 | 2043 | 1844 | 1166 | 48 | 1 | 0 | 0 | 0 | 0 | 17842 | 75.50 | 5.11 |
| | Total | 9560 | 4956 | 2199 | 1961 | 1180 | 48 | 1 | 0 | 0 | 0 | 0 | 19905 | 75.50 | 4.81 |
| 201604-201810 | TEPCO | 1266 | 508 | 159 | 117 | 20 | 0 | 0 | 0 | 0 | 0 | 0 | 2070 | 30.68 | 2.29 |
| | Contractors | 8349 | 4464 | 2076 | 1869 | 1198 | 53 | 1 | 0 | 0 | 0 | 0 | 18010 | 75.50 | 5.18 |
| | Total | 9615 | 4972 | 2235 | 1986 | 1218 | 53 | 1 | 0 | 0 | 0 | 0 | 20080 | 75.50 | 4.88 |
| 201604-201811 | TEPCO | 1252 | 519 | 164 | 119 | 22 | 0 | 0 | 0 | 0 | 0 | 0 | 2076 | 31.48 | 2.34 |
| | Contractors | 8415 | 4444 | 2113 | 1897 | 1239 | 59 | 1 | 0 | 0 | 0 | 0 | 18168 | 75.50 | 5.27 |
| | Total | 9667 | 4963 | 2277 | 2016 | 1261 | 59 | 1 | 0 | 0 | 0 | 0 | 20244 | 75.50 | 4.97 |
| 201604-201812 | TEPCO | 1253 | 521 | 171 | 118 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 2089 | 32.48 | 2.38 |
| | Contractors | 8443 | 4448 | 2144 | 1931 | 1273 | 64 | 4 | 0 | 0 | 0 | 0 | 18307 | 75.68 | 5.37 |
| | Total | 9696 | 4969 | 2315 | 2049 | 1299 | 64 | 4 | 0 | 0 | 0 | 0 | 20396 | 75.68 | 5.06 |
| 201604-201901 | TEPCO | 1251 | 527 | 174 | 118 | 29 | 0 | 0 | 0 | 0 | 0 | 0 | 2099 | 34.11 | 2.42 |
| | Contractors | 8467 | 4428 | 2164 | 1977 | 1310 | 65 | 5 | 0 | 0 | 0 | 0 | 18416 | 77.27 | 5.46 |
| | Total | 9718 | 4955 | 2338 | 2095 | 1339 | 65 | 5 | 0 | 0 | 0 | 0 | 20515 | 77.27 | 5.15 |
| 201604-201902 | TEPCO | 1247 | 530 | 172 | 124 | 33 | 0 | 0 | 0 | 0 | 0 | 0 | 2106 | 34.21 | 2.48 |
| | Contractors | 8491 | 4443 | 2157 | 2041 | 1348 | 70 | 6 | 0 | 0 | 0 | 0 | 18556 | 79.90 | 5.57 |
| | Total | 9738 | 4973 | 2329 | 2165 | 1381 | 70 | 6 | 0 | 0 | 0 | 0 | 20662 | 79.90 | 5.25 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 201604-201903 | TEPCO | 1238 | 534 | 172 | 129 | 35 | 0 | 0 | 0 | 0 | 0 | 0 | 2108 | 35.21 | 2.55 |
| | Contractors | 8513 | 4445 | 2185 | 2068 | 1377 | 81 | 6 | 0 | 0 | 0 | 0 | 18675 | 79.90 | 5.66 |
| | Total | 9751 | 4979 | 2357 | 2197 | 1412 | 81 | 6 | 0 | 0 | 0 | 0 | 20783 | 79.90 | 5.34 |
| 201604-201904 | TEPCO | 1253 | 538 | 170 | 132 | 36 | 0 | 0 | 0 | 0 | 0 | 0 | 2129 | 35.81 | 2.59 |
| | Contractors | 8568 | 4447 | 2193 | 2070 | 1413 | 91 | 6 | 0 | 0 | 0 | 0 | 18788 | 79.90 | 5.71 |
| | Total | 9821 | 4985 | 2363 | 2202 | 1449 | 91 | 6 | 0 | 0 | 0 | 0 | 20917 | 79.90 | 5.40 |
| 201604-201905 | TEPCO | 1249 | 543 | 171 | 134 | 38 | 0 | 0 | 0 | 0 | 0 | 0 | 2135 | 36.51 | 2.64 |
| | Contractors | 8654 | 4457 | 2198 | 2074 | 1451 | 100 | 6 | 0 | 0 | 0 | 0 | 18940 | 79.90 | 5.76 |
| | Total | 9903 | 5000 | 2369 | 2208 | 1489 | 100 | 6 | 0 | 0 | 0 | 0 | 21075 | 79.90 | 5.45 |
| 201604-201906 | TEPCO | 1286 | 549 | 171 | 138 | 39 | 0 | 0 | 0 | 0 | 0 | 0 | 2183 | 36.91 | 2.64 |
| | Contractors | 8708 | 4478 | 2209 | 2093 | 1479 | 105 | 6 | 0 | 0 | 0 | 0 | 19078 | 79.90 | 5.82 |
| | Total | 9994 | 5027 | 2380 | 2231 | 1518 | 105 | 6 | 0 | 0 | 0 | 0 | 21261 | 79.90 | 5.50 |
| 201604-201907 | TEPCO | 1307 | 560 | 171 | 138 | 41 | 0 | 0 | 0 | 0 | 0 | 0 | 2217 | 38.14 | 2.66 |
| | Contractors | 8801 | 4485 | 2224 | 2106 | 1509 | 112 | 7 | 0 | 0 | 0 | 0 | 19244 | 79.90 | 5.88 |
| | Total | 10108 | 5045 | 2395 | 2244 | 1550 | 112 | 7 | 0 | 0 | 0 | 0 | 21461 | 79.90 | 5.54 |
| 201604-201908 | TEPCO | 1325 | 558 | 176 | 135 | 45 | 0 | 0 | 0 | 0 | 0 | 0 | 2239 | 39.17 | 2.68 |
| | Contractors | 8855 | 4496 | 2231 | 2129 | 1517 | 128 | 9 | 0 | 0 | 0 | 0 | 19365 | 79.90 | 5.92 |
| | Total | 10180 | 5054 | 2407 | 2264 | 1562 | 128 | 9 | 0 | 0 | 0 | 0 | 21604 | 79.90 | 5.59 |
| 201604-201909 | TEPCO | 1328 | 557 | 175 | 137 | 48 | 0 | 0 | 0 | 0 | 0 | 0 | 2245 | 41.10 | 2.71 |
| | Contractors | 8937 | 4515 | 2242 | 2144 | 1547 | 140 | 9 | 0 | 0 | 0 | 0 | 19534 | 79.90 | 5.98 |
| | Total | 10265 | 5072 | 2417 | 2281 | 1595 | 140 | 9 | 0 | 0 | 0 | 0 | 21779 | 79.90 | 5.64 |
| 201604-201910 | TEPCO | 1325 | 564 | 179 | 133 | 53 | 0 | 0 | 0 | 0 | 0 | 0 | 2254 | 41.28 | 2.75 |
| | Contractors | 9028 | 4513 | 2278 | 2155 | 1570 | 157 | 9 | 0 | 0 | 0 | 0 | 19710 | 79.90 | 6.04 |
| | Total | 10353 | 5077 | 2457 | 2288 | 1623 | 157 | 9 | 0 | 0 | 0 | 0 | 21964 | 79.90 | 5.70 |
| 201604-201911 | TEPCO | 1323 | 569 | 182 | 134 | 57 | 0 | 0 | 0 | 0 | 0 | 0 | 2265 | 42.60 | 2.80 |
| | Contractors | 9146 | 4535 | 2301 | 2169 | 1604 | 164 | 10 | 0 | 0 | 0 | 0 | 19929 | 79.90 | 6.07 |
| | Total | 10469 | 5104 | 2483 | 2303 | 1661 | 164 | 10 | 0 | 0 | 0 | 0 | 22194 | 79.90 | 5.74 |
| 201604-201912 | TEPCO | 1316 | 579 | 185 | 134 | 58 | 0 | 0 | 0 | 0 | 0 | 0 | 2272 | 43.25 | 2.83 |
| | Contractors | 9196 | 4542 | 2329 | 2194 | 1634 | 178 | 11 | 0 | 0 | 0 | 0 | 20084 | 79.90 | 6.14 |
| | Total | 10512 | 5121 | 2514 | 2328 | 1692 | 178 | 11 | 0 | 0 | 0 | 0 | 22356 | 79.90 | 5.81 |
| 201604-202001 | TEPCO | 1311 | 585 | 183 | 137 | 59 | 0 | 0 | 0 | 0 | 0 | 0 | 2275 | 44.58 | 2.87 |
| | Contractors | 9268 | 4523 | 2376 | 2226 | 1663 | 189 | 12 | 0 | 0 | 0 | 0 | 20257 | 79.90 | 6.21 |
| | Total | 10579 | 5108 | 2559 | 2363 | 1722 | 189 | 12 | 0 | 0 | 0 | 0 | 22532 | 79.90 | 5.87 |
| 201604-202002 | TEPCO | 1304 | 592 | 187 | 134 | 63 | 0 | 0 | 0 | 0 | 0 | 0 | 2280 | 45.00 | 2.91 |
| | Contractors | 9328 | 4548 | 2382 | 2278 | 1704 | 207 | 12 | 0 | 0 | 0 | 0 | 20459 | 79.90 | 6.29 |
| | Total | 10632 | 5140 | 2569 | 2412 | 1767 | 207 | 12 | 0 | 0 | 0 | 0 | 22739 | 79.90 | 5.95 |
| 201604-202003 | TEPCO | 1299 | 594 | 182 | 140 | 67 | 0 | 0 | 0 | 0 | 0 | 0 | 2282 | 46.61 | 2.96 |
| | Contractors | 9445 | 4550 | 2375 | 2320 | 1743 | 222 | 13 | 0 | 0 | 0 | 0 | 20668 | 79.90 | 6.36 |
| | Total | 10744 | 5144 | 2557 | 2460 | 1810 | 222 | 13 | 0 | 0 | 0 | 0 | 22950 | 79.90 | 6.02 |
| 201604-202004 | TEPCO | 1295 | 592 | 186 | 144 | 68 | 0 | 0 | 0 | 0 | 0 | 0 | 2285 | 46.82 | 2.99 |
| | Contractors | 9525 | 4564 | 2375 | 2317 | 1772 | 235 | 18 | 0 | 0 | 0 | 0 | 20806 | 80.02 | 6.42 |
| | Total | 10820 | 5156 | 2561 | 2461 | 1840 | 235 | 18 | 0 | 0 | 0 | 0 | 23091 | 80.02 | 6.08 |
| 201604-202005 | TEPCO | 1296 | 592 | 187 | 144 | 69 | 0 | 0 | 0 | 0 | 0 | 0 | 2288 | 46.94 | 3.02 |
| | Contractors | 9607 | 4583 | 2380 | 2310 | 1815 | 242 | 21 | 0 | 0 | 0 | 0 | 20958 | 81.30 | 6.47 |
| | Total | 10903 | 5175 | 2567 | 2454 | 1884 | 242 | 21 | 0 | 0 | 0 | 0 | 23246 | 81.30 | 6.13 |
| 201604-202006 | TEPCO | 1338 | 596 | 192 | 141 | 72 | 0 | 0 | 0 | 0 | 0 | 0 | 2339 | 48.64 | 3.00 |
| | Contractors | 9699 | 4587 | 2454 | 2313 | 1839 | 255 | 23 | 0 | 0 | 0 | 0 | 21170 | 82.70 | 6.53 |
| | Total | 11037 | 5183 | 2646 | 2454 | 1911 | 255 | 23 | 0 | 0 | 0 | 0 | 23509 | 82.70 | 6.17 |
| 201604-202007 | TEPCO | 1350 | 594 | 191 | 144 | 74 | 0 | 0 | 0 | 0 | 0 | 0 | 2353 | 48.84 | 3.03 |
| | Contractors | 9770 | 4599 | 2461 | 2335 | 1861 | 271 | 25 | 0 | 0 | 0 | 0 | 21322 | 85.60 | 6.59 |
| | Total | 11120 | 5193 | 2652 | 2479 | 1935 | 271 | 25 | 0 | 0 | 0 | 0 | 23675 | 85.60 | 6.24 |
| 201604-202008 | TEPCO | 1354 | 594 | 190 | 147 | 75 | 0 | 0 | 0 | 0 | 0 | 0 | 2360 | 49.05 | 3.05 |
| | Contractors | 9833 | 4597 | 2454 | 2339 | 1889 | 279 | 26 | 0 | 0 | 0 | 0 | 21417 | 86.30 | 6.63 |
| | Total | 11187 | 5191 | 2644 | 2486 | 1964 | 279 | 26 | 0 | 0 | 0 | 0 | 23777 | 86.30 | 6.27 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 201604-202009 | TEPCO | 1354 | 593 | 194 | 146 | 79 | 0 | 0 | 0 | 0 | 0 | 0 | 2366 | 49.35 | 3.09 |
| | Contractors | 9913 | 4589 | 2470 | 2341 | 1911 | 286 | 34 | 0 | 0 | 0 | 0 | 21544 | 87.00 | 6.68 |
| | Total | 11267 | 5182 | 2664 | 2487 | 1990 | 286 | 34 | 0 | 0 | 0 | 0 | 23910 | 87.00 | 6.32 |
| 201604-202010 | TEPCO | 1380 | 596 | 195 | 148 | 81 | 1 | 0 | 0 | 0 | 0 | 0 | 2401 | 56.34 | 3.09 |
| | Contractors | 9980 | 4614 | 2478 | 2352 | 1933 | 299 | 38 | 0 | 0 | 0 | 0 | 21694 | 87.30 | 6.73 |
| | Total | 11360 | 5210 | 2673 | 2500 | 2014 | 300 | 38 | 0 | 0 | 0 | 0 | 24095 | 87.30 | 6.36 |
| 201604-202011 | TEPCO | 1400 | 601 | 195 | 150 | 81 | 2 | 0 | 0 | 0 | 0 | 0 | 2429 | 57.81 | 3.10 |
| | Contractors | 10049 | 4653 | 2484 | 2378 | 1961 | 307 | 42 | 0 | 0 | 0 | 0 | 21874 | 87.40 | 6.78 |
| | Total | 11449 | 5254 | 2679 | 2528 | 2042 | 309 | 42 | 0 | 0 | 0 | 0 | 24303 | 87.40 | 6.41 |
| 201604-202012 | TEPCO | 1400 | 610 | 197 | 152 | 83 | 2 | 0 | 0 | 0 | 0 | 0 | 2444 | 58.07 | 3.14 |
| | Contractors | 10141 | 4680 | 2490 | 2411 | 1973 | 314 | 49 | 0 | 0 | 0 | 0 | 22058 | 87.50 | 6.81 |
| | Total | 11541 | 5290 | 2687 | 2563 | 2056 | 316 | 49 | 0 | 0 | 0 | 0 | 24502 | 87.50 | 6.44 |
| 201604-202101 | TEPCO | 1398 | 612 | 197 | 152 | 86 | 2 | 0 | 0 | 0 | 0 | 0 | 2447 | 58.72 | 3.17 |
| | Contractors | 10260 | 4708 | 2492 | 2426 | 2002 | 321 | 50 | 0 | 0 | 0 | 0 | 22259 | 87.80 | 6.84 |
| | Total | 11658 | 5320 | 2689 | 2578 | 2088 | 323 | 50 | 0 | 0 | 0 | 0 | 24706 | 87.80 | 6.47 |
| 201604-202102 | TEPCO | 1403 | 608 | 201 | 154 | 87 | 2 | 0 | 0 | 0 | 0 | 0 | 2455 | 58.89 | 3.21 |
| | Contractors | 10322 | 4750 | 2522 | 2433 | 2025 | 334 | 55 | 0 | 0 | 0 | 0 | 22441 | 88.32 | 6.88 |
| | Total | 11725 | 5358 | 2723 | 2587 | 2112 | 336 | 55 | 0 | 0 | 0 | 0 | 24896 | 88.32 | 6.52 |
| 201604-202103 | TEPCO | 1391 | 613 | 201 | 159 | 90 | 2 | 0 | 0 | 0 | 0 | 0 | 2456 | 59.73 | 3.27 |
| | Contractors | 10345 | 4782 | 2531 | 2451 | 2050 | 350 | 59 | 0 | 0 | 0 | 0 | 22568 | 88.62 | 6.96 |
| | Total | 11736 | 5395 | 2732 | 2610 | 2140 | 352 | 59 | 0 | 0 | 0 | 0 | 25024 | 88.62 | 6.60 |

Note)

• The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

• The record months of the internal exposure dose of workers in the data above can be changed, even if the evaluation values of their internal exposure dose have not changed, when their "inhalation exposure days" (the days when they inhaled radioactive materials) are reviewed. In the case that the record months have been changed, that effect will be described.

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 202104-202104 | TEPCO | 944 | 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 969 | 2.19 | 0.10 |
| | Contractors | 4602 | 366 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4974 | 6.40 | 0.28 |
| | Total | 5546 | 391 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 5943 | 6.40 | 0.25 |
| 202104-202105 | TEPCO | 963 | 59 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1022 | 4.44 | 0.19 |
| | Contractors | 4777 | 740 | 50 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 5568 | 11.10 | 0.51 |
| | Total | 5740 | 799 | 50 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6590 | 11.10 | 0.46 |
| 202104-202106 | TEPCO | 1052 | 89 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1142 | 5.34 | 0.26 |
| | Contractors | 4795 | 1112 | 140 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6073 | 15.28 | 0.79 |
| | Total | 5847 | 1201 | 141 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7215 | 15.28 | 0.71 |
| 202104-202107 | TEPCO | 1066 | 111 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1180 | 6.55 | 0.34 |
| | Contractors | 4792 | 1393 | 230 | 66 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6481 | 16.50 | 1.03 |
| | Total | 5858 | 1504 | 233 | 66 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7661 | 16.50 | 0.92 |
| 202104-202108 | TEPCO | 1069 | 123 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1197 | 6.85 | 0.37 |
| | Contractors | 4749 | 1589 | 311 | 89 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6738 | 16.50 | 1.20 |
| | Total | 5818 | 1712 | 316 | 89 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7935 | 16.50 | 1.07 |
| 202104-202109 | TEPCO | 1066 | 135 | 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1212 | 7.43 | 0.43 |
| | Contractors | 4661 | 1753 | 507 | 143 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7064 | 16.50 | 1.49 |
| | Total | 5727 | 1888 | 518 | 143 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8276 | 16.50 | 1.34 |
| 202104-202110 | TEPCO | 1095 | 154 | 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1266 | 9.39 | 0.48 |
| | Contractors | 4726 | 1850 | 612 | 214 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7402 | 16.90 | 1.69 |
| | Total | 5821 | 2004 | 629 | 214 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8668 | 16.90 | 1.52 |
| 202104-202111 | TEPCO | 1114 | 165 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1305 | 9.79 | 0.54 |
| | Contractors | 4751 | 2056 | 668 | 281 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7756 | 16.94 | 1.88 |
| | Total | 5865 | 2221 | 694 | 281 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9061 | 16.94 | 1.69 |
| 202104-202112 | TEPCO | 1114 | 175 | 40 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1330 | 10.02 | 0.62 |
| | Contractors | 4759 | 2125 | 783 | 367 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8034 | 16.94 | 2.08 |
| | Total | 5873 | 2300 | 823 | 368 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9364 | 16.94 | 1.87 |
| 202104-202201 | TEPCO | 1109 | 179 | 49 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1340 | 10.68 | 0.69 |
| | Contractors | 4768 | 2161 | 850 | 509 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8288 | 17.08 | 2.30 |
| | Total | 5877 | 2340 | 899 | 512 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9628 | 17.08 | 2.08 |
| 202104-202202 | TEPCO | 1098 | 187 | 56 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1346 | 11.60 | 0.76 |
| | Contractors | 4753 | 2242 | 941 | 638 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8574 | 17.26 | 2.54 |
| | Total | 5851 | 2429 | 997 | 643 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9920 | 17.26 | 2.30 |
| 202104-202203 | TEPCO | 1083 | 209 | 59 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1358 | 13.10 | 0.85 |
| | Contractors | 4771 | 2247 | 925 | 836 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8779 | 17.46 | 2.77 |
| | Total | 5854 | 2456 | 984 | 843 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 10137 | 17.46 | 2.51 |
| 202104-202204 | TEPCO | 1066 | 232 | 63 | 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1374 | 15.95 | 0.95 |
| | Contractors | 4935 | 2267 | 949 | 912 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 9066 | 20.71 | 2.85 |
| | Total | 6001 | 2499 | 1012 | 925 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 10440 | 20.71 | 2.60 |
| 202104-202205 | TEPCO | 1062 | 241 | 66 | 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1387 | 16.44 | 1.00 |
| | Contractors | 5115 | 2276 | 964 | 961 | 12 | 0 | 0 | 0 | 0 | 0 | 0 | 9328 | 22.71 | 2.92 |
| | Total | 6177 | 2517 | 1030 | 979 | 12 | 0 | 0 | 0 | 0 | 0 | 0 | 10715 | 22.71 | 2.67 |
| 202104-202206 | TEPCO | 1110 | 244 | 71 | 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1448 | 16.84 | 1.04 |
| | Contractors | 5271 | 2299 | 999 | 1008 | 57 | 0 | 0 | 0 | 0 | 0 | 0 | 9634 | 24.22 | 3.06 |
| | Total | 6381 | 2543 | 1070 | 1031 | 57 | 0 | 0 | 0 | 0 | 0 | 0 | 11082 | 24.22 | 2.79 |
| 202104-202207 | TEPCO | 1130 | 250 | 72 | 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1480 | 17.14 | 1.08 |
| | Contractors | 5403 | 2344 | 1011 | 1058 | 106 | 0 | 0 | 0 | 0 | 0 | 0 | 9922 | 25.93 | 3.16 |
| | Total | 6533 | 2594 | 1083 | 1086 | 106 | 0 | 0 | 0 | 0 | 0 | 0 | 11402 | 25.93 | 2.89 |
| 202104-202208 | TEPCO | 1138 | 257 | 74 | 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1499 | 18.01 | 1.11 |
| | Contractors | 5484 | 2384 | 1051 | 1085 | 128 | 0 | 0 | 0 | 0 | 0 | 0 | 10132 | 26.78 | 3.24 |
| | Total | 6622 | 2641 | 1125 | 1115 | 128 | 0 | 0 | 0 | 0 | 0 | 0 | 11631 | 26.78 | 2.96 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 202104-202209 | TEPCO | 1146 | 265 | 75 | 33 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1519 | 18.31 | 1.16 |
| | Contractors | 5626 | 2429 | 1080 | 1117 | 181 | 0 | 0 | 0 | 0 | 0 | 0 | 10433 | 29.68 | 3.35 |
| | Total | 6772 | 2694 | 1155 | 1150 | 181 | 0 | 0 | 0 | 0 | 0 | 0 | 11952 | 29.68 | 3.07 |
| 202104-202210 | TEPCO | 1137 | 279 | 75 | 35 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1528 | 20.41 | 1.22 |
| | Contractors | 5880 | 2407 | 1136 | 1168 | 213 | 0 | 0 | 0 | 0 | 0 | 0 | 10804 | 32.27 | 3.42 |
| | Total | 7017 | 2686 | 1211 | 1203 | 215 | 0 | 0 | 0 | 0 | 0 | 0 | 12332 | 32.27 | 3.15 |
| 202104-202211 | TEPCO | 1134 | 285 | 82 | 36 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1539 | 21.12 | 1.27 |
| | Contractors | 6021 | 2414 | 1158 | 1229 | 253 | 0 | 0 | 0 | 0 | 0 | 0 | 11075 | 32.82 | 3.55 |
| | Total | 7155 | 2699 | 1240 | 1265 | 255 | 0 | 0 | 0 | 0 | 0 | 0 | 12614 | 32.82 | 3.27 |
| 202104-202212 | TEPCO | 1132 | 288 | 87 | 38 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1547 | 21.12 | 1.32 |
| | Contractors | 6143 | 2420 | 1186 | 1268 | 296 | 0 | 0 | 0 | 0 | 0 | 0 | 11313 | 32.86 | 3.65 |
| | Total | 7275 | 2708 | 1273 | 1306 | 298 | 0 | 0 | 0 | 0 | 0 | 0 | 12860 | 32.86 | 3.37 |
| 202104-202301 | TEPCO | 1132 | 295 | 86 | 40 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1555 | 21.22 | 1.36 |
| | Contractors | 6258 | 2434 | 1206 | 1314 | 322 | 0 | 0 | 0 | 0 | 0 | 0 | 11534 | 33.09 | 3.73 |
| | Total | 7390 | 2729 | 1292 | 1354 | 324 | 0 | 0 | 0 | 0 | 0 | 0 | 13089 | 33.09 | 3.45 |
| 202104-202302 | TEPCO | 1126 | 301 | 90 | 41 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 1561 | 21.32 | 1.41 |
| | Contractors | 6342 | 2449 | 1231 | 1343 | 379 | 0 | 0 | 0 | 0 | 0 | 0 | 11744 | 33.62 | 3.85 |
| | Total | 7468 | 2750 | 1321 | 1384 | 382 | 0 | 0 | 0 | 0 | 0 | 0 | 13305 | 33.62 | 3.56 |
| 202104-202303 | TEPCO | 1127 | 304 | 92 | 43 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 1570 | 21.62 | 1.46 |
| | Contractors | 6474 | 2445 | 1234 | 1380 | 451 | 0 | 0 | 0 | 0 | 0 | 0 | 11984 | 34.22 | 3.97 |
| | Total | 7601 | 2749 | 1326 | 1423 | 455 | 0 | 0 | 0 | 0 | 0 | 0 | 13554 | 34.22 | 3.68 |
| 202104-202304 | TEPCO | 1123 | 307 | 96 | 48 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 1578 | 22.12 | 1.51 |
| | Contractors | 6619 | 2456 | 1229 | 1392 | 529 | 0 | 0 | 0 | 0 | 0 | 0 | 12225 | 39.92 | 4.11 |
| | Total | 7742 | 2763 | 1325 | 1440 | 533 | 0 | 0 | 0 | 0 | 0 | 0 | 13803 | 39.92 | 3.81 |
| 202104-202305 | TEPCO | 1123 | 315 | 98 | 47 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 1589 | 23.51 | 1.53 |
| | Contractors | 6774 | 2443 | 1250 | 1401 | 580 | 0 | 0 | 0 | 0 | 0 | 0 | 12448 | 42.32 | 4.18 |
| | Total | 7897 | 2758 | 1348 | 1448 | 586 | 0 | 0 | 0 | 0 | 0 | 0 | 14037 | 42.32 | 3.88 |
| 202104-202306 | TEPCO | 1175 | 310 | 105 | 47 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 1645 | 23.81 | 1.52 |
| | Contractors | 6880 | 2455 | 1290 | 1402 | 642 | 0 | 0 | 0 | 0 | 0 | 0 | 12669 | 44.52 | 4.30 |
| | Total | 8055 | 2765 | 1395 | 1449 | 650 | 0 | 0 | 0 | 0 | 0 | 0 | 14314 | 44.52 | 3.98 |
| 202104-202307 | TEPCO | 1199 | 313 | 104 | 47 | 11 | 0 | 0 | 0 | 0 | 0 | 0 | 1674 | 24.01 | 1.53 |
| | Contractors | 6994 | 2515 | 1298 | 1421 | 689 | 0 | 0 | 0 | 0 | 0 | 0 | 12917 | 45.32 | 4.38 |
| | Total | 8193 | 2828 | 1402 | 1468 | 700 | 0 | 0 | 0 | 0 | 0 | 0 | 14591 | 45.32 | 4.05 |
| 202104-202308 | TEPCO | 1223 | 315 | 103 | 49 | 11 | 0 | 0 | 0 | 0 | 0 | 0 | 1701 | 24.11 | 1.53 |
| | Contractors | 7085 | 2566 | 1321 | 1429 | 716 | 0 | 0 | 0 | 0 | 0 | 0 | 13117 | 46.62 | 4.42 |
| | Total | 8308 | 2881 | 1424 | 1478 | 727 | 0 | 0 | 0 | 0 | 0 | 0 | 14818 | 46.62 | 4.09 |
| 202104-202309 | TEPCO | 1228 | 328 | 102 | 49 | 13 | 0 | 0 | 0 | 0 | 0 | 0 | 1720 | 24.92 | 1.56 |
| | Contractors | 7210 | 2561 | 1389 | 1442 | 757 | 0 | 0 | 0 | 0 | 0 | 0 | 13359 | 47.41 | 4.50 |
| | Total | 8438 | 2889 | 1491 | 1491 | 770 | 0 | 0 | 0 | 0 | 0 | 0 | 15079 | 47.41 | 4.16 |
| 202104-202310 | TEPCO | 1231 | 332 | 100 | 52 | 13 | 0 | 0 | 0 | 0 | 0 | 0 | 1728 | 27.52 | 1.60 |
| | Contractors | 7362 | 2575 | 1416 | 1498 | 803 | 0 | 0 | 0 | 0 | 0 | 0 | 13654 | 48.72 | 4.58 |
| | Total | 8593 | 2907 | 1516 | 1550 | 816 | 0 | 0 | 0 | 0 | 0 | 0 | 15382 | 48.72 | 4.24 |
| 202104-202311 | TEPCO | 1233 | 336 | 102 | 51 | 16 | 0 | 0 | 0 | 0 | 0 | 0 | 1738 | 28.02 | 1.63 |
| | Contractors | 7475 | 2574 | 1478 | 1536 | 842 | 0 | 0 | 0 | 0 | 0 | 0 | 13905 | 49.82 | 4.66 |
| | Total | 8708 | 2910 | 1580 | 1587 | 858 | 0 | 0 | 0 | 0 | 0 | 0 | 15643 | 49.82 | 4.33 |
| 202104-202312 | TEPCO | 1230 | 343 | 101 | 50 | 19 | 0 | 0 | 0 | 0 | 0 | 0 | 1743 | 29.42 | 1.68 |
| | Contractors | 7565 | 2599 | 1517 | 1575 | 882 | 1 | 0 | 0 | 0 | 0 | 0 | 14139 | 50.52 | 4.75 |
| | Total | 8795 | 2942 | 1618 | 1625 | 901 | 1 | 0 | 0 | 0 | 0 | 0 | 15882 | 50.52 | 4.41 |
| 202104-202401 | TEPCO | 1228 | 347 | 102 | 49 | 21 | 0 | 0 | 0 | 0 | 0 | 0 | 1747 | 30.32 | 1.71 |
| | Contractors | 7628 | 2630 | 1544 | 1593 | 922 | 1 | 0 | 0 | 0 | 0 | 0 | 14318 | 50.62 | 4.80 |
| | Total | 8856 | 2977 | 1646 | 1642 | 943 | 1 | 0 | 0 | 0 | 0 | 0 | 16065 | 50.62 | 4.47 |
| 202104-202402 | TEPCO | 1224 | 351 | 99 | 54 | 21 | 0 | 0 | 0 | 0 | 0 | 0 | 1749 | 30.52 | 1.74 |
| | Contractors | 7728 | 2640 | 1570 | 1648 | 956 | 1 | 0 | 0 | 0 | 0 | 0 | 14543 | 50.72 | 4.87 |
| | Total | 8952 | 2991 | 1669 | 1702 | 977 | 1 | 0 | 0 | 0 | 0 | 0 | 16292 | 50.72 | 4.54 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | 100-150 (mSv) | 150-200 (mSv) | 200-250 (mSv) | Above 250 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|---------------|---------------|---------------|-----------------|----------------------|------------------|---------------|
| 202104-202403 | TEPCO | 1212 | 358 | 106 | 55 | 22 | 0 | 0 | 0 | 0 | 0 | 0 | 1753 | 31.12 | 1.79 |
| | Contractors | 7840 | 2647 | 1576 | 1689 | 993 | 1 | 0 | 0 | 0 | 0 | 0 | 14746 | 50.82 | 4.94 |
| | Total | 9052 | 3005 | 1682 | 1744 | 1015 | 1 | 0 | 0 | 0 | 0 | 0 | 16499 | 50.82 | 4.60 |
| 202104-202404 | TEPCO | 1204 | 364 | 111 | 53 | 25 | 0 | 0 | 0 | 0 | 0 | 0 | 1757 | 31.42 | 1.82 |
| | Contractors | 7970 | 2655 | 1580 | 1713 | 1028 | 2 | 0 | 0 | 0 | 0 | 0 | 14948 | 51.92 | 4.98 |
| | Total | 9174 | 3019 | 1691 | 1766 | 1053 | 2 | 0 | 0 | 0 | 0 | 0 | 16705 | 51.92 | 4.65 |
| 202104-202405 | TEPCO | 1199 | 365 | 117 | 55 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 1762 | 31.52 | 1.86 |
| | Contractors | 8111 | 2683 | 1566 | 1736 | 1063 | 4 | 0 | 0 | 0 | 0 | 0 | 15163 | 53.32 | 5.00 |
| | Total | 9310 | 3048 | 1683 | 1791 | 1089 | 4 | 0 | 0 | 0 | 0 | 0 | 16925 | 53.32 | 4.67 |
| 202104-202406 | TEPCO | 1253 | 364 | 118 | 58 | 27 | 0 | 0 | 0 | 0 | 0 | 0 | 1820 | 31.72 | 1.85 |
| | Contractors | 8237 | 2687 | 1557 | 1751 | 1112 | 14 | 0 | 0 | 0 | 0 | 0 | 15358 | 55.82 | 5.07 |
| | Total | 9490 | 3051 | 1675 | 1809 | 1139 | 14 | 0 | 0 | 0 | 0 | 0 | 17178 | 55.82 | 4.73 |
| 202104-202407 | TEPCO | 1272 | 364 | 121 | 60 | 27 | 0 | 0 | 0 | 0 | 0 | 0 | 1844 | 31.92 | 1.86 |
| | Contractors | 8351 | 2727 | 1581 | 1770 | 1144 | 19 | 0 | 0 | 0 | 0 | 0 | 15592 | 57.52 | 5.12 |
| | Total | 9623 | 3091 | 1702 | 1830 | 1171 | 19 | 0 | 0 | 0 | 0 | 0 | 17436 | 57.52 | 4.78 |
| 202104-202408 | TEPCO | 1294 | 366 | 120 | 64 | 27 | 0 | 0 | 0 | 0 | 0 | 0 | 1871 | 32.12 | 1.87 |
| | Contractors | 8417 | 2744 | 1600 | 1786 | 1155 | 29 | 0 | 0 | 0 | 0 | 0 | 15731 | 58.52 | 5.17 |
| | Total | 9711 | 3110 | 1720 | 1850 | 1182 | 29 | 0 | 0 | 0 | 0 | 0 | 17602 | 58.52 | 4.82 |
| 202104-202409 | TEPCO | 1301 | 366 | 125 | 65 | 27 | 0 | 0 | 0 | 0 | 0 | 0 | 1884 | 32.22 | 1.90 |
| | Contractors | 8502 | 2762 | 1622 | 1795 | 1174 | 40 | 0 | 0 | 0 | 0 | 0 | 15895 | 59.42 | 5.21 |
| | Total | 9803 | 3128 | 1747 | 1860 | 1201 | 40 | 0 | 0 | 0 | 0 | 0 | 17779 | 59.42 | 4.86 |
| 202104-202410 | TEPCO | 1302 | 370 | 126 | 67 | 28 | 0 | 0 | 0 | 0 | 0 | 0 | 1893 | 32.52 | 1.94 |
| | Contractors | 8629 | 2811 | 1667 | 1822 | 1205 | 47 | 0 | 0 | 0 | 0 | 0 | 16181 | 61.02 | 5.27 |
| | Total | 9931 | 3181 | 1793 | 1889 | 1233 | 47 | 0 | 0 | 0 | 0 | 0 | 18074 | 61.02 | 4.92 |
| 202104-202411 | TEPCO | 1305 | 374 | 125 | 69 | 30 | 0 | 0 | 0 | 0 | 0 | 0 | 1903 | 33.32 | 1.98 |
| | Contractors | 8718 | 2842 | 1670 | 1860 | 1217 | 73 | 0 | 0 | 0 | 0 | 0 | 16380 | 62.52 | 5.35 |
| | Total | 10023 | 3216 | 1795 | 1929 | 1247 | 73 | 0 | 0 | 0 | 0 | 0 | 18283 | 62.52 | 5.00 |
| 202104-202412 | TEPCO | 1298 | 379 | 130 | 68 | 31 | 0 | 0 | 0 | 0 | 0 | 0 | 1906 | 34.42 | 2.02 |
| | Contractors | 8828 | 2867 | 1697 | 1899 | 1226 | 88 | 0 | 0 | 0 | 0 | 0 | 16605 | 63.92 | 5.39 |
| | Total | 10126 | 3246 | 1827 | 1967 | 1257 | 88 | 0 | 0 | 0 | 0 | 0 | 18511 | 63.92 | 5.04 |
| 202104-202501 | TEPCO | 1292 | 383 | 136 | 69 | 31 | 0 | 0 | 0 | 0 | 0 | 0 | 1911 | 34.62 | 2.05 |
| | Contractors | 8881 | 2909 | 1721 | 1910 | 1257 | 102 | 0 | 0 | 0 | 0 | 0 | 16780 | 65.32 | 5.45 |
| | Total | 10173 | 3292 | 1857 | 1979 | 1288 | 102 | 0 | 0 | 0 | 0 | 0 | 18691 | 65.32 | 5.10 |
| 202104-202502 | TEPCO | 1295 | 385 | 138 | 70 | 33 | 0 | 0 | 0 | 0 | 0 | 0 | 1921 | 34.92 | 2.07 |
| | Contractors | 8943 | 2920 | 1766 | 1942 | 1299 | 108 | 0 | 0 | 0 | 0 | 0 | 16978 | 66.22 | 5.54 |
| | Total | 10238 | 3305 | 1904 | 2012 | 1332 | 108 | 0 | 0 | 0 | 0 | 0 | 18899 | 66.22 | 5.19 |
| 202104-202503 | TEPCO | 1297 | 379 | 142 | 72 | 35 | 0 | 0 | 0 | 0 | 0 | 0 | 1925 | 35.22 | 2.11 |
| | Contractors | 8997 | 2899 | 1761 | 2003 | 1337 | 118 | 0 | 0 | 0 | 0 | 0 | 17115 | 66.62 | 5.64 |
| | Total | 10294 | 3278 | 1903 | 2075 | 1372 | 118 | 0 | 0 | 0 | 0 | 0 | 19040 | 66.62 | 5.29 |
| 202104-202504 | TEPCO | 1293 | 383 | 143 | 71 | 37 | 0 | 0 | 0 | 0 | 0 | 0 | 1927 | 36.72 | 2.14 |
| | Contractors | 9118 | 2921 | 1759 | 2015 | 1367 | 126 | 0 | 0 | 0 | 0 | 0 | 17306 | 68.12 | 5.69 |
| | Total | 10411 | 3304 | 1902 | 2086 | 1404 | 126 | 0 | 0 | 0 | 0 | 0 | 19233 | 68.12 | 5.33 |
| 202104-202505 | TEPCO | 1292 | 388 | 139 | 74 | 38 | 0 | 0 | 0 | 0 | 0 | 0 | 1931 | 36.92 | 2.16 |
| | Contractors | 9225 | 2939 | 1772 | 2010 | 1396 | 134 | 0 | 0 | 0 | 0 | 0 | 17476 | 70.06 | 5.72 |
| | Total | 10517 | 3327 | 1911 | 2084 | 1434 | 134 | 0 | 0 | 0 | 0 | 0 | 19407 | 70.06 | 5.37 |
| 202104-202506 | TEPCO | 1367 | 389 | 139 | 77 | 38 | 0 | 0 | 0 | 0 | 0 | 0 | 2010 | 37.26 | 2.11 |
| | Contractors | 9343 | 2936 | 1797 | 1991 | 1436 | 144 | 0 | 0 | 0 | 0 | 0 | 17647 | 72.37 | 5.75 |
| | Total | 10710 | 3325 | 1936 | 2068 | 1474 | 144 | 0 | 0 | 0 | 0 | 0 | 19657 | 72.37 | 5.38 |

Note)

•The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

•Aggregation periods are set based on the data management periods: from March 11, 2011 to March 31, 2016, from April 1, 2016 to March 31, 2021 and from April 1, 2021 to March 31, 2026.

(Aggregation period: March 11, 2011 - June 30, 2025)

Table 16. Cumulative Data of Equivalent Dose to the Skin by Fiscal Year

FY2011

| Dose ranges (mSv) | March 2011-March 2012 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 1000 | 0 | 0 | 0 |
| 500-1000 | 0 | 2 | 2 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 1 | 1 |
| 200-250 | 0 | 2 | 2 |
| 150-200 | 7 | 5 | 12 |
| 100-150 | 61 | 14 | 75 |
| 75-100 | 114 | 34 | 148 |
| 50-75 | 229 | 237 | 466 |
| 20-50 | 671 | 2584 | 3255 |
| 10-20 | 555 | 2809 | 3364 |
| 5-10 | 424 | 2508 | 2932 |
| 1-5 | 598 | 4697 | 5295 |
| 1 or less | 756 | 4830 | 5586 |
| Total | 3415 | 17723 | 21138 |
| Maximum (mSv) | 188.14 | 665.42 | 665.42 |
| Average (mSv) | 19.35 | 9.70 | 11.26 |

• Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the skin is 500mSv/year (the emergency exposure dose limit is 1Sv).

• Two contractors shown in the "500-1000" cell of the dose range above were exposed to radiation during the period when the dose limit for radiation workers engaged in emergency work was set at 1Sv.

FY2012

| Dose ranges (mSv) | April 2012-March 2013 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 1 | 1 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 1 | 1 |
| 75-100 | 0 | 2 | 2 |
| 50-75 | 2 | 78 | 80 |
| 20-50 | 73 | 1064 | 1137 |
| 10-20 | 138 | 1939 | 2077 |
| 5-10 | 255 | 1711 | 1966 |
| 1-5 | 571 | 3124 | 3695 |
| 1 or less | 587 | 4195 | 4782 |
| Total | 1626 | 12115 | 13741 |
| Maximum (mSv) | 56.46 | 221.20 | 221.20 |
| Average (mSv) | 4.80 | 7.09 | 6.82 |

FY2013

| Dose ranges (mSv) | April 2013-March 2014 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 1 | 1 |
| 100-150 | 0 | 4 | 4 |
| 75-100 | 1 | 15 | 16 |
| 50-75 | 8 | 117 | 125 |
| 20-50 | 62 | 1468 | 1530 |
| 10-20 | 118 | 1840 | 1958 |
| 5-10 | 213 | 1654 | 1867 |
| 1-5 | 636 | 3396 | 4032 |
| 1 or less | 654 | 4559 | 5213 |
| Total | 1692 | 13054 | 14746 |
| Max. (mSv) | 81.10 | 193.30 | 193.30 |
| Average (mSv) | 4.36 | 7.79 | 7.39 |

FY2014

| Dose ranges (mSv) | April 2014-March 2015 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 1 | 1 |
| 100-150 | 0 | 1 | 1 |
| 75-100 | 1 | 4 | 5 |
| 50-75 | 1 | 120 | 121 |
| 20-50 | 20 | 1824 | 1844 |
| 10-20 | 81 | 2498 | 2579 |
| 5-10 | 172 | 2402 | 2574 |
| 1-5 | 602 | 4968 | 5570 |
| 1 or less | 811 | 7224 | 8035 |
| Total | 1688 | 19042 | 20730 |
| Maximum (mSv) | 80.60 | 162.04 | 162.04 |
| Average (mSv) | 2.74 | 6.86 | 6.53 |

FY2015

| Dose ranges (mSv) | April 2015-March 2016 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 6 | 6 |
| 75-100 | 0 | 25 | 25 |
| 50-75 | 0 | 117 | 117 |
| 20-50 | 17 | 1466 | 1483 |
| 10-20 | 54 | 1928 | 1982 |
| 5-10 | 124 | 2047 | 2171 |
| 1-5 | 525 | 4509 | 5034 |
| 1 or less | 977 | 6401 | 7378 |
| Total | 1697 | 16499 | 18196 |
| Maximum (mSv) | 38.00 | 145.81 | 145.81 |
| Average (mSv) | 2.13 | 6.54 | 6.12 |

FY2016

| Dose ranges (mSv) | April 2016-March 2017 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 7 | 7 |
| 75-100 | 0 | 12 | 12 |
| 50-75 | 0 | 50 | 50 |
| 20-50 | 2 | 733 | 735 |
| 10-20 | 32 | 1308 | 1340 |
| 5-10 | 94 | 1384 | 1478 |
| 1-5 | 402 | 3913 | 4315 |
| 1 or less | 1148 | 6750 | 7898 |
| Total | 1678 | 14157 | 15835 |
| Maximum (mSv) | 21.60 | 138.30 | 138.30 |
| Average (mSv) | 1.39 | 4.63 | 4.29 |

FY2017

| Dose ranges (mSv) | April 2017-March 2018 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 1 | 1 |
| 75-100 | 0 | 7 | 7 |
| 50-75 | 0 | 58 | 58 |
| 20-50 | 4 | 495 | 499 |
| 10-20 | 26 | 1208 | 1234 |
| 5-10 | 96 | 1091 | 1187 |
| 1-5 | 295 | 3249 | 3544 |
| 1 or less | 1109 | 6304 | 7413 |
| Total | 1530 | 12413 | 13943 |
| Maximum (mSv) | 37.49 | 105.10 | 105.10 |
| Average (mSv) | 1.33 | 4.27 | 3.95 |

FY2018

| Dose ranges (mSv) | April 2018-March 2019 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 301 | 301 |
| 10-20 | 23 | 964 | 987 |
| 5-10 | 76 | 926 | 1002 |
| 1-5 | 246 | 2682 | 2928 |
| 1 or less | 1098 | 4990 | 6088 |
| Total | 1443 | 9863 | 11306 |
| Maximum (mSv) | 16.31 | 46.70 | 46.70 |
| Average (mSv) | 1.11 | 3.61 | 3.29 |

FY2019

| Dose ranges (mSv) | April 2019-March 2020 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 1 | 1 |
| 20-50 | 0 | 183 | 183 |
| 10-20 | 17 | 994 | 1011 |
| 5-10 | 60 | 862 | 922 |
| 1-5 | 289 | 2265 | 2554 |
| 1 or less | 1018 | 5019 | 6037 |
| Total | 1384 | 9324 | 10708 |
| Maximum (mSv) | 15.18 | 68.50 | 68.50 |
| Average (mSv) | 1.05 | 3.44 | 3.13 |

FY2020

| Dose ranges (mSv) | April 2020-March 2021 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 2 | 2 |
| 50-75 | 0 | 3 | 3 |
| 20-50 | 0 | 83 | 83 |
| 10-20 | 12 | 1025 | 1037 |
| 5-10 | 69 | 866 | 935 |
| 1-5 | 233 | 2232 | 2465 |
| 1 or less | 1023 | 4771 | 5794 |
| Total | 1337 | 8982 | 10319 |
| Maximum (mSv) | 15.13 | 91.44 | 91.44 |
| Average (mSv) | 1.01 | 3.34 | 3.04 |

FY2021

| Dose ranges (mSv) | April 2021-March 2022 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 2 | 51 | 53 |
| 10-20 | 13 | 972 | 985 |
| 5-10 | 62 | 920 | 982 |
| 1-5 | 205 | 2194 | 2399 |
| 1 or less | 1076 | 4642 | 5718 |
| Total | 1358 | 8779 | 10137 |
| Maximum (mSv) | 40.21 | 41.60 | 41.60 |
| Average (mSv) | 0.97 | 3.18 | 2.88 |

FY2022

| Dose ranges (mSv) | April 2022-March 2023 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 4 | 4 |
| 20-50 | 0 | 53 | 53 |
| 10-20 | 9 | 927 | 936 |
| 5-10 | 54 | 907 | 961 |
| 1-5 | 224 | 2189 | 2413 |
| 1 or less | 1125 | 5822 | 6947 |
| Total | 1412 | 9902 | 11314 |
| Maximum (mSv) | 13.91 | 62.50 | 62.50 |
| Average (mSv) | 0.84 | 2.77 | 2.53 |

FY2023

| Dose ranges (mSv) | April 2023-March 2024 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 3 | 3 |
| 50-75 | 0 | 5 | 5 |
| 20-50 | 0 | 80 | 80 |
| 10-20 | 5 | 1029 | 1034 |
| 5-10 | 31 | 1031 | 1062 |
| 1-5 | 182 | 2061 | 2243 |
| 1 or less | 1198 | 6320 | 7518 |
| Total | 1416 | 10529 | 11945 |
| Maximum (mSv) | 17.3 | 93.4 | 93.4 |
| Average (mSv) | 0.63 | 2.91 | 2.64 |

FY2024

| Dose ranges (mSv) | April 2024-March 2025 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 1 | 1 |
| 50-75 | 0 | 4 | 4 |
| 20-50 | 0 | 59 | 59 |
| 10-20 | 8 | 1027 | 1035 |
| 5-10 | 47 | 938 | 985 |
| 1-5 | 171 | 2010 | 2181 |
| 1 or less | 1184 | 6460 | 7644 |
| Total | 1410 | 10499 | 11909 |
| Maximum (mSv) | 14.4 | 76.9 | 76.9 |
| Average (mSv) | 0.72 | 2.69 | 2.46 |

FY2025

| Dose ranges (mSv) | April 2025-June 2025 | | |
|-------------------|----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 500 | 0 | 0 | 0 |
| 300-500 | 0 | 0 | 0 |
| 250-300 | 0 | 0 | 0 |
| 200-250 | 0 | 0 | 0 |
| 150-200 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 3 | 3 |
| 10-20 | 0 | 48 | 48 |
| 5-10 | 0 | 242 | 242 |
| 1-5 | 50 | 1085 | 1135 |
| 1 or less | 1183 | 6310 | 7493 |
| Total | 1233 | 7688 | 8921 |
| Maximum (mSv) | 3.88 | 27.2 | 27.2 |
| Average (mSv) | 0.14 | 0.75 | 0.66 |

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.
- Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the skin is 500 mSv/year (the emergency exposure dose limit is 1 Sv).
- Equivalent dose to the skin is measured at a depth of 70 micrometers from the skin surface. When the equivalent dose is measured with a dosimeter other than the one put on around the chest and the abdomen, for example, a finger dosimeter, the maximum measurement value is counted as the equivalent dose.

(Aggregation period: March 11, 2011 - June 30, 2025)

Table 17. Cumulative Data of Equivalent Dose to the Lens of the Eye by Fiscal Year

FY2011

| Dose ranges (mSv) | March 2011-March 2012 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 200 | 0 | 0 | 0 |
| 150-200 | 7 | 3 | 10 |
| 100-150 | 59 | 8 | 67 |
| 75-100 | 108 | 29 | 137 |
| 50-75 | 233 | 236 | 469 |
| 20-50 | 671 | 2492 | 3163 |
| 10-20 | 555 | 2822 | 3377 |
| 5-10 | 427 | 2568 | 2995 |
| 1-5 | 599 | 4722 | 5321 |
| 1 or less | 756 | 4843 | 5599 |
| Total | 3415 | 17723 | 21138 |
| Maximum (mSv) | 188.14 | 199.42 | 199.42 |
| Average (mSv) | 19.21 | 9.34 | 10.94 |

Note)

- Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the lens of the eye is 150mSv/year (the emergency exposure dose limit is 300mSv).
- Seven TEPCO's employees and three contractors shown in the "150-200"cell of the dose range above were exposed to radiation during the period when the dose limit for radiation workers engaged in emergency work was set at 300mSv.

FY2012

| Dose ranges (mSv) | April 2012-March 2013 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 1 | 54 | 55 |
| 20-50 | 65 | 733 | 798 |
| 10-20 | 133 | 1970 | 2103 |
| 5-10 | 259 | 1843 | 2102 |
| 1-5 | 580 | 3295 | 3875 |
| 1 or less | 588 | 4220 | 4808 |
| Total | 1626 | 12115 | 13741 |
| Maximum (mSv) | 55.60 | 67.30 | 67.30 |
| Average (mSv) | 4.55 | 6.31 | 6.10 |

FY2013

| Dose ranges (mSv) | April 2013-March 2014 | | |
|-------------------|-----------------------|-------------|--------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 1 | 1 |
| 75-100 | 0 | 1 | 1 |
| 50-75 | 2 | 34 | 36 |
| 20-50 | 52 | 835 | 887 |
| 10-20 | 100 | 2050 | 2150 |
| 5-10 | 210 | 1829 | 2039 |
| 1-5 | 644 | 3620 | 4264 |
| 1 or less | 684 | 4684 | 5368 |
| Total | 1692 | 13054 | 14746 |
| Maximum (mSv) | 68.30 | 106.88 | 106.88 |
| Average (mSv) | 3.78 | 6.10 | 5.83 |

FY2014

| Dose ranges (mSv) | April 2014-March 2015 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 1 | 70 | 71 |
| 20-50 | 12 | 1232 | 1244 |
| 10-20 | 68 | 2605 | 2673 |
| 5-10 | 159 | 2640 | 2799 |
| 5-1 | 630 | 5183 | 5813 |
| 1 or less | 818 | 7312 | 8130 |
| Total | 1688 | 19042 | 20730 |
| Maximum (mSv) | 56.50 | 62.91 | 62.91 |
| Average (mSv) | 2.42 | 5.97 | 5.68 |

FY2015

| Dose ranges (mSv) | April 2015-March 2016 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 6 | 6 |
| 50-75 | 0 | 44 | 44 |
| 20-50 | 8 | 879 | 887 |
| 10-20 | 52 | 2079 | 2131 |
| 5-10 | 114 | 2180 | 2294 |
| 5-1 | 529 | 4788 | 5317 |
| 1 or less | 994 | 6523 | 7517 |
| Total | 1697 | 16499 | 18196 |
| Maximum (mSv) | 24.43 | 87.90 | 87.90 |
| Average (mSv) | 1.92 | 5.31 | 4.99 |

FY2016

| Dose ranges (mSv) | April 2016-March 2017 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 1 | 1 |
| 50-75 | 0 | 20 | 20 |
| 20-50 | 0 | 380 | 380 |
| 10-20 | 25 | 1302 | 1327 |
| 5-10 | 92 | 1477 | 1569 |
| 5-1 | 406 | 4080 | 4486 |
| 1 or less | 1155 | 6897 | 8052 |
| Total | 1678 | 14157 | 15835 |
| Maximum (mSv) | 16.30 | 75.30 | 75.30 |
| Average (mSv) | 1.30 | 3.71 | 3.45 |

FY2017

| Dose ranges (mSv) | April 2017-March 2018 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 6 | 6 |
| 50-75 | 0 | 42 | 42 |
| 20-50 | 0 | 267 | 267 |
| 10-20 | 22 | 1233 | 1255 |
| 5-10 | 87 | 1138 | 1225 |
| 5-1 | 303 | 3317 | 3620 |
| 1 or less | 1118 | 6410 | 7528 |
| Total | 1530 | 12413 | 13943 |
| Maximum (mSv) | 19.80 | 86.20 | 86.20 |
| Average (mSv) | 1.19 | 3.77 | 3.48 |

FY2018

| Dose ranges (mSv) | April 2018-March 2019 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 49 | 49 |
| 10-20 | 23 | 886 | 909 |
| 5-10 | 70 | 951 | 1021 |
| 5-1 | 251 | 2840 | 3091 |
| 1 or less | 1099 | 5137 | 6236 |
| Total | 1443 | 9863 | 11306 |
| Maximum (mSv) | 16.23 | 26.93 | 26.93 |
| Average (mSv) | 1.07 | 2.90 | 2.66 |

FY2019

| Dose ranges (mSv) | April 2019-March 2020 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 64 | 64 |
| 10-20 | 16 | 921 | 937 |
| 5-10 | 59 | 866 | 925 |
| 5-1 | 288 | 2384 | 2672 |
| 1 or less | 1021 | 5089 | 6110 |
| Total | 1384 | 9324 | 10708 |
| Maximum (mSv) | 14.68 | 26.30 | 26.30 |
| Average (mSv) | 1.03 | 2.97 | 2.72 |

FY2020

| Dose ranges (mSv) | April 2020-March 2021 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 12 | 965 | 977 |
| 5-10 | 66 | 858 | 924 |
| 5-1 | 231 | 2320 | 2551 |
| 1 or less | 1028 | 4839 | 5867 |
| Total | 1337 | 8982 | 10319 |
| Maximum (mSv) | 15.03 | 20.00 | 20.00 |
| Average (mSv) | 0.99 | 2.94 | 2.68 |

Note)

- From FY2018, our own equivalent dose limit to the lens of the eye has been used and the equivalent dose is measured with one of the following method:

①The case of using dosimeter put inside full-face mask

②The case of using dosimeter put around the chest, the abdomen or the head and neck (excluding the case of ①)

FY2021

| Dose ranges (mSv) | April 2021-March 2022 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 8 | 898 | 906 |
| 5-10 | 62 | 894 | 956 |
| 5-1 | 208 | 2229 | 2437 |
| 1 or less | 1080 | 4758 | 5838 |
| Total | 1358 | 8779 | 10137 |
| Maximum (mSv) | 13.02 | 17.90 | 17.90 |
| Average (mSv) | 0.87 | 2.85 | 2.58 |

FY2022

| Dose ranges (mSv) | April 2022-March 2023 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 8 | 798 | 806 |
| 5-10 | 48 | 926 | 974 |
| 5-1 | 228 | 2239 | 2467 |
| 1 or less | 1128 | 5939 | 7067 |
| Total | 1412 | 9902 | 11314 |
| Maximum (mSv) | 11.84 | 19.00 | 19.00 |
| Average (mSv) | 0.81 | 2.42 | 2.22 |

FY2023

| Dose ranges (mSv) | April 2023-March 2024 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 5 | 935 | 940 |
| 5-10 | 29 | 1055 | 1084 |
| 5-1 | 179 | 2132 | 2311 |
| 1 or less | 1203 | 6407 | 7610 |
| Total | 1416 | 10529 | 11945 |
| Maximum (mSv) | 13.6 | 18.1 | 18.1 |
| Average (mSv) | 0.60 | 2.55 | 2.32 |

FY2024

| Dose ranges (mSv) | April 2024-March 2025 | | |
|-------------------|-----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 6 | 941 | 947 |
| 5-10 | 42 | 921 | 963 |
| 5-1 | 172 | 2043 | 2215 |
| 1 or less | 1190 | 6594 | 7784 |
| Total | 1410 | 10499 | 11909 |
| Maximum (mSv) | 11.8 | 17.2 | 17.2 |
| Average (mSv) | 0.68 | 2.44 | 2.23 |

FY2025

| Dose ranges (mSv) | April 2025-June 2025 | | |
|-------------------|----------------------|-------------|-------|
| | TEPCO's employees | Contractors | Total |
| Above 150 | 0 | 0 | 0 |
| 100-150 | 0 | 0 | 0 |
| 75-100 | 0 | 0 | 0 |
| 50-75 | 0 | 0 | 0 |
| 20-50 | 0 | 0 | 0 |
| 10-20 | 0 | 29 | 29 |
| 5-10 | 0 | 208 | 208 |
| 5-1 | 46 | 1073 | 1119 |
| 1 or less | 1187 | 6378 | 7565 |
| Total | 1233 | 7688 | 8921 |
| Maximum (mSv) | 3.88 | 13.98 | 13.98 |
| Average (mSv) | 0.14 | 0.68 | 0.60 |

Note)

- The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or the dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.
- Equivalent dose is a measure of the radiation dose to organs and tissues, and the equivalent dose limit to the lens of the eye is 50 mSv/year and 100 mSv/5 years (the emergency exposure dose limit is 300 mSv). Equivalent dose limit to the lens of the eye was 150mSv/year (the emergency exposure dose limit was 300 mSv) before April 1, 2021.

- The equivalent dose to the lens of the eye is measured at a depth of 1 centimeter for neutron ray, 3 millimeters for X-ray, gamma ray and beta ray from the skin surface. However, as for X-ray, gamma ray and beta ray, it is measured at a depth of 1 centimeter or 70 micrometer when deemed appropriate with consideration for radiation type and energy type.

Table 18. Cumulative Data of Equivalent Dose to the Lens of the Eye for Five Years

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | Above 100 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|-----------------|----------------------|------------------|---------------|
| 202104-202104 | TEPCO | 943 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 969 | 2.19 | 0.11 |
| | Contractors | 4593 | 373 | 8 | 0 | 0 | 0 | 0 | 0 | 4974 | 7.30 | 0.29 |
| | Total | 5536 | 399 | 8 | 0 | 0 | 0 | 0 | 0 | 5943 | 7.30 | 0.26 |
| 202104-202105 | TEPCO | 961 | 61 | 0 | 0 | 0 | 0 | 0 | 0 | 1022 | 4.39 | 0.20 |
| | Contractors | 4772 | 742 | 53 | 1 | 0 | 0 | 0 | 0 | 5568 | 10.20 | 0.51 |
| | Total | 5733 | 803 | 53 | 1 | 0 | 0 | 0 | 0 | 6590 | 10.20 | 0.46 |
| 202104-202106 | TEPCO | 1049 | 92 | 1 | 0 | 0 | 0 | 0 | 0 | 1142 | 5.34 | 0.26 |
| | Contractors | 4784 | 1119 | 141 | 29 | 0 | 0 | 0 | 0 | 6073 | 15.70 | 0.81 |
| | Total | 5833 | 1211 | 142 | 29 | 0 | 0 | 0 | 0 | 7215 | 15.70 | 0.72 |
| 202104-202107 | TEPCO | 1063 | 114 | 3 | 0 | 0 | 0 | 0 | 0 | 1180 | 6.55 | 0.34 |
| | Contractors | 4781 | 1396 | 235 | 69 | 0 | 0 | 0 | 0 | 6481 | 17.00 | 1.05 |
| | Total | 5844 | 1510 | 238 | 69 | 0 | 0 | 0 | 0 | 7661 | 17.00 | 0.94 |
| 202104-202108 | TEPCO | 1067 | 125 | 5 | 0 | 0 | 0 | 0 | 0 | 1197 | 6.85 | 0.38 |
| | Contractors | 4739 | 1581 | 323 | 95 | 0 | 0 | 0 | 0 | 6738 | 17.00 | 1.22 |
| | Total | 5806 | 1706 | 328 | 95 | 0 | 0 | 0 | 0 | 7935 | 17.00 | 1.09 |
| 202104-202109 | TEPCO | 1065 | 136 | 11 | 0 | 0 | 0 | 0 | 0 | 1212 | 7.43 | 0.44 |
| | Contractors | 4656 | 1736 | 527 | 145 | 0 | 0 | 0 | 0 | 7064 | 17.00 | 1.51 |
| | Total | 5721 | 1872 | 538 | 145 | 0 | 0 | 0 | 0 | 8276 | 17.00 | 1.35 |
| 202104-202110 | TEPCO | 1094 | 156 | 16 | 0 | 0 | 0 | 0 | 0 | 1266 | 9.39 | 0.49 |
| | Contractors | 4707 | 1858 | 625 | 212 | 0 | 0 | 0 | 0 | 7402 | 17.11 | 1.71 |
| | Total | 5801 | 2014 | 641 | 212 | 0 | 0 | 0 | 0 | 8668 | 17.11 | 1.53 |
| 202104-202111 | TEPCO | 1111 | 167 | 27 | 0 | 0 | 0 | 0 | 0 | 1305 | 9.79 | 0.55 |
| | Contractors | 4721 | 2063 | 673 | 299 | 0 | 0 | 0 | 0 | 7756 | 17.11 | 1.91 |
| | Total | 5832 | 2230 | 700 | 299 | 0 | 0 | 0 | 0 | 9061 | 17.11 | 1.71 |
| 202104-202112 | TEPCO | 1112 | 176 | 41 | 1 | 0 | 0 | 0 | 0 | 1330 | 10.02 | 0.64 |
| | Contractors | 4745 | 2115 | 779 | 395 | 0 | 0 | 0 | 0 | 8034 | 17.11 | 2.11 |
| | Total | 5857 | 2291 | 820 | 396 | 0 | 0 | 0 | 0 | 9364 | 17.11 | 1.90 |
| 202104-202201 | TEPCO | 1105 | 181 | 51 | 3 | 0 | 0 | 0 | 0 | 1340 | 10.51 | 0.70 |
| | Contractors | 4750 | 2137 | 864 | 537 | 0 | 0 | 0 | 0 | 8288 | 17.15 | 2.34 |
| | Total | 5855 | 2318 | 915 | 540 | 0 | 0 | 0 | 0 | 9628 | 17.15 | 2.11 |
| 202104-202202 | TEPCO | 1093 | 189 | 59 | 5 | 0 | 0 | 0 | 0 | 1346 | 11.43 | 0.78 |
| | Contractors | 4739 | 2215 | 933 | 687 | 0 | 0 | 0 | 0 | 8574 | 17.90 | 2.60 |
| | Total | 5832 | 2404 | 992 | 692 | 0 | 0 | 0 | 0 | 9920 | 17.90 | 2.35 |
| 202104-202203 | TEPCO | 1080 | 208 | 62 | 8 | 0 | 0 | 0 | 0 | 1358 | 13.02 | 0.87 |
| | Contractors | 4758 | 2229 | 894 | 898 | 0 | 0 | 0 | 0 | 8779 | 17.90 | 2.85 |
| | Total | 5838 | 2437 | 956 | 906 | 0 | 0 | 0 | 0 | 10137 | 17.90 | 2.58 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | Above 100 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|-----------------|----------------------|------------------|---------------|
| 202104-202204 | TEPCO | 1061 | 235 | 65 | 13 | 0 | 0 | 0 | 0 | 1374 | 15.65 | 0.97 |
| | Contractors | 4920 | 2254 | 931 | 949 | 12 | 0 | 0 | 0 | 9066 | 24.30 | 2.94 |
| | Total | 5981 | 2489 | 996 | 962 | 12 | 0 | 0 | 0 | 10440 | 24.30 | 2.68 |
| 202104-202205 | TEPCO | 1059 | 242 | 67 | 19 | 0 | 0 | 0 | 0 | 1387 | 16.14 | 1.02 |
| | Contractors | 5102 | 2248 | 961 | 994 | 23 | 0 | 0 | 0 | 9328 | 24.80 | 3.01 |
| | Total | 6161 | 2490 | 1028 | 1013 | 23 | 0 | 0 | 0 | 10715 | 24.80 | 2.75 |
| 202104-202206 | TEPCO | 1107 | 246 | 71 | 24 | 0 | 0 | 0 | 0 | 1448 | 16.54 | 1.06 |
| | Contractors | 5255 | 2268 | 998 | 1032 | 81 | 0 | 0 | 0 | 9634 | 26.70 | 3.15 |
| | Total | 6362 | 2514 | 1069 | 1056 | 81 | 0 | 0 | 0 | 11082 | 26.70 | 2.88 |
| 202104-202207 | TEPCO | 1124 | 258 | 70 | 28 | 0 | 0 | 0 | 0 | 1480 | 16.84 | 1.09 |
| | Contractors | 5381 | 2320 | 1021 | 1054 | 146 | 0 | 0 | 0 | 9922 | 28.13 | 3.26 |
| | Total | 6505 | 2578 | 1091 | 1082 | 146 | 0 | 0 | 0 | 11402 | 28.13 | 2.98 |
| 202104-202208 | TEPCO | 1133 | 264 | 71 | 31 | 0 | 0 | 0 | 0 | 1499 | 18.01 | 1.13 |
| | Contractors | 5471 | 2348 | 1059 | 1086 | 168 | 0 | 0 | 0 | 10132 | 28.30 | 3.34 |
| | Total | 6604 | 2612 | 1130 | 1117 | 168 | 0 | 0 | 0 | 11631 | 28.30 | 3.05 |
| 202104-202209 | TEPCO | 1139 | 270 | 75 | 35 | 0 | 0 | 0 | 0 | 1519 | 18.31 | 1.18 |
| | Contractors | 5614 | 2397 | 1086 | 1109 | 227 | 0 | 0 | 0 | 10433 | 29.20 | 3.45 |
| | Total | 6753 | 2667 | 1161 | 1144 | 227 | 0 | 0 | 0 | 11952 | 29.20 | 3.16 |
| 202104-202210 | TEPCO | 1129 | 285 | 76 | 36 | 2 | 0 | 0 | 0 | 1528 | 20.41 | 1.24 |
| | Contractors | 5866 | 2382 | 1122 | 1164 | 270 | 0 | 0 | 0 | 10804 | 30.30 | 3.52 |
| | Total | 6995 | 2667 | 1198 | 1200 | 272 | 0 | 0 | 0 | 12332 | 30.30 | 3.24 |
| 202104-202211 | TEPCO | 1126 | 292 | 81 | 38 | 2 | 0 | 0 | 0 | 1539 | 21.12 | 1.29 |
| | Contractors | 6006 | 2389 | 1145 | 1224 | 311 | 0 | 0 | 0 | 11075 | 31.76 | 3.65 |
| | Total | 7132 | 2681 | 1226 | 1262 | 313 | 0 | 0 | 0 | 12614 | 31.76 | 3.37 |
| 202104-202212 | TEPCO | 1125 | 294 | 87 | 39 | 2 | 0 | 0 | 0 | 1547 | 21.12 | 1.34 |
| | Contractors | 6118 | 2407 | 1164 | 1265 | 359 | 0 | 0 | 0 | 11313 | 32.46 | 3.76 |
| | Total | 7243 | 2701 | 1251 | 1304 | 361 | 0 | 0 | 0 | 12860 | 32.46 | 3.47 |
| 202104-202301 | TEPCO | 1125 | 301 | 85 | 42 | 2 | 0 | 0 | 0 | 1555 | 21.22 | 1.38 |
| | Contractors | 6232 | 2415 | 1193 | 1296 | 398 | 0 | 0 | 0 | 11534 | 32.60 | 3.84 |
| | Total | 7357 | 2716 | 1278 | 1338 | 400 | 0 | 0 | 0 | 13089 | 32.60 | 3.55 |
| 202104-202302 | TEPCO | 1121 | 305 | 88 | 44 | 3 | 0 | 0 | 0 | 1561 | 21.32 | 1.43 |
| | Contractors | 6315 | 2429 | 1224 | 1315 | 461 | 0 | 0 | 0 | 11744 | 33.00 | 3.96 |
| | Total | 7436 | 2734 | 1312 | 1359 | 464 | 0 | 0 | 0 | 13305 | 33.00 | 3.66 |
| 202104-202303 | TEPCO | 1122 | 307 | 92 | 45 | 4 | 0 | 0 | 0 | 1570 | 21.81 | 1.48 |
| | Contractors | 6441 | 2425 | 1227 | 1364 | 527 | 0 | 0 | 0 | 11984 | 33.80 | 4.09 |
| | Total | 7563 | 2732 | 1319 | 1409 | 531 | 0 | 0 | 0 | 13554 | 33.80 | 3.79 |
| 202104-202304 | TEPCO | 1118 | 311 | 98 | 44 | 7 | 0 | 0 | 0 | 1578 | 22.21 | 1.53 |
| | Contractors | 6584 | 2440 | 1219 | 1373 | 609 | 0 | 0 | 0 | 12225 | 38.85 | 4.24 |
| | Total | 7702 | 2751 | 1317 | 1417 | 616 | 0 | 0 | 0 | 13803 | 38.85 | 3.93 |
| 202104-202305 | TEPCO | 1118 | 318 | 101 | 43 | 9 | 0 | 0 | 0 | 1589 | 23.51 | 1.56 |
| | Contractors | 6741 | 2434 | 1233 | 1371 | 669 | 0 | 0 | 0 | 12448 | 41.48 | 4.33 |
| | Total | 7859 | 2752 | 1334 | 1414 | 678 | 0 | 0 | 0 | 14037 | 41.48 | 4.01 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | Above 100 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|-----------------|----------------------|------------------|---------------|
| 202104-202306 | TEPCO | 1171 | 312 | 107 | 44 | 11 | 0 | 0 | 0 | 1645 | 23.81 | 1.55 |
| | Contractors | 6848 | 2442 | 1272 | 1380 | 727 | 0 | 0 | 0 | 12669 | 43.68 | 4.45 |
| | Total | 8019 | 2754 | 1379 | 1424 | 738 | 0 | 0 | 0 | 14314 | 43.68 | 4.12 |
| 202104-202307 | TEPCO | 1195 | 316 | 104 | 44 | 15 | 0 | 0 | 0 | 1674 | 24.01 | 1.55 |
| | Contractors | 6961 | 2493 | 1290 | 1397 | 776 | 0 | 0 | 0 | 12917 | 46.30 | 4.54 |
| | Total | 8156 | 2809 | 1394 | 1441 | 791 | 0 | 0 | 0 | 14591 | 46.30 | 4.20 |
| 202104-202308 | TEPCO | 1219 | 318 | 104 | 45 | 15 | 0 | 0 | 0 | 1701 | 24.11 | 1.56 |
| | Contractors | 7054 | 2546 | 1305 | 1405 | 807 | 0 | 0 | 0 | 13117 | 46.74 | 4.58 |
| | Total | 8273 | 2864 | 1409 | 1450 | 822 | 0 | 0 | 0 | 14818 | 46.74 | 4.23 |
| 202104-202309 | TEPCO | 1224 | 330 | 104 | 47 | 15 | 0 | 0 | 0 | 1720 | 25.11 | 1.58 |
| | Contractors | 7177 | 2538 | 1370 | 1433 | 841 | 0 | 0 | 0 | 13359 | 49.14 | 4.67 |
| | Total | 8401 | 2868 | 1474 | 1480 | 856 | 0 | 0 | 0 | 15079 | 49.14 | 4.31 |
| 202104-202310 | TEPCO | 1226 | 335 | 101 | 50 | 16 | 0 | 0 | 0 | 1728 | 27.71 | 1.62 |
| | Contractors | 7338 | 2551 | 1391 | 1489 | 885 | 0 | 0 | 0 | 13654 | 49.24 | 4.76 |
| | Total | 8564 | 2886 | 1492 | 1539 | 901 | 0 | 0 | 0 | 15382 | 49.24 | 4.40 |
| 202104-202311 | TEPCO | 1227 | 339 | 105 | 50 | 17 | 0 | 0 | 0 | 1738 | 28.21 | 1.65 |
| | Contractors | 7446 | 2558 | 1450 | 1525 | 926 | 0 | 0 | 0 | 13905 | 49.34 | 4.85 |
| | Total | 8673 | 2897 | 1555 | 1575 | 943 | 0 | 0 | 0 | 15643 | 49.34 | 4.49 |
| 202104-202312 | TEPCO | 1222 | 347 | 103 | 51 | 20 | 0 | 0 | 0 | 1743 | 29.61 | 1.70 |
| | Contractors | 7537 | 2567 | 1492 | 1568 | 975 | 0 | 0 | 0 | 14139 | 49.44 | 4.94 |
| | Total | 8759 | 2914 | 1595 | 1619 | 995 | 0 | 0 | 0 | 15882 | 49.44 | 4.59 |
| 202104-202401 | TEPCO | 1220 | 350 | 103 | 52 | 22 | 0 | 0 | 0 | 1747 | 30.51 | 1.73 |
| | Contractors | 7596 | 2615 | 1499 | 1602 | 1006 | 0 | 0 | 0 | 14318 | 49.54 | 5.00 |
| | Total | 8816 | 2965 | 1602 | 1654 | 1028 | 0 | 0 | 0 | 16065 | 49.54 | 4.65 |
| 202104-202402 | TEPCO | 1217 | 352 | 102 | 56 | 22 | 0 | 0 | 0 | 1749 | 30.71 | 1.77 |
| | Contractors | 7705 | 2619 | 1520 | 1649 | 1050 | 0 | 0 | 0 | 14543 | 49.90 | 5.08 |
| | Total | 8922 | 2971 | 1622 | 1705 | 1072 | 0 | 0 | 0 | 16292 | 49.90 | 4.72 |
| 202104-202403 | TEPCO | 1205 | 359 | 110 | 55 | 24 | 0 | 0 | 0 | 1753 | 31.31 | 1.81 |
| | Contractors | 7806 | 2631 | 1529 | 1683 | 1097 | 0 | 0 | 0 | 14746 | 50.00 | 5.15 |
| | Total | 9011 | 2990 | 1639 | 1738 | 1121 | 0 | 0 | 0 | 16499 | 50.00 | 4.79 |
| 202104-202404 | TEPCO | 1197 | 365 | 115 | 54 | 26 | 0 | 0 | 0 | 1757 | 31.61 | 1.85 |
| | Contractors | 7940 | 2637 | 1518 | 1713 | 1134 | 6 | 0 | 0 | 14948 | 52.60 | 5.19 |
| | Total | 9137 | 3002 | 1633 | 1767 | 1160 | 6 | 0 | 0 | 16705 | 52.60 | 4.84 |
| 202104-202405 | TEPCO | 1192 | 369 | 117 | 57 | 27 | 0 | 0 | 0 | 1762 | 31.71 | 1.89 |
| | Contractors | 8081 | 2669 | 1498 | 1736 | 1167 | 12 | 0 | 0 | 15163 | 54.80 | 5.22 |
| | Total | 9273 | 3038 | 1615 | 1793 | 1194 | 12 | 0 | 0 | 16925 | 54.80 | 4.87 |
| 202104-202406 | TEPCO | 1245 | 368 | 121 | 58 | 28 | 0 | 0 | 0 | 1820 | 31.91 | 1.88 |
| | Contractors | 8202 | 2680 | 1495 | 1749 | 1209 | 23 | 0 | 0 | 15358 | 56.80 | 5.30 |
| | Total | 9447 | 3048 | 1616 | 1807 | 1237 | 23 | 0 | 0 | 17178 | 56.80 | 4.94 |
| 202104-202407 | TEPCO | 1265 | 368 | 123 | 60 | 28 | 0 | 0 | 0 | 1844 | 32.78 | 1.89 |
| | Contractors | 8316 | 2713 | 1515 | 1782 | 1236 | 30 | 0 | 0 | 15592 | 57.80 | 5.36 |
| | Total | 9581 | 3081 | 1638 | 1842 | 1264 | 30 | 0 | 0 | 17436 | 57.80 | 4.99 |

| Year and month | TEPCO/ Contractors | 1 or less (mSv) | 1-5 (mSv) | 5-10 (mSv) | 10-20 (mSv) | 20-50 (mSv) | 50-75 (mSv) | 75-100 (mSv) | Above 100 (mSv) | Number of workers | Maximum (mSv) | Average (mSv) |
|----------------|-----------------------|-----------------|-----------|------------|-------------|-------------|-------------|--------------|-----------------|----------------------|------------------|---------------|
| 202104-202408 | TEPCO | 1288 | 369 | 122 | 64 | 28 | 0 | 0 | 0 | 1871 | 32.78 | 1.91 |
| | Contractors | 8382 | 2732 | 1529 | 1790 | 1258 | 40 | 0 | 0 | 15731 | 61.80 | 5.41 |
| | Total | 9670 | 3101 | 1651 | 1854 | 1286 | 40 | 0 | 0 | 17602 | 61.80 | 5.04 |
| 202104-202409 | TEPCO | 1295 | 370 | 126 | 65 | 28 | 0 | 0 | 0 | 1884 | 33.38 | 1.93 |
| | Contractors | 8468 | 2750 | 1546 | 1809 | 1277 | 45 | 0 | 0 | 15895 | 64.60 | 5.46 |
| | Total | 9763 | 3120 | 1672 | 1874 | 1305 | 45 | 0 | 0 | 17779 | 64.60 | 5.08 |
| 202104-202410 | TEPCO | 1294 | 375 | 128 | 67 | 29 | 0 | 0 | 0 | 1893 | 33.48 | 1.97 |
| | Contractors | 8600 | 2787 | 1595 | 1838 | 1303 | 58 | 0 | 0 | 16181 | 64.60 | 5.52 |
| | Total | 9894 | 3162 | 1723 | 1905 | 1332 | 58 | 0 | 0 | 18074 | 64.60 | 5.14 |
| 202104-202411 | TEPCO | 1298 | 378 | 127 | 68 | 32 | 0 | 0 | 0 | 1903 | 34.38 | 2.01 |
| | Contractors | 8687 | 2817 | 1601 | 1874 | 1316 | 85 | 0 | 0 | 16380 | 64.60 | 5.60 |
| | Total | 9985 | 3195 | 1728 | 1942 | 1348 | 85 | 0 | 0 | 18283 | 64.60 | 5.23 |
| 202104-202412 | TEPCO | 1291 | 383 | 131 | 68 | 33 | 0 | 0 | 0 | 1906 | 34.88 | 2.05 |
| | Contractors | 8796 | 2845 | 1617 | 1921 | 1330 | 96 | 0 | 0 | 16605 | 64.97 | 5.65 |
| | Total | 10087 | 3228 | 1748 | 1989 | 1363 | 96 | 0 | 0 | 18511 | 64.97 | 5.28 |
| 202104-202501 | TEPCO | 1286 | 385 | 138 | 69 | 33 | 0 | 0 | 0 | 1911 | 34.88 | 2.09 |
| | Contractors | 8855 | 2878 | 1650 | 1934 | 1354 | 109 | 0 | 0 | 16780 | 65.07 | 5.72 |
| | Total | 10141 | 3263 | 1788 | 2003 | 1387 | 109 | 0 | 0 | 18691 | 65.07 | 5.35 |
| 202104-202502 | TEPCO | 1290 | 385 | 141 | 71 | 34 | 0 | 0 | 0 | 1921 | 35.28 | 2.11 |
| | Contractors | 8913 | 2884 | 1695 | 1973 | 1390 | 123 | 0 | 0 | 16978 | 65.07 | 5.82 |
| | Total | 10203 | 3269 | 1836 | 2044 | 1424 | 123 | 0 | 0 | 18899 | 65.07 | 5.44 |
| 202104-202503 | TEPCO | 1292 | 381 | 144 | 72 | 36 | 0 | 0 | 0 | 1925 | 35.88 | 2.15 |
| | Contractors | 8965 | 2878 | 1686 | 2023 | 1423 | 140 | 0 | 0 | 17115 | 65.66 | 5.93 |
| | Total | 10257 | 3259 | 1830 | 2095 | 1459 | 140 | 0 | 0 | 19040 | 65.66 | 5.55 |
| 202104-202504 | TEPCO | 1286 | 387 | 145 | 70 | 39 | 0 | 0 | 0 | 1927 | 36.72 | 2.18 |
| | Contractors | 9086 | 2898 | 1695 | 2016 | 1457 | 154 | 0 | 0 | 17306 | 68.26 | 5.98 |
| | Total | 10372 | 3285 | 1840 | 2086 | 1496 | 154 | 0 | 0 | 19233 | 68.26 | 5.60 |
| 202104-202505 | TEPCO | 1285 | 392 | 142 | 72 | 40 | 0 | 0 | 0 | 1931 | 36.92 | 2.20 |
| | Contractors | 9192 | 2921 | 1703 | 1997 | 1494 | 169 | 0 | 0 | 17476 | 71.10 | 6.02 |
| | Total | 10477 | 3313 | 1845 | 2069 | 1534 | 169 | 0 | 0 | 19407 | 71.10 | 5.64 |
| 202104-202506 | TEPCO | 1360 | 393 | 142 | 75 | 40 | 0 | 0 | 0 | 2010 | 37.27 | 2.14 |
| | Contractors | 9306 | 2904 | 1739 | 1983 | 1537 | 178 | 0 | 0 | 17647 | 73.39 | 6.05 |
| | Total | 10666 | 3297 | 1881 | 2058 | 1577 | 178 | 0 | 0 | 19657 | 73.39 | 5.65 |

Note)

•The values of the exposure dose and the number of the workers in the table above are subject to change, because there are cases that APD data are replaced with monthly dose data measured by integral dosimeters. Or dose data of workers who wore only an integral dosimeter (ex., workers who entered only the Seismic Isolation Building) need to be updated in the table after the publication of the data.

•Aggregation periods are set based on the data management periods: from April 1, 2021 to March 31, 2026.