

携行品汚染発生状況報告(平成27年11月)

場所: 雑固体廃棄物焼却設備建屋

(単位: 件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24	0	0	0	0	0
25	1	1	2	2	0
26	4	0	4	2	2
27	0	0	0	0	0
28	0	0	0	0	0
29	6	0	6	2	4
30	3	0	3	2	1
合計	14	1	15	8	7