

# 車両汚染部位記録シート(平成28年12月)

(単位:台数)

| 日  | 測定台数 | スクリーニングレベル超過車 | 除染後退構可車 | 除染後退構不可車 |
|----|------|---------------|---------|----------|
| 1  | 413  | 0             | 0       | 0        |
| 2  | 483  | 4             | 4       | 0        |
| 3  | 201  | 0             | 0       | 0        |
| 4  | 25   | 1             | 1       | 0        |
| 5  | 453  | 2             | 2       | 0        |
| 6  | 433  | 2             | 2       | 0        |
| 7  | 400  | 1             | 1       | 0        |
| 8  | 362  | 1             | 1       | 0        |
| 9  | 400  | 3             | 2       | 1        |
| 10 | 133  | 0             | 0       | 0        |
| 11 | 22   | 0             | 0       | 0        |
| 12 | 370  | 2             | 2       | 0        |
| 13 | 435  | 2             | 1       | 1        |
| 14 | 418  | 2             | 2       | 0        |
| 15 | 407  | 2             | 1       | 1        |
| 16 | 402  | 4             | 3       | 1        |
| 17 | 262  | 0             | 0       | 0        |
| 18 | 28   | 0             | 0       | 0        |
| 19 | 358  | 1             | 0       | 1        |
| 20 | 379  | 2             | 2       | 0        |
| 21 | 404  | 3             | 3       | 0        |
| 22 | 389  | 3             | 2       | 1        |
| 23 | 198  | 2             | 2       | 0        |
| 24 | 150  | 0             | 0       | 0        |
| 25 | 25   | 0             | 0       | 0        |
| 26 | 341  | 3             | 2       | 1        |
| 27 | 260  | 4             | 4       | 0        |
| 28 | 88   | 0             | 0       | 0        |
| 29 | 30   | 0             | 0       | 0        |
| 30 | 25   | 0             | 0       | 0        |
| 31 | 23   | 0             | 0       | 0        |
| 合計 | 8317 | 44            | 37      | 7        |