

# 携行品汚染発生状況報告(2019年10月)

場所: 雑固体廃棄物焼却設備建屋

(単位: 件数)

日	4Bq/cm <sup>2</sup> 以上 40Bq/cm <sup>2</sup> 以下	40Bq/cm <sup>2</sup> 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	1	0	1	0	1
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	1	0	1	0	1