

身体汚染発生状況報告(2020年6月)

場所: 免震重要棟休憩所 第三工区

(単位: 件数)

日	身体汚染 (4Bq/cm ² 以上)	下着汚染 (4Bq/cm ² 以上)	一般服汚染 (4Bq/cm ² 以上)	装備汚染 (4Bq/cm ² 以上)
1	0	4	0	0
2	0	2	1	0
3	0	0	0	0
4	0	1	0	0
5	1	3	0	0
6	0	5	0	0
7	0	0	0	0
8	0	1	0	0
9	0	4	1	0
10	0	6	0	0
11	0	9	0	0
12	0	4	2	0
13	0	0	0	0
14	0	0	0	0
15	1	3	2	0
16	0	4	0	0
17	0	2	1	0
18	0	4	0	0
19	2	3	4	0
20	1	1	0	0
21	0	0	0	0
22	2	3	0	0
23	0	7	0	0
24	0	2	0	0
25	1	1	0	0
26	0	2	0	0
27	0	0	0	0
28	0	0	0	0
29	0	1	3	0
30	0	10	1	0
合計	8	82	15	0

携行品汚染発生状況報告(2020年6月)

場所: 免震重要棟休憩所 第三工区

(単位: 件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	1	0	1	0	1
2	1	0	1	0	1
3	1	0	1	0	1
4	0	0	0	0	0
5	1	0	1	0	1
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	1	1	2	0	2
10	1	0	1	0	1
11	2	0	2	0	2
12	1	0	1	0	1
13	0	0	0	0	0
14	0	0	0	0	0
15	2	0	2	0	2
16	1	0	1	0	1
17	1	0	1	0	1
18	0	0	0	0	0
19	2	0	2	0	2
20	0	0	0	0	0
21	0	0	0	0	0
22	1	0	1	0	1
23	0	0	0	0	0
24	1	0	1	0	1
25	0	0	0	0	0
26	1	0	1	0	1
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	2	0	2	0	2
合計	20	1	21	0	21

身体汚染発生状況報告(2020年6月)

場所: 3/4号機 サービス建屋 休憩所

(単位: 件数)

日	身体汚染 (4Bq/cm ² 以上)	下着汚染 (4Bq/cm ² 以上)	一般服汚染 (4Bq/cm ² 以上)	装備汚染 (4Bq/cm ² 以上)
1	0	0	0	0
2	0	0	0	0
3	0	0	0	0
4	0	0	0	0
5	0	0	0	0
6	0	0	0	0
7	0	0	0	0
8	0	0	0	0
9	0	0	0	0
10	0	0	0	0
11	0	0	0	0
12	0	0	0	0
13	0	0	0	0
14	0	0	0	0
15	0	0	0	0
16	0	0	0	0
17	0	0	0	0
18	0	0	0	0
19	0	0	0	0
20	0	0	0	0
21	0	0	0	0
22	0	0	0	0
23	0	0	0	0
24	0	0	0	0
25	0	0	0	0
26	0	0	0	0
27	0	0	0	0
28	0	0	0	0
29	0	0	0	0
30	0	0	0	0
合計	0	0	0	0

携行品汚染発生状況報告(2020年6月)

場所: 3/4号機 サービス建屋 休憩所

(単位: 件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
合計	0	0	0	0	0