

身体汚染発生状況報告(2022年10月)

場所:事務本館 汚染検査所

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

(単位:件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	1	0	0	0
4	0	1	0	2	0
5	0	1	0	1	0
6	0	0	0	0	0
7	1	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	1	0
16	0	0	0	0	0
17	0	0	0	0	0
18	2	0	0	1	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	1	0	0	0
25	0	0	1	0	0
26	0	0	0	0	0
27	0	0	0	2	0
28	0	0	0	0	0
29	0	0	1	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	3	4	2	7	0

基準値:4[Bq/cm²]以下

携行品汚染発生状況報告(2022年10月)

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

場所:事務本館 汚染検査所

(単位:件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	6	0	6	0	6
4	1	0	1	0	1
5	1	0	1	0	1
6	2	0	2	0	2
7	1	0	1	0	1
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	1	0	1	0	1
17	2	0	2	0	2
18	3	0	3	0	3
19	4	0	4	0	4
20	3	0	3	0	3
21	1	0	1	0	1
22	1	0	1	0	1
23	0	0	0	0	0
24	2	0	2	0	2
25	1	0	1	0	1
26	0	1	1	0	1
27	1	0	1	0	1
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	30	1	31	0	31

身体汚染発生状況報告(2022年10月)

場所: 免震重要棟休憩所 第三工区

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	1	0	0	0
4	0	0	1	1	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	1	0
12	0	0	1	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	1	0	0
18	0	0	1	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	1	0
25	0	0	0	1	0
26	0	0	0	0	0
27	0	0	1	0	0
28	0	0	2	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	1	0	0
合計	0	1	8	4	0

基準値: 4[Bq/cm²] 以下

携行品汚染発生状況報告(2022年10月)

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

場所: 免震重要棟休憩所 第三工区

(単位: 件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	1	0	1	0	1
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	1	0	1	0	1
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	1	0	1	0	1
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	3	0	3	0	3

身体汚染発生状況報告(2022年10月)

場所: 免震重要棟 2階 チェックポイント

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	1	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	1	0	0	0

基準値: 4[Bq/cm²] 以下

携行品汚染発生状況報告(2022年10月)

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

場所: 免震重要棟 2階 チェックポイント

(単位: 件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

身体汚染発生状況報告(2022年10月)

場所: 1/2号機 サービス建屋(1F) 休憩所

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm²] 以下

携行品汚染発生状況報告(2022年10月)

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

場所:1/2号機 サービス建屋(1F) 休憩所

(単位:件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

身体汚染発生状況報告(2022年10月)

場所: 1/2号機 サービス建屋(1F) 装備交換所

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm²] 以下

携行品汚染発生状況報告(2022年10月)

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

場所:1/2号機 サービス建屋(1F) 装備交換所

(単位:件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

身体汚染発生状況報告(2022年10月)

場所: 1/2号機 サービス建屋(2F) 休憩所

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm²] 以下

携行品汚染発生状況報告(2022年10月)

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

場所:1/2号機 サービス建屋(2F) 休憩所

(単位:件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

身体汚染発生状況報告(2022年10月)

場所: 3/4号機 サービス建屋(2F) 休憩所

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

(単位: 件数)

日	身体汚染	下着汚染	靴下汚染	一般服汚染	装備品汚染
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0

基準値: 4[Bq/cm²] 以下

携行品汚染発生状況報告(2022年10月)

作成日	2022年11月1日(火)
作成者	
審査者	
承認者	

場所:3/4号機 サービス建屋(2F) 休憩所

(単位:件数)

日	4Bq/cm ² 以上 40Bq/cm ² 以下	40Bq/cm ² 超過	汚染発生合計	除染措置	
				持出可	持出不可
1	0	0	0	0	0
2	0	0	0	0	0
3	0	0	0	0	0
4	0	0	0	0	0
5	0	0	0	0	0
6	0	0	0	0	0
7	0	0	0	0	0
8	0	0	0	0	0
9	0	0	0	0	0
10	0	0	0	0	0
11	0	0	0	0	0
12	0	0	0	0	0
13	0	0	0	0	0
14	0	0	0	0	0
15	0	0	0	0	0
16	0	0	0	0	0
17	0	0	0	0	0
18	0	0	0	0	0
19	0	0	0	0	0
20	0	0	0	0	0
21	0	0	0	0	0
22	0	0	0	0	0
23	0	0	0	0	0
24	0	0	0	0	0
25	0	0	0	0	0
26	0	0	0	0	0
27	0	0	0	0	0
28	0	0	0	0	0
29	0	0	0	0	0
30	0	0	0	0	0
31	0	0	0	0	0
合計	0	0	0	0	0