

Definite Results of Nuclides Analysis at Fukushima Daiichi Nuclear Power Station (Announced on November 1 - 15, 2012)

< Legend > - : γ nuclides except for the major 3 nuclides (I-131, Cs-134, Cs-137) were not detected. Please refer to the preliminary reports for the result of the major nuclides.
 : γ nuclides other than the major 3 nuclides (I-131, Cs-134, Cs-137) were detected. Please refer to the following pages.
 / : Not applicable or cancelled due to the bad weather

Sampling Point	Announcement Date of the Preliminary Report															
	November															
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	
Nuclides Analysis Result of the Radioactive Materials in the Air at Fukushima Nuclear Power Stations	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Nuclides Analysis Result of the Radioactive Materials in the Air at the Sea Side of Fukushima Nuclear Power Stations	/	-	/	/	/	/	/	/	-	/	/	/	/	/	/	/
Nuclides Analysis Result of Radioactive Materials in the Seawater < Coast >	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Nuclides Analysis Result of the Radioactive Materials in the Seawater of the Port	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Nuclides Analysis Result of the Sub-drain of Fukushima Daiichi NPS	-	/	-	/	/	-	/	-	/	-	/	/	-	/	-	/
Nuclides Analysis Result of Marine Soil	/	-	/	/	/	-	-	/	/	/	/	/	/	/	/	/
Nuclides Analysis Result of the Sub-drain Water in the Surroundings of the Central Radioactive Waste Treatment Facility	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Nuclides Analysis Result of the Radioactive Materials in the Seawater < Coast, Fukushima Daiichi Nuclear Power Station, Remeasurement >	/	/	/	/	/	/	/	-	/	/	/	/	/	/	/	/
Nuclide Analysis Results of Radioactive Materials in the Air above the Reactor Building at Fukushima Daiichi Power Station (Upper Part of Unit 1 Reactor Building)	/	/	/	/	/	/	/	/	-	/	/	/	/	/	/	/
Nuclide Analysis Results of Radioactive Materials in the Air above the Reactor Building at Fukushima Daiichi Power Station (Upper Part of Unit 2 Reactor Building)	/	/	/	/	/	/	/	/	-	/	/	/	/	/	/	/
Nuclide Analysis Results of Radioactive Materials in the Air above the Reactor Building at Fukushima Daiichi Power Station (Unit 3 Upper Part of the Reactor Building)	/	/	/	/	/	/	/	/	-	/	/	/	/	/	/	/
Nuclide Analysis Results of Radioactive Materials in the Air above the Reactor Building at Fukushima Daiichi Power Station (Unit 3 Waste Treatment Building Opening)	/	/	/	/	/	/	/	/	-	/	/	/	/	/	/	/