

Detailed Analysis Results in the Port of Fukushima Daiichi NPS, around Discharge Channel and Bank Protection (Underground Water Obtained at Bank Protection)

Unit: Bq/L

	North of well point between Unit 2, 3 water intake channel	Central of well point between Unit 2, 3 water intake channel	South of well point between Unit 2, 3 water intake channel
Date of sampling	Nov 27, 2013	Nov 27, 2013	Nov 27, 2013
Time of sampling	10:00 AM	10:00 AM	10:00 AM
Cs-134 (Approx. 2 years)	4.3	ND(0.38)	ND(0.42)
Cs-137 (Approx.30 years)	10	ND(0.50)	0.68
The other γ			
All β	55,000	1,400	280
H-3 (Approx. 12 years)	1,500	1,200	510

* Water was sampled from well point by a sampler.

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* "-" indicates that the measurement was out of range.