


## Detailed Analysis Results in the Port of Fukushima Daiichi NPS, around Discharge Channel and Bank Protection (Pumped Water Obtained from Bank Protection)

Unit: Bq/L

		Pumped water from groundwater observation hole No.0-3-2	Pumped water from groundwater observation hole No.1-16
Date of Sampling		Dec 18, 2013	/
Time of sampling		12:00 PM	
Cs-134 (Approx. 2 years)		ND(0.40)	
Cs-137 (Approx.30 years)		ND(0.51)	
The other γ			
Gross β		ND(20)	
H-3 (Approx. 12 years)		Under analysis	

\* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

\* "-" indicates that the measurement was out of range.



[Sampling locations at bank protection]