


Detailed Analysis Results in the Port of Fukushima Daiichi NPS, around Discharge Channel and Bank Protection (Pumped Water Obtained from Bank Protection)

Unit: Bq/L

		Pumped water from groundwater observation hole No.0-3-2
Date of Sampling		Dec 24, 2013
Time of sampling		11:30 AM
Cs-134 (Approx. 2 years)		ND(0.44)
Cs-137 (Approx.30 years)		ND(0.50)
The other γ		
Gross β		ND(18)
H-3 (Approx. 12 years)		Under analysis

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

* "-" indicates that the measurement was out of range.



[Sampling locations at bank protection]