

## Detailed Analysis Results in the Port of Fukushima Daiichi NPS, around Discharge Channel and Bank Protection (Groundwater Obtained from Bank Protection)

Unit: Bq/L (exclude chloride)

		Groundwater observation hole No.1-11
Date of sampling		Dec 26, 2013
Time of sampling		11:12 AM
Chloride (unit: ppm)		-
Cs-134 (Approx. 2 years)		0.72
Cs-137 (Approx.30 years)		1.4
The other γ		
Gross β		2,300
H-3 (Approx. 12 years)		Under analysis
Sr-90 (Approx. 29 years)		-

\* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

\* "-" indicates that the measurement was out of range.

