

Sampling Results Regarding the Influence on the Water Leak at a Tank in the H4 area in Fukushima Daiichi Nuclear Power Station (Around the H4 Area)

Unit: Bq/L

| | Groundwater around H4 area | | | | | | |
|------------------------|----------------------------|----------------|----------------|----------------|----------------|-----|-----|
| | E-1 | E-2 | E-3 | E-4 | E-5 | E-6 | E-8 |
| Date of Sampling | Oct 4, 2013 | Oct 4, 2013 | Oct 4, 2013 | Oct 4, 2013 | Oct 4, 2013 | | |
| Time of sampling | 9:10 AM | 9:21 AM | 9:34 AM | 9:41 AM | 9:55 AM | | |
| All β | 110 | 36 | 57 | 29 | ND(18) | | |
| H-3 (Approx. 12 years) | Under analysis | Under analysis | Under analysis | Under analysis | Under analysis | | |

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

