

Sampling Results Regarding the Influence on the Water Leak at a Tank in the H4 area in Fukushima Daiichi Nuclear Power Station (Pump Well)

Unit: Bq/L

| | Pump wells of the groundwater bypass | | | | | | | |
|------------------------|--------------------------------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|
| | No.5 | No.6 | No.7 | No.8 | No.9 | No.10 | No.11 | No.12 |
| Date of Sampling | Oct 22, 2013 | Oct 22, 2013 | Oct 22, 2013 | Oct 22, 2013 | Oct 22, 2013 | Oct 22, 2013 | Oct 22, 2013 | Oct 22, 2013 |
| Time of sampling | 10:53 AM | 11:03 AM | 11:06 AM | 11:16 AM | 11:20 AM | 11:24 AM | 11:34 AM | 11:39 AM |
| All β | ND(15) | ND(15) | ND(16) | ND(16) | ND(16) | ND(16) | ND(16) | ND(16) |
| H-3 (Approx. 12 years) | 28 | 160 | 320 | 63 | 66 | 290 | 480 | 890 |

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

