Sampling Results Regarding the Influence on the Water Leak at a Tank in the H4 area in Fukushima Daiichi Nuclear Power Station (Around the H4 Area)

Unit: Ba/L

| | Groundwater around H4 area | | | | | |
|------------------------|----------------------------|--------------|--------------|--------------|--------------|--------------|
| | E-1 | E-2 | E-3 | E-4 | E-5 | E-6 |
| Date of Sampling | Sep 25, 2013 | Sep 25, 2013 | Sep 25, 2013 | Sep 25, 2013 | Sep 25, 2013 | Sep 25, 2013 |
| Time of sampling | 11:10 AM | 11:16 AM | 11:40 AM | 11:35 AM | 11:30 AM | 12:00 PM |
| All β | 190 | 22 | 190 | ND(18) | 76 | 25 |
| H-3 (Approx. 12 years) | 170,000 | 360 | 170 | 390 | ND(120) | 340 |

* "ND" indicates that the measurement result is below the detection limit, and the detection limit of each nuclide is provided in parentheses.

