

Nuclides Analysis Result of the Sub-drain Water in the Surroundings of the Central Radioactive Waste Treatment Facility

I-131(Bq/cm³)

Table with columns: Sampling Location, After transfer, May 12, May 13, May 14, May 15, May 16, May 17, May 18, May 19, May 20, May 21, May 22, May 23, May 24, May 25, May 26. Rows 1-9.

Cs-134(Bq/cm³)

Table with columns: Sampling Location, May 12, May 13, May 14, May 15, May 16, May 17, May 18, May 19, May 20, May 21, May 22, May 23, May 24, May 25, May 26. Rows 1-9.

Cs-137(Bq/cm³)

Table with columns: Sampling Location, May 12, May 13, May 14, May 15, May 16, May 17, May 18, May 19, May 20, May 21, May 22, May 23, May 24, May 25, May 26. Rows 1-9.

* Hyphen "-" indicates that neither sampling nor measurement was implemented.
* ⑥ was selected as a sampling location in the upstream of groundwater (sampling done once a week starting from April 29, 2011) since it became unable to do sampling at ④.
* Sampling at ⑦ (located in the downstream of the groundwater) has been done since May 26, 2011.
* Sampling at ⑧ since May 30, 2011
* Sampling at ⑨ has been done since August 2, 2011
* "ND" indicates that the measurement result is below the detection limit.

I-131: Approx. 0.01Bq/cm³, Cs-134: Approx.0.02Bq/cm³, Cs-137: Approx.0.02Bq/cm³ (May 26, 2013)
As the detection limit may vary depending on the detectors and sample properties, there are cases where nuclides below the detection limit are detected.

- <Place of Sampling>
① Southeast of Unit 4 Turbine Building
② Northeast of the Process Main Building
③ Southeast of the Process Main Building
④ Southwest of the Process Main Building
⑤ South Part of the Miscellaneous Solid Waste Volume Reduction Treatment Building
⑥ Southwest Part of the On-site Bunker Building
⑦ West Side of the Incineration Workshop Building
⑧ North Part of the Miscellaneous Solid Waste Volume Reduction Treatment Building
⑨ Southeast Part of the On-site Bunker Building