

Result of Pu Nuclide Analysis of Sub-Drain at Fukushima Daiichi Nuclear Power Station

1. Measurement Result:

(Unit: Bq/cm³)

Place of Sampling	Date	Pu-238	Pu-239+Pu-240
Unit 2 Sub-Drain	Dec 10, 2012	N.D. [$<6.2 \times 10^{-7}$]	N.D. [$<6.2 \times 10^{-7}$]
Unit 4 Sub-Drain		N.D. [$<7.5 \times 10^{-7}$]	N.D. [$<7.5 \times 10^{-7}$]

[] shows below the detection limit.

2. Analytical Institution

KAKEN Inc.

3. Evaluation:

Pu-238 and Pu-239+Pu-240 were not detected in the sample collected this time.

End