

## Analysis Results of Rainwater Obtained Inside the Dike at the Tank Area After Treated by the Rainwater Treatment System

### <Mobile RO membrane system>

Sampling place	Place of analysis	Sampling date	Sampling time	Bq/L	Bq/L	Bq/L	Bq/L	Notification density rate
				Cs-134	Cs-137	Gross $\beta$	Tritium	
Treated water tank	Chemical Analysis	May 15	11:20 AM	<4.6E-01	<6.0E-01	<4.4E+00	<1.2E+02	0.16
	Laboratory at Unit 5 and 6	May 15	11:20 AM	<4.6E-01	9.0E-01	<4.3E+00	<1.1E+02	0.16

### <Desalination RO membrane system>

Sampling place	Place of analysis	Sampling date	Sampling time	Bq/L	Bq/L	Bq/L	Bq/L	Notification density rate
				Cs-134	Cs-137	Gross $\beta$	Tritium	
Treated water tank	Chemical Analysis	May 15	11:50 AM	<8.2E-01	<7.4E-01	<4.4E+00	2.0E+02	0.17
	Laboratory at Unit 5 and 6	May 15	11:50 AM	<5.2E-01	<7.6E-01	<4.3E+00	1.4E+02	0.16