

Results of the radioactive material analysis related to the leaked water from the pipeline connecting from Desalination System (Reverse Osmosis Membrane) to Concentrated Water Storage Tank in Fukushima Daiichi Nuclear Power Station

Unit 1 to 4 side of South Discharge Channel

【Sampling Point】 Unit 1 to 4 side of South Discharge Channel, Fukushima Daiichi NPS

【Sampling Date and Time】 At 6:00 AM on October 21, 2014

【Results】

| Nuclide | Concentration of Radioactive Material (Bq/cm ³) | Detection Limit (Bq/cm ³) | Half-life Period |
|---------|---|---------------------------------------|------------------|
| I-131 | Below Detection Limit | 6.8X10 ⁻⁴ | About 8 days |
| Cs-134 | Below Detection Limit | 8.1X10 ⁻⁴ | About 2 years |
| Cs-137 | 1.1X10 ⁻³ | 4.6X10 ⁻⁴ | About 30 years |
| Gross β | 1.1X10 ⁻² | 4.7X10 ⁻³ | - |

This shows only detected γ nuclides.