Nuclides Analysis Result of the Sub-drain Water in the Surroundings of the Central Radioactive Waste Treatment Facility

I-131(Ba/cm³)

1 10 1(B0	Tro (Layerin)																		
Sampling																			
Location	Oct 5	Oct 6	Oct 7	Oct 8	Oct 9	Oct 10	Oct 11	Oct 12	Oct 13	Oct 14	Oct 15	Oct 16	Oct 17	Oct 18	Oct 19	Oct 20	Oct 21		
1	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
2	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
3	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
4	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
⑤	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
6	-	* 1	ND	-	-	-	-	-	ND	-	-	-	-	-	-	ND	-		
7	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
8	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
9	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								

Cs-134(Rg/cm³)

C3-13 -1 (Dq/GIII /																		
Sampling																			
Location	Oct 5	Oct 6	Oct 7	Oct 8	Oct 9	Oct 10	Oct 11	Oct 12	Oct 13	Oct 14	Oct 15	Oct 16	Oct 17	Oct 18	Oct 19	Oct 20	Oct 21		
1	ND	* 1	0.019	ND	ND	0.012	ND	ND	ND	* 1	0.018	ND	0.022	ND	ND	0.023	ND		
2	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
3	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
4	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
(5)	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
6	-	* 1	ND	-	-	-	-	-	ND	-	-	-	-	-	-	ND	-		
7	0.032	* 1	0.015	0.032	0.03	0.021	0.037	0.029	0.049	* 1	0.034	0.016	0.035	0.022	0.039	0.026	0.037		
8	ND	* 1	0.033	0.043	0.026	0.019	0.018	0.018	0.014	* 1	0.029	0.019	0.02	0.019	0.028	0.013	0.026		
9	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								

Cs-137(Bq/cm³)

Sampling																			
Location	Oct 5	Oct 6	Oct 7	Oct 8	Oct 9	Oct 10	Oct 11	Oct 12	Oct 13	Oct 14	Oct 15	Oct 16	Oct 17	Oct 18	Oct 19	Oct 20	Oct 21		
1	ND	* 1	0.041	ND	ND	0.044	ND	ND	ND	* 1	0.056	0.027	0.068	0.022	0.02	0.08	0.034		
2	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
3	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
4	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		
⑤	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								
6	-	* 1	ND	-	-	-	-	-	ND	-	-	-	-	-	-	ND	-		
7	0.083	* 1	0.061	0.098	0.1	0.083	0.11	0.12	0.11	* 1	0.087	0.065	0.13	0.085	0.12	0.073	0.095		
8	ND	* 1	0.098	0.097	0.061	0.046	0.08	0.058	0.063	* 1	0.089	0.071	0.063	0.067	0.042	0.03	0.053		
9	ND	* 1	ND	ND	ND	ND	ND	ND	ND	* 1	ND								

- * Hyphen "-" indicates that neither sampling nor measurement was implemented.
 * (6) was selected as a sampling location in the upstream of groundwater (sampling done once a

- starting from April 29, 2011) since it became unable to do sampling at 4. * Sampling at 7 (located in the downstream of the groundwater) has been done since May 26, 2011.
- * Samping at ® since May 30, 2011
- * Sampling at (9) has been done since August 2, 2011
- * "ND" indicates that the measurement result is below the detection limit.
- I-131: Approx. 0.01Bq/cm³, Cs-134: Approx.0.01Bq/cm³, Cs-137: Approx.0.02Bq/cm³ (October 21, 2014)

As the detection limit may vary depending on the detectors and sample properties, there are cases where nuclides below the detection limit are detected.

<Place of Sampling>

- 1 Southeast of Unit 4 Turbine Building
- ② Northeast of the Process Main Building
- 3 Southeast of the Process Main Building
- 4 Southwest of the Process Main Building
- ⑤ South Part of the Miscellaneous Solid Waste Volume Reduction

Treatment Building

- 6 Southwest Part of the On-site Bunker Building
- (7) West Side of the Incineration Workshop Building
- 8 North Part of the Miscellaneous Solid Waste Volume Reduction Treatment
- Southeast Part of the On-site Bunker Building

^{*1} Not sampled because of bad weather (October 6 and 14, 2014)