

December 3, 2012

Partial Corrections to “Overview of the Radiation Exposure Doses of the Workers at Fukushima Daiichi Nuclear Power Station”

With regard to page 8 of the handout “Overview of the Radiation Exposure Doses of the Workers at Fukushima Daiichi Nuclear Power Station” which announced on December 3, 2012, it has been confirmed that there were some incorrect descriptions and therefore we hereby would like to correct them as follows.

We had already corrected the handout posted on our website.

The summary is as follows.

< Page 8 >

1-4 Cumulative Exposure Dose after the Accident

- The majority of the workers were dismissed with exposure dose substantially lower than the dose limit stipulated by law, and therefore are still capable of engaging in radiation work.
- Of the **74** dismissed workers with exposure dose exceeding 100mSv or close to the dose limit stipulated by law (exceeding 75mSv), **71** workers are still employed in locations other than Fukushima Daiichi Nuclear Power Station.

(Source: Interview with the main contractor regarding the workers dismissed by July 31, 2012. As of November 2012)

False: 95

False: 91

8

* We have counted workers with exposure dose exceeding 100mSv twice.
(Reference)
Workers with exposure dose exceeding 100mSv: 21
(including 20 workers still employed in locations other than Fukushima Daiichi NPS)
Workers with exposure dose exceeding 75mSv and less or equal to 100mSv: 53
(including 51 workers still employed in locations other than Fukushima Daiichi NPS)

* Website address of this handout
http://www.tepco.co.jp/en/nu/fukushima-np/images/handouts_121203_01-e.pdf