


Completion of Reliability Improvement Work for Units 2-4 Accumulated Water Transfer Pipeline at Fukushima Daiichi Nuclear Power Station



Units 2-4 Accumulated water transfer pipeline (replaced with polyethylene pipe)

- Transfer pipeline which has been replaced with polyethylene pipe
- Transfer pipeline where pressure hose is used
- Transfer pipeline which has been replaced with polyethylene pipe this time