

# Power Supply Facilities Failure at Fukushima Daiichi Nuclear Power Station (As of 4:30 PM on March 20)

< Reference >  
March 20, 2013  
Tokyo Electric Power Company




Full view of Units 3-4 temporary M/C M/C (A) (Photo taken at Units 3-4 switchyard)



Appearance of Units 3-4 temporary M/C



Inspection of Units 3-4 temporary M/C



Units 3-4 temporary M/C M/C (A) power panel and its door




Units 3-4 temporary M/C with the power panel door opened (below the power panel where soot was found)



Soot found on the instrument current transformer (terminal) of Units 3-4 temporary M/C



Soot found on the walls of Units 3-4 temporary M/C



Units 3-4 temporary M/C M/C (A) power panel and its door



Small animal found dead (Photo taken from above)