


Condition of the Skimmer Surge Tank Hatch Cover Found During Debris Removal from the Upper Part of Unit 3 Reactor Building at Fukushima Daiichi Nuclear Power Station (1)


< Reference >

April 19, 2013

Tokyo Electric Power Company



Location of the skimmer surge tank



Equipment hatch

Condition of the Skimmer Surge Tank Hatch Cover Found During Debris Removal from the Upper Part of Unit 3 Reactor Building at Fukushima Daiichi Nuclear Power Station (2)




1. Before work (April 17, 2013)



3. Hatch returned to its original position (April 18, 2013)



2. During work (April 18, 2013)



4. After work (April 18, 2013)

End