
Progress of the Water Transfer from the Underground Reservoirs



^{*1} The transferred amount was confirmed by the water gauge installed at the H2 area tank.

^{*3} Around 12:15 PM on June 5, water transfer was suspended since the water leakage was found at G6 tank.

Transfer route	Progress of Started	of transfer Ended
No.6 → G6 tank*2	6/5 9:25 6/6 14:38	6/5 12:45 ^{*3} 6/6 16:59
	6/7 9:36	6/7 16:54

^{*2} Remaining water is transferred utilizing a temporary line during daytime.