

# Oil Leakage at the Desalination System (RO-3) in Fukushima Daiichi Nuclear Power Station

<Reference>  
July 22, 2013  
Tokyo Electric Power Company

## ■ Leakage condition



Appearance of a high-pressure pump



Oil filler opening of a high-pressure pump




Oil filler cap (same item with the cap used when the incident occurred)



Oil gauge (same item with the gauge used when the incident occurred)

# Oil Leakage Location of the Desalination System (RO3)

- Temporary house of the desalination system (RO3)



# Oil Leakage Location of the Desalination System (RO3)

From the waste liquid  
RO supply pump

