



Condition of the Bank Protection Area at Fukushima Daiichi Nuclear Power Station

<Reference>
September 4, 2013
Tokyo Electric Power Company




* Automatic measurement data measured by water gauge

■Progress Status of Ground Improvement Construction between Unit 1 and 2 (as of the morning on September 4)




* The range of the construction is subject to change depends on the site status.

■Progress Status of Ground Improvement Construction between Unit 2 and 3 (as of the morning on September 4)



■Progress Status of Ground Improvement Construction between Unit 3 and 4 (as of the morning on September 4)



*1 The range of the construction is subject to change depends on the site status.

*2 Groundwater observation hole No.3-1 will be not in use due to the ground improvement construction.