


Unit 3 Reactor Building, at Fukushima Daiichi Nuclear Power Station, The Bent-Down Tip Jib Mast and Main Mast of a Remote Control Large-Scale Crane

<Reference>
September 10, 2013
Tokyo Electric Power Company


On September 10, we laid the tip jib mast and the main mast of a remote control large-scale crane on the ground in order to bring the crane into a more stable-situation, regarding that the masts of the crane bent down on September 5, 2013.

We will perform a safety check including investigation of the cause of the tip jib mast bent down.

■ Current situation of the involved crane after work



■ Current situation of laying the tip jib mast and the main mast on the ground



Before work



After work

Photos taken on September 10 and provided by TEPCO