Revised VersionSandbags at the Drainage Channel B Being Swept Away Due to RainfallSeptfrom the Approaching Typhoon at Fukushima Daiichi NPSTokyo Electric F

infall <a href="https://www.example.com"><a href="https://www.example.com"><a href="https://www.example.com"><a href="https://www.example.com"><a href="https://www.example.com"><a href="https://www.example.com"><a href="https://www.example.com"></a></a></a>
September 17, 2013
Tokyo Electric Power Company


## (Chronological order)


- At around 1:30 PM today (on September 15), sandbags that had been set at the drainage channel B (at a point immediately short of the junction with the drainage channel C) in the contaminated water storage tank area were found to have been swept away due to rainfall from the approaching typhoon.

- At 3:20 PM on the same day, we completed work of resetting sandbags at this location.


- Before sandbags were swept away, we already collected residual water in front of the sandbags set at the drainage channel B using a pump by the morning on September 15\*, in preparation for the typhoon.

\* We have corrected the date from September 14 to September 15. (Correction date: September 17)





Condition before the sandbags were swept away (Photo was taken By TEPCO on September 15, 2013)



Condition after the sandbags were swept away (Photo was taken By TEPCO on September 15, 2013)